
DISTRIBUTION:

National Register property file

Nominating Authority (without nomination attachment)

	Name of Property
	County and State
n number Page	Name of multiple property listing (if applicable)
and the state of t	
SUPPLEMENTARY LIST	TING RECORD
NRIS Reference Number: 07001021	
Property Name: Converse Heights Historic District	
County: Spartanburg State: South Carolina	
Multiple Name: <u>N/A</u>	
This property is listed in the National Register of Historic	Places in accordance with the attached
nomination documentation subject to the following except	ions, exclusions, or amendments,
notwithstanding the National Park Service certification inc	cluded in the nomination documentation.
I suche le	
Signature of the Keeper Date of A	er 25, 2007 Action
) Signature of the recept	
Amended Items in Nomination:	
Section 10: The Acreage for this district is, hereby, entered	d oc 699 pares
	d as odd acres.

### National Register of Historic Places Registration Form



102

OMB No. 1024-0018

This form is for use in nominating or requesting determinations for individual properties and districts. See instructions in How to Complete the National Register of Historic Places Registration Form (National Register Bulletin 16A). Complete each item by marking "x" in the appropriate box or by entering the information requested. If any item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions. Place additional entries and narrative items on continuation sheets (NPS Form 10-900a). Use a typewriter, word processor, or computer to complete all items.

1. Name of Property
historic name Converse Heights Historic District other names/site number
2. Location
street & numberSE of E. Main St. and NE of Pine St., containing properties along portions of Clifton, Connecticut, & Glendalyn Aves., Hale & Maple Sts., Mills Ave., Norwood St., Otis Blvd., Palmetto, Plume, Poplar, & Rutledge Sts., S. Fairview Ave, and Woodland St not for publication N/A city or town Spartanburg vicinity stateSouth Carolina code SCcountySpartanburg code083 zip code29302
3. State/Federal Agency Certification
As the designated authority under the National Historic Preservation Act of 1986, as amended, I hereby certify that this X_nomination request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property X_meetsdoes not meet the National Register Criteria. I recommend that this property be considered significant nationallystatewide X locally. (See continuation sheet for additional comments.)
Signature of certifying official Date 8 03 0 7 Rodger E. Stroup, State Historic Preservation Officer, S.C. Dept. of Archives and History, Columbia, S.C. State or Federal agency and bureau
In my opinion, the property meetsdoes not meet the National Register criteria. (See continuation sheet for additional comments.)
Signature of commenting or other official Date
State or Federal agency and bureau
4. National Park Service Certification
Signature of the Keeper Date of Action I, hereby certify that this property is:
entered in the National RegisterSee continuation sheetdetermined eligible for the National RegisterSee continuation sheetdetermined not eligible for the National Registerremoved from the National Registerother (explain):

Spartanburg County, South Carolina County and State

Converse H	eights Historic	District	
Name of Prop	perty		

	$\sim$		4:	4:
Э.	U	assi	nca	tion

Ownership of Prope (Check as many boxes as apply)		rty Number of Res (Do not include previou	sources within last sly listed resources)	Property
X privatepublic-localpublic-Statepublic-Federal	building(s) _X district site structure	Contributing 460	Noncontribu 75	ting buildings sites structures
	_ object	460	75	objects Total
Name of related multiple (Enter "N/A" if property is not par N/A  6. Function or Use		Number of contributing r in the National Register 1	esources previous	sly listed
Historic Functions (Enter categories from instruction	ns)			
Category: Domesti Domesti Landsca	ic	Single Dwelling Multiple Dwelling Park		
Current Functions (Enter categories from instruction	ns)			
Category: Domesti Domesti Recreat	<u> </u>	Single Dwelling Multiple Dwelling Outdoor Recreat		

### 7. Description

Ar	cni	tectur	al C	lassiti	cation

(Enter categories from instructions)

Late 19<sup>th</sup> & 20<sup>th</sup> Century Revivals /

Late 19<sup>th</sup> & Early 20<sup>th</sup> Century American Movements/

Bungalow, Craftsman

#### Materials

(Enter categories from instructions) **Brick** 

foundation

Wood walls

Brick

Stone

Asphalt

<u>Tile</u>

Slate

other

roof

National	Register	of	<b>Historic</b>	<b>Places</b>
Continua	ation She	et		

Section number	7	Page	5	
		ugo _	_	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

#### NARRATIVE DESCRIPTION

The Converse Heights Historic District is a collection of 526 primarily single and multi-family residential properties in the City of Spartanburg. The neighborhood is located due east of the downtown business district and was originally one of Spartanburg's "streetcar suburbs". The district includes 461 contributing buildings and 65 non-contributing buildings.

The Converse Heights Historic District is roughly bounded by East Main Street to the north; Pine Street to the west; Woodland, Connecticut and Palmetto Streets to the south and includes properties along portions of Clifton Avenue, Connecticut Avenue, Glendalyn Avenue, Hale Street, Maple Street, Mills Avenue, Norwood Street, Otis Boulevard, Palmetto Street, Plume Street, Poplar Street, Rutledge Street, South Fairview Avenue, and Woodland Street.

This district, which began official development as a separate neighborhood in 1907 and continued to grow through the 1950s, includes single and multi-family residential buildings in the Queen Anne, American Foursquare, Craftsman, Spanish Mission, Tudor Revival, Colonial Revival, Neo-Classical and Minimal Traditional styles.

Today, properties within the Converse Heights neighborhood remain primarily single-family residences. There are several duplexes scattered throughout the district. There have been some homes demolished within the district and many homes have had alterations over time, but the overall character of the Converse Heights neighborhood has remained through the preservation of historic landscapes, streetscapes and architectural styles. Changes to area homes has and will continue to occur, but is being done in a sensitive manner that will continue to preserve the overall feel and style of this continually evolving neighborhood.

### National Register of Historic Places Continuation Sheet

Section	number	7	Page _	6	
000000			~9~ _		

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

### **Contributing Properties**

#### **CLIFTON AVENUE**

- 1. 166 Clifton Avenue ca. 1922 The two story home is wood frame construction with weatherboard exterior, brick foundation, and lateral gable roof clad in composition shingles. There is a large shed dormer on the main façade, wrap porch, entry door with sidelgiths and transom, six-over-one double hung sash windows, roof brackets, and porch supported with tripartite wooden columns resting on brick piers.
- 2. 177 Clifton Avenue ca. 1920 The two story home is wood frame construction with weatherboard exterior siding, brick foundation, and lateral gable roof clad in composition shingles. The recessed entry porch has been enclosed. There are shed dormers, six-over-one and eight-over-one double hung sash windows, exposed rafter tails beneath the eaves and attic vent in the gable end.
- 3. **178 Clifton Avenue** ca. 1925 The two story home is wood frame construction with weatherboard exterior siding, brick foundation, and pyramidal roof clad in compositions shingles. The American Foursquare style home has a front and side porch both supported with tapered wooden posts resting on brick piers, entry door with transom, six-over-one double hung sash windows, and decorative brackets beneath the eaves.
- 4. **183 Clifton Avenue** ca. 1927 The one story home is wood frame construction with weatherboard exterior, brick foundation, and hip roof clad in composition shingles. The porch is supported with tripartite columns and there is a six-pane window flanked by attic vents in the gable end. There are six-over-one double hung sash windows.
- 5. **184 Clifton Avenue** ca. 1920 The one story home is wood frame construction with weatherboard and wood shingle exterior, brick foundation and cross gable roof clad in composition shingles. The gable porch is supported with paired wooden posts resting on brick piers with a ten-pane window in the gable end. There are six-over-one and eight-over-one double hung sash windows, exposed rafter tails beneath the eaves, and tapered chimney on the north elevation.
- 6. **189 Clifton Avenue** ca. 1920 The one story home is wood frame construction with aluminum exterior siding, brick foundation and gable roof clad in composition shingles. The bungalow has gently arched front porch openings supported with tripartite wooden posts resting on brick piers. The windows are have a large central pane framed by four small square pones on the top and bottom.

### National Register of Historic Places Continuation Sheet

Section number	7	Page	7
Section number		raye _	

- 7. 199 Clifton Avenue ca. 1920 The two story home is wood frame construction with weatherboard exterior siding, brick foundation, and hipped roof clad in composition shingles. The American Four Square home has a twelve-pane glass entry door with matching side lights and transom, flat roof over the entry porch supported with paired classical columns, paired nine-over-one double hung sash windows with shutters, and brick chimney on the south elevation.
- 8. **211 Clifton Avenue** ca. 1920 The one story home is wood frame construction with wood shingle and synthetic exterior siding and hipped roof clad in composition shingles. There is a porte cochere on the north elevation, entry door with sidelights, six-over-one and four-over-one double hung sash windows, porch supported with paired wooden posts resting on brick piers and decorative roof brackets beneath the eaves.
- 9. **212 Clifton Avenue** ca. 1920 The two story home is wood frame construction with synthetic exterior siding, brick foundation, and gambrel roof clad in composition shingles. There are six-over-one double hung sash windows, gently arched entry supported with paired columns, and entry door with sidelights and fanlight.
- 10. **216 Clifton Avenue** ca. 1920 The two story home is wood frame construction with synthetic exterior siding, brick foundation, and lateral gable roof clad in composition shingles. There are six-over-one double hung sash windows, gently arched entry supported with paired columns, and entry door with sidelights and fanlight. There is a two car garage on the rear façade.
- 11. **217 Clifton Avenue** ca. 1920 The one story home is wood frame construction with weatherboard exterior, brick foundation, and hipped roof clad in composition shingles. There are three-over-one, four-over-one, and six-over-one double hung sash windows; porte cochere, centered attic dormer with six pane window; entry door with sidelights; and porch supported with paired wooden posts on brick piers.
- 12. **222 Clifton Avenue** ca. 1935 The one story home is wood frame construction with wood shingle and synthetic exterior siding, brick foundation and lateral gable roof clad in composition shingles. The porch is supported with paired and tripartite square columns and has a louvered vent in the gable end. There are six-over-one double hung sash windows and central chimney.
- 13. **223** Clifton Avenue ca. 1920 The one story home is wood frame construction with wood shingle exterior, brick foundation, and hipped roof clad in composition shingles. There is a central dormer on the main façade with hipped roof containing a three paned window flanked by attic vents. There are five-over-one double hung sash windows, entry door with sidelights and transom, porch supported with paired wooden columns resting on brick piers and central chimney.

### National Register of Historic Places Continuation Sheet

Section number	7	Page	8	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 14. **227 Clifton Avenue** ca. 1920 The one story home is wood frame construction with weatherboard and wood shingle exterior, brick foundation, and lateral gable roof clad in composition shingles. There are three-over-one double hung sash windows with shutters, gable porch with steeply pitched roofline supported with paired wooden posts resting on brick piers and a central chimney.
- 15. **235 Clifton Avenue** ca. 1922 The two story home is wood frame construction with synthetic exterior siding, brick foundation and hipped roof clad in composition shingles. The American Four Square home has eight-over-one double hung sash windows, an entry door with sidelights, gable porch with pediment over the entry door supported with classical columns, and sun porch with modern casement windows and quoin detailing.

#### CONNECTICUT AVENUE

- 16. 120 Connecticut Avenue 1925 The two story home is wood frame construction with gable porch supported with large, square posts. There are exposed rafter tails beneath the eaves and double hung sash windows.
- 17. **124 Connecticut Avenue** ca. 1910 The two story home is wood frame construction with shiplap exterior siding and brick foundation. The main entry door has a transom and sidelights.
- 18. **125** Connecticut Avenue ca. 1922 The one story home is wood frame construction with wood shingle exterior and brick foundation. The main entry door has a transom and sidelights. There are exposed rafter tails beneath the eaves. The porch on the main façade is supported with Craftsman style piers.
- 19. **140 Connecticut Avenue** ca. 1930 The one story home is wood frame construction with front gable roof clad in composition shingles and gable porch that extends to a porte cochere on the right elevation. Square wooden posts on brick piers support the gable porch. Windows are five-over-one double hung sash.
- 20. **150 Connecticut Avenue** ca. 1930 The one story home is wood frame construction with stucco exterior and front gable roof. Tapered wooden posts resting on brick piers support the engaged porch. The entry door is flanked by craftsman-style sidelights. Windows are six-over-one double hung sash.
- 21. **157 Connecticut Avenue** ca. 1925 The one story home is wood frame construction with stucco exterior and slate roof. The windows are four-over-one double hung sash windows and the entry is arched. There is a circular window to the right of the main entry door.
- 22. **163 Connecticut Avenue** ca. 1925 The one story home is wood frame construction with stucco exterior and hip roof.

### National Register of Historic Places Continuation Sheet

Section number _	7	Page	9

- 23. **176 Connecticut Avenue** ca. 1920 The one story home is wood frame construction with wood shingle exterior and brick foundation. The side gable roof has a dormer on the main façade. The full façade porch is partially screened.
- 24. 177 Connecticut Avenue ca. 1920 The two story home is wood frame with aluminum exterior siding and brick foundation. The porch is supported with square posts. The gable end on the main façade contains a single attic vent. The main entry door is topped with a transom. There are exposed rafter tails beneath the roof eaves.
- 25. **180 Connecticut Avenue** ca. 1920 The one story home is wood frame construction with wood shingle exterior and brick foundation. The porch is supported with square wooden posts resting on brick piers.
- 26. **183 Connecticut Avenue** ca. 1927 The two story home is wood frame construction with aluminum exterior siding and hip roof. The porch is supported with Doric columns and is offset on the main façade. The main entry door has a transom and sidelights. There is a bay window on the main façade with copper roof.
- 27. **184 Connecticut Avenue** ca. 1920 The one story home is wood frame construction with wood shingle exterior, brick foundation, and lateral gable roof with gable dormer. The porch is supported with wooden posts resting on brick piers and wood shingle balustrade. The front door is flanked with sidelights.
- 28. **187 Connecticut Avenue** ca. 1925 The two story home is wood frame with aluminum exterior siding and brick foundation. The side gable roof contains a single eyebrow dormer. The porch to the right is supported with classical columns.
- 29. **199 Connecticut Avenue** ca. 1927 The two story home is wood frame construction with stucco exterior and hip roof. The full façade porch is supported with classical columns. The main entry door is flanked by sidelights.
- 30. **211 Connecticut Avenue** ca. 1940 The one story home is wood frame construction with weatherboard & brick exterior. The small entry porch has an arched entryway. There is a brick exterior chimney.
- 31. **215 Connecticut Avenue** ca. The one story Craftsman Bungalow home is wood frame construction with wood shingle exterior and brick foundation. The gable end contains an attic window flanked by louvered vents. The main entry door has a transom and sidelights. There are exposed rafter tails beneath the eaves.

## National Register of Historic Places Continuation Sheet

Section number	7	Page	10	

- 32. **218 Connecticut Avenue** ca. 1927 The home is masonry construction with brick exterior and hip roof clad in clay tile. The entry door sits beneath an arched gable and has a transom and sidelights. There are gable porches on the side elevations.
- 33. **221 Connecticut Avenue** ca. 1927 The one story home is wood frame construction with synthetic siding exterior, brick foundation and hip roof. The windows are nine-over-one double hung sash. The porch is supported with square posts.
- 34. **228 Connecticut Avenue** ca. 1924 The one story home is wood frame construction with wood shingle and brick exterior and brick foundation. The front and side porches are supported with square posts.
- 35. **229 Connecticut Avenue** ca. 1927 The one story home is wood frame construction with synthetic exterior siding, brick foundation and hip roof with gable dormer on the main façade. There is a set of ribbon windows on the main façade.
- 36. **232 Connecticut Avenue** ca. 1924 The one story home is wood frame construction with synthetic exterior siding and brick foundation. There is a gable dormer on the main façade containing a louvered attic vent. The porch is supported by Craftsman style columns and there is a set of ribbon windows on the main façade.
- 37. **237 Connecticut Avenue** ca. 1910 The one story home is wood frame construction with wood shingle exterior and brick foundation. The hip roof has a gable dormer on the main façade and the porch is supported with square wooden posts.
- 38. **242 Connecticut Avenue** ca. 1927 The two story home is wood frame construction with brick veneer exterior and hip roof. The entry door has a transom and sidelights,
- 39. **246 Connecticut Avenue** ca. 1925 The one story home is wood frame construction with weatherboard exterior and brick foundation. The main entry door has a transom and sidelights. The dormer on the main façade contains a single attic vent. The porch is supported with brick columns.
- 40. **254 Connecticut Avenue** ca. 1919 The two story American Four-Square home is wood frame construction with weatherboard & wood shingle exterior with brick foundation and hip roof clad in tile. The hip roof porch is supported with square posts. There is a dormer on the main façade.

# National Register of Historic Places Continuation Sheet

Section number	7	Page	11

- 41. **269 Connecticut Avenue** ca. 1945 The two story home is wood frame construction with yellow brick veneer exterior and hipped roof clad in tile. The double entry door has frosted sidelights and transom and sits beneath a curved porch supported with ionic columns. There is a second entry door above the main entry sitting beneath a dome supported by wrought iron posts. The second story porch wraps to the side elevations and has a wrought iron balustrade. There are projecting bay windows on the main façade flanking the main entry door.
- 42. **329 Connecticut Avenue** ca. 1950 The two story home is masonry construction with painted brick exterior and lateral gable roof clad in slate tiles. Windows are six-over-six double hung sash. There is a flat entry porch in the center of the main façade supported with simple classical columns. There is a two-story gable wing on the right elevation.
- 43. 330 Connecticut Avenue 1925 The two story home is frame construction with weatherboard exterior, brick foundation and hip roof. The windows are six-over-six double hung sash and the paneled entry door has a simple pediment.
- 44. **331 Connecticut Avenue** ca. 1923 The two story home is masonry construction with painted brick exterior and hipped roof clad in red clay tiles. There is a semi-circular entry porch supported with simple classical columns with iron balustrade along the roofline. Windows are eight-over-eight double hung sash and the main entry door has sidelights with a fanlight above.
- 45. **332 Connecticut Avenue** 1942 The two story home is masonry construction with brick exterior and hip roof. The roof is flared over the entryway with dentil detailing and square column supports. There are one-story wings on each side elevation.
- 46. **344 Connecticut Avenue** 1925 The home has a hip roof, small gable entry porch, paneled entry door with fanlight above. Windows are six-over-one double hung sash.
- 47. **Jeffords, S.L. House, 354 Connecticut Avenue** 1927 The one story home was the residence of S.L. Jeffords, district agronomist for Clemson College. The wood frame home is clad in weatherboard with a brick foundation. The porch is supported with tapered wooden posts resting on brick piers. There are exposed rafter tails and brackets beneath the eaves. Windows are six-over-one double hung sash.
- 48. **364 Connecticut Avenue** ca. 1919 The one story home is masonry construction with stucco exterior and flat roof with parapet wall. There are casement windows and shed roof side entry both with tile roofs. There is a square entry porch supported with square posts with arched detailing.

## National Register of Historic Places Continuation Sheet

Castian number	7	Dogo	10
Section number		Page _	12

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 49. **368 Connecticut Avenue** ca. 1933 The one-and-one-half story home is masonry construction with stucco exterior and lateral gable roof clad in composition shingles. There is a gable dormer on the main façade containing a six-over-six double hung sash windows. There is a front facing gable on the main façade that contains the arched entry door and exterior chimney with arched panel detail. There are nine-over-nine double hung sash windows, engaged porch enclosed with screen to the left of the main entry, and Tudor style gable decoration.
- 50. **370 Connecticut Avenue** ca. 1940 The one-and-one-half story home is masonry construction with stucco exterior, and lateral gable roof clad in composition shingles. There are six-over-one double hung sash windows, large gable dormer on the main façade with six-over-six double hung sash windows and thin half-timber detailing, and small entry porch with arched entry.
- 51. 372 Connecticut Avenue ca. 1940 The two story home is wood frame construction with weatherboard exterior siding, brick foundation, and lateral gable roof clad in composition shingles. There are eight-over-eight double hung sash windows, entry door with sidelights, shallow front projecting gable on the left side of the main façade and second story that slightly projects over the first floor. There is a gable porch on the left elevation and large porch on the rear.
- 52. **400 Connecticut Avenue** ca. 1925 The one-and-one-half story home is masonry construction with brick exterior and lateral gable roof clad in composition shingles. There are two front facing gables on the main façade, the smaller containing the slightly arched entry. There is an exterior chimney on the main façade, four-over-one double hung sash windows (alternating paired and tripartite throughout), a large hipped roof wing on the rear of the home and small windows in each gable end.
- 53. **402 Connecticut Avenue** ca. 1925 The two story home is wood frame construction with weatherboard exterior, brick foundation, and lateral gable roof clad in composition shingles. There is a small gable entry porch, six-over-six double hung sash windows, one-story gable porch enclosed with screen on the left elevation, large two-story addition on the rear façade, and exterior end brick chimney on the right elevation.

#### SOUTH FAIRVIEW AVENUJE

- 54. **129 South Fairview Avenue** ca. 1935 The one-and-one-half story home is wood frame construction with brick veneer exterior and gable roof clad in composition shingles.
- 55. **151 South Fairview Avenue** ca. 1925 The one-story home is wood frame construction with weatherboard exterior and gable roof clad in composition shingles.
- 56. **155 South Fairview Avenue** ca. 1925 The two-story home is wood frame construction with vinyl exterior siding and hip roof clad in composition shingles.

### National Register of Historic Places Continuation Sheet

Section number	7	Page	13	

- 57. **167 South Fairview Avenue** ca. 1915 The one-and-one-half story home is wood frame construction with brick veneer exterior.
- 58. 178 South Fairview Avenue ca. 1925 The two-story home has a brick exterior and hip roof clad in composition shingles.
- 59. **179 South Fairview Avenue** ca. 1927 The one story home is wood frame construction with synthetic exterior siding, brick foundation and jerkinhead roof clad in composition shingles. The bungalow has an entry door with transom and sidelights, porch supported with paired wooden posts resting on brick piers, and four-over-one double hung sash windows.
- 60. 193 South Fairview Avenue ca. 1927 The one story home is wood frame construction with wood shingle exterior, brick foundation, and hipped roof clad in composition shingles. The bungalow has gable wings on the side elevations, hipped roof dormer over the entry door, entry door with transom and sidelights, twelve-over-one and eight-over-one double hung sash windows, porch supported with paired and tripartite square wood columns resting on brick piers and exposed rafter tails beneath the eaves.
- 61. 198 South Fairview Avenue ca. 1915 The two-and-one-half sotry home is wood frame construction with weatherboard and wood shingle exterior, brick foundation, and hipped roof clad in composition shingles. The Queen Anne style home has a steeply pitched roof, wide boxed eaves, double entry door with beveled glass, ten-over-one double hung sash windows with shutters, entry with decorative crown molding, porch supported with five square columns with capitals, and brick chimney on the south elevation.
- 62. **203 South Fairview Avenue** ca. 1925 The one story home is wood frame construction with synthetic exterior siding, brick foundation, and front gable roof clad in composition shingles. The recessed porch is supported with tapered posts resting on brick piers. The entry door is surrounded with a transom and sidelights. Windows are four-over-one double hung sash.
- 63. **204 South Fairview Avenue** ca. 1927 The two story home is wood frame construction with synthetic exterior siding, brick foundation, and hipped roof clad in composition shingles. There are four-over-one and six-over-one double hung sash windows, three porches (main façade, south façade, and north façade porte cochere) supported with paired columns with capitals and flat roofs, and entry door with transom and sidelights.
- 64. **209 South Fairview Avenue** ca. 1927 The one story home is wood frame construction with wood shingle exterior siding, brick foundation, and gable roof clad in composition shingles. There are four-over-one double hung sash windows, entry door with transom and sidelights, and porch supported with tapered masonry posts resting on brick piers.

### National Register of Historic Places Continuation Sheet

Section number	7	Page _	14
		~9~ _	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 65. **212 South Fairview Avenue** ca. 1922 The one story home is wood frame construction with wood shingle exterior, brick foundation, and lateral gable roof clad in composition shingles. The gable porch is supported with tapered masonry posts on stuccoed piers with wood shingle balustrade. There are three-over-one, four-over-one and five-over-one double hung sash windows, entry door with dentil molding and fluted pilasters and exposed rafter tails beneath the eaves.
- 66. 213-215 South Fairview Avenue ca. 1950 The one story, multi-family home is masonry construction with concrete block exterior and lateral gable roof clad in composition shingle. There are six-over-six double hung sash windows, central brick chimney, and brick quoining and detail work around the windows and entry doors.

#### **GLENDALYN AVENUE**

- 67. **490 Glendalyn Avenue** 1937 The two story home is wood frame construction with shiplap exterior siding and side gable roof clad in composition shingles.
- 68. **496 Glendalyn Avenue** 1930 The two story home is wood frame construction with wood shingle siding and brick foundation. The porch is supported with tapered brick supports resting on brick piers. The main façade has a set of ribbon windows.
- 69. **511 Glendalyn Avenue** 1927 The two story home is wood frame construction with brick veneer exterior, flat roof and two-story porch on the main façade supported with Greek columns. The double entry doors are offset to the left side fo the main façade with an arched entry porch.
- 70. **512 Glendalyn Avenue** 1867 The two-and-one-half story home is wood frame construction with weatherboard exterior and brick foundation. The full façade porch is supported with paired classical columns.
- 71. 515 Glendalyn Avenue ca. 1927 The two story home is wood frame construction with weatherboard exterior and brick foundation. There is a full façade porch supported with tapered wooden posts resting on brick piers. The main entry door is flanked with sidelights. Decorative details include a sloping chimney and decorative shutters.
- 72. **517 Glendalyn Avenue** ca. 1927 The one story home is wood frame construction with brick veneer exterior and pyramidal roof clad in composition shingles. The porch is supported with wooden posts resting on brick piers with a solid balustrade that dips between each post.

### National Register of Historic Places Continuation Sheet

Section nur	mber	7	Page _	15	
					-

- 73. **519 Glendalyn Avenue** ca. 1921 The two story home is wood frame construction with brick veneer exterior. There are two gable dormers on the main façade containing lunette windows that mirror the fanlights over the entry doors. There are French doors on either side of the main entry door. The entry porch is supported with classical columns.
- 74. **520 Glendalyn Avenue** ca. 1924 The three story home is wood frame construction with weatherboard exterior siding, brick foundation and gambrel roof. The porch wraps to the side elevation and is supported with classical columns. The main entry door has a transom and sidelights.
- 75. **527 Glendalyn Avenue** ca. 1921 The two story home is wood frame construction with weatherboard exterior, stuccoed foundation and pyramidal roof. The wraparound porch has a balcony above. The entry door has a transom and sidelights.
- 76. **532 Glendalyn Avenue** ca. 1924 The two-and-one-half story home is wood frame construction with brick veneer exterior and side gable roof with hipped dormers on the main façade. The front and side porches are supported with square brick posts. The main entry door has a transom and sidelights.
- 77. **537 Glendalyn Avenue** ca. 1921 The one story home is wood frame construction with weatherboard exterior and stuccoed masonry foundation. There is a small entry porch on the main façade.
- 78. **540 Glendalyn Avenue** ca. 1921 The two story home is wood frame with weatherboard exterior siding and concrete block foundation. The hip roof contains a gable dormer with window. The porch is supported with paired columns and the entry door is topped with a multi-light transom.
- 79. **543 Glendalyn Avenue** ca. 1921 The one story home is wood frame construction with wood shingle exterior, brick foundation and pyramidal roof with projecting gable in the center. The main entry door has a transom and sidelights and the porch is supported with wooden posts resting on brick piers.
- 80. **547 Glendalyn Avenue** ca. 1921 The one story home is wood frame construction with wood shingle exterior and brick foundation. The main façade has symmetrically placed ribbon windows and a gable dormer in the center of the roofline. The porch is supported with wooden posts resting on brick piers.
- 81. **552 Glendalyn Avenue** ca. 1921 The one story home is wood frame construction with synthetic exterior siding and brick foundation.
- 82. 553 Glendalyn Avenue ca. 1920 The one story home is wood frame construction with wood shingle exterior and brick foundation. The main entry door has a transom and sidelights. There are two chimneys on the roof ridge.

### National Register of Historic Places Continuation Sheet

_			
Section number	7	Page	16
Occion number		I ago	

- 83. **559 Glendalyn Avenue** ca. 1920 The one story home is wood frame construction with weatherboard exterior and brick foundation. There is a recessed entry porch with entry door flanked by sidelights. The home has canted corners.
- 84. **560 Glendalyn Avenue** ca. 1920 The two story home is wood frame construction with wood shingle exterior and brick foundation. There is a gable on the main façade over the entry door.
- 85. **600 Glendalyn Avenue** ca. 1927 The one story home is wood frame construction with wood shingle exterior siding, brick foundation and gable roof clad in composition shingles. There are five-over-one double hung sash windows, gable wings on the side elevations, entry door with transom and sidelights, porch supported with tapered brick posts resting on brick piers, and exposed rafter tails beneath the eaves.
- 86. **604 Glendalyn Avenue** ca. 1927 The one story home is wood frame construction with weatherboard exterior siding, brick foundation, and hipped roof clad in composition shingles. There are nine-over-one and twelve-over-one double hung sash windows, entry door with fanlight and keystone detail, entry porch with arched ceiling supported with classical columns, and interior brick chimney.
- 87. **610 Glendalyn Avenue** ca. 1925 The one story home is wood frame construction with synthetic exterior siding, brick foundation, and cross gable roof clad in composition shingles. There is an offset gable porch supported with tapered posts resting on brick piers, four-over-one double hung sash windows, gable wing on the right elevation, and knee brackets beneath the eaves.
- 88. 616 Glendalyn Avenue ca. 1927 The one story home is wood frame construction with weatherboard and wood shingle exterior siding and front gable roof clad in composition shingles. The bungalow has gable wings on the east and west elevations, attic vents surrounded with decorative molding in the gable end, exposed rafter tails and brackets beneath the eaves and entry door with transom and sidelights.
- 89. **643 Glendalyn Avenue** ca. 1927 The one story home is wood frame construction with wood shingle exterior, brick foundation, and front gable roof clad in composition shingles. The bungalow has exposed rafter tails and roof brackets, porch supported with four Classical columns resting on a wood shingle balustrade, and six-over-one double hung sash windows.
- 90. **647 Glendalyn Avenue** ca. 1924 The one story home is wood frame construction with wood shingle and synthetic exterior siding, brick foundation, and front gable roof clad in composition shingles. The bungalow has an offset gable porch supported with paired wood posts with lattice detail between, six-over-one double hung sash windows, and four pane window in the porch gable end.

## National Register of Historic Places Continuation Sheet

+			
Section number	7	_ Page _	17
Section number _		_raye_	

- 91. **653 Glendalyn Avenue** ca. 1924 The one story home is wood frame construction with wood shingle exterior, brick foundation, and hipped roof clad in composition shingles. There are six-over-one double hung sash windows, offset gable porch supported with square posts, entry door with decorative surround, and exposed rafter tails and roof brackets beneath the eaves.
- 92. **656 Glendalyn Avenue** ca. 1927 The one story home is wood frame construction with brick and synthetic siding on the exterior, brick foundation and jerkinhead roof clad in composition shingles. There is an engaged porch supported with tapered wooden posts resting on brick piers and solid brick balustrade.
- 93. **658 Glendalyn Avenue** ca. 1925 The one story home is wood frame construction with brick and synthetic siding exterior, brick foundation and lateral gable roof clad in composition shingles. There are four-over-one double hung sash windows, arched windows with stuccoed surrounds and keystone detailing, an exterior chimney on the main façade with arched panel detail, offset gable porch supported with wrought iron posts on brick piers and solid brick balustrade.
- 94. **660 Glendalyn Avenue** ca. 1928 The one story home is wood frame construction with brick exterior and lateral gable roof clad in composition shingles. There is a large gable over the porch supported with square brick posts resting on the stone balustrade. There is an addition on the rear façade.
- 95. **668 Glendalyn Avenue** ca. 1860 The two-and-one-half story home is wood frame construction with synthetic exterior siding, brick foundation, and hipped roof clad in composition shingles. The porch wraps to the right and is supported by thin columns and has a turned balustrade. There is a hipped dormer in the center of the main façade that contains a new one-over-one double hung sash window. There is a central stuccoed chimney, wide five-over-three double hung sash windows. The house was originally on East Main Street and was moved to current location after 1860 according to the current owner.
- 96. **707 Glendalyn Avenue** ca. 1920 The one story home is wood frame construction with asbestos shingle exterior siding and brick foundation. The gable porch is supported with tripartite Doric columns and has a turned balustrade. The three-light entry door has a federal style surround with fluted pilasters and dentil cornice and is flanked by four-over-one double hung sash windows. There is a semi-circular vent in the gable end.
- 97. **709 Glendalyn Avenue** ca. 1930 The one-story home is wood frame construction with vinyl exterior siding and brick foundation. There is a pediment over the arched entry porch.
- 98. **710 Glendalyn Avenue** ca. 1925 The one story home is wood frame construction with weatherboard novelty siding and brick foundation. The offset gable porch is supported with wooden posts resting on brick piers with large brackets on the corners. The side elevation has tripartite eight-over-one double hung sash windows. There are exposed rafter tails beneath the eaves.

### National Register of Historic Places Continuation Sheet

Section	number	7	Page	18	

- 99. **715 Glendalyn Avenue** ca. 1930 The one-story home is wood frame construction with weatherboard exterior and brick foundation. The entry door is on the right side elevation beneath a gable porch supported with tapered wooden posts resting on brick piers. The porch has been enclosed with screen. There is a shallow projecting gable on the main façade containing a semi-circular attic vent and tripartite window. There are exposed rafter tails beneath the eaves.
- 100. **716 Glendalyn Avenue** ca. 1930 The one-story home is wood frame construction with weatherboard exterior and brick foundation. The gable porch is supported with square wooden posts. Windows on the main façade are twelve-over-one double hung sash, remaining windows are eight-over-one double hung sash. There is an exterior end chimney on the left elevation that pierces the roofline.
- 101. **721 Glendalyn Avenue** ca. 1920 The one story home is wood frame construction clad in wood shingles. There is a gable dormer on the main façade containing a tripartite attic vent. The porch is supported with square wooden posts on wood piers. There are exposed rafter tails and roof beams beneath the eaves.
- 102. **722** Glendalyn Avenue ca. 1920 The one story home is wood frame construction with vinyl exterior siding and brick foundation. The full façade porch is engaged and supported with wrought iron posts. There is a single-pane window flanked by attic vents in the gable end. Windows are four-over-one double hung sash. The main entry door is surrounded by sidelights and transom.
- 103. **Dean, E.B. House, 734 Glendalyn Avenue** 1912 The one-and-one-half story home was constructed for E.B. Dean, great-grandson of Charles Dean who came to the Carolinas from England in the 1700s. The building is wood frame construction with wood shingle exterior. The porch wraps to the right elevation (enclosed with screen) and is supported with large, square stuccoed columns with solid balustrade. There is a large gable dormer in the center of the main façade with flared eaves and exposed rafter tails and roof brackets. The dormer contains four, nine-over-one double hung sash windows and a door that accesses a small porch.
- 104. **763 Glendalyn Avenue** ca. 1925 The one-story home is wood frame construction with weatherboard exterior, stuccoed masonry foundation and hip roof. The porch is engaged and wraps to the right elevation and is supported with paired and tripartite square posts. Exposed rafter tails can be seen beneath the eaves.
- 105. **766 Glendalyn Avenue** ca. 1920 The two story home is wood frame construction with weatherboard exterior, brick foundation, and hip roof. The main entry door is offset to the left and surrounded by a transom and sidelights. There is a porte cochere on the left elevation. Windows are paired, twelve-over-twelve double hung sash.

### National Register of Historic Places Continuation Sheet

Section number	7	Page _	19	

- 106. **769 Glendalyn Avenue** ca. 1922 The one-story home is wood frame construction with weatherboard exterior and brick foundation. The gable porch is supported with wooden posts resting on brick piers. There are triangular knee brackets in the gable ends. Windows are four-over-one double hung sash.
- 107. 772 Glendalyn Avenue ca. 1910 the one-story home is wood frame construction with weatherboard exterior. The gable porch is supported with both paired wooden posts resting on brick piers as well as large, square posts on the porch. The gable end contains a diamond-shaped attic vent and is decorated with wood shingles, knee brackets and dentil work. The main entry door is flanked by one-over-one windows and fluted pilasters.
- 108. 773 Glendalyn Avenue ca. 1922 The one-story home is wood frame construction with weatherboard exterior and brick foundation. There are knee brackets and wood shingles in the gable ends. The offset porch is supported by thin, tapered wooden posts. Windows are paired, four-over-one double hung sash.
- 109. 778 Glendalyn Avenue ca. 1905 The one-and-one-half story home is wood frame construction with weatherboard exterior and brick foundation. The full façade porch is engaged, supported with paired and tripartite wooden posts resting on brick piers. There are exposed roof brackets and rafter tails beneath the eaves. The front gable end is clad in wood shingles and contains a six-pane window flanked by attic vents. The entry door is surrounded by multi-pane transom and sidelights.
- 110. 779 Glendalyn Avenue ca. 1920 The one-story home is wood frame construction with wood shingle exterior. The full façade porch is engaged, supported with paired wooden posts on stone piers. The gable end is decorated with multiple types of wooden shingles as well as a diamond-shaped attic vent.
- 111. **783 Glendalyn Avenue** ca. 1920 The one story home is wood frame construction with weatherboard siding and brick foundation. The gable porch is supported with paired wooden posts resting on brick piers. Windows are five-over-one double hung sash. The gable end contains knee brackets, wood shingle detailing, and a square attic vent. Exposed rafter tails are visible beneath the eaves.
- 112. **789 Glendalyn Avenue** ca. 1920 The one story home is wood frame construction with weatherboard exterior and brick foundation. The porch has a jerkinhead roofline with paired attic vent in the gable end. Windows are three-over-one double hung sash.
- 113. **792** Glendalyn Avenue ca. 1925 The one-and-one-half story home is wood frame construction with weatherboard novelty siding on the exterior and brick foundation. The gambrel roof has a long shed dormer on the main façade. The hip porch is supported with simple Doric columns.
- 114. 793 Glendalyn Avenue ca. 1920 The one story home is clad in weatherboard with brick foundation and hip roof. The full façade porch is engaged, supported with paired and tripartite wooden posts resting on brick piers. There is a hip dormer on the main façade containing a horizontal four-pane window flanked by attic vents. The entry door is surrounded by multi-light transom and sidelights.

### National Register of Historic Places Continuation Sheet

Section number 7	7 Page 20	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 115. **798 Glendalyn Avenue** ca. 1925 The one story home is wood frame construction with weatherboard exterior and brick foundation. The full façade porch is engaged, supported with large brick posts at the corners and thin wooden posts resting on brick piers at the entry. The gable end contains decorative wood shingle siding and a stained glass window flanked by attic vents. The four-light entry door mimics the four-over-one double hung sash windows.
- 116. **804 Glendalyn Avenue** ca. 1920 The one story home is wood frame construction with synthetic exterior siding and brick foundation. The offset gable porch has been enclosed with louvered windows. There are exposed roof beam beneath the eaves.
- 117. **805** Glendalyn Avenue ca. 1920 The one story home is wood frame construction with synthetic exterior siding and brick foundation. The full façade porch is engaged, supported with brick posts resting on brick piers.
- 118. Park ca. 1920 park, part of the original development of Converse Heights.

#### HALE STREET

- 119. 399 Hale Street ca. 1940 The one story home is wood frame construction with brick exterior and stucco half-timbering in the gable ends. The side gable roof is clad in composition shingles and has three front facing gables on the main façade with a steeply sloping side gable. There is arched brickwork over the main entry door and side entry door with keystone details. There is an exterior chimney on the north façade and three-over-one double hung sash ribbon windows.
- 120. 400 Hale Street ca. 1920 The two story home is wood frame construction with brick veneer exterior, lateral gable roof with front facing gable, gable dormer with attic vent, exterior end chimney, and paneled entry door with sidelights.
- 121. 401/403 Hale Street ca. 1940 The two story duplex is wood frame construction with painted brick veneer exterior and weatherboard in the gable end. The lateral gable roof is clad in composition shingles. There are eight four-over-one double hung sash windows on the main façade and two entry porches.
- 122. 405 Hale Street ca. 1938 The one-and-one-half story home is wood frame construction with brick veneer exterior with asbestos shingle siding on the dormers. The gambrel roof is clad in composition shingles with a large shed dormer on the main façade. There are three-over-one double hung sash windows, rectangular attic vents in the gable ends, and exposed rafter tails on the rear façade.
- 123. 406 Hale Street ca. 1930 The two story home is wood frame construction with painted brick veneer exterior, hipped roof clad in composition shingles, hip dormer in the center of the main façade, and six-over-six double hung sash windows. There is a shed porch on the main façade supported with square brick columns. The main entry door is flanked by sidelights. There is a side entry with brick patio.

### National Register of Historic Places Continuation Sheet

Castian number	7	Dono	01	
Section number	/	Page	21	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

#### MAPLE STREET

- 123. 601 Maple Street ca. 1920 The one story home is wood frame construction with synthetic exterior siding, brick foundation, and front gable roof clad in composition shingles. There are exposed rafter tails beneath the eaves, porch supported with tapered brick columns and rectangular columns, four-over-one double hung sash windows, and single pane window in the gable end. The main entry door has a transom and sidelights with door surround that has fluted pilasters and wide cornice.
- 124. **606 Maple Street** ca. 1920 The one story house is masonry construction with brick exterior and lateral gable roof clad with composition shingles. There are six-over-six double hung sash windows with decorative shutters, paneled entry door, and single car garage at the west end of the house.
- 125. **607 Maple Street** ca. 1920 The one-and-one-half story home is wood frame construction with aluminum exterior siding and gable roof clad in composition shingles. There are six-over-six double hung sash windows and exterior chimney on the main façade.
- 126. 613 Maple Street ca. 1920 The one story home is wood frame construction with wood shingle exterior siding, brick foundation, and front gable roof clad in composition shingles containing a decorative single-pane window flanked by attic vents. There are five-over-one double hung sash windows; stuccoed gable end on the main façade; entry door with dentil detailing on top of the entablature, fluted pilasters, and flanked by sidelights.
- 127. 614 Maple Street ca. 1928 The two story home is wood frame construction with wood shingle exterior siding, brick foundation, and lateral gable roof clad in composition shingles. There are six-over-six double hung sash windows, dentil detailing in the entablature beneath the roofline, and entry door flanked by leaded sidelights and fanlight transom.
- 128. 617 Maple Street ca. 1920 The one story home is wood frame construction with wood shingle exterior siding, brick foundation, and front gable roof clad in composition shingles. There are five-overone double hung sash windows, exposed rafter tails beneath the eaves, porch supported by square fluted columns, and entry door flanked by a transom and sidelights and fluted pilasters.
- 129. 623 Maple Street ca. 1920 The one story home is wood frame construction with wood shingle exterior siding, brick foundation, and cross gable roof clad in composition shingles. The main entry door has fluted pilasters and an entablature. The porch is supported with four Doric columns and a turned balustrade. There are two exterior end chimneys and four-over-one double hung sash windows.
- 130. **627 Maple Street** ca. 1920 The two story wood frame home has synthetic exterior siding, brick foundation, and hipped roof clad in composition shingles. The porch curves as it wraps around the corner of the house and is supported by Doric columns. There are one-over-one double hung sash windows, entry door with fluted pilasters and entablature and pediment over the entry.

## National Register of Historic Places Continuation Sheet

Section number	7	Page _	22

- 131. **639 Maple Street** ca. 1920 The one story home is wood frame construction with weatherboard exterior, brick foundation and gable roof clad in composition shingles.
- 132. **647 Maple Street** ca. 1930 The two-story home is wood frame construction with vinyl exterior siding, brick foundation and hip roof clad in composition shingles.
- 133. **652 Maple Street** ca. 1910 The two-story home is wood frame construction with weatherboard exterior siding, brick foundation and gable roof clad in composition shingles.
- 134. **656 Maple Street** ca. 1920 The two-story home is wood frame construction with weatherboard exterior siding, brick foundation and hip roof clad in composition shingles.
- 135. **657 Maple Street** ca. 1925 The one-story home is wood frame construction with weatherboard exterior siding and brick foundation.
- 136. **659 Maple Street** ca. 1925 The two-story home is wood frame construction with brick veneer exterior and hip roof clad in composition shingles.
- 137. **660 Maple Street** ca. 1920 The two-story home is wood frame construction with weatherboard exterior siding, brick foundation and hip roof clad in composition shingles.
- 138. 664 Maple Street ca. 1920 The two-story home is wood frame construction with vinyl exterior siding, brick foundation and cross gable roof clad in composition shingles.
- 139. 668 Maple Street ca. 1940 The one-story home is wood frame construction with brick veneer exterior with gable roof clad in composition shingles.
- 140. **699 Maple Street** ca. 1920 The one story home is wood frame construction with weatherboard exterior siding, brick foundation, and lateral gable roof clad in composition shingles. There are double hung sash windows and Doric columns supporting the hipped roof porch.
- 141. 702 Maple Street ca. 1912– The one story home is wood frame construction with wood shingle exterior siding, brick foundation, and gable roof clad in composition shingles. There are Arts & Crafts style windows with multiple pane lights over single pane double hung sash windows, exposed rafter tails beneath the eaves, and square wooden posts supporting the porch.
- 142. **705 Maple Street** ca. 1930– The two story home is wood frame construction with synthetic exterior siding, brick foundation, and hipped roof clad in composition shingles. There is a dormer centered on the main façade containing a diamond-paned window, interior brick chimney, and new brick wall constructed along the front of the home that comes to the base of the windows.

## National Register of Historic Places Continuation Sheet

Section number	7	Page _	23	

- 143. 708 Maple Street ca. 1930 The home is wood frame construction with weatherboard exterior siding, brick foundation, and cross gable roof clad in composition shingles. There are six-over-one double hung sash windows, Doric columns supporting the porch and attic vent in the porch gable end.
- 144. **709 Maple Street** ca. 1926 The two story home is wood frame construction with brick veneer exterior and hipped roof clad in composition shingles. There are nine-over-one double hung sash windows, stained glass decorative window over the porch, front door with beveled glass and beveled sidelights, porch columns are tapered wooden posts on brick piers.
- 145. **712 Maple Street** ca. 1926 The one story home is wood frame construction with weatherboard exterior siding, brick foundation, and gable roof clad in composition shingles. The tapered exterior chimney is stuccoed. There are six paned casement windows, entry porch supported with square wooden posts, and exposed rafter tails beneath the eaves.
- 146. 713 Maple Street ca. 1935 The two-and-one-half story Tudor home is wood frame construction with wood shingle and brick exterior siding, brick foundation, and cross gable roof clad in composition shingles. There is a small entry porch as the side of the house with single Doric column, multi-pane windows, shed dormer, and shingle detailing in the gable ends.
- 147. 718 Maple Street ca. 1912 The two story home is wood frame construction with wood shingle exterior siding, brick foundation, and lateral gable roof clad in composition shingles. There is a large front facing gable on the main façade and flat roof porch supported by square wooden posts. There are four-over-one and twelve-over-one double hung sash windows, arched attic vents in the gable ends, and decorative attic windows in the gable ends with eight triangular panes of glass inset with exposed false beams above the window opening.
- 148. 722 Maple Street ca. 1932 The one-and-one-half story home is wood frame construction with brick veneer exterior and gable roof clad in composition shingles. There is an exterior chimney on the main façade, dormer window, six-over-one double hung sash windows, entry door on the side elevation with transom window and masonry detail spanning the porch.
- 149. **725 Maple Street** ca. 1925 The home is wood frame construction is wood shingle exterior, brick foundation, and lateral gable roof clad in composition shingles. There are four-over-one double hung sash windows, square porch columns resting on brick piers, entry door with transom and sidelights, exposed rafter tails beneath the eaves, and dormer on the main façade with paired windows flanked by rectangular attic vents.
- 150. **730 Maple Street** ca. 1934 The one story home is wood frame construction with brick veneer exterior and hip roof with gable wings clad in composition shingles. There is an entry porch with fluted Doric columns, entry door with sidelights and transom window with four triangular panes.

### National Register of Historic Places Continuation Sheet

Section number	7	Page _	24

- 151. 731 Maple Street ca. 1927 The one story home is wood frame construction with wood shingle exterior siding, brick foundation, and gable roof clad in composition shingles. There are Arts & Crafts style windows, exposed rafter tails beneath the eaves, porch supported with paired wooden posts resting on brick piers, and decorative window in the porch gable end.
- 152. 736 Maple Street ca. 1922 The two story home is wood frame construction with gambrel roof clad in composition shingles. There is a shed dormer on the main façade and engaged porch with decorative bracket supports. There is diamond-shaped brick decoration on the front façade between the two upper story windows, central chimney, entry door with two large sidelights and a transom. Windows are six-over-one and twelve-over-one double hung sash.
- 153. **737 Maple Street** ca. 1925 The one story home is wood frame construction with wood shingle exterior siding and gable roof clad in composition shingles. There are shingled columns on the porch, multi-pane lights over single light double hung sash windows, exposed rafter tails beneath the eaves, and two chimneys-one internal and one external.
- 154. **749 Maple Street** ca. 1925 The one story home is wood frame construction with weatherboard exterior, jerkinhead roof clad in composition shingles, gable porch on the main façade with cornice returns supported with simple columns. The entry door has a four-pane transom. There are eight-over-one double hung sash windows and arched attic vents in the gable ends.
- 155. **755 Maple Street** ca. 1925 The one story home is wood frame construction with weatherboard exterior, hip roof clad in composition shingles, gable porch on the main façade with cornice returns and rectangular attic vent in the gable end. Windows are six-over-six double hung sash.
- 156. **759 Maple Street** ca. 1930 The one story home is wood frame construction with weatherboard exterior, jerkinhead roof clad in composition shingles, gable entry porch supported with simple columns, main entry door with transom and ribbon windows on each side of the main entry door (six-over-one double hung sash windows).
- 157. **763 Maple Street** ca. 1930 The one story home is wood frame construction with weatherboard exterior, hipped roof clad in composition shingles, and gable entry porch supported with simple columns. There are ribbon windows on each side of the main entry door (six-over-one double hung sash window flanked by four-over-one double hung sash windows). There is a screened porch with hipped roof on the west façade.
- 158. 771 Maple Street ca. 1925 The one story home is wood frame construction with hipped roof clad in composition shingles. The recessed porch is supported with paired wooden posts resting on brick piers. There are paired four-over-one double hung sash windows.

### National Register of Historic Places Continuation Sheet

Section	number	7	Page _	25	
000000					_

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 159. **775 Maple Street** ca. 1925 The one story home is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. The recessed porch is supported with paired wooden posts resting on brick piers. There are paired four-over-one double hung sash windows.
- 160. 779-781 Maple Street ca. 1945 The one story duplex is wood frame construction with weatherboard exterior siding, concrete block foundation and gable roof clad in composition shingles.
- 161. **785 Maple Street** ca. 1945 The one story duplex is wood frame construction with weatherboard exterior siding, concrete block foundation and gable roof clad in composition shingles.
- 162. 787 Maple Street ca. 1945 The one story duplex is wood frame construction with weatherboard exterior siding, concrete block foundation and gable roof clad in composition shingles.
- 163. **791-793 Maple Street** ca. 1945 The one story duplex is wood frame construction with weatherboard exterior siding, concrete block foundation and cross gable roof clad in composition shingles.
- 164. 799 Maple Street ca. 1900 The one story home is wood frame construction with vinyl exterior siding, brick foundation and gable roof clad in composition shingles.

#### MILLS AVENUE

- 165. **128 Mills Avenue** ca. 1910 The two story home is wood frame construction with weatherboard and wood shingle exterior siding, hip roof clad in composition shingles, and hip dormer in the center of the main façade.
- 166. 129 Mills Avenue ca. 1900 The two story home is wood frame construction with weatherboard exterior siding, hip roof clad in composition shingles, and hip roof porch that wraps to the north façade supported by paired posts. There is a small hip dormer containing attic vents in the center of the main façade.
- 167. 136 Mills Avenue ca. 1925 The two story home is wood frame construction with weatherboard exterior siding, a gable roof clad in composition shingles, and a brick foundation.
- 168. 141 Mills Avenue ca. 1910 The two-and-one-half story home is wood frame construction with wood shingle exterior siding and front gable roof clad in composition shingles. A transom and sidelights surround the central entry door. The porch has a brick floor and 4 arched openings.
- **169. 146 Mills Avenue** ca. 1925 This two-story home is masonry construction with brick exterior and hip roof clad in composition shingles.

# National Register of Historic Places Continuation Sheet

Section numb	per 7	Page	26

- 170. 147 Mills Avenue ca. 1900 The two story home is wood frame construction with vinyl exterior siding and hip roof clad in composition shingles. Square brick posts support the front porch and there is a pediment over the entry supported by paired wooden posts. There is a hip dormer in the center of the main façade that contains two four-light windows.
- 171. **154 Mills Avenue** ca. 1913 The one-story bungalow is wood frame construction with wood shingle exterior siding and hip roof clad in composition shingles. The main entry door is offset to the left with multi-light transom. The engaged porch is supported with paired wooden posts.
- 172. 157 Mills Avenue ca. 1922 The two-story home is wood frame construction with grey brick veneer exterior. The entry door is offset to the left on the main façade beneath a flat-roof porch supported by ionic columns. There is a one-story wing on the right side.
- 173. 164 Mills Avenue ca. 1914 The one-and-one-half story bungalow home is wood frame construction with wood shingle exterior siding and lateral gable roof clad in composition shingles. There is a large dormer in the center of the main façade and entry door with transom. There is a projecting wing to the left of the main entry door and porch supported with large square piers (on the outside) and thin paired posts (at the entry).
- 174. 169 Mills Avenue ca. 1922 The two-story home is wood frame construction with brick veneer exterior and main entry door offset to the left on the main façade with fanlight and sidelights. There is a one-story wing to the right.
- 175. 176 Mills Avenue ca. 1924 The two-story home is wood frame construction with brick veneer exterior and central entry beneath a flat roof porch supported by fluted columns. A transom and sidelights surround the main entry door. Windows are one-over- one double hung sash.
- 176. 185 Mills Avenue ca. 1924 The one-story bungalow is wood frame construction with brick veneer exterior and front gable roof clad in composition shingles. There is an engaged porch supported with tapered brick piers. A transom and sidelights surround the entry door. There is a single pane window flanked by attic vents in the front gable end and porte cochere to the right of the entry.
- 177. 192 Mills Avenue Vacant lot.
- 178. 198 Mills Avenue ca. 1914 The one-story bungalow home is wood frame construction with wood shingle exterior siding and front gable roof clad in composition shingles. There are decorative brackets beneath the eaves, engaged porch supported with brick posts, multi-pane window in the front gable end flanked by attic vents and covered with a bracketed shed roof, and entry door with transom and sidelights.

### National Register of Historic Places Continuation Sheet

0 1' 1	-	<b>D</b>	07	
Section number	- 1	Page	27	

- 179. 199 Mills Avenue ca. 1925 The two-story home is wood frame construction with weatherboard exterior and hip roof clad in composition shingles. The main entry door is topped with a multi-pane transom and sits beneath a porch supported with classical columns. There is a one-story wing on the right façade.
- 180. 203 Mills Avenue ca. 1912 The one-story bungalow home is wood frame construction with wood shingle exterior and front gable roof clad in composition shingles. Large tapered posts support the porch. There is a window in the center of the front gable end flanked by attic vents.
- 181. 209 Mills Avenue ca. 1915 The two-story home is wood frame construction with vinyl exterior siding and hipped roof clad in composition shingles. The porch wraps to the left façade and is enclosed to the right of the entry door. The entry door is flanked by sidelights. Windows are four-over-one double hung sash.
- 182. 210 Mills Avenue ca. 1909 The two-story home is wood frame construction with vinyl exterior siding and hipped roof clad in composition shingles. The entry door is slightly offset to the right on the main façade. The porch is supported by decorative brick posts with a pediment over the entry door. A hipped dormer in the center of the main façade contains a multi-pane decorative window.
- 183. 216 Mills Avenue ca. 1900 The two-story home is wood frame construction with weatherboard exterior siding and hipped roof clad in composition shingles. The porch wraps to the left façade and is supported by Ionic columns with a pediment over the main entry. There is a hip dormer in the center of the main façade containing an attic vent flanked by decorative windows.
- 184. 217 Mills Avenue ca. 1915 The two-story home is wood frame construction with vinyl exterior siding and hipped roof clad in composition shingles. The porch wraps to both side elevations and is supported by fluted columns with a pediment over the main entry. There is a hip dormer in the center of the main façade containing paired decorative windows.
- 185. **220 Mills Avenue** ca. 1920-1930 The one-and-one-half story home is wood frame construction with stucco exterior and cross gable roof clad in slate. The home was constructed in the Tudor style with half-timber detailing.
- 186. 240 Mills Avenue ca. 1915-1925 The one story home is wood frame construction with wood shingle exterior and brick foundation. The front-facing hip roof has side projecting gables and is clad in composition shingles. The home has eight-over-one double hung sash windows and vented dormer over the main entry. There is an addition on the rear façade, painted brick chimney and painted foundation.

## National Register of Historic Places Continuation Sheet

Section number	7	Page	28	

- 187. **241 Mills Avenue** ca. 1920-1930 The two story home is wood frame construction with weatherboard exterior and brick foundation. The lateral gable roof is clad in composition shingles. There entry porch has an arched roofline and is supported with Doric columns. There are arched dormer windows on the main façade and eight-over-one double hung sash windows. There is an addition on the rear façade.
- 188. 244 Mills Avenue ca. 1910-1920 The two story home is wood frame construction with weatherboard exterior and brick foundation. The pyramidal roof is clad in composition shingles. The home is an American Four Square style with hip dormer on the main façade. The windows on the first floor are one-over-one double hung sash with two-over-two double hung sash on the second story. The wrap porch is supported with Doric columns. There are additions on the rear and side elevations and vinyl siding has been added to the side elevations.
- 189. 247 Mills Avenue ca. 1920-1930 The two story home is wood frame construction with weatherboard exterior, brick foundation and pyramidal roof clad in composition shingles. The full width porch has been partially enclosed. There is a small porch at the side entry door. The home has eight-over-one double hung sash windows in the Craftsman style, a one-story sunroom, and garage outbuilding with upper apartment. Vinyl siding has been added to the exterior.
- 190. **250 Mills Avenue** ca. 1915-1925 The two-and-one-half story home is wood frame construction with weatherboard exterior and brick foundation. The lateral gable roof is clad in asphalt shingles. The porch wraps to the side elevation and is supported with ionic columns. There is a bracketed cornice, large dormer on the main façade, glass entry door with sidelights and transom and Palladian windows at the main gable ends.
- 191. **268 Mills Avenue** ca. 1920-1925 The two story home is wood frame construction with brick veneer and cast stone exterior. The pyramidal roof is clad in asphalt shingles but was originally tile. There are one-over-one double hung sash windows (tripartite on the first story and paired on the second story), bracketed eaves, stone accents, and columned entry with full entablature and balustrade. The side entry porch has been enclosed with screen and the exterior brick painted.
- 192. 320 Mills Avenue ca. 1935 The two story home is wood frame construction with weatherboard exterior siding, brick foundation, and gable roof clad in composition shingles.
- 193. 321 Mills Avenue ca. 1930 The one-story home is wood frame construction with wood exterior, brick foundation and gable roof clad in composition shingles.
- 194. 325 Mills Avenue ca. 1925 The one-story home is wood frame construction with vinyl exterior siding, brick foundation and gable roof clad in composition shingles.
- 195. 331 Mills Avenue ca. 1940 The one-and-one-half story home is wood frame construction with vinyl exterior siding, brick foundation and gable roof clad in composition shingles.

# National Register of Historic Places Continuation Sheet

Section number	7	Page _	29	

- 196. 343 Mills Avenue ca. 1940 The one-story home is wood frame construction with weatherboard exterior siding, brick foundation and gable roof clad in composition shingles.
- 197. 344 Mills Avenue ca. 1930 This one-story home has a gable roof clad in composition shingles, brink foundation and weatherboard exterior.
- 198. 347 Mills Avenue ca. 1940 The one-story home is wood frame construction with wooden exterior siding, brick foundation and gable roof clad in composition shingles.
- 199. 358 Mills Avenue ca. 1930 The one-story home is wood frame construction with weatherboard exterior siding, brick foundation and gable roof clad in composition shingles.
- 200. 361 Mills Avenue ca. 1920 The two story apartment building is wood frame construction with brick veneer exterior and hipped roof clad in composition shingles. The home has decorative ironwork on the front porch and entry door with sidelights. There are ribbon windows on the main façade.
- 201. 362 Mills Avenue ca. 1930 The one-story home is wood frame construction with brick veneer exterior, brick foundation and gable roof clad in composition shingles.
- 202. 382 Mills Avenue ca. 1920 The one story home is wood frame construction with shiplap exterior siding, stuccoed foundation, and front gable roof clad in composition shingles. There are eight-over-one double hung sash windows, entry door flanked by sidelights, and recessed gable porch supported by thin posts on stuccoed masonry balustrade. There is a single pane window flanked by attic vents as well as knee brackets in the front gable end.
- 203. 386 Mills Avenue ca. 1910 The one story home is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There is a front facing gable over the main entry door containing an arched attic vent. Windows are six-over-six double hung sash. The main entry door is decorated with a broken pediment.
- 204. 387 Mills Avenue ca. 1930 The one story home is wood frame construction with brick veneer exterior and porch with brick piers and brick balustrade. There are ribbon windows on the main façade and chimney on the main façade with rounded brick inset arches and decorative brickwork.
- 205. 395 Mills Avenue ca. 1925 The one-story home is wood frame construction with weatherboard exterior siding and gable roof clad in composition shingles.

### National Register of Historic Places Continuation Sheet

0	 <b>D</b>	00
Section number	 Page _	30

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 206. 396 Mills Avenue ca. 1910 The one story home is wood frame construction with brick veneer exterior and cross gable roof clad in composition shingles. There are four-over-one double hung sash windows, arched entryway with keystone detail beneath a thin gable wing, and gable wing on the left end of the main façade balanced by a front facing gable on the right both containing arched attic vents. There is a patio on the main façade stretching to the right of the entry door.
- 207. 397 Mills Avenue ca. 1930 The one story home is wood frame construction with brick veneer exterior and gable roof clad in composition shingles
- 208. 398 Mills Avenue ca. 1910 The one-and-one-half story home is wood frame construction with brick veneer exterior, cross gable roof clad in composition shingles, and recessed porch on the main façade supported with wrought iron posts resting on brick piers. There is a chimney in the center of the front gable wing with recessed panel decoration with contrasting white brick detail. Windows are four-over-one double hung sash—arched on the front gable wing flanking the chimney. The side gable ends are stuccoed.
- 209. **402 Mills Avenue** ca. 1925 The one story home is wood frame construction with painted brick veneer exterior, cross gable roof clad in composition shingles, gable entry porch, three-over-one double hung sash windows, and tapered chimney on the main façade. There is a shallow gable wing projecting from the left side of the main façade.
- 210. 403 Mills Avenue ca. 1910 The one-and-one-half story home is masonry construction with brick exterior and gambrel roof clad in composition shingles.
- 211. 404 Mills Avenue ca. 1910 The one story home is wood frame construction with brick veneer exterior, cross gable roof clad in composition shingles, front facing gable on the left side of the main façade and a smaller gable which contains the arched entry door recessed beneath an arched opening. Windows are four-over-one double hung sash. The side gable ends are stuccoed.

#### NORWOOD STREET

- 212. 500 Norwood Street ca. 1920 The one story home is masonry construction with stucco exterior and cross gable roof clad in composition shingles. There are wood brackets supporting the eaves, eight-pane window in the front porch gable, entry door with transom and sidelights.
- 213. 507 Norwood Street ca. 1923 The one story home is wood frame construction with shiplap exterior siding, gable-on-hip roof clad in composition shingles, and brick foundation. There is a dormer on the main façade containing a two-pane window flanked by attic vents with decorative brackets beneath the eaves. The windows are four-over-one double hung sash. The porch is supported by wooden posts.

### National Register of Historic Places Continuation Sheet

Section	number	7	Page _	31

- 214. 508 Norwood Street ca. 1912 The two story home is wood frame construction with synthetic exterior siding and hipped roof clad with composition shingles. The main entry door is paneled with tripartite transom and sidelights. The windows are four-over-one and five-over-one double hung sash. The porch on the main façade is red tile with brick balustrade with half moon decoration. There is a hipped dormer on the main façade containing a tripartite ribbon window.
- 215. **509 Norwood Street** ca. 1923 The one-and-one-half story home is wood frame construction with weatherboard exterior, brick foundation and lateral gable roof clad in composition shingles. The porch is supported by wooden posts resting on brick piers. There are five-over-one double hung sash windows. The main façade contains a gable dormer with exposed rafter tails.
- 216. 511 Norwood Street ca. 1924 The one story home is wood frame construction with weatherboard exterior, brick foundation and lateral gable roof clad in composition shingles. The windows are three-over-one and eight-over-one double hung sash. There are decorative knee brackets beneath the eaves. There are paired attic vents in the gable ends.
- 217. **512** Norwood Street ca. 1924 The one story home is wood frame construction with shiplap exterior siding, brick foundation and front gable roof clad in composition shingles. The windows are ten-over-one and twelve-over-one double hung sash. There are exposed rafter tails beneath the eaves, decorative stacked gables on the main façade, brick chimney on the main façade, and windows flanked by attic vents in the gable ends.
- 218. 515 Norwood Street ca. 1924 The one story home is wood frame construction with shiplap exterior siding, brick foundation, and front gable roof clad in composition shingles. A portion of the porch on the main façade is recessed and is supported by tripartite columns resting on brick piers. There are five-overone double hung sash windows. There is a decorative gable on the side elevation and decorative knee brackets beneath the eaves.
- 219. 516 Norwood Street ca. 1924 The one story home is wood frame construction with weatherboard exterior, brick foundation and hipped roof clad in composition shingles. The gable porch is supported with tripartite columns and a double rectangular attic vent in the gable end. There are decorative brackets beneath the eaves.
- 220. **521 Norwood Street** ca. 1932 The one story home is masonry construction with stucco exterior and lateral gable roof clad in composition shingles. Bungalow style home with tripartite ribbon windows on the main façade with a twelve-over-one double hung sash window flanked by six-over-one double hung sash windows.

### National Register of Historic Places Continuation Sheet

Section number	7	Page	32	
Section number		I age	UL	

- 221. **522 Norwood Street** ca. 1924 The two-and-one-half story home is wood frame construction with asbestos shingle siding, brick foundation, and lateral gable roof clad in composition shingles. The main entry door has six panels with six pane transom above. The full façade porch is supported with paired wooden supports with cutwork detailing between. There are six-over-one double hung sash windows.
- 222. 525 Norwood Street ca. 1927 The one story home is wood frame construction with weatherboard exterior, brick foundation, and gable roof clad in composition shingles. The bungalow style home has exposed rafter tails beneath the eaves and decorative roof brackets, diamond shaped attic vents in the gable ends, and paired eight-over-one double hung sash windows.
- 223. 530 Norwood Street ca. 1925 The one story home is wood frame construction with wood shingle exterior, brick foundation and gable roof clad in composition shingles. The porch is supported by tapered wooden posts on brick piers. There are paired four-over-four double hung sash windows in the gable ends, slats for roof ventilation in the gable ends, porte cochere, and eight-over-one double hung sash windows.
- 224. 531 Norwood Street ca. 1924 The one story home is wood frame construction with synthetic exterior siding and gambrel roof clad in composition shingles. The gambrel roof porch is supported by paired columns and has octagonal attic vents in the gable ends.
- 225. **536 Norwood Street** ca. 1926 The one story home is masonry construction with brick exterior and dual pitched hipped roof clad in composition shingles. There are six-over-one double hung sash windows, decorative brickwork around the foundation, bay windows on the side elevations, and tripartite ribbon windows supported by four half-moon wooden brackets.
- 226. 537 Norwood Street ca. 1924 The one story home is wood frame construction with shiplap siding, brick foundation, and dual pitched hip roof clad in composition shingles. There is a small entry porch. Exposed rafter tails and knee brackets support the wide eaves. There are eight-over-one double hung sash windows, central chimney, and decorative wood moldings on the corners of the home.
- 227. 541 Norwood Street ca. 1920 The two story home is wood frame construction with synthetic exterior siding, brick foundation and hipped roof clad in composition shingles. There are six-over-one double hung sash windows, four columns supporting the shed porch, and brick chimney on the side elevation.
- 228. 542 Norwood Street ca. 1924 The one story home is wood frame construction with synthetic exterior siding, brick foundation, and gable roof clad in composition shingles. There are four-over-one double hung sash windows, wide eaves with exposed rafter tails, gable wings on the side elevations, attic vents in the peaks of the gable ends, and half-glass main entry door.

# National Register of Historic Places Continuation Sheet

Section number _	7	_ Page	33	_
				_

- 229. **547 Norwood Street** ca. 1927 The one story home is wood frame construction with shiplap siding, brick foundation, and dual pitched hip roof clad in composition shingles. There are paired rectangular attic vents in the side gable ends, paired six-over-one double hung sash windows, entry door with single light transom, and entry door with half-moon four light window.
- 230. 548 Norwood Street ca. 1930 The one story home is wood frame construction with weatherboard exterior, brick foundation, and gable roof clad in composition shingles. There is a half-moon attic window in the gable end, six-over-six double hung sash windows, exposed rafter tails beneath the eaves, paneled entry door, rectangular attic vents in the side gable ends, and entry porch supported by four square wooden posts.
- 231. 555 Norwood Street ca. 1927 The two story home is wood frame construction with synthetic exterior siding, brick foundation, and hipped roof clad with composition shingles. There are tripartite ribbon windows on the main façade, four-over-one double hung sash windows, wide eaves, and rear shed room.
- 232. 556 Norwood Street ca. 1924 The two story home is wood frame construction with brick veneer exterior and hipped roof clad in composition shingles. There are six-ver-one double hung sash windows, entry door with transom, wide eaves supported with wooden corbels and decorative brick chimney.
- 233. 603 Norwood Street ca. 1925 The one story home is wood frame construction with front gable roof and wood shingle exterior siding. The front gable end contains a two-pane window flanked by attic vents. The engaged porch is supported by two large tapered wooden posts and two thin wooden posts, all resting on brick piers.
- 234. 609 Norwood Street ca. 1930 The two story home is wood frame construction with hip roof and hip porch on the main façade supported with square wooden posts resting on brick piers. There are paired four-over-one double hung sash windows and an entry door flanked by sidelights offset to the right on the main façade.
- 235. 613 Norwood Street ca. 1925 The one story home is wood frame construction with synthetic exterior siding and front gable roof. The main entry door has a transom and sidelights and the gable porch is supported by paired wooden posts with wooden trelliswork between.
- 236. 619 Norwood Street ca. 1925 The one story home is wood frame construction with weatherboard exterior and front gable roof clad in composition shingles. The engaged porch is supported with paired wooden posts resting on brick piers. The front gable end contains a two-pane windows flanked by attic vents. The main entry door has a transom and sidelights.

### National Register of Historic Places Continuation Sheet

Section nun	abor	7	Page	2/	
Section num	ibei		Page _	34	- 20

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 237. **627 Norwood Street** ca. 1920 The two story home has a stucco exterior and large one-over-one double hung sash windows with leaded transoms and sidelights for each. The main entry door is offset to the left on the main façade and is surrounded by a leaded transom and leaded sidelights. The hip porch extends to a porte cochere on the left.
- 238. 638 Norwood Street ca. 1935 The one story home is wood frame construction with synthetic exterior siding and brick foundation.
- 239. **644 Norwood Street** ca. 1935 The one story home is wood frame construction with weatherboard and brick veneer exterior and cross gable roof. There are square brackets beneath the eaves.
- 240. 647 Norwood Street ca. 1940 The two story home is wood frame construction with brick veneer exterior and hip roof. The entry porch has a flat roof and balustrade along the roofline.
- 241. 650 Norwood Street ca. 1925 The one story home is wood frame construction with weatherboard exterior and brick foundation. The entry porch is offset with triangular pediment. The entry door is flanked by sidelights.
- 242. **652 Norwood Street** ca. 1925 The one-and-one-half story home is wood frame construction clad in asbestos shingle siding. The gable on the main façade contains two nine-over-one double hung sash windows. The entry door is flanked by sidelights.
- 243. 660 Norwood Street ca. 1915 The one-and-one-half story home is wood frame construction clad in asbestos shingle siding. The porch is offset.
- 244. **663 Norwood Street** ca. 1935 The one-and-one-half story home is wood frame construction with weatherboard exterior and brick foundation. There is a sun-porch on the left façade that has a decorative balustrade along the roofline.
- 245. **664 Norwood Street** ca. 1935 The one story home is wood frame construction with weatherboard exterior and brick foundation. The hip roof has a single hip dormer on the main façade.

#### OTIS BOULEVARD

246. **504 Otis Boulevard** – ca. 1920 – The two story home is wood frame construction with brick veneer exterior. The hip roof is clad in asphalt shingles. The home is typical of the "four square" construction style with porte cochere balanced with a porch on the side elevations. Windows on the first floor are six-over-one double hung sash flanked by sidelights. There are cutwork brackets beneath the eaves.

### National Register of Historic Places Continuation Sheet

Section number	7	Page _	35	

- 247. **514 Otis Boulevard** ca. 1920 The two story home is wood frame construction with stucco exterior. The cross gable roof is clad in wood shakes. There is a bay window on the main façade with stone surround and casement windows throughout.
- 248. 538 Otis Boulevard ca. 1920 The two story home is masonry construction with brick exterior. The hip roof is clad in clay tile. There is a half-round entry porch with balustrade supported by ionic columns. The porch on the eastern façade was enclosed shortly after construction and an addition has been added to the rear façade.
- 249. **539 Otis Boulevard** ca. 1941 The two story home is masonry construction with gable entry porch and two exterior end brick chimneys. Windows are eight-over-eight double hung sash. There is a shed porch on the left façade.
- 250. **543 Otis Boulevard** ca. 1925 The two story home is wood frame construction with weatherboard exterior and brick foundation. The hip roof is clad in pressed metal shingles. The entry porch is highly detailed with pilasters and corner boards. Windows on the main floor are eight-over-eight double hung sash. Second floor windows are six-over-six double hung sash.
- 251. **544 Otis Boulevard** ca. 1920 The two story home is wood frame construction with shiplap exterior siding and brick foundation. The hip roof is clad in slate. The windows are six-over-one double hung sash. The home has a porte cochere.
- 252. **551 Otis Boulevard** ca. 1925 The one story home is wood frame construction with weatherboard exterior and brick foundation. The cross gable roof is clad in asphalt shingles. The roofline has exposed rafter tails and there are cutwork brackets beneath the gable and eaves. There is a porte cochere on the side elevation.
- 253. 573 Otis Boulevard ca. 1910 The one story home is wood frame construction with wood shingle exterior and brick/stone foundation. The roofline has exposed rafter tails and there are cutwork brackets beneath the gable and eaves. The full façade porch has stone piers. The windows are six-over-one and eight-over-one (main façade) double hung sash. There is a stone retaining wall along the front of the property and an original garage located to the rear.
- 254. **Byrnes House, 576 Otis Boulevard** ca. 1925 The two story home is masonry construction with brick exterior and highly detailed cornice. The side gable roof is clad in slate. The six-over-six double hung sash windows have blind arches on the main floor. There is an entry porch and side porch. There is an addition on the western facade.
- 255. **584 Otis Boulevard** ca. 1910 The one story home is wood frame construction. The front facing gable roof is clad in asphalt shingles. The roofline has exposed rafter tails and there are cutwork brackets beneath the gable and eaves. The windows are ten-over-one double hung sash.

### National Register of Historic Places Continuation Sheet

Section number	7	Page	36	
Section number _		raye_	30	

- 256. **585 Otis Boulevard** ca. 1925 The two story home is wood frame construction with shiplap siding and brick foundation. The hip roof is clad in asphalt shingles. The side entry door has an arched covering. The windows are four-over-one double hung sash. The original front porch has been replaced, the brick exterior has been painted and a garage has been added.
- 257. **591 Otis Boulevard** ca. 1925 The one-and-one-half story home is wood frame construction with stucco/brick/stone veneer exterior and stone foundation. The side gable roof is clad in asphalt shingles. The front porch has a flared roofline with stone foundation and balustrade. There is a large dormer on the main façade. The original entry door has been changed.
- 258. **592 Otis Boulevard** ca. 1910 The one story home is wood frame construction with wood shingle exterior and brick foundation. The pyramidal shaped roof is clad in composition shingles with exposed rafter tails beneath the eaves. There is a pedimented entry on the porch. The windows are leaded with a diamond pattern in the upper sashes over a single pane sash.
- 259. **599 Otis Boulevard** ca. 1935 The one-and-one-half story home is wood frame with brick veneer/asbestos shingle siding and brick foundation. An entry porch has been added, the original windows have been replaced and the brick has been painted.
- 260. **602 Otis Boulevard** ca. 1920 The one story home is wood frame construction with wood shingle exterior and brick foundation. The windows are leaded with a diamond pattern in the upper sashes over a single pane sash. The roofline has exposed rafter tails and there are cutwork brackets beneath the gable and eaves. The home has a half-glass entry door with pediment.
- 261. **605 Otis Boulevard** ca. 1925 The one-and-one-half story home is wood frame construction with synthetic exterior siding and brick foundation. There are arched dormers on the main façade.
- 262. 608 Otis Boulevard- 1914 The one-story home is wood frame construction with stucco exterior. The gable ends contain wood shingle detailing. The windows are leaded with a diamond pattern in the upper sashes over a single pane sash. There is a pedimented entry door with sidelights and a transom. The porch floor is composed of hexagonal ceramic tile with Greek Key inlay.
- 263. 616 Otis Boulevard ca. 1920 The two story home is masonry construction with brick/stone veneer exterior. The pyramidal roof is clad in slate shingles. The offset stone porch includes a porte cochere and has a wrought iron balustrade. The windows are nine-over-one double hung sash. There is one louvered dormer, exposed rafter tails beneath the eaves, copper flashing on the roof, stone chimneys, and arched window and door openings on the first floor.

## National Register of Historic Places Continuation Sheet

Section number	7	_ Page _	37	
Occitori nambor		_ ' " " -		

- 264. **626 Otis Boulevard** ca. 1910 The one-and-one-half story home is wood frame construction with weatherboard/wood shingle exterior. There are exposed rafter tails as well as cutwork brackets beneath the eaves. The home has a pedimented, 8-light entry door with sidelights and transom, nine-over-one double hung sash windows and porte cochere.
- 265. **627 Otis Boulevard** ca. 1935 The one-and-one-half story home is wood frame construction with weatherboard exterior and brick foundation. The home has a large central dormer on the main façade and porte cochere on the side. Windows are eight-over-eight double hung sash.
- 266. 634 Otis Boulevard ca. 1910 The one-and-one-half story home is wood frame construction with wood shingle exterior and brick foundation. The "airplane bungalow" style home has exposed rafter tails as well as cutwork brackets beneath the eaves, eight-over-one double hung sash windows, and garage to the rear.
- 267. 641 Otis Boulevard ca. 1920 The one story home is wood frame construction with wood shingle exterior and brick foundation. The windows are five-over-one double hung sash. There has been major construction on the main façade and the porch has been enclosed.
- 268. 644 Otis Boulevard ca. 1935 The two story home is wood frame construction with synthetic exterior siding and brick foundation. The windows are eight-over-eight double hung sash.
- 269. **650 Otis Boulevard** ca. 1925 The two story home is wood frame construction with brick exterior. The roof is clad in clay tiles. The porch is supported with stone columns and has a wrought iron balustrade. The side porch also has stone column supports with exposed rafter tails. The windows are six-over-one double hung sash.
- 270. **656 Otis Boulevard** ca. 1930 The two story home is wood frame construction with weatherboard exterior and brick foundation. The front and side porches are supported with Ionic columns and both have wrought iron balustrades. The entry door is arched with arched sidelights. Arched doors and windows are also access the side porch.
- 271. 662 Otis Boulevard 1922 The two story home is wood frame construction with stucco exterior and brick foundation. There are two flat roofed wings projecting on either side of the main façade. The entry porch is recessed, supported with Doric columns. The main entry door is flanked with multi-pane sidelights.
- 272. 663 Otis Boulevard ca. 1920 The one-and-one-half story home is wood frame construction with wood shingle exterior and brick foundation. Front porch columns are grouped in threes. There are six-over-one double hung sash windows, entry door with sidelights, and bay window on the side elevation.

# National Register of Historic Places Continuation Sheet

Section number	7	Page	38	
Section number _		raye.	30	_

- 273. **700 Otis Boulevard** ca. 1950 The two story home is wood frame construction with monumental shed porch supported with square posts. Windows are eight-over-eight double hung sash. There is an exterior end chimney on the left façade and a one-story gable wing on the right. The main entry door is flanked by sidelights.
- 274. **670 Otis Boulevard** ca. 1920 The one story home is wood frame construction with brick exterior. The hip roof is clad in asphalt shingles. The jerkinhead entry porch is supported with Doric columns. The home has an addition on the rear façade.
- 275. **685 Otis Boulevard** ca. 1925 The two story home is wood frame construction with brick exterior. The hip roof is clad in clay tiles. There is a stone retaining wall that runs along the front of the property.
- 276. **701 Otis Boulevard** ca. 1940 The two story home is wood frame construction with weatherboard and brick veneer exterior. The entry door is centered on the main façade with paired pilasters flanking the entry door and triangular pediment above. There is a large addition to the left of the home.
- 277. **705 Otis Boulevard** ca. 1930 The one story home is wood frame construction with gable roof. The front porch is supported with simple Doric columns. There is cutwork vergeboard in the porch gable end. There are casement windows on either side of the main entry door and a sun room on the right elevation.
- 278. **709 Otis Boulevard** ca. 1930 The one story home is wood frame construction with brick veneer exterior and gable roof. There are two front facing gables on the main façade, both with half-timbering. The main entry door is recessed beneath a gable with arched entry. There is a chimney on the main façade with decorative top.
- 279. **713 Otis Boulevard** ca. 1930 The one story home is wood frame construction with brick veneer exterior and gable roof. There is a gable in the center of the main façade with semi-circular window. The main entry door is topped with a fanlight. There are casement ribbon windows on both sides of the main entry door with arched molding. There is a stone chimney.
- 280. **715 Otis Boulevard** ca. 1935 The one story home is wood frame construction with brick veneer exterior and gable-on-hip roof. The gable on the main façade is decorated with half-timbering. The main entry door is surrounded by a transom and sidelights. There is rough-faced stone set into the brick surrounding the entry door. The chimney is on the main façade with decorative stone detailing.
- 281. Evans/Russell House, 716 Otis Boulevard 1892 Individually listed in the National Register of Historic Places on 21 March 2007. The two story house was constructed for John Gary Evans, Governor of South Carolina from 1894-1897. This was also the home of Donald Russell, former Governor of South Carolina, United States Senator, and United States Circuit Court Judge. The home is wood frame construction with weatherboard exterior and stone foundation. There is a monumental portico on the

# National Register of Historic Places Continuation Sheet

Section	number	7	Page	39	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

main façade supported by four Corinthian columns. The second story has a balcony with balustrade and large pediment above. There are dormers on the main roofline containing Palladian windows. There are two large brick chimneys, two dual-pitched side gables containing Palladian windows.

- 282. 717 Otis Boulevard ca. 1950 The one-and-one-half story home has a stucco exterior, lateral gable roof with three gable dormers on the main roof slope, entry door with fanlight and sidelights, and gable entry porch supported by paired posts.
- 283. **720 Otis Boulevard** ca. 1950 The two story home is wood frame construction with gable roof and offset entry door. The main entry door has a transom and sidelights and sits beneath a shallow gable entry porch. There is a large two story lateral gable wing on the left façade and one-story gable wing on the right façade.
- 284. **729 Otis Boulevard** ca. 1930 The two story home is wood frame construction with brick veneer exterior and gable roof. The front door is beneath a rounded arch and has a triangular pediment, sidelights and fanlight. There are casement ribbon windows on the right side of the main façade. The porch on the left elevation has large, arched openings. There are heavy brick piers around the patio.
- 285. **735 Otis Boulevard** ca. 1930 The one story home is wood frame construction with brick veneer exterior and steeply pitched gable roof. The chimney has two arched niches. The side gables and the main façade all contain tripartite casement windows. The porch roof is supported with tapered stone piers.
- 286. **741 Otis Boulevard** ca. 1927 The one story home is masonry construction with a large front facing gable with flared eave containing a tripartite casement window on the main façade. The entry is arched.
- 287. 747 Otis Boulevard ca. 1931 The one story home is wood frame construction with brick veneer exterior and gable roof. There are two front facing gables on the main façade. The entry is recessed beneath a rounded arch and there are tripartite casement windows on the main façade. The small porch on the eastern elevation has been enclosed.
- 288. **764 Otis Boulevard** ca. 1940 The home has a monumental portico on the main façade supported by Doric columns and has a turned balustrade. There pediment contains an oval window. The main entry door has sidelights and a fanlight. There is a second story balcony over the main entry door with balustrade.
- 289. **765 Otis Boulevard** ca. 1930 The one story home is wood frame construction wth brick veneer exterior. The front gable has a flared eave over the main entry door. The chimney is on the main façade with sloping siding. The main entry door is recessed beneath a segmental arch. Arches over the main entry door and porch openings contain keystones.

### National Register of Historic Places Continuation Sheet

Section number	7	Page _	40

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

290. **767 Otis Boulevard** – ca. 1940 – The one story home is wood frame construction with synthetic exterior siding and brick foundation. There is a gable on the main façade containing tripartite casement windows. The main entry door is located beneath a small ornamental gable with elliptical arch. There are paired pillars on each side of the entry door.

#### PALMETTO STREET

- 291. **537 Palmetto Street** ca. 1920 The two story home is woo drame construction with weatherboard exterior siding, lateral gable roof, eight-over-eight double hung sash windows and entry door with fanlight and sidelights.
- 292. **539 Palmetto Street** ca. 1940 The one-and-one-half story home is wood frame construction with stucco exterior and lateral gable roof with two gable dormers. The main entry has a flat roof porch with balustrade supported with thin posts.
- 293. **540 Palmetto Street** ca. 1940 The two story home is wood frame construction with synthetic exterior siding, lateral gable roof and gable entry porch supported with wrought iron posts. Windows are eight-over-eight double hung sash. There is a one-story gable wing on the left elevation.
- 294. **541 Palmetto Street** ca. 1945 The one story home has a stucco exterior, lateral gable roof and six-over-six double hung sash windows. There is a large front facing gable on the left side of the main façade that contains the main entry door. The entry sits beneath an arched opening within a shallow gable wing. There is a bay window on the left side of the main façade.
- 295. **542 Palmetto Street** ca. 1920 The two story home is masonry construction with brick exterior and hip roof. There is a two-story porch on the main façade supported with square posts. The main entry door is flanked with sidelights. Windows are six-over-six double hung sash.
- 296. **546 Palmetto Street** ca. 1915 The two-story home is wood frame construction with hip roof. There is a two-story gable wing projecting from the left side of the main façade. The second story is clad with shingle decoration. All of the original windows have been replaced.
- 297. **548 Palmetto Street** 1947 The one-story wood frame cottage has an interior brick chimney, eight-over-eight double hung sash windows and central entry door.
- 298. 549 Palmetto Street ca. 1940 The one-and-one-half story duplex is wood frame construction with lateral gable roof containing four gable dormers and engaged shed porch between two projecting shed wings.

### National Register of Historic Places Continuation Sheet

Section number	7	Page _	41	

- 299. **550 Palmetto Street** 1948 The one story home is masonry construction with stucco exterior and hipped roof clad in composition shingles. There is a gable entry porch supported with paired ionic columns.
- 300. **554 Palmetto Street** ca. 1930 The one-and-one-half story home is wood frame construction with synthetic siding on the exterior and cross gable roof. There is a small, arched entry porch and a second porch on the left side of the main façade that extends to include a porte cochere. The gable end contains a six-pane window flanked by attic vents.
- 301. **556 Palmetto Street** ca. 1925 The two story home is wood frame construction with weatherboard exterior and gambrel roof. The hip roof porch is supported with simple columns.
- 302. **559 Palmetto Street** ca. 1930 The one story home is wood frame construction with front gable roof, offset gable porch supported with square posts, three-over-one double hung sash windows, and knee brackets beneath the eaves.
- 303. **597 Palmetto Street** ca. 1900 The one story home is wood frame construction with synthetic exterior siding. The full-façade porch is engaged and supported with tapered wooden posts on brick piers. The gable end contains a single-pane window flanked by attic vents.
- 304. **605 Palmetto Street** ca. 1930 The one story home is wood frame construction with stucco exterior. The offset porch is supported with large square posts resting on brick piers. Windows are four-over-one double hung sash windows (paired on the main façade) and the main entry door is flanked with Craftsman style sidelights.
- 305. **606 Palmetto Street** ca. 1927 The one-and-one-half story home has a recessed entry door beneath a small projecting gable, chimney on the main façade, and half-timbering in the gable ends. The porch to the right of the main entry has been enclosed.
- 306. **608 Palmetto Street** ca. 1920 The one-and-one-half story home is wood frame construction with weatherboard exterior. The main entry door is on the left side of the main façade beneath a small gable. There is a tapered chimney on the main façade. Windows are eight-over-one double hung sash.
- 307. **610 Palmetto Street** ca. 1925 The two story home is wood frame construction with weatherboard exterior and brick foundation. The entry porch is arched, supported with simple Doric columns. The entry door surround is tapered and includes a single-light transom window. There are decorative brackets beneath the eaves.

# National Register of Historic Places Continuation Sheet

Section number	7	Page	42	
Occuon number		i age _	74	

- 308. 615 Palmetto Street ca. 1925 The one-and-one-half story home is wood frame construction with weatherboard exterior and side gable roof. There is a small gable dormer on the right side of the main roofline containing a six-over-six double hung sash window. There is a front facing gable on the left side of the main façade that contains the entry porch and tri-partite window. The entry door has sidelights and transom. There are one-story wings on each side elevation.
- 309. **618 Palmetto Street** ca. 1920 The two story home is wood frame construction with weatherboard exterior. There is a large shed dormer on the main façade. The entry porch is arched and supported with wood brackets. The entry door is flanked by sidelights and topped with a small fanlight. Windows are paired, six-over-one double hung sash.
- 310. **626 Palmetto Street** ca. 1920 The one-and-one-half story home is wood frame construction with weatherboard exterior, gambrel roof and interior chimney. There is an engaged entry porch on the right side of the main façade supported with paired wooden posts on stuccoed masonry piers. There are two shed dormers on the main façade, the longer containing three double hung sash windows.
- 311. **627 Palmetto Street** ca. 1925 The one-and-one-half story home is wood frame construction with stucco exterior. The gable porch extends to include a porte cochere and is supported with square wooden posts resting on brick piers. The main entry door is flanked by sidelights. There is a gable dormer on the right elevation.
- 312. McMillan, Walter House, 641 Palmetto Street 1927 The home was built by the Little Construction Company for Walter McMillan, a bookkeeper for the Carolina National Bank. The one-and-one-half story home is wood frame construction with weatherboard exterior and stone foundation. There is an exterior end stone chimney, eyebrow vent on the main façade, and exposed rafter tails and brackets beneath the eaves. There are oval attic vents in the gable ends. The home has casement windows with fixed transoms as well as six-over-one double hung sash windows. A small dormer has been added on the main façade and double-hung sash windows have been added in the gable ends.
- 313. Shepherd, Ernest House, 642 Palmetto Street 1934 The home was constructed for Ernest Shepherd, a local dentist. The two story home is wood frame construction with weatherboard exterior and brick foundation. The porch stretches across the main façade but is uncovered except for an entry portico. The main body of the house is flanked by two, one-story wings with flat roofs. There are two exterior end brick chimneys. Each gable end contains a semi-circular attic vent.
- 314. **Johnston, T. Henry House, 649 Palmetto Street** 1930 The home was constructed for Thomas Henry Johnson. The one story wood frame home is clad in weatherboard with a brick foundation and hip roof. The porch is supported by wooden posts resting on brick piers. Windows are six-over-one double hung sash.

# National Register of Historic Places Continuation Sheet

Section number	7	Page _	43	

- 315. Wardlaw, James House, 650 Palmetto Street 1937 The home was constructed for James Wardlaw, the treasurer of Drayton Mills in Spartanburg. The two story house is wood frame construction with asbestos shingle exterior. There is a small entry porch on the main façade.
- 316. **655 Palmetto Street** 1930 The one story home is wood frame construction with weatherboard exterior, brick foundation and hip roof. There is a gable dormer on the main façade containing three single pane windows. The full façade, engaged porch has an open rail balustrade and is supported with paired/tripartite wooden posts resting on brick piers. The windows are six-over-one double hung sash.
- 317. Finney, R.P. House, 661 Palmetto Street 1927 The one story wood frame home is clad in weatherboard with a brick foundation. There is a gable dormer on the main façade containing a fixed window flanked by attic vents. The full façade porch is supported with square wooden posts resting on brick piers. There is one exterior end brick chimney.
- 318. Webb, St. Claire House, 662 Palmetto Street 1927 The one story home was the residence of St. Claire Webb, general manager of Southern Paving Company. The one-story masonry home has a cross gable roof and two exterior end chimneys. The full façade porch is supported with brick posts. Brick stairs lead to the 12-light entry door. Windows are six-over-one double hung sash.
- 319. Black, Hugh House, 666 Palmetto Street 1927 The one story home was the residence of Dr. Hugh Black, associated with Mary Black clinic and hospital. The home is wood frame construction with weatherboard exterior and brick foundation. There are tripartite six-over-one double hung sash windows, porch and porte cochere supported with tapered brick posts on brick piers, and paneled entry door.
- 320. **712 Palmetto Street** ca. 1937 The one story home is wood frame construction with painted brick veneer exterior and hipped roof clad in composition shingles. There is a front projecting gable wing on the left side of the main façade with sloping edge containing a tapered exterior chimney and arched entry porch. Windows are four-over-one double hung sash.
- 321. **716 Palmetto Street** ca. 1936 The two story home is wood frame construction with wood shingle exterior and lateral gable roof clad in composition shingles. The main entry door is offset to the left with broken pediment. Windows are six-over-six double hung sash. There is a one-story shed porch on the right elevation.
- 322. **724 Palmetto Street** ca. 1934 The one-and-one-half story home is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There are two front facing gables on each end of the main façade, the left containing a casement window and circular attic window in the gable end. The right gable contains the recessed entry porch with arched openings and a smaller gable that contains the arched entry door. There is an addition on the rear elevation.

# National Register of Historic Places Continuation Sheet

Section number	7	Page _	44	
				_

- 323. **730 Palmetto Street** ca. 1924 The one story home is wood frame construction with painted brick veneer exterior and lateral gable roof clad in composition shingles. There is a large gable porch on the main façade supported with square wooden and square brick posts resting on brick piers with a broken brick balustrade. There are wood shingles in the porch's gable end. Windows are four-over-one double hung sash.
- 324. **732 Palmetto Street** ca. 1940 The one story home is wood frame construction with weatherboard exterior and lateral gable roof clad in composition shingles. There is an offset gable porch on the right side of the main façade that has been enclosed with screen. Windows are six-over-six double hung sash.
- 325. **734 Palmetto Street** ca. 1940 The two story home is wood frame construction with painted brick veneer exterior and lateral gable roof clad in composition shingles. The symmetrical façade has eight-over-eight double hung sash windows with central entry door flanked by pilasters and topped with an arched fan decoration. There is a large addition on the rear façade.
- 326. **756 Palmetto Street** ca. 1939 The one-and-one-half story home is wood frame construction with wood shingle exterior and lateral gable roof clad in composition shingles. There are stacked projecting gables on the left side of the main façade the larger of which contains the main entry door and a smaller gable clad in fieldstone. There is a gable porch on the right elevation supported with large fieldstone columns.
- 327. **762 Palmetto Street** ca. 1930 The one story home is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There is a central entry door with shed porch flanked by a tapered chimney to the right and front projecting gable wing to the left. There is a large addition on the rear of the house.
- 328. **766 Palmetto Street** ca. 1927 The two story home is wood frame construction with brick veneer exterior and jerkinhead roof clad in slate shingles. The home has a large projecting wing on the left side of the main façade with long roof slope that includes the arched entry and projecting bay window. There is a small jerkinhead dormer on the right side fo the main façade. Windows are six-over-six and four-over-four double hung sash.
- 329. **770 Palmetto Street** ca. 1920 The two story home is wood frame construction with brick veneer exterior and saltbox roof clad in composition shingles. There are three gable dormers on the main façade. The main entry door is offset to the right of the main façade. There is a projecting bay window on the left side of the main façade.

### National Register of Historic Places Continuation Sheet

Section	number	7	Page	15	
Section	number_		_Page_	45	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 330. 772 Palmetto Street ca. 1938 The one story home is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There are stacked gables in the center of the main façade containing an exterior chimney with stone detailing and the arched entry door with stone detail. There is a front facing gable on the left side of the main façade as well. Both gable ends contain arched attic vents. Windows are six-over-six double hung sash. The porch on the right elevation has been enclosed.
- 331. 776 Palmetto Street ca. 1935 The two story home is wood frame construction with brick veneer exterior and jerkinhead roof clad in composition shingles. The porch is supported by square brick posts. Windows are six-over-six double hung sash. The entry door is flanked by sidelights. There is half-timbering in the side gable ends.
- 332. 778 Palmetto Street ca. 1932 The one story home is wood frame construction with yellow brick veneer exterior and lateral gable roof clad in composition shingles. There is a large front facing gable on the left side of the main façade with sloping eave and half-timber detailing. There is a smaller front facing gable on the right side of the main façade with a round attic vent and half timber detailing. Windows are six-over-six and four-over-four double hung sash.
- 333. 800 Palmetto Street ca. 1930 The one story home is wood frame construction with stucco exterior and lateral gable roof clad in composition shingles. There is a large projecting gable wing on the right side of the main façade containing a small recessed entry porch. Windows are six-over-six double hung sash.
- 334. 802 Palmetto Street ca. 1928 The one story home is wood frame construction with brick veneer and weatherboard exterior and jerkinhead roof clad in composition shingles. There is an offset porch on the left side of the main façade supported with brick posts. There are gable dormers on the east and west facades. Windows are eight-over-one double hung sash.

#### PLUME STREET

- 335. **706 Plume Street** ca. 1925 The one story home is wood frame construction with wooden shingle exterior siding, brick foundation, and front gable roof clad in composition singles. There are shallow projecting gable wings on the side elevations. The recessed entry porch is supported with paired wooden posts resting on brick piers. There are exposed roof beams and rafter tails beneath the eaves.
- 336. **710 Plume Street** ca. 1920 The one-and-one-half story home is wood frame construction with wood shingle exterior, lateral gable roof clad in composition shingles with gable dormer in the center of the main façade containing a two-pane window flanked by rectangular attic vents. The shed porch is supported with tapered brick posts resting on short brick piers. Windows are twelve-over-one double hung sash.

# National Register of Historic Places Continuation Sheet

Section number 7 Page 46				
	Section number	7	Page	46

- 337. **716 Plume Street** ca. 1926 The one story home is wood frame construction with weatherboard exterior and hipped roof clad in composition shingles. There is a hipped dormer on the main façade containing a single window flanked by rectangular attic vents. The recessed porch is supported by thin wooden posts resting on brick piers (paired at the corners). Windows are four-over-one double hung sash.
- 338. 722 Plume Street Vacant lot.
- 339. **728 Plume Street** ca. 1920 The two story home is wood frame construction with synthetic exterior siding, hipped roof clad in composition shingles with hipped dormer on the main façade. The hipped porch is supported with paired classical columns, has a pediment over the main entry door and wraps to the left façade. Windows are new six-over-one double hung sash. There is an exterior brick chimney on the east façade.
- 340. **736 Plume Street** ca. 1915 The two story home is brick construction with lateral gable roof clad in composition shingles and hipped entry porch supported with heavy classical columns. Windows are nine-over-one double hung sash. There is a double entry door. There is a hipped porch on the east façade supported with four classical columns enclosed with screen.
- 341. **755 Plume Street** ca. 1924 The two story Tudor style home is frame construction with stucco exterior. The cross gable roof is clad in asphalt shingles. The home has casement windows, interior sloping chimney, dormer on the main façade, and half timbering in the gable ends. There was an addition placed on the rear of the home in 1952. The home was purchased in 1937 by Walter Montgomery who was the former president of Spartan Mills. The home is currently owned by his granddaughter, Sally Spencer.
- 342. **763 Plume Street** ca. 1940 The two story home is wood frame construction with weatherboard exterior and brick foundation. The hip roof is clad in asphalt shingles. There is an entry porch supported with paired square columns. The side porch is screened with a metal balustrade along the roofline. There are three eyebrow gables on the main façade.
- 343. **764 Plume Street** ca. 1940 The two story Colonial Revival home is wood frame construction with weatherboard exterior and brick pier foundation. The windows are six-over-one double hung sash. The entry porch is supported with tripartite Doric columns. The side porch was enclosed in the 1990s and in the 1970s, a flat roofed rear addition was added.
- 344. **766 Plume Street ca**. 1930 The one-and-one-half story home is masonry construction with brick exterior. The salt-box style roof is clad in asphalt shingles. There are two gable dormers on the main façade, eight-over-eight double hung sash windows, exterior brick chimney.

## National Register of Historic Places Continuation Sheet

e <u>47</u>	
1	e <u>47</u>

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 345. **784 Plume Street** ca. 1930 The one story home is wood frame construction with wood shingle exterior and brick foundation. The hip roof is clad in asphalt shingles. The windows are nine-over-one double hung sash. The main entry door has a transom and sidelights.
- 346. **785 Plume Street** ca. The one-and-one-half story Colonial Revival home is wood frame construction with weatherboard exterior and brick foundation. The side gable roof has three gable dormers with double-hung sash windows. There is an arched entry door with fanlight and sidelights.
- 347. **796 Plume Street** ca. 1930 The one-and-one-half story home is wood frame construction with jerkinhead roofline, weatherboard exterior and brick foundation. The eaves have a wide overhang with brackets beneath. The front gable end contains an attic vent and the side gable contains a double-pane, side hinged window. Windows are six-over-one double hung sash.
- 348. 802 Plume Street Vacant lot.
- 349. **Barnwell, Robert House, 805 Plume Street** 1927 The two story home is wood frame with stucco exterior. The hip roof is clad in slate. There is an eyebrow dormer in the center of the main façade, six-over-six double hung sash windows, and two exterior chimneys.

#### POPLAR STREET

- 350. **518 Poplar Street** The one-story home is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There is a large gable porch supported with tapered brick piers.
- 351. **519 Poplar Street** ca. 1945 The one story home is wood frame with painted brick veneer exterior and lateral gable roof clad in composition shingles. There is a front projecting gable wing on the right side of the main façade containing the main entry door. Windows are six-over-six double hung sash.
- 352. **520 Poplar Street** ca. 1940 The one-story home is wood frame construction with synthetic exterior siding and cross gable roof clad in composition shingles. The entry door is offset to the right side and there is a shallow bay window on the main façade.
- 353. **522 Poplar Street** ca. 1940 The one-story home is wood frame conststruction with brick veneer exterior and hip roof clad in composition shingles. There is a wing projecting on the right side of the main façade.
- 354. **523 Poplar Street** ca. 1940 The one-and-one-half story home is wood frame construction with wood shingle exterior and front gable roof. The entry porch is supported by wood brackets. To the left of the entry is a projecting bay window with six-over-six double hung sash windows. There are three gable dormers on the east elevation and a one-story gable wing on the west elevation containing a garage.

# National Register of Historic Places Continuation Sheet

Section number	7	Page	48
Section number		Page _	40

- 355. **524 Poplar Street** ca. 1940 The one-and-one-half story home is wood frame construction with asbestos shingle exterior siding and lateral gable roof clad in composition shingles. There are two gable dormers on the main façade.
- 356. **525 Poplar Street** ca. 1945 The one story home is wood frame construction with synthetic exterior siding and lateral gable roof clad in composition shingles. There are stacked front facing gables on the right side of the main façade, the smaller gable containing the entry door with entry porch. There is a recessed porch on the left side of the main façade containing a second entry door. Windows are six-over-six double hung sash.
- 357. **527 Poplar Street** ca. 1945 The one story duplex is wood frame construction with a painted brick veneer exterior, asbestos shingle siding in the gable ends, lateral gable roof clad in composition shingles, and large front facing gable in the center of the main façade. There are two entry doors in the center of the main façade flanked by projecting bay windows.
- 358. **529 Poplar Street** ca. 1930 The one story home is wood frame construction with brick veneer exterior, lateral gable roof clad in composition shingles, and three-over-one double hung sash windows. There is a chimney on the main façade with a recessed rectangular panel decoration. The recessed entry porch sits beneath a large gable supported with square brick posts.
- 359. **530 Poplar Street** ca. 1940 The one-and-one-half story home is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There are two gable dormers on the main façade.
- 360. **531 Poplar Street** ca. 1950 The one story home is wood frame construction with brick veneer exterior, hip roof clad in composition shingles, gable porch on the right side of the main façade with arched openings, and six-over-six double hung sash windows.
- 361. 532 Poplar Street ca. 1940 The one-story home is wood frame construction with brick veneer exterior and cross gable roof clad in composition shingles. There is a gable wing on the right side of the main façade.
- 362. 533 Poplar Street ca. 1930 The one-and-one-half story home is wood frame construction with brick veneer exterior (weatherboard in the top gable end). The porch is offset to the right beneath stacked gables, the smaller of which contains the recessed entry. Windows are six-over-one double hung sash with single pane windows in the gable ends.
- 363. 534 Poplar Street ca. 1940 The one-story home is wood frame construction with vinyl exterior siding, lateral gable roof clad in composition shingles and six-over-six double hung sash windows.

#### National Register of Historic Places Continuation Sheet

Section number	7	Page _	49	
				_

- 364. 537 Poplar Street ca. 1935 The one-and-one-half story home is wood frame construction with asbestos shingle exterior siding and lateral gable roof clad in composition shingles. There is a front facing gable in the center of the main façade containing the main entry door and exterior chimney (to the right of the entry). There are two gable dormers on the main façade and a recessed porch to the left of the entry door enclosed with screen.
- 365. **539 Poplar Street** ca. 1935 The one story home is wood frame construction with asbestos shingle exterior and lateral gable roof clad in composition shingles. There is a front facing gable on the main façade containing an exterior chimney with sloping side and four-pane attic window. The main entry door has an arched transom and arched entry porch supported with brackets.
- 366. 540 Poplar Street ca. 1940 The one-and-one-half story home is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There are two gable dormers on the main façade and a gable containing the main entry door. There is a porch to the right of the main façade.
- 367. **544 Poplar Street** ca. 1930 The one-story home is wood frame construction with brick veneer exterior and jerkinhead roof clad in composition shingles. There is a porch to the left of the main entry door enclosed with vinyl windows. The main entry door is beneath a small shed roof porch supported with simple columns.
- 368. **545 Poplar Street** ca. 1937 The one-and-one-half story home is wood frame construction with synthetic exterior siding, cross gable roof clad in composition shingles and recessed porch supported with tapered wooden posts on brick piers (partially enclosed and screened). There are stacked gables on the side elevations.
- 369. **549 Poplar Street** ca. 1935 The one-and-one-half story home is wood frame construction with brick veneer exterior and half timber detailing in the gable ends. There are stacked front facing gables on the right side of the main façade containing the small, shed entry porch. There is a projecting gable porch on the east elevation. A metal porch awning has been added to the main façade.
- 370. **550 Poplar Street** ca. 1930 The one-story home is wood frame construction with weatherboard exterior siding. The porch is offset to the right on the main façade and supported with square brick posts.
- 371. **554 Poplar Street** ca. 1925 The one-story home is masonry construction with brick & stucco exterior and lateral gable roof clad in composition shingles. There is a gable porch on the main façade that has been enclosed.

### National Register of Historic Places Continuation Sheet

Section number	7	Page _	50	

- 372. 555 Poplar Street ca. 1925 The one story home is wood frame construction with synthetic exterior siding, jerkinhead roof clad in composition shingles, and recessed entry porch supported by two classical columns with two entry doors on each side. The entry doors sit beneath a shallow gable containing a lunette attic vent. A stone has been placed around the water table on the main façade. There is a carport on the right side of the home.
- 373. 559 Poplar Street ca. 1924 The one story home is wood frame construction with shiplap exterior siding and lateral gable roof clad in composition shingles. There is an exterior chimney on the main façade with an arched panel decoration. Windows are six-over-one and six-over-six double hung sash. There is a gable entry porch supported with wrought iron posts. There are exposed rafter tails beneath the eaves.
- 374. **560 Poplar Street** ca. 1925 The one-story home is wood frame construction with wood shingle exterior siding and jerkinhead roof clad in composition shingles. The engaged porch has been enclosed with screen.
- 375. **597 Poplar Street** ca. 1927 The one-story home is wood frame construction with vinyl exterior and wood shingles in the gable ends. The porch has brick piers with small wooden post supports. There are wide eave overhangs with decorative brackets. There is a transom over the entry door.
- 376. **600 Poplar Street** ca. 1930 The one story home is wood frame construction with weatherboard exterior and brick foundation. There are ribbon windows on the east and west elevations of the home. There are arched attic vents in the front and side gable ends.
- 377. **603 Poplar Street** ca. 1925 The one story home is wood frame construction with weatherboard exterior and brick foundation. The gable roof is clad in composition shingles. The gable porch is supported by slender Doric columns. There are pilasters and a decorative pediment over the front entry door.
- 378. **604 Poplar Street** ca. 1932 The one story house is wood frame construction with weatherboard exterior and brick foundation. There is a small gable over the front entry. The gable roof is clad in composition shingles. There is a slope chimney on the rear of the roof.
- 379. 608 Poplar Street ca. 1932 The one story home is wood frame construction with weatherboard exterior and brick foundation. The hipped roof is clad in composition shingles and has projecting gables on the side elevations. There is a peak chimney in the center of the roofline. The porch has pilasters and decorative pediment.
- 380. **609 Poplar Street** ca. 1935 The one story home is wood frame construction with weatherboard exterior and brick foundation. The home has a steeply pitched roof clad in composition shingles. There is a shed dormer on the main façade and small gable over the entry on the main façade.

# National Register of Historic Places Continuation Sheet

	AND STANDARD STANDARDS	-	11	1440	
Section	number	7	Page _	51	
					•

- 381. 613 Poplar Street ca. 1930 The two story home is wood frame construction with weatherboard exterior and brick foundation. The hipped roof is clad in composition shingles. The front entry door is flanked by sidelights. There are wide eave overhangs with decorative brackets. There is a one-story wing on the west elevation with hipped roof.
- 382. 614 Poplar Street ca. 1927 The one story home is wood frame construction with weatherboard exterior and brick foundation. The porch is supported with brick piers and the entry door is flanked by sidelights.
- 383. 619 Poplar Street ca. 1925 The two story home is wood frame construction with brick veneer exterior and hipped roof clad in composition shingles. The entry porch is slightly curved and supported with ionic columns. There are bay windows flanking the main entry door. There is a one-story wing with hipped roof on the west elevation. A chimney with decorative brickwork is on the east elevation.
- 384. **620 Poplar Street** -ca. 1927 The one-and-one-half story home is wood frame construction with weatherboard (side elevations) and stucco (main façade) exterior and lateral gable roof clad in composition shingles. The main entry porch has four Doric columns and two pilasters. The covered porch has rounded arch on the east elevation. There is a large gable addition on the rear façade.
- 385. 625 Poplar Street ca. 1929 The one-story home is wood frame construction with brick foundation with cross gable roof clad in composition shingles. The main entry door has a small gable.
- 386. 626 Poplar Street ca. 1927 The one story home is wood frame construction with brick veneer and wood shingle exterior and brick foundation. The front and side gables have wide eave overhangs with decorative brackets. There are ribbon windows on the east elevation.
- 387. 635 Poplar Street ca. 1925 The one story home is masonry construction with brick foundation and lateral gable roof clad in composition shingles. There is a gable roofed porch on the left side of the main façade supported with wooden posts resting on stone piers, four-over-one double hung sash windows, and stone chimney on the main façade flanked by arched windows.
- 388. 638 Poplar Street ca. 1927 The one story home is masonry construction with brick foundation, hip roof clad in composition shingles. There is a gable porch with roof return, exposed rafter tails beneath the eaves, and six-over-six and six-over-one double hung sash windows as well as eight pane casement windows.
- 389. 647 Poplar Street ca. 1925 The one story home is masonry construction with brick exterior and front gable roof clad in composition shingles. The gable ends are stucco with an arched window flanked by rectangular attic vents in the main gable end. The porch is supported with brick posts and there are shallow gable wings on the side elevations. The main entry door is flanked by sidelights.

### National Register of Historic Places Continuation Sheet

Section number	7	Page	52	
Section number _		_ Page	52	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 390. **648 Poplar Street** ca. 1927 The one story home is masonry construction with painted brick exterior, gable roof clad in composition shingles and gable porch supported with square wooden posts with decorative brackets beneath the eaves. There are ribbon windows on the main façade, interior chimneys, and four-over-one double hung sash windows.
- 391. 649 Poplar Street ca. 1920 The one-and-one-half story home is wood frame construction with synthetic siding and lateral gable roof clad in composition shingles with flared eaves. There is a large gable dormer on the main façade containing paired windows. The shed porch is supported with tapered wooden posts resting on brick piers and there is a paired entry doors with sidelights.
- 392. 653 Poplar Street ca. 1925 The one story home is masonry construction with brick exterior and lateral gable roof clad in composition shingles. There is a tapered exterior chimney on the main façade, stacked gables on the main façade, the smaller containing the arched entry porch with stone detailing. There are four-over-one double hung sash windows and rectangular attic vents in the gable ends.
- 393. **654 Poplar Street** ca. 1927 The one story home is wood frame construction with weatherboard exterior siding, brick foundation, and gable roof clad in composition shingles. There is a small entry porch supported with paired wooden posts, four-over-one double hung sash windows, shed porch on the side elevation, and four interior chimneys.
- 394. **658 Poplar Street** ca. 1927 The one story home is wood frame construction with synthetic exterior siding, brick foundation, and gable roof clad in composition shingles. There are four-over-one double hung sash windows, and offset gable porch supported with decorative square brick posts. There is a large gable addition on the rear façade.
- 395. **664 Poplar Street** ca. 1927 The one story home is wood frame construction with weatherboard exterior siding, brick foundation and gable roof clad in composition shingles. There are one-over-one double hung sash windows, exposed rafter tails and knee brackets beneath the eaves, recessed porch supported with square wooden posts, and single pane attic window in the front gable end.
- 396. **665 Poplar Street** ca. 1940 The two story wood frame house has weatherboard exterior siding, brick foundation, lateral gable roof clad in composition shingles, and one-story gable wing on the left elevation. There are paired six-over-six double hung sash windows on the main façade, offset entry door with bay window projecting to the left of the entry, and lunette attic vents in the gable ends.

#### RUTLEDGE STREET

397. **601 Rutledge Street** – ca. 1914 – The two story home is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. There is a hipped attic dormer in the center of the main façade. The hipped porch wraps to the left façade and is supported with simple Doric columns. The entry door has a transom and is flanked with pilasters.

### National Register of Historic Places Continuation Sheet

Section number	7	Page	53	

- 398. **606 Rutledge Street** ca. 1915 The two story home is wood frame construction with wood shingle exterior siding and hipped roof clad in composition shingles. The hipped porch is supported with square posts on brick piers. The right side of the porch has been enclosed. Windows are six-over-one double hung sash. There is a transom over the main entry door.
- 399. **610 Rutledge Street** ca. 1913 The two story home is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. There is a hip dormer on the main façade. The hipped porch is supported by square brick posts with diamond accents. The main entry door is offset to the left on the main façade.
- 400. **611 Rutledge Street** ca. 1915 The two story home is wood frame construction with brick veneer exterior and hipped roof clad in composition shingles. The main entry door is offset to the right of the main façade with a transom and sidelights. The flat roofed entry porch is supported with simple Doric columns with a wooden balustrade along the roofline. There is a one story hipped roof wing on the east façade.
- 401. **620 Rutledge Street** ca. 1912 The one-and-one-half story home is wood frame construction with weatherboard and wood shingle exterior and lateral gable roof clad in composition shingles. There is a large front facing gable in the center of the main façade containing two circular windows and a circular attic vent as well as three one-over-one double hung sash windows. The hipped porch is offset to the right and the main entry door is flanked by fluted pilasters and topped with a transom.
- 402. **626 Rutledge Street** ca. 1922 The one story home is wood frame construction with synthetic exterior siding and lateral gable roof clad in composition shingles. There is a gable dormer in the center of the main façade containing a three-pane window. The main entry door is surrounded by a transom and sidelights. Windows are six-over-one double hung sash.
- 403. **650 Rutledge Street** ca. 1907 The one story home is wood frame construction with wood shingle exterior and brick foundation. The porch is supported with paired columns. Windows are five-over-one double hung sash. This home was once used as the Parsonage for Trinity Methodist Church.
- 404. **649 Rutledge Street** The one-and-one-half story home is wood frame construction with weatherboard exterior, brick foundation and hip roof. There is a hip dormer on the main façade. The porch is supported with paired columns.
- 405. **655 Rutledge Street** ca. 1920 The one-and-one-half story home is wood frame construction with wood shingle exterior and stuccoed masonry foundation. The side gable roof has two small dormers (added in the 1980s) on the main façade. The main entry door is surrounded by a transom and sidelights.

### National Register of Historic Places Continuation Sheet

Section	number	7	_ Page _	54	

- 406. **656 Rutledge Street** ca. 1924 The one story home is wood frame construction with weatherboard exterior and brick foundation. The pyramidal roof has dormers on the main and side elevations. The porch is supported by paired wooden posts. The home was constructed by a builder who lived at 674 Rutledge Street.
- 407. **664 Rutledge Street** ca. 1920 The one story home is wood frame construction with wood shingle siding and brick foundation. The porch is supported by turned posts and turned balustrade. There is a front facing gable over the porch. The home was constructed by a builder who lived at 674 Rutledge Street.
- 408. **668 Rutledge Street** ca. 1920 The one story home is wood frame construction with wood shingle exterior and stuccoed masonry foundation. The porch is supported with brick posts and has a solid balustrade clad in wood shingles. There is a front facing gable over the porch. The home was constructed by a builder who lived at 674 Rutledge Street.
- 409. **674 Rutledge Street** ca. 1920 The one story home is wood frame construction clad in wood shingle siding and brick foundation. The porch is supported with tapered wooden posts resting on brick piers. Four homes on Rutledge Street were constructed by the builder who lived in this home.
- 410. **680 Rutledge Street** The one story home has a brick exterior and entry porch supported with tripartite columns.
- 411. 707 Rutledge Street ca. 1920 The one story home is wood frame construction with wood shingle exterior siding, brick foundation and hipped roof clad with composition shingles. There are four-over-one double hung sash windows, paired wooden posts on brick piers supporting the porch, main entry door surrounded by a transom and sidelights and dormer on the main façade containing a single pane window flanked by rectangular attic vents.
- 412. **708 Rutledge Street** ca. 1920 The one story home is wood frame construction with wood shingle exterior siding, brick foundation and front gable roof clad with composition shingles. There are exposed rafter tails, four-over-one double hung sash windows, porch supported with paired wooden posts resting on brick piers, and decorative stained glass window flanked by attic vents in the front gable end.
- 413. 712 Rutledge Street ca. 1920 The one story home is wood frame construction with wood shingle exterior siding, brick foundation and hipped roof clad in comoposition shingles. There are four-over-one double hung sash windows, porch supported with paired wooden posts resting on brick piers, entry door with transom and sidelights, and dormer containing a single paned window flanked by rectangular attic vents.
- 414. 717 Rutledge Street ca. 1920 The one story home is wood frame construction with synthetic exterior siding, brick foundation, and cross gable roof clad in composition shingles.

# National Register of Historic Places Continuation Sheet

Section number	7	Page	55	
		<u> </u>		_

- 415. **720 Rutledge Street** ca. 1920 The home is wood frame construction with wood shingle exterior siding, brick foundation, and front gable roof clad in composition shingles. There are four-over-one double hung sash windows, porch supported with tapered wooden columns resting on brick piers, paired windows flanked by rectangular attic vents in the gable end, and decorative roof brackets.
- 416. **723 Rutledge Street** ca. 1918 The one story home is wood frame construction with synthetic exterior siding, and stuccoed masonry foundation. The home was totally rebuilt in the 1980s. The 1918 date was found carved by the builder on a stud beneath the house.
- 417. **726 Rutledge Street** ca. 1920 The one story home is wood frame construction with weatherboard exterior siding, brick foundation, jerkinhead roof clad in composition shingles, and porch supported with two Doric columns. There are six-over-one double hung sash windows, jerkinhead porch supported by wooden posts.
- 418. **750 Rutledge Street** ca. 1930 The one-story home is wood frame construction with weatherboard exterior and gable roof clad in composition shingles.
- 419. **754 Rutledge Street** ca. 1930 The one story home is wood frame construction with synthetic exterior siding and front gable roof clad in composition shingles. The recessed porch is supported with tapered brick and wood posts resting on brick piers. There is a louvered attic vent in the front gable end flanked by craftsman style windows.
- 420. **758 Rutledge Street** ca. 1920 The one story home is wood frame construction with jerkinhead roof clad in composition shingles. The jerkinhead porch is supported with paired wooden posts resting on brick piers. The windows are four-over-one double hung sash. The main entry door is flanked by sidelights.
- 421. **764 Rutledge Street** ca. 1924 The one story home is wood frame construction with synthetic exterior siding and lateral gable roof clad in composition shingles. There is a large gable porch on the main façade supported with paired wooden posts on brick piers and contains a single pane window flanked by louvered attic vents in the gable end. The entry door is flanked by sidelights. Windows are six-over-one double hung sash.
- 422. **765 Rutledge Street** ca. 1915 The one story home is wood frame construction with synthetic exterior siding and hip roof clad in composition shingles. The engaged porch is supported with tapered wooden posts resting on brick piers. Windows are four-over-one double hung sash.
- 423. **769 Rutledge Street** ca. 1915 The one story home is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. There is an offset gable porch supported with square brick posts enclosed with screen. Windows are four-over-one double hung sash.

### National Register of Historic Places Continuation Sheet

Section nun	nber	7	Page	56	

- 424. 774 Rutledge Street ca. 1922 The one story home is wood frame construction with weatherboard exterior siding and hipped roof clad in composition shingles. The engaged porch is supported with tapered posts resting on brick piers. The main entry door is slightly offset to the left flanked with sidelights. Windows are four-over-one double hung sash.
- 425. **775 Rutledge Street** ca. 1925 The one story home is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. The gable porch is supported with tripartite wooden posts resting on brick piers and contains decorative shingles in the gable end.
- 426. **780 Rutledge Street** ca. 1926 The one story home is wood frame construction with synthetic exterior and hipped roof clad in composition shingles. The engaged porch is supported with square posts resting on brick piers. There is a hipped dormer in the center of the main façade.
- 427. **781 Rutledge Street** ca. 1930 The one story home is wood frame construction with synthetic exterior siding and lateral gable roof clad in composition shingles. The gable porch is supported with tapered wooden posts resting on brick piers. There are knee brackets and exposed rafter tails beneath the eaves. Windows are four-over-one double hung sash.
- 428. **784 Rutledge Street** ca. 1920 The one story home is wood frame construction with weatherboard and wood shingle exterior and front gable roof clad in composition shingles. The engaged porch is supported with paired wooden posts on brick piers. The front gable end contains decorative shingles and stained glass window flanked by louvered attic vents. Windows are four-over-one double hung sash.
- 429. **787 Rutledge Street** ca. 1920 The one story home is wood frame construction with weatherboard exterior and lateral gable roof clad in composition shingles. The gable porch is supported with thin wooden posts resting on brick piers.
- 430. **791 Rutledge Street** ca. 1920 The one story home is wood frame construction with weatherboard exterior and front gable roof clad in composition shingles. The engaged porch is supported with paired wooden posts resting on brick piers. The front gable end contains 4 gothic attic vents and wood shingle decoration. There are shallow gable wings on the side elevations.
- 431. **795 Rutledge Street** ca. 1920 The one story home is wood frame construction with weatherboard exterior siding and front gable roof clad in composition shingles. The engaged porch is supported with brick an dwooden posts resting on brick piers. There are wood shingles in the front gable end. Windows are five-over-one double hung sash.
- 432. **801 Rutledge Street** ca. 1922 The one-and-one-half story home is wood frame construction with wood shingle exterior siding and lateral gable roof clad in composition shingles. There is a large shed dormer on the main façade. Windows are four-over-one double hung sash.

### National Register of Historic Places Continuation Sheet

Section number	7	_ Page	57
Occion number		I ago	01

- 433. **805 Rutledge Street** ca. 1917 The one story home is wood frame construction with weatherboard exterior siding and front gable roof clad in composition shingles. The gable porch is supported with paired wooden posts on brick piers and contains a six pane window flanked with louvered attic vents in the gable end. Windows are six-over-one double hung sash.
- 434. **806 Rutledge Street** ca. 1925 The one story home is wood frame construction with synthetic exterior siding and front gable roof clad in composition shingles. The gable porch is supported with wrought iron posts and the gable end contains a six-pane window flanked by louvered attic vents. Windows are nine-over-one double hung sash.
- 435. **812 Rutledge Street** ca. 1925 The one story home is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. The engaged porch is supported with wooden posts resting on brick piers. Windows are nine-over-one double hung sash. There is a hipped dormer on the main façade.
- 436. **815 Rutledge Street** ca. 1930 The one story home is wood frame construction with weatherboard exterior and jerkinhead roof clad in composition shingles. The jerkinhead porch is supported with fluted columns. Windows are one-over-one double hung sash.
- 437. **816 Rutledge Street** ca. 1925 The one story home is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. The gable porch is supported with wooden posts resting on brick piers. The entry door is offset to the right with paired five-over-one double hung sash windows to the left.
- 438. **823 Rutledge Street** ca. 1930 The one sotry home is wood frame construction with wood shingle exterior and lateral gable roof clad in composition shingles. There is a recessed porch on the right end of the main façade supported with paired wooden posts on a brick pier. Windows are four-over-one double hung sash.
- 439. **828 Rutledge Street** ca. 1920 The one sory home is wood frame construction with wood shingle exterior and lateral gable roof clad in composition shingles. The gable porch is supported with paired wooden posts and contains knee brackets, exposed rafter tails beneath the eaves and paired louvered attic vents. The main entry door is offset to the right.
- 440. **833 Rutledge Street** ca. 1921 The one story home is wood frame construction with weatherboard exterior and front gable roof clad in composition shingles. There is an engaged porch on the right side of the main façade supported with paired wooden posts on brick piers. Windows are six-over-six double hung sash. The main entry door is flanked by sidelights.

# National Register of Historic Places Continuation Sheet

Section number	7	Page	58	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 441. 835 Rutledge Street ca. 1921 The one story home is wood frame construction with brick veneer exterior and front gable roof clad in composition shingles. The porch is supported with square brick posts. Windows are six-over-one double hung sash.
- 442. 836 Rutledge Street ca. 1923 The one story home is wood frame construction with wood shingle exterior and lateral gable roof clad in composition shingles. The gable porch is supprted with paired wooden posts resting on brick piers. There are paired louvered attic vents in the front gable end. The main entry door is flanked by sidelights. There are knee brackets and exposed rafter tails beneath the eaves.
- 443. 839 Rutledge Street ca. 1920 The one story home is wood frame construction with wood shingle exterior and lateral gable roof clad in composition shingles. The gable porch is supprted with paired wooden posts resting on brick piers. There are paired louvered attic vents in the front gable end. The main entry door is flanked by sidelights. There are knee brackets and exposed rafter tails beneath the eaves.

#### WOODLAND STREET

- 444. 552-554 Woodland Street ca. 1910 The one story duplex is wood frame construction with brick veneer exterior and lateral gable roof clad in composition shingles. There is a large gable porch on the main façade with synthetic siding in the gable end supported with paired posts resting on brick piers. There are two entry doors on the main façade. Windows are eight-over-one double hung sash. There are two exterior end chimneys.
- 445. **556-558 Woodland Street** ca. 1926 The two story duplex is wood frame construction with synthetic exterior siding and hipped roof clad in composition shingles. There are two gable entry porches, each supported with tapered posts resting on brick piers. Windows are six-over-six double hung sash.
- 446. **595 Woodland Street** ca. 1925 The one story home is wood frame construction with weatherboard exterior and brick foundation. There are brackets beneath the eaves.
- 447. **598 Woodland Street** ca. 1930 The one-and-one-half story home is wood frame construction with synthetic siding and brick exterior. The home has a gable porch and entry door with fanlight.
- 448. **601 Woodland Street** ca. 1925 The one-and-one-half story hoem is wood frame construction with synthetic siding and brick foundation. There are brackets beneath the eaves.
- 449. 604 Woodland Street ca. 1930 The one story home is wood frame construction with synthetic exterior siding. The porch is supported with square posts. The entry door is flanked by sidelights.

# National Register of Historic Places Continuation Sheet

Section number	7	Page	59	

- 450. **605 Woodland Street** ca. 1925 The one story home is wood frame construction with weatherboard exterior and brick foundation.
- 451. **608 Woodland Street** ca. 1938 The one story home is wood frame construction with brick veneer exterior. The side porch has arched openings and has been enclosed with screen. There is an arched window in the front gable end and arched entry.
- 452. **609 Woodland Street** ca. 1925 The one-and-one-half story home is wood frame construction with synthetic siding.
- 453. 612 Woodland Street ca. 1930 The one-and-one-half story home is wood frame construction with brick veneer exterior. There is a gable porch to the right of the main entry with arched openings. There is a paneled chimney to the left of the entry door.
- 454. **615 Woodland Street** ca. 1925 The one-and-one-half story home is wood frame construction with synthetic exterior siding and brick foundation.
- 455. **616 Woodland Street** ca. 1930 The one story home is wood frame construction with synthetic exterior and steeply pitched gable roof. The gable porch is supported with wooden brackets.
- 456. **617 Woodland Street** ca. 1926 The one-and-one-half story home is wood frame construction with synthetic exterior siding and brick foundation.
- 457. **626 Woodland Street** ca. 1930 The two story home is wood frame construction with brick foundation. There is a shed addition on the right side and a one-story gable ell on the rear façade.
- 458. **642 Woodland Street** ca. 1927 The one story home is masonry construction with brick exterior and lateral gable roof clad in composition shingles. There are six-over-one double hung sash windows, exposed rafter tails beneath the eaves, entry door with sidelights and gable porch with tripartite column supports.
- 459. **648 Woodland Street** ca. 1927 The one-and-one-half story home is masonry construction with brick exterior and lateral gable roof clad in composition shingles. There is an offset gable porch supported with tapered brick posts resting on brick piers, arched entry door flanked with sidelights, interior brick chimney, and exposed rafter tails beneath the eaves.
- 460. **652 Woodland Street** ca. 1927 The one story home is masonry construction with brick exterior, gable roof clad in composition shingles and offset gable porch with roof return supported with square brick posts on short brick piers. There are four-over-one double hung sash windows, entry door with sidelights, and stuccoed gable ends.

# National Register of Historic Places Continuation Sheet

-		-			
Section	number	7	Page	ന	
Section	Hullibel	-	raue	UU	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

461. **668 Woodland Street** – ca. 1927 – The one story home is wood frame construction with weatherboard exterior siding and front gable roof with return clad in composition shingles. There is an offset gable porch supported with paired wooden posts, entry door with sidelights, and four-over-one double hung sash windows. There are shallow gable wings on the side elevations.

#### NON-CONTRIBUTING PROPERTIES

- 192 Clifton Street alterations
- 2. **146 Connecticut Avenue** alterations
- 3. **167 Connecticut Avenue** alterations
- 4. **203 Connecticut Avenue** alterations
- 5. **263-265 Connecticut Avenue** post-1950
- 6. **268 Connecticut Avenue** alterations
- 504 Glendalyn Avenue alterations
- 8. **525 Glendalyn Avenue** post-1950
- 9. **568 Glendalyn Avenue** post-1950
- 10. **659 Glendalyn Avenue** post-1950
- 11. 799 Glendalyn Avenue alterations
- 12. 645 Maple Street alterations
- 13. **667 Maple Street** post-1950
- 14. **695 Maple Street** post-1950
- 15. **142 Mills Avenue** post-1950
- 16. **167 Mills Avenue** post-1950
- 17. **170 Mills Avenue** alterations
- 18. **179 Mills Avenue** post-1950
- 19. **184 Mills Avenue** alterations
- 20. 193 Mills Avenue alterations
- 21. **204 Mills Avenue** alterations

# National Register of Historic Places Continuation Sheet

Section number 7 Page 61

- 22. **238 Mills Avenue** post-1950
- 23. **239 Mills Avenue** post-1950
- 24. **255 Mills Avenue** post-1950
- 25. **261 Mills Avenue** post-1950
- 26. 348 Mills Avenue alterations
- 27. 353 Mills Avenue alterations
- 28. 354 Mills Avenue alterations
- 29. 360 Mills Avenue alterations
- 30. 401 Mills Avenue alterations
- 31. **546 Norwood Street** post-1950
- 32. **649 Norwood Street** post-1950
- 33. 661 Norwood Street alterations
- 34. **524-526 Otis Boulevard** post-1950
- 35. **529 Otis Boulevard** post-1950
- **36. 607 Otis Boulevard** post-1950
- 37. **655 Otis Boulevard** post-1950
- 38. **700 Otis Boulevard** post-1950
- 39. **723 Otis Boulevard** post-1950
- 40. **725 Otis Boulevard** post-1950
- 41. **529 Palmetto Street** alterations
- 42. **531 Palmetto Street** post-1950
- 43. **533 Palmetto Street** post-1950
- 44. **552 Palmetto Street** post-1950

# National Register of Historic Places Continuation Sheet

Section number \_\_\_\_\_7 Page \_\_62

- 45. **553 Palmetto Street** post-1950
- 46. **555 Palmetto Street** post-1950
- 47. **645 Palmetto Street** alterations
- 48. 665 Palmetto Street alterations
- 49. **710 Palmetto Street** post-1950
- 50. **758 Palmetto Street** post-1950
- 51. **520 Poplar Street** alterations
- 52. **536 Poplar Street** post-1950
- **53**. **705 Plume Street** post-1950
- 54. 776 Plume Street alterations
- 55. **792 Plume Street** post-1950
- 56. **616 Rutledge Street** alterations
- 57. **644 Rutledge Street** alterations
- 58. **657 Rutledge Street** post-1950
- 59. **713 Rutledge Street** alterations
- 60. **788 Rutledge Street** post-1950
- 61. **804 Rutledge Street** post-1950
- **62. 506 Woodland Street** post-1950
- 63. 510 Woodland Street alterations
- 64. **518-520 Woodland Street** post-1950
- 65. **656 Woodland Street** post-1950

Converse Heights Historic District  Name of Property	Spartanburg County, South Carolina County and State
Narrative Description (Describe the historic and current condition of the property on one or respectively)	nore continuation sheets.)
8. Statement of Significance	
B Property is associated with the lives of persons single C Property embodies the distinctive characteristics of the control o	le a significant contribution to the broad patterns of our history. Ignificant in our past. Ignificant in our past. Ignificant in our past. In a type, period, or method of construction or represents the work represents a significant and distinguishable entity whose
Criteria Considerations  (Mark "X" in all the boxes that apply.)  _ a owned by a religious institution or used for religious be removed from its original location.  _ c a birthplace or a grave.  _ d a cemetery.  _ e a reconstructed building, object, or structure.  _ f a commemorative property.  _ g less than 50 years of age or achieved significance.	Α
Areas of Significance (Enter categories from instructions) Architecture Social History Community Planning & Development	Period of Significance  ca. 1900 - ca. 1950  Significant Dates 1906
Significant Person (Complete if Criterion B is marked above)	Cultural Affiliation
5	Architect/Builder
Narrative Statement of Significance (Explain the significance of the property on one or more continuation s	sheets.)
9. Major Bibliographical References	
(Cite the books, articles, and other sources used in preparing this form	n on one or more continuation sheets.)
Previous documentation on file (NPS):  _ preliminary determination of individual listing (36 CFF requested.  _ previously listed in the National Register  _ previously determined eligible by the National Register  _ designated a National Historic Landmark  _ recorded by Historic American Buildings Survey #  _ recorded by Historic American Engineering Record #	Other State agencyFederal agencyLocal governmentUniversityOther

United States Department of the Interior National Park Service

# National Register of Historic Places Continuation Sheet

Section number	8	Page _	63	

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

The Converse Heights Historic District is significant as an intact collection of residential architecture documenting architectural styles from ca. 1900 through the 1940s. It is eligible for listing in the National Register of Historic Places under Criterion A for its connection to community development and planning and Criterion C for its intact collection of early to mid-twentieth century residential architecture. The district documents the prevalent housing types for middle and upper class citizens in the early to mid-twentieth century and demonstrates the pattern of suburban development as automobile use became prevalent and as social views of housing shifted.

#### Neighborhood Beginnings: 1860-1907

The neighborhood now known as Converse Heights received its name from Converse College, the women's college located immediately north of the neighborhood across East Main Street. Originally farmland, the area was owned by Civil War Major Govan Mills (1805-1862). Born in North Carolina, Mills settled in Spartanburg County and owned a large plantation on the outskirts of the city. The United States Census from 1850 lists Mills (age 45) as a farmer living with his wife Nancy (age 43) and three children: Mary (age 14), Robert (age 12) and John (age 10). In 1865, the site played host to enlisted men and horses of Brigadier General William J. Palmer's forces who stopped for the night in Spartanburg while searching for Jefferson Davis during his flight from Richmond.

In the early 1900s, the city of Spartanburg was undergoing a significant building boom. As rail lines reached the upstate and textile mills opened in Union, Gaffney and Spartanburg, the city's size quickly began to grow. US Census figures show that in the decades between 1890 and 1916, Spartanburg's population more that tripled—growing from 3,253 to 11,395. The construction of numerous textile manufacturing facilities allowed for capital improvements around the city that had previously gone unfulfilled. A ten-year street improvement project was underway in the early part of the twentieth century that resulted in the paving of streets and sidewalks in the downtown area and the installation of electric lights in the business district along Magnolia Street to Morgan Square and out East Main Street to Converse College. It was along that same route that a streetcar line was constructed, connecting the College and the newly developing Converse Heights neighborhood to the burgeoning downtown.

Because many downtown residences were being demolished to make room for the growing commercial center, the demand for in-town housing grew. As development pushed out Main and Church Streets, small neighborhood developments began to emerge. In 1906, Govan Mills' son Otis divided the family farm into plots to open up the land for residential development. Two of the main streets in Converse Heights: Otis Boulevard and Mills Avenue pay homage to the family on whose land the development was taking place. By 1910, local newspapers were printing advertisements for J.T. Willard who was announcing "Lots for Sale" on East Main Street and on Mills Avenue in Converse Heights. Despite the fact that the neighborhood was officially opened for development in 1906, the 1910 Spartanburg City Directory still made no mention of Otis Boulevard or Palmetto Street and Sanborn Fire Insurance Maps from 1912 show a street grid with no homes. In fact, by 1923, there were only 10 homes in the neighborhood. Today, however, the neighborhood of Converse Heights includes 35 streets with more than 1300 homes located between Pine Street and Lawson's Fork Creek, East Main Street and Crystal Drive.

United States Department of the Interior National Park Service

# National Register of Historic Places Continuation Sheet

Section number	8	Page	64	

Converse Heights Neighborhood Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Suburban Development: 1906-1950

The Converse Heights neighborhood showcases each of the key architectural styles used throughout the twentieth century. The district, which was developed continuously from 1906 through the 1950s, includes single and multi-family residential buildings in the Queen Anne, American Foursquare, Craftsman, Spanish Mission, Tudor, Colonial Revival, Neo-Classical and Minimal Traditional styles.

The location of the neighborhood—close to the fast-growing business district—and the construction of a streetcar line that ran to the neighborhood entrance made the district and ideal location for local businessmen and professionals working in downtown Spartanburg. Within Converse Heights, restrictions were placed on new homebuilders mandating that homeowners spend at least \$1500 on the construction of their homes which also attracted a certain level of Spartanburg's business elite. The overall development of the Converse Heights neighborhood truly reflects the economic and social changes that Spartanburg was experiencing in the early to mid-twentieth century. The neighborhood is what many would call a "streetcar suburb", a precursor to the modern-day suburban neighborhood.

As the neighborhood began to develop, larger two-story homes were concentrated along Mills Avenue while smaller, one-story dwellings were built on the secondary streets. A majority of the early homes constructed in Converse Heights, with a few notable exceptions, are modest in size and design constructed in the Craftsman or Bungalow style. These smaller homes were becoming increasingly popular in the early to mid-twentieth century in the pages of *Ladies Home Journal* and *Good Housekeeping* as well as the distribution of pattern books and kit homes available for purchase. Maple and Rutledge Streets, as well as Glendalyn Avenue, were lined with these small family friendly homes.

Each of the streets within the neighborhood has a unique story to tell. Otis and Mills Streets were both named to honor members of the Mills family on whose property the neighborhood was constructed. Both were divided by planted medians designating them as the two main streets within the development. Connecticut Avenue, one of the most heavily traveled streets in the neighborhood, was originally the driveway leading to the Evans [later Evans-Russell] House. Constructed in 1901 by former Governor John Gary Evans for \$9,900, the house now sits on Otis Boulevard and is part of the Converse Heights neighborhood. Maple Street garners its name from the many maple trees that were originally planted throughout the neighborhood.

#### Architecture

The architectural styles present within the neighborhood reflect the mood of the era in which they were built as well as the social stature of those who lived there. At the time of Converse Heights' development, the Queen Anne and Colonial Revival styles had cemented themselves as the favorites for early neighborhood developments. While the popularity of the Queen Anne was tapering off by 1910, Colonial Revival in its various forms lasted well into the 1950s. Homes along Mills Avenue and Connecticut Avenue reflect the Colonial Revival style in its differing forms.

United States Department of the Interior National Park Service

# National Register of Historic Places Continuation Sheet

Section	number	8	Page	65	

Converse Heights Historic District

Name of Property

Spartanburg County, South Carolina

County and State

Also popular during the growth and development of Converse Heights was the Craftsman Style and its Bungalow single family home. Inspired by the work of Charles Sumner Greene [1868-1957] and his brother Henry Mather Greene [1870-1954] of the Pasadena, California, based firm of Greene & Greene, the Craftsman house blended characteristics of the Arts and Crafts movement with the small single family home. A majority of the homes in Converse Heights along Glendalyn Avenue and Norwood and Rutledge Streets reflect this popular architectural style.

Lastly, homes constructed during the final developmental phases of the neighborhood reflect the post-war period of brick veneer home construction. Because most construction ceased during the years 1942-1945, the return to residential construction reflected the new ingenuity of post-war America and the new ideals that went along with the automobile era. Known by many as Minimal Traditional, this "style" of post war housing was loosely based on the Tudor revival style that was popular in the late 1920s and 1930s. Like its predecessor, Minimal Traditional homes have dominant front gables and massive chimneys while lowering the steep pitch of the Tudor revival gables and simplifying the main façade by omitting the half-timber detailing. By the early 1950s, these homes were being replaced by what we now know as suburban ranch housing. The end of the development of Converse Heights coincides with the "white flight" from city neighborhoods to sprawling suburban neighborhood developments that were much more automobile friendly.

# National Register of Historic Places Continuation Sheet

Section number 9 Page 66

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

#### BIBLIOGRAPHY

- Foster, Vernon, ed. Spartanburg: Facts Reminiscences, Folklore. Spartanburg: The Reprint Company, 1998.
- Landrum, John Belton O'Neal. *History of Spartanburg County*. Atlanta, Ga., The Franklin Printing and Publishing Company, 1900.
- Leonard, Michael. Our Heritage: A Community History of Spartanburg County, South Carolina. Spartanburg: Band & White, Inc., 1983.
- McAllister, Virginia & Lee. A Field Guide to American Houses. New York: Alfred A. Knopf, 1998.
- Packard, Robert T., AIA, and Balthazar Korab. *Encyclopedia of American Architecture* [Second Edition]. New York: McGraw-Hill, Inc., 1995.
- Pericone, Laura J. "Families make everything new again in historic area." *Spartanburg Herald Journal* Online, accessed August 6, 2006:
  - http://www.goupstate.com/apps/pbcs.dll/article?AID=/20060806/NEWS/608060325/1028/YOURLIFE
- Racine, Philip N. Seeing Spartanburg: A History in Images. Spartanburg, S.C.: Hub City Writers Project, 1999.
- Smith, Gretchen, ed. Master Builders, A Guide to Famous American Architects [Building Watchers Series, edited by Diane Maddex]. Washington, DC: The Preservation Press, National Trust for Historic Preservation, 1985.
- Willis, Jeffrey R. Spartanburg. Charleston: Arcadia Publishers, Inc., 1999.

USDI/NPS NRHP Registration Form	Page 4
Converse Heights Historic District Name of Property	Spartanburg County, South Carolina County and State
10. Geographical Data	
Acreage of Property	
UTM References (Place additional UTM references on a continuation sheet)	
Zone Easting Northing       Zone Easting Northing         1 17 416951 3868508       3 17 417200 3867992         2 17 417024 3868457       4 17 417242 3867928	
X See continuation sheet.	
Verbal Boundary Description (Describe the boundaries of the property on Boundary Justification (Explain why the boundaries were selected on a confidence of the property of th	
11. Form Prepared By	
name/title organization	date3 August 2007 telephone803-361-7253 atezip code29201
Additional Documentation	
Submit the following items with the completed form:	
Continuation Sheets Maps A USGS map (7.5 or 15 minute series) indicating the property A sketch map for historic districts and properties having large Photographs Representative black and white photographs of the property. Additional items	acreage or numerous resOUICES.

(Check with the SHPO or FPO for any additional items)

Pro	perty	Owner
_		

(Complete this item at the request of the SHPO or FPO.)

name Multiple Owners (see continuation sheets)
street & number telephone
city or town state zip code

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C. 470 et seq.). Estimated Burden Statement: Public reporting burden for this form is estimated to average 18.1 hours per response including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Chief, Administrative Services Division, National Park Service, P.O. Box 37127, Washington, DC 20013-7127; and the Office of Management and Budget, Paperwork Reductions Project (1024-0018), Washington, DC 20503.

# National Register of Historic Places Continuation Sheet

Section number 10 Page 67

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

### **Property Owners**

David & Theresa Cheser 166 Clifton Avenue Spartanburg SC 29302

Stephen & Karen Michelman 177 Clifton Avenue Spartanburg SC 29302

Carl & Patricia Pittillo 178 Clifton Avenue Spartanburg SC 29302

Jon Zoole 183 Clifton Avenue Spartanburg SC 29302

Benjamin Graves 184 Clifton Avenue Spartanburg SC 29302

Rosa Shand Turner 189 Clifton Avenue Spartanburg SC 29302

Shawn Jacobs 199 Clifton Avenue Spartanburg SC 29302

Kenneth & Mary Norton 211 Clifton Avenue Spartanburg SC 29302

Robert & Stacey Davis 212 Clifton Avenue Spartanburg SC 29302

Yon & Diane Lambert 216 Clifton Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 68

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Brian & Dorcas Miller 217 Clifton Avenue Spartanburg SC 29302

John Wofford 222 Clifton Avenue Spartanburg SC 29302

Ronald McCraw 223 Clifton Avenue Spartanburg SC 29302

Elizabeth Froneberger 227 Clifton Avenue Spartanburg SC 29302

Herbert Fritz 235 Clifton Avenue Spartanburg SC 29302

Michael & Alice Cooper 265 Connecticut Avenue Spartanburg SC 29302

Martin & Karen Cornelson 329 Connecticut Avenue Spartanburg SC 29302

David & Margaret Henderson 331Connecticut Avenue Spartanburg SC 29302

Oren & Mary Webb 364 Connecticut Avenue Spartanburg SC 29302

Joseph & Sharon Lauer 368 Connecticut Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 69

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Harry & Mary Johnson 370 Connecticut Avenue Spartanburg SC 29302

Claire & Leonard Reese 372 Connecticut Avenue Spartanburg SC 29302

Ann & Douglas Caton 400 Connecticut Avenue Spartanburg SC 29302

Theodore & Nancy Gage 402 Connecticut Avenue Spartanburg SC 29302

Kathleen Owens 120 Connecticut Avenue Spartanburg SC 29302

Larry & Patricia Fix 124 Connecticut Avenue Spartanburg SC 29302

Christopher & Gail Ebert 125 Connecticut Avenue Spartanburg SC 29302

Wilson Boggs 157 Connecticut Avenue Spartanburg SC 29302

Harley & Alma Parks 163 Connecticut Avenue Spartanburg SC 29302

Edward & Geri Burke 167 Connecticut Avenue Spartanburg SC 29302

# United States Department of the Interior National Park Service

### National Register of Historic Places Continuation Sheet

Section number 10 Page 70

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

George & Frances Loudon 176 Connecticut Avenue Spartanburg SC 29302

John William & Annette Nelson 177 Connecticut Avenue Spartanburg SC 29302

Susan Bennett 180 Connecticut Avenue Spartanburg SC 29302

Ray Thompson, Jr. 183 Connecticut Avenue Spartanburg SC 29302

Janette S. Hines 184 Connecticut Avenue Spartanburg SC 29302

John & Marilyn Lankford 187 Connecticut Avenue Spartanburg SC 29302

Marcia Lyn Kirby 199 Connecticut Avenue Spartanburg SC 29302

David & Laurie Osbon 203 Connecticut Avenue Spartanburg SC 29302

Marshall C. Stone, III 211 Connecticut Avenue Spartanburg SC 29302

Sheila Ingle & John Collins 215 Connecticut Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 71

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

George & Carol Dunn 218 Connecticut Avenue Spartanburg SC 29302

Carolyn L. Mulligan 221 Connecticut Avenue Spartanburg SC 29302

Miriam Lowry 228 Connecticut Avenue Spartanburg SC 29302

Same & Jennifer Latto 229 Connecticut Avenue Spartanburg SC 29302

Amelia Hinson 232 Connecticut Avenue Spartanburg SC 29302

Marion Elizabeth Greene 237 Connecticut Avenue Spartanburg SC 29302

Michael & Nancy Anderson 242 Connecticut Avenue Spartanburg SC 29302

Sheena Anderson 246 Connecticut Avenue Spartanburg SC 29302

Frances & Robert Patton 254 Connecticut Avenue Spartanburg SC 29302

Bradley Cooper 263 Connecticut Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 72

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Marion L. Repokis, Trustee 269 Connecticut Avenue Spartanburg SC 29302

James & Margaret Hallett 330 Connecticut Avenue Spartanburg SC 29302

Claude Cole & Ester Lewis 332 Connecticut Avenue Spartanburg SC 29302

Alan Shufelt 344 Connecticut Avenue Spartanburg SC 29302

Mark & Elizabeth Hatton 354 Connecticut Avenue Spartanburg SC 29302

Rebecca Burchette 600 Glendalyn Avenue Spartanburg SC 29302

Adam Hawkins & Ann Gerber 604 Glendalyn Avenue Spartanburg SC 29302

Willie Mefford 610 Glendalyn Avenue Spartanburg SC 29302

Russell Broome 616 Glendalyn Avenue Spartanburg SC 29302

Diecy Lawrence Gray 643 Glendalyn Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 73

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

David Eskew 647 Glendalyn Avenue Spartanburg SC 29302

Clary & Pamela Greenway 653 Glendalyn Avenue Spartanburg SC 29302

Charles & Brenda Janulis 656 Glendalyn Avenue Spartanburg SC 29302

Phillip Cole King 658 Glendalyn Avenue Spartanburg SC 29302

Elizabeth & Jenny Fowler 660 Glendalyn Avenue Spartanburg SC 29302

Jeffrey & Vickie Schwartz 668 Glendalyn Avenue Spartanburg SC 29302

Kathryn Scales et al 490 Glendalyn Avenue Spartanburg SC 29302

Robert Ivey, Jr. 496 Glendalyn Avenue Spartanburg SC 29302

Rosanna Lapham 504 Glendalyn Avenue Spartanburg SC 29302

Maxwell & Lora Chambers 511 Glendalyn Avenue Spartanburg SC 29302

#### National Register of Historic Places Continuation Sheet

Section number 10 Page 74

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Pocholo Palacio 512 Glendalyn Avenue Spartanburg SC 29302

Walter & Clair Hopkins 515 Glendalyn Avenue Spartanburg SC 29302

Mark Smith 517 Glendalyn Avenue Spartanburg SC 29302

Janet Estes 519 Glendalyn Avenue Spartanburg SC 29302

Walter Parker 520 Glendalyn Avenue Spartanburg SC 29302

Cecil M. Amick, Jr. 525 Glendalyn Avenue Spartanburg SC 29302

John & Mary Roper 527 Glendalyn Avenue Spartanburg SC 29302

Penelope Clements 532 Glendalyn Avenue Spartanburg SC 29302

Clyde Moore, Jr. 537 Glendalyn Avenue Spartanburg SC 29302

L&L Properties, LLC 540 Glendalyn Avenue Spartanburg SC 29302

#### National Register of Historic Places Continuation Sheet

Section number 10 Page 75

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Maci Shannon Phillips 543 Glendalyn Avenue Spartanburg SC 29302

Waseley Stoddard 547 Glendalyn Avenue Spartanburg SC 29302

Nick Lambroukos 552 Glendalyn Avenue Spartanburg SC 29302

Lee Lasnier & Curtis Gentry 553 Glendalyn Avenue Spartanburg SC 29302

Frances Lee Roper 559 Glendalyn Avenue Spartanburg SC 29302

Leslie Young 560 Glendalyn Avenue Spartanburg SC 29302

Barbara Wagner Deles 568 Glendalyn Avenue Spartanburg SC 29302

Thomas McLeod et al 707 Glendalyn Avenue Spartanburg SC 29302

Ogreeda & Glenn Gowan 709 Glendalyn Avenue Spartanburg SC 29302

Michael Ring, V 710 Glendalyn Avenue Spartanburg SC 29302

#### National Register of Historic Places Continuation Sheet

Section number 10 Page 76

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Judy Cash 715 Glendalyn Avenue Spartanburg SC 29302

Demillia Little 716 Glendalyn Avenue Spartanburg SC 29302

Ned & Elizabeth Workman 721Glendalyn Avenue Spartanburg SC 29302

Paul Lansberry 722 Glendalyn Avenue Spartanburg SC 29302

Andrew Albenesius 734 Glendalyn Avenue Spartanburg SC 29302

Mark & Andrea Wilcox 763 Glendalyn Avenue Spartanburg SC 29302

Beverly Tesseneer 766 Glendalyn Avenue Spartanburg SC 29302

Joseph McGeady, Jr. 768 Glendalyn Avenue Spartanburg SC 29302

Dora Harrell 769 Glendalyn Avenue Spartanburg SC 29302

Ned & Elizabeth Workman 772 Glendalyn Avenue Spartanburg SC 29302

## National Register of Historic Places Continuation Sheet

Section number 10 Page 77

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Kiley Brown 773 Glendalyn Avenue Spartanburg SC 29302

Kevin & Joyce Watson 778 Glendalyn Avenue Spartanburg SC 29302

Ed & Janet Lee Skaggs 779 Glendalyn Avenue Spartanburg SC 29302

Jeffrey Murrell 783 Glendalyn Avenue Spartanburg SC 29302

Malcolm Robbins 789 Glendalyn Avenue Spartanburg SC 29302

Joel George 792 Glendalyn Avenue Spartanburg SC 29302

Richard Hall & Sarah Bryan 793Glendalyn Avenue Spartanburg SC 29302

Stacy Dyer 799 Glendalyn Avenue Spartanburg SC 29302

Thomas & Janet Sumerel 804 Glendalyn Avenue Spartanburg SC 29302

Virginia Helen Cline 805 Glendalyn Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 78

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

James Scardo 399 Hale Street Spartanburg SC 29302

Mildred Finch 400 Hale Street Spartanburg SC 29302

Caroline Worthy 401 Hale Street Spartanburg SC 29302

Phillip Petros & Daphne Ro 405 Hale Street Spartanburg SC 29302

Jennifer Crook 406 Hale Street Spartanburg SC 29302

George Kyser Crow 500 Hale Street Spartanburg SC 29302

Trent Dikeman 601 Maple Street Spartanburg SC 29302

Emily McElhenney Life Est. 606 Maple Street Spartanburg SC 29302

Samuel & Elise Mercer 607 Maple Street Spartanburg SC 29302

Emily Martin 613 Maple Street Spartanburg SC 29302 NPS Form 10-900-a (8-86)

### United States Department of the Interior National Park Service

## National Register of Historic Places Continuation Sheet

Section number 10 Page 79

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Lisa & Wade Clark 614 Maple Street Spartanburg SC 29302

Daniel Falcon 617 Maple Street Spartanburg SC 29302

Samuel J. Dupree, III 623 Maple Street Spartanburg SC 29302

Thomas & Susan Shealy 627 Maple Street Spartanburg SC 29302

Nick Trainor 699 Maple Street Spartanburg SC 29302

Earl Troglin 702 Maple Street Spartanburg SC 29302

L&L Properties, LLC 705 Maple Street Spartanburg SC 29302

Lucas Patterson 708 Maple Street Spartanburg SC 29302

Kathy Smith 709 Maple Street Spartanburg SC 29302

Ted Fansher 712 Maple Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 80

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Stuart & Sherri Teffeteller 713 Maple Street Spartanburg SC 29302

Frances Myers 718 Maple Street Spartanburg SC 29302

Jay Carter 722 Maple Street Spartanburg SC 29302

John Hamilton 725 Maple Street Spartanburg SC 29302

Betty Jo Harris 730 Maple Street Spartanburg SC 29302

Thomas & Van Sant Clare 731 Maple Street Spartanburg SC 29302

Sara Brown 736 Maple Street Spartanburg SC 29302

Jesse Cleveland 737 Maple Street Spartanburg SC 29302

Tate Osterman 749 Maple Street Spartanburg SC 29302

Stephanie Angelo 755 Maple Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number \_\_\_10 \_\_\_ Page \_\_81

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Neal Harper 759 Maple Street Spartanburg SC 29302

Melissa Hatchell 763 Maple Street Spartanburg SC 29302

Oscar Schmiedl 771 Maple Street Spartanburg SC 29302

Stephne & Joann Bryson 775 Maple Street Spartanburg SC 29302

Household Finance Company 220 Mills Avenue Spartanburg SC 29302

Frances Cannon 238 Mills Avenue Spartanburg SC 29302

Juliet C. Eaves 239 Mills Avenue Spartanburg SC 29302

Carl & Susan Prestipino 240 Mills Avenue Spartanburg SC 29302

Brooks & Carolyn Crenshaw 241 Mills Avenue Spartanburg SC 29302

Andrew & Isabel Park 244 Mills Avenue Spartanburg SC 29302 NPS Form 10-900-a (8-86)

### United States Department of the Interior National Park Service

## National Register of Historic Places Continuation Sheet

Section number 10 Page 82

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Richard & Jennifer Pitts 247 Mills Avenue Spartanburg SC 29302

Daniel Falcon 250 Mills Avenue Spartanburg SC 29302

Cole Family Limited Partnership 255 Mills Avenue Spartanburg SC 29302

Harold & Betty Wolfe 261 Mills Avenue Spartanburg SC 29302

William & Elizabeth Fort 268 Mills Avenue Spartanburg SC 29302

Woodridge Investment Service 361 Mills Avenue Spartanburg SC 29302

Jeannine Miller 382 Mills Avenue Spartanburg SC 29302

Edward Crenshaw 386 Mills Avenue Spartanburg SC 29302

S.R. Matthews, Jr. 387 Mills Avenue Spartanburg SC 29302

James & Judy Riddle 396 Mills Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 83

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Carolyn Roberts 398 Mills Avenue Spartanburg SC 29302

Donna Wiltsie 402 Mills Avenue Spartanburg SC 29302

Harris Lyndon & Kirsten Ruth 404 Mills Avenue Spartanburg SC 29302

Daniel Ahern 500 Norwood Street Spartanburg SC 29302

Kimberly Fly 507 Norwood Street Spartanburg SC 29302

Barbara Rominski 508 Norwood Street Spartanburg SC 29302

Virginia Gasswint 509 Norwood Street Spartanburg SC 29302

James Dallas Boyd, Jr. 511 Norwood Street Spartanburg SC 29302

Paula Moore 512 Norwood Street Spartanburg SC 29302

Martha Rebecca Evans 515 Norwood Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 84

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Carolyn & Robert Hammett 516 Norwood Street Spartanburg SC 29302

George Stephen Eshleman 521 Norwood Street Spartanburg SC 29302

Cecil & Barbara Brown 522 Norwood Street Spartanburg SC 29302

Gerald Lawson, Sr. 525 Norwood Street Spartanburg SC 29302

Gerald Lawson, Sr. 530 Norwood Street \Spartanburg SC 29302

Brian Murdoch 531Norwood Street Spartanburg SC 29302

Tracy Lukanic 536 Norwood Street Spartanburg SC 29302

April Williams 537 Norwood Street Spartanburg SC 29302

James Bearden III 541 Norwood Street Spartanburg SC 29302

Martha Saunders 542 Norwood Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 85

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Kim Keith 546 Norwood Street Spartanburg SC 29302

Susan Chapman 547 Norwood Street Spartanburg SC 29302

Kate Murphy 548 Norwood Street Spartanburg SC 29302

Brenda Park 555 Norwood Street Spartanburg SC 29302

Lynne Fairfield 556 Norwood Street Spartanburg SC 29302

Mr. & Mrs. Harold Roberts 663 Norwood Street Spartanburg SC 29302

John Floyd 664 Norwood Street Spartanburg SC 29302

Mr. & Mrs. Douglas Pridgeon 638 Norwood Street Spartanburg SC 29302

Troy Beavers 644 Norwood Street Spartanburg SC 29302

Mr. & Mrs. George Holbrook 647 Norwood Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 86

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Marjorie Cannon 649 Norwood Street Spartanburg SC 29302

Colonial Trust Company 650 Norwood Street Spartanburg SC 29302

Martha Boggs 652 Norwood Street Spartanburg SC 29302

Mr. & Mrs. Stanley Williams 660 Norwood Street Spartanburg SC 29302

Carmen Miller & Cheryle Moore 661 Norwood Street Spartanburg SC 29302

Aileen L. Belmont 526 Otis Boulevard Spartanburg SC 29302

Donald & Sarah Love 608 Otis Boulevard Spartanburg SC 29302

Oles Womick 504 Otis Boulevard Spartanburg SC 29302

David & Margie Ann Jones 514 Otis Boulevard Spartanburg SC 29302

Jo Ann McMillan 524 Otis Boulevard Spartanburg SC 29302

## National Register of Historic Places Continuation Sheet

Section number 10 Page 87

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Ruth Gray Chapman 538 Otis Boulevard Spartanburg SC 29302

Robert & Lacy Chapman 543 Otis Boulevard Spartanburg SC 29302

Garrett & Catherine Scott 544 Otis Boulevard Spartanburg SC 29302

Dillard & Patricia Copeland 551Otis Boulevard Spartanburg SC 29302

Martha Beth Jackson 552 Otis Boulevard Spartanburg SC 29302

James Burnett 561Otis Boulevard Spartanburg SC 29302

Willam & Judith Drake 573 Otis Boulevard Spartanburg SC 29302

Louisa Berry 576 Otis Boulevard Spartanburg SC 29302

Helen France etal 584 Otis Boulevard Spartanburg SC 29302

Albert & Anne Jeter 585 Otis Boulevard Spartanburg SC 29302

### National Register of Historic Places Continuation Sheet

Section number 10 Page 88

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Junie Lee White 591 Otis Boulevard Spartanburg SC 29302

Roy & Jean Hardigree 592 Otis Boulevard Spartanburg SC 29302

Betty Lee Smith 599 Otis Boulevard Spartanburg SC 29302

Elizabeth Fenner 602 Otis Boulevard Spartanburg SC 29302

Paul & Gwen Weaver 605 Otis Boulevard Spartanburg SC 29302

Roberta Haynsworth 607 Otis Boulevard Spartanburg SC 29302

James David Cobb, Jr. 616 Otis Boulevard Spartanburg SC 29302

Dan & Katherine Maultsby 626 Otis Boulevard Spartanburg SC 29302

Roger Milliken 627 Otis Boulevard Spartanburg SC 29302

Elisabeth Allen Smith 634 Otis Boulevard Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 89

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

David & Michelle Clyburn 641 Otis Boulevard Spartanburg SC 29302

Ann Turner 644 Otis Boulevard Spartanburg SC 29302

Mel & Myra Garrett 650 Otis Boulevard Spartanburg SC 29302

Ernestine R. Steadman 655 Otis Boulevard Spartanburg SC 29302

Mary Ellen McElhanney etal 656 Otis Boulevard Spartanburg SC 29302

Cynthia E. Moseley 662 Otis Boulevard Spartanburg SC 29302

Allen & Mary Ann Stoddard 663Otis Boulevard Spartanburg SC 29302

Kathryn Morgan 670 Otis Boulevard Spartanburg SC 29302

Leland & Gloria Close 685 Otis Boulevard Spartanburg SC 29302

John & Kirsten Cribb 700 Otis Boulevard Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 90

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

701 Partnership LP 701 Otis Boulevard Spartanburg SC 29302

Nancy B. Tiller 705 Otis Boulevard Spartanburg SC 29302

Mr. & Mrs. Ralph Wessinger 709 Otis Boulevard Spartanburg SC 29302

James Amick 713 Otis Boulevard Spartanburg SC 29302

Betty Ruth Walker 715 Otis Boulevard Spartanburg SC 29302

Mr. & Mrs. Chip Hurst 716 Otis Boulevard Spartanburg SC 29302

Thomas Stokes 717 Otis Boulevard Spartanburg SC 29302

Mr. & Mrs. Morrison Lowndes 720 Otis Boulevard Spartanburg SC 29302

Michael Kehoe 723 Otis Boulevard Spartanburg SC 29302

Louise Wood 725 Otis Boulevard Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 91

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Tracy Lukanic 729 Otis Boulevard Spartanburg SC 29302

Joan Merril 735 Otis Boulevard Spartanburg SC 29302

Elsie Ruth Wright 741Otis Boulevard Spartanburg SC 29302

Mr. & Mrs. Mark Ward 747 Otis Boulevard Spartanburg SC 29302

Maxie & Janis Edwards 764 Otis Boulevard Spartanburg SC 29302

Mr. & Mrs. Steven Hall 765 Otis Boulevard Spartanburg SC 29302

Rebecca Thurmond 767 Otis Boulevard Spartanburg SC 29302

Brantley & Claire Bass 542 Palmetto Street Spartanburg SC 29302

Carolyn Jolly 546 Palmetto Street Spartanburg SC 29302

Dorothy Darr 548 Palmetto Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 92

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Caroline Worthy 550 Palmetto Street Spartanburg SC 29302

Mary Cannon 552 Palmetto Street Spartanburg SC 29302

Kimberly Jackson 554 Palmetto Street Spartanburg SC 29302

Jacob & Clara Delamar 556 Palmetto Street Spartanburg SC 29302

John & Audrey Hope 597 Palmetto Street Spartanburg SC 29302

Dorothy Williams 605 Palmetto Street Spartanburg SC 29302

Martha Swann 606 Palmetto Street Spartanburg SC 29302

Marcel & Sharol Gauthier 608 Palmetto Street Spartanburg SC 29302

Lori Butehorn 610 Palmetto Street Spartanburg SC 29302

Joseph & Jennifer Biber 615 Palmetto Street Spartanburg SC 29302 NPS Form 10-900-a (8-86)

### United States Department of the Interior National Park Service

# National Register of Historic Places Continuation Sheet

Section number 10 Page 93

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

William & Holly Broadwell 618 Palmetto Street Spartanburg SC 29302

Susan Rothemich 626 Palmetto Street Spartanburg SC 29302

John & Rebecca Manatis 627 Palmetto Street Spartanburg SC 29302

Hans & Lucia Balmer 710 Palmetto Street Spartanburg SC 29302

Eduardo Chen 712 Palmetto Street Spartanburg SC 29302

Mary Ann Alford Fruit 716 Palmetto Street Spartanburg SC 29302

Robert & Cathy Torres 724 Palmetto Street Spartanburg SC 29302

William Wakefield 730 Palmetto Street Spartanburg SC 29302

Elizabeth A. Upton 732 Palmetto Street Spartanburg SC 29302

Clifford & Susan Gaubert 734 Palmetto Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 94

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Ralph & Ann Paquin 756 Palmetto Street Spartanburg SC 29302

Joseph Elsa Hudson 758 Palmetto Street Spartanburg SC 29302

Jerry & Carolyn Setzler 762 Palmetto Street Spartanburg SC 29302

Charles Adams 766 Palmetto Street Spartanburg SC 29302

Avril Alexander 770 Palmetto Street Spartanburg SC 29302

Carmine Squatriglia 772 Palmetto Street Spartanburg SC 29302

David & Elizabeth Pellegrin 776 Palmetto Street Spartanburg SC 29302

Kathleen Hines 778 Palmetto Street Spartanburg SC 29302

James & Patricia Hasty 800 Palmetto Street Spartanburg SC 29302

Richard Kenneth Orr 802 Palmetto Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number \_\_\_\_10 \_\_\_ Page \_\_\_95\_\_

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Dianne Ansley 641 Palmetto Street Spartanburg SC 29302

Frances Little 642 Palmetto Street Spartanburg SC 29302

Isabella G. Tipton 645 Palmetto Street Spartanburg SC 29302

Eleanor S. White Trustee 649 Palmetto Street Spartanburg SC 29302

Stephen & Karen Parrott 650 Palmetto Street Spartanburg SC 29302

Lewis Lancaster, III 655 Palmetto Street Spartanburg SC 29302

Nancy Kochenower 661 Palmetto Street Spartanburg SC 29302

David & Kimberley Sorrels 662 Palmetto Street Spartanburg SC 29302

Marshall Stone, III 665 Palmetto Street Spartanburg SC 29302

Vergene Colloms 666 Palmetto Street Spartanburg SC 29302

#### National Register of Historic Places Continuation Sheet

Section number \_\_\_\_10 \_\_\_ Page \_\_\_96

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Jerry Horne 706 Plume Street Spartanburg SC 29302

Kent & Melody Shurll 710 Plume Street Spartanburg SC 29302

Eric Foust 716 Plume Street Spartanburg SC 29302

Robert Rainer 728 Plume Street Spartanburg SC 29302

Dennis & Shirley Smith 736 Plume Street Spartanburg SC 29302

Warwick & Sarah Spencer 755 Plume Street Spartanburg SC 29302

Mary Kinard 763 Plume Street Spartanburg SC 29302

Norman & Martha Chapman 764 Plume Street Spartanburg SC 29302

Todd & Debra Kleman 766 Plume Street Spartanburg SC 29302

Ann Kelly 776 Plume Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 97

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

John & Kate Dargan 777 Plume Street Spartanburg SC 29302

Geraldine R. Crenshaw 784 Plume Street Spartanburg SC 29302

Bennie Stone Larj 785 Plume Street Spartanburg SC 29302

Boyce L. Bomar, Jr. 796 Plume Street Spartanburg SC 29302

John & Susan Murphy 805 Plume Street Spartanburg SC 29302

J. Squires 519 Poplar Street Spartanburg SC 29302

Donna Lee 523 Poplar Street Spartanburg SC 29302

Michael Lowe 525 Poplar Street Spartanburg SC 29302

Diecy Gray 527 Poplar Street Spartanburg SC 29302

Peggy Thomas 529 Poplar Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 98

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Kathi Johnson 531 Poplar Street Spartanburg SC 29302

Kirsten Aigner 533 Poplar Street Spartanburg SC 29302

George Clements 537 Poplar Street Spartanburg SC 29302

Gerald & Lisa Ellsworth 539 Poplar Street Spartanburg SC 29302

Frances Kendrick 545 Poplar Street Spartanburg SC 29302

Joe Lynch, Jr. 549 Poplar Street Spartanburg SC 29302

Nancy Osborne 555 Poplar Street Spartanburg SC 29302

Joshua Gross 559 Poplar Street Spartanburg SC 29302

Helen K. Bell 597 Poplar Street Spartanburg SC 29302

Bonnie C. Elrod 600 Poplar Street Spartanburg SC 29302

## National Register of Historic Places Continuation Sheet

Section number 10 Page 99

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Stephen & Hannel Abercrombie 603 Poplar Street Spartanburg SC 29302

Clara Love McIntyre 604 Poplar Street Spartanburg SC 29302

William & Margary Burroughs 608 Poplar Street Spartanburg SC 29302

Noel M. Turner 609 Poplar Street Spartanburg SC 29302

Philip & Joan Cope 613 Poplar Street Spartanburg SC 29302

Gwendolyn McAbee 614 Poplar Street Spartanburg SC 29302

Stephen & Susan Bowie 619 Poplar Street Spartanburg SC 29302

Linda McGarity 620 Poplar Street Spartanburg SC 29302

William & Kelly Cheek 625 Poplar Street Spartanburg SC 29302

Bert & Katherine Barre 626 Poplar Street Spartanburg SC 29302

## National Register of Historic Places Continuation Sheet

Section number 10 Page 100

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Marc Merrill 635 Poplar Street Spartanburg SC 29302

Patricia Ratliff 638 Poplar Street Spartanburg SC 29302

Adolf & Susan Schweizer 647 Poplar Street Spartanburg SC 29302

Dorothy Thompson 648 Poplar Street Spartanburg SC 29302

Carolyn Kreuzer 649 Poplar Street Spartanburg SC 29302

Catherine McCutchen 653 Poplar Street Spartanburg SC 29302

Thomas Coleman 654 Poplar Street Spartanburg SC 29302

Julia Smith 658 Poplar Street Spartanburg SC 29302

Carlos & Pamel Agudelo 664 Poplar Street Spartanburg SC 29302

Matthew & Kari Copeland 665 Poplar Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 101

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Robert Stoddard 601 Rutledge Street Spartanburg SC 29302

Wade Crow & Shelley Foster 606 Rutledge Street Spartanburg SC 29302

Lela Elizabeth Bartel 610 Rutledge Street Spartanburg SC 29302

Thomas & Paige Hannah 611 Rutledge Street Spartanburg SC 29302

Cabana Partnership 616 Rutledge Street Spartanburg SC 29302

James Edward Roberts 620 Rutledge Street Spartanburg SC 29302

Virginia Borders 626 Rutledge Street Spartanburg SC 29302

Mike & Nancy Corbin 644 Rutledge Street Spartanburg SC 29302

Christopher & Susan Dekle 649 Rutledge Street Spartanburg SC 29302

Jane May 650 Rutledge Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 102

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Dell & Harriet Jennings 655 Rutledge Street Spartanburg SC 29302

Atha McBride 656 Rutledge Street Spartanburg SC 29302

Merike Tamm & John Seitz 657 Rutledge Street Spartanburg SC 29302

Mary Ann Munn 664 Rutledge Street Spartanburg SC 29302

Alice Lominack 668 Rutledge Street Spartanburg SC 29302

Bertha McArthur 674 Rutledge Street Spartanburg SC 29302

Broadus Littlejohn 680 Rutledge Street Spartanburg SC 29302

Kasey & Kimberly Myers 707 Rutledge Street Spartanburg SC 29302

Barbara A. Lathum 708 Rutledge Street Spartanburg SC 29302

Edna Park 710 Rutledge Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 103

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Susan Woodard 712 Rutledge Street Spartanburg SC 29302

Cecilia Kelley 713 Rutledge Street Spartanburg SC 29302

Michael Saad 720 Rutledge Street Spartanburg SC 29302

Paul & Sue Lansberry 723 Rutledge Street Spartanburg SC 29302

Matthew Hogan 726 Rutledge Street Spartanburg SC 29302

Rupert & Sally Hodges 746 Rutledge Street Spartanburg SC 29302

Theresa Mann 750 Rutledge Street Spartanburg SC 29302

Edgar Fargis 754 Rutledge Street Spartanburg SC 29302

Raymond & Elaine Sturm 758 Rutledge Street Spartanburg SC 29302

Beta LLC 764 Rutledge Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 104

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Don King 765 Rutledge Street Spartanburg SC 29302

Heinz Kunz 769 Rutledge Street Spartanburg SC 29302

Michael Miller 774 Rutledge Street Spartanburg SC 29302

Jennifer Lipscomb 775 Rutledge Street Spartanburg SC 29302

Elizabeth Jeffries 780 Rutledge Street Spartanburg SC 29302

Richard & Lindsay Lowry 781 Rutledge Street Spartanburg SC 29302

Elizabeth Littlefield 784 Rutledge Street Spartanburg SC 29302

John Frick 787 Rutledge Street Spartanburg SC 29302

Clay & Rebecca Keim 788 Rutledge Street Spartanburg SC 29302

Troy Hanna 791Rutledge Street Spartanburg SC 29302 NPS Form 10-900-a (8-86)

### United States Department of the Interior National Park Service

# National Register of Historic Places Continuation Sheet

Section number 10 Page 105

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Rebecca Littlefield 795 Rutledge Street Spartanburg SC 29302

Betty Braswell 804 Rutledge Street Spartanburg SC 29302

Brent & Michelle Hawkins 805 Rutledge Street Spartanburg SC 29302

Ruth Smith 806 Rutledge Street Spartanburg SC 29302

Helga Schmettau 812 Rutledge Street Spartanburg SC 29302

John & Gretchen Maultsby 815 Rutledge Street Spartanburg SC 29302

Brian Williamson 816 Rutledge Street Spartanburg SC 29302

John & Demitra Watson 823 Rutledge Street Spartanburg SC 29302

James Harrison 828 Rutledge Street Spartanburg SC 29302

Elizabeth Brady 833 Rutledge Street Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 106

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Barry & Dorothy Hull 835 Rutledge Street Spartanburg SC 29302

William & Julia Kirby 836 Rutledge Street Spartanburg SC 29302

Eric Hubbell 839 Rutledge Street Spartanburg SC 29302

Steve & Margaret Moore 179 South Fairview Avenue Spartanburg SC 29302

Matz Lischerong 193 South Fairview Avenue Spartanburg SC 29302

Monty Grubbs & James Bolt 198 South Fairview Avenue Spartanburg SC 29302

Christopher Miles 203 South Fairview Avenue Spartanburg SC 29302

David Anderson 204 South Fairview Avenue Spartanburg SC 29302

Charlotte Rogers 209 South Fairview Avenue Spartanburg SC 29302

Ryan & Leslie Christianson 212 South Fairview Avenue Spartanburg SC 29302

# National Register of Historic Places Continuation Sheet

Section number 10 Page 107

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

R&E Properties LLC 213 South Fairview Avenue Spartanburg SC 29302

R&E Properties LLC 215 South Fairview Avenue Spartanburg SC 29302

Leslie Larson 506 Woodland Street Spartanburg SC 29302

Tom & Bonnie Webster 510 Woodland Street Spartanburg SC 29302

EKB, LLC 514 Woodland Street Spartanburg SC 29302

Pierce Family Partnership 518 Woodland Street Spartanburg SC 29302

R&E Properties LLC 552 Woodland Street Spartanburg SC 29302

Lawsons Fork Investment LLC 556 Woodland Street Spartanburg SC 29302

Wendie Boone 591 Woodland Street Spartanburg SC 29302

James Paul Lathan 595 Woodland Street Spartanburg SC 29302

## National Register of Historic Places Continuation Sheet

Section number 10 Page 108

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Sara Smith 598 Woodland Street Spartanburg SC 29302

Nancy Inabinet 601 Woodland Street Spartanburg SC 29302

Charles Cox 604 Woodland Street Spartanburg SC 29302

Aaron Fulmer 605 Woodland Street Spartanburg SC 29302

Evelyn Hurt 608 Woodland Street Spartanburg SC 29302

Pat Anderson 609 Woodland Street Spartanburg SC 29302

James & Jamie Brock 612 Woodland Street Spartanburg SC 29302

Charles Blackwell 615 Woodland Street Spartanburg SC 29302

Edna Crow 616 Woodland Street Spartanburg SC 29302

Elisabeth Boatwright 617 Woodland Street Spartanburg SC 29302

### National Register of Historic Places Continuation Sheet

Section number 10 Page 109

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

Mary Katherine Bishop 626 Woodland Street Spartanburg SC 29302

Fern Powell 642 Woodland Street Spartanburg SC 29302

Margaret Lee 648 Woodland Street Spartanburg SC 29302

Cosette Martin 652 Woodland Street Spartanburg SC 29302

Ernest May 656 Woodland Street Spartanburg SC 29302

Sandra Higginbotham 668 Woodland Street Spartanburg SC 29302

## National Register of Historic Places Continuation Sheet

Section number 10 Page 110

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

#### **Additional UTM References**

	Zone	Easting	Northing
5:	17	417106	3867544
6:	17	416535	3867157
7:	17	416380	3867352
8:	17	416111	3867787
9:	17	416159	3867979
10:	17	416418	3868225
11:	17	416701	3868404

#### **Verbal Boundary Description**

The boundary of the historic district is shown as the black line on the accompanying map "Converse Heights – Proposed Historic District," drawn at a scale of 1" = 140'.

#### **Boundary Justification**

The boundary of the nominated property is restricted to the highest concentration of buildings that date from the period ca. 1900-ca. 1950, illustrating the creation, growth, and development of Converse Heights as one of Spartanburg's most significant early-to-mid-twentieth century neighborhoods..

### National Register of Historic Places Continuation Sheet

Section number PHOTOGRAPHS Page 111

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

The following information is the same for each of the photographs:

Name of Property:

Converse Heights Historic District

Location of Property:

Spartanburg, Spartanburg County, S.C.

Name of Photographer: Date of Photographs Jennifer S. Revels, S.C. Department of Archives & History

November 2006

Location of Digital Images:

S.C. Department of Archives and History

- 504 Otis Boulevard
- 2. 573 Otis Boulevard
- 591 Otis Boulevard
- 634 Otis Boulevard
- 5. 709 Otis Boulevard
- 6. 715 Otis Boulevard
- 7. 716 Otis Boulevard
- 8. 720 Otis Boulevard
- 9. 725 Otis Boulevard
- 10. 710 Plume Street
- 11. 755 Plume Street
- 12. 763 Plume Street
- 13. 120 Connecticut Avenue
- 14. 140 Connecticut Avenue
- 15. 150 Connecticut Avenue
- 16. 176 Connecticut Avenue
- 17. Connecticut Avenue between 203 & 215
- 18. 221 Connecticut Avenue
- 19. 254 Connecticut Avenue
- 20. 269 Connecticut Avenue
- 21. 364 Connecticut Avenue
- 22. 368 Connecticut Avenue
- 23. 511 Glendalyn Avenue
- 24. 512 Glendalyn Avenue
- 25. 600 Glendalyn Avenue
- 26. 668 Glendalyn Avenue
- 27. 734 Glendalyn Avenue
- 28. 606 Palmetto Street
- 29. 724 Palmetto Street
- 30. 778 Palmetto Street
- 31. 802 Palmetto Street
- 32. 406 Hale Street

#### National Register of Historic Places Continuation Sheet

Section number PHOTOGRAPHS Page 112

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 33. 647 Norwood Street
- 34. 663 Norwood Street
- 35. 611 Rutledge Street
- 36. 620 Rutledge Street
- 37. 626 Rutledge Street
- 38. 674 Rutledge Street
- 39. 707 Rutledge Street
- 40. 712 Rutledge Street
- 41. 720 Rutledge Street
- 42. 774 Rutledge Street
- 43. 784 Rutledge Street
- 44. 558 Woodland Street
- 45. 612 Woodland Street
- 46. 128 Mills Avenue
- 47. 129 Mills Avenue
- 48. 141 Mills Avenue
- 49. 204 Mills Avenue
- 50. 216 Mills Avenue
- 51. 220 Mills Avenue
- 52. 343 Mills Avenue
- 53. 362 Mills Avenue
- 54. 398 Mills Avenue
- 55. 613 Poplar Street
- 56. 627 Maple Street
- 57. 639 Maple Street
- 58. 645 Maple Street
- 59. 656 Maple Street
- 60. 718 Maple Street
- 61. 725 Maple Street
- 62. 199 Clifton Avenue
- 63. 223 Clifton Avenue
- 64. 142 Mills Avenue (Noncontributing)
- 65. 167 Mills Avenue (Noncontributing)
- 66. 170 Mills Avenue (Noncontributing)
- 67. 179 Mills Avenue (Noncontributing)
- 68. 184 Mills Avenue (Noncontributing)
- 69. 193 Mills Avenue (Noncontributing)
- 70. 204 Mills Avenue (Noncontributing)
- 71. 238 Mills Avenue (Noncontributing)
- 72. 239 Mills Avenue (Noncontributing)

# National Register of Historic Places Continuation Sheet

Section number PHOTOGRAPHS Page 113

Converse Heights Historic District
Name of Property
Spartanburg County, South Carolina
County and State

- 73. Streetscape 1
- 74. Streetscape 2
- 75. Streetscape 3
- 76. Streetscape 4
- 77. Streetscape 5
- 78. Streetscape 6




























































































































































# **Missing Core Documentation**

Property Name	County, State	Reference Number 07001021
Converse Heights Historic District	Spartanburg, SC	07001021
The following Core Document	ation is missing	from this entry:
ė.	*	
Nomination Form		
X Photographs (missing #9)	*	12
USGS Map	,	



## National Register of Historic Places

## Note to the record

Additional Documentation: 2014

Title:

#### United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations for individual properties and districts. See instructions BECEN Register 80 Bulletin, How to Complete the National Register of Historic Places Registration Form. If any item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions. 1. Name of Property NAT REGISTER OF HISTORIC PLACES NATIONER PARK SERVICE Historic name: Converse Heights Historic District (Amended) Other names/site number: Name of related multiple property listing: (Enter "N/A" if property is not part of a multiple property listing N/A 2. Location Street & number: SE of E. Main St. and NE of Pine St., containing properties along portions of Clifton, Connecticut, & Glendalyn Aves., Hale & Maple Sts., Mills Ave., Norwood St., Otis Blvd., Palmetto, Plume, Poplar, & Rutledge Sts., S. Fairview Ave. and Woodland St. City or town: Spartanburg State: South Carolina County: Spartanburg Not For Publication: Vicinity: 3. State/Federal Agency Certification As the designated authority under the National Historic Preservation Act, as amended, I hereby certify that this x nomination request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property  $\underline{x}$  meets does not meet the National Register Criteria. I recommend that this property be considered significant at the following level(s) of significance: national statewide x local Applicable National Register Criteria: x A Signature of certifying official/Title: Elizabeth M. Johnson, Deputy SHPO, South Carolina Department of Archives and History State or Federal agency/bureau or Tribal Government does not meet the National Register criteria. In my opinion, the property meets Signature of commenting official: Date

State or Federal agency/bureau

or Tribal Government

(Expires 5/31/2012)

#### United States Department of the Interior National Park Service

(Rev. 01/2009)

#### National Register of Historic Places Continuation Sheet

Name of Property Converse Heights Historic District (Amended) County and State Spartanburg, South Carolina Name of multiple property listing (if applicable)

Section number 7 Page 60a

The Converse Heights Historic District was listed in the National Register of Historic Places on September 25, 2007, and consists of a collection of over 460 historic residences constructed between ca. 1900 and ca. 1950. One residence, located at 268 Connecticut Avenue [corner of Norwood Street], in the city of Spartanburg, the county seat of Spartanburg County, South Carolina, is within the boundaries of the Converse Heights Historic District, but was categorized as noncontributing when the National Register nomination was prepared in 2007. The house at 268 Connecticut Avenue (#6 in the inventory of non-contributing properties) was thought at the time to have been altered extensively; however, in 2010 the owner brought to the attention of the State Historic Preservation Office staff that the house was essentially intact from its time of construction, with only a poorly designed and executed, non-historic side porch enclosure by a previous owner. The following property should be deleted from the Non-Contributing Properties inventory #6, and added to the inventory of Contributing properties, with inventory # 463:

#### Ben Hill Brown House, 268 Connecticut Avenue

Constructed of brick laid in an American or common bond variant on the first level, the house at 268 Connecticut Avenue is either of frame construction clad with stucco or masonry construction clad with stucco on the second level. The steeply-pitched lateral gabled roof is clad with original variagated-gray Virginia slates and features a central projecting entry gable on the façade [northeast] elevation and two large gabled ell extensions to the rear [southwest elevation]. The rear slope of the main roof, between what appear to be rear ells, extends at a more gradual slope – a feature that is likely a stylistic architectural device to disguise the actual depth of the main block of the house. The design achieved the visual characteristices of a single-pile Tudor revival based upon its historical antecedents while encompassing a double-pile square footage. Slightly projecting end chimneys with slate-clad steeply-pitched shoulders rise above the roofline at the side gables' peaks. Quarter round windows flank each chimney in the gables. The façade's central projecting gable features a shallow projecting entry portal with cantilevered copper-clad belcast hood that contains a recessed, single-leaf wood plank door with strap hinges, a four-pane, fixed leaded glass window, and a five-light transom. To either side of the entry portal are twelve-light, wood-framed casement window sidelights with chevron-patterned brick underpanels. The house's façade is balanced symetrically with triple twelve-over-twelve light, double-hung sash windows with louvered wood shutters to either side of the entry. The façade's upper level features a paired, sixover-six, double-hung sash window with louvered wood shutters above the entry, and flanking tripartite windows [six-over-six light central window with flanking four-over-four light windows] with louvered wood shutters. The roof features copper gutters with copper scupper boxes and downspouts. Extending from the southeast gable end elevation at that end of the façade is a porte cochere, and from the northwest gable end elevation at that end of the façade is a porch [now enclosed]. Each of these extensions is supported by three

## United States Department of the Interior National Park Service

#### **National Register of Historic Places Continuation Sheet**

County and State	Spartanburg, South Carolina
------------------	-----------------------------

Section number 7 Page 60b

piers with simple brackets at each of the two outer corners and corresponding pilaster piers with brackets at the end wall of the house. A slat-panelled balustrade surrounds the roof of each. The architectural features of the side porch are still expressed in spite of the enclosure. To the rear (west) of the house is a modern swimming pool, a non-contributing structure on the property.

Built in 1924-25 for Ben Hill Brown (1882-1944), former state legislator and mayor of Spartanburg, and his wife, Clara Twitty Colcock Brown, this substantial period revival house with Tudor Revival architectural elements was designed by Lockwood, Greene & Company, well-known for its design and construction of textile mills throughout New England and the South and whose southern regional headquarters had just been relocated from Atlanta to Spartanburg's newly-built, and Lockwood, Greene & Company-designed, Montgomery Building at 187 North Church Street (listed in the National Register on May 25, 2011). Brown, a prominent local attorney who had a successful career of public, civic, and community service, was elected to the South Carolina House of Representatives from Spartanburg in 1908 and served until 1912. During the First World War he supported the war effort through many local patriotic organizations, serving as chairman of the Spartanburg County Council of Defense, War Savings Committee, and War Industries Board. He was president of the Wofford College alumni association, served on the board of trustees of Converse College, the board of directors of the Cowpens Mills, the board of the Spartanburg Chamber of Commerce, and was a member of a number of fraternal organizations. He was elected mayor of Spartanburg in 1925, at about the time he built this house, and was re-elected to serve until 1933. Under his leadership as mayor the city of Spartanburg opened South Carolina's first commercial airport in 1927 and, to much fanfare, hosted famed aviator Charles A. Lindbergh, who flew his "Spirit of St. Louis" into that airport on October 12, 1927. Local tradition holds that Brown hosted Lindbergh in his relatively new home at 268 Connecticut Avenue. The house, built at a cost of approximately \$30,000, remained in Brown's ownership until 1930. Subsequent owners during the historic period included John Dean McCravy and Alvin H. Wells. In 1946, Lt. John Adger Law, Jr. (1907-1980), son of Saxon Mills owner, John Adger Law, purchased the house, and remained there until 1964, when Norman C. Armitage and his wife, Constance Dean Armitage, both by then well known in the Olympic sport of fencing, acquired it. The

<sup>&</sup>lt;sup>1</sup> John E. Wells and Robert E. Dalton, *The South Carolina Architects, 1885-1935: A Biographical Dictionary* (Richmond, VA: New South Architectural Press, 1992), pp. 110-111; Yates Snowden, ed., *History of South Carolina, Volume III, Illustrated* (Chicago and New York: The Lewis Publishing Company, 1920), pp. 214-215; David Duncan Wallace, *The History of South Carolina, Biographical Volume IV* (New York: The American Historical Society, Inc., 1934), pp. 161-162; Walter B. Edgar, ed. *Biographical Directory of the South Carolina House of Representatives, Volume I: Session Lists, 1692-1973* (Columbia, SC: University of South Carolina PRess, 1974), pp. 491-498; Death Certificate, Ben Hill Brown, June 29, 1944 (filed July 10, 1944) Bureau of Vital Records, South Carolina Department of Health and Environmental Control, Columbia, South Carolina; National Register Files, State Historic Preservation Office, South Carolina Department of Archives and History, Columbia, South Carolina.

OMB No. 1024-0018

(Expires 5/31/2012)

#### United States Department of the Interior **National Park Service**

(Rev. 01/2009)

#### National Register of Historic Places Continuation Sheet

County and State	Spartanburg, South Carolina
Journey and State	Spartanoung, South Carolina
	operty listing (if applicable)

60c Section number Page

house was owned by several other families from the 1980s to 2007 when the current owners, Henry Fritz Butehorn and Lori J. Butehorn, purchased it.

The house is a relatively rare and intact example of the residential work of the firm of Lockwood, Greene & Company, much better known for its prolific generation of designs for textile mill and other industrial and institutional buildings and complexes throughout New England and the South. Amos D. Lockwood or his firm, Lockwood, Greene & Company, founded with Stephen Greene, and John W. Danielson in Providence, Rhode Island, in 1882, engineered, designed, and built over fifty cotton mills in South Carolina between 1873 and 1911. The firm, which maintained offices in Boston, Charlotte, and Atlanta, as well as Greenville and Spartanburg, South Carolina, introduced the New England prototype textile mill in South Carolina. Many of their textile mill complexes included the villages with numerous examples of operative housing, but the firm's records show few individual residential commissions. There are four other known residential commissions in Spartanburg, at or about the same time as the Ben Hill Brown House, that were handled by Lockwood, Greene & Company. They are the Henry J. Blackford Residence on Connecticut Avenue (1924), and the James Chapman, the R.F.H. Chapman, and the Dr. L.J. Blake Residences, all in a "group estate" on Plume Street in Converse Heights.

United States Department of the Interior
National Park Service / National Register of Historic Places Registration Form
NPS Form 10-900

OMB No. 1024-0018

Converse Heights Historic District (Amended)
Name of Property

Spartanburg County, SC County and State

#### **Photographs**

Submit clear and descriptive photographs. The size of each image must be 1600x1200 pixels (minimum), 3000x2000 preferred, at 300 ppi (pixels per inch) or larger. Key all photographs to the sketch map. Each photograph must be numbered and that number must correspond to the photograph number on the photo log. For simplicity, the name of the photographer, photo date, etc. may be listed once on the photograph log and doesn't need to be labeled on every photograph.

#### **Photo Log**

Name of Property: Ben Hill Brown House, 268 Connecticut Avenue

Converse Heights Historic District (Amended)

City or Vicinity: Spartanburg

County: Spartanburg

State: South Carolina

Photographer: Glen B. Boggs, AIA

PO Box 13

Pauline, SC 29374

Date Photographed: 2/27/12

Description of Photograph(s) and number, include description of view indicating direction of camera:


1 of 3. Facade (East elevation)

2 of 3. South elevation

3 of 3. Northwest oblique of rear ell and pool house

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C.460 et seq.).

Estimated Burden Statement: Public reporting burden for this form is estimated to average 100 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Office of Planning and Performance Management. U.S. Dept. of the Interior, 1849 C. Street, NW, Washington, DC.









## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: ADDITIONAL DOCUMENTATION				
PROPERTY Converse Heights Historic District NAME:				
MULTIPLE NAME:				
STATE & COUNTY: SOUTH CAROLINA, Spartanburg				
DATE RECEIVED: 3/07/14 DATE OF PENDING LIST: DATE OF 16TH DAY: DATE OF 45TH DAY: 4/23/14 DATE OF WEEKLY LIST:				
REFERENCE NUMBER: 07001021				
REASONS FOR REVIEW:				
APPEAL: N DATA PROBLEM: N LANDSCAPE: N LESS THAN 50 YEARS: N OTHER: N PDIL: N PERIOD: N PROGRAM UNAPPROVED: N REQUEST: N SAMPLE: N SLR DRAFT: N NATIONAL: N				
COMMENT WAIVER: N				
ACCEPTRETURNREJECTDATE				
ABSTRACT/SUMMARY COMMENTS:				
Additional Documentation Approved				
RECOM. / CRITERIA COCCEPTATO O CONTROL O CONTR				
REVIEWER Color Meal DISCIPLINE Tholony				
TELEPHONE DATE 4.21.14				
DOCUMENTATION see attached comments Y/N see attached SLR Y/N				
If a nomination is returned to the nominating authority, the nomination is no longer under consideration by the NPS.				

### National Register of Historic Places Memo to File

# Correspondence

The Correspondence consists of communications from (and possibly to) the nominating authority, notes from the staff of the National Register of Historic Places, and/or other material the National Register of Historic Places received associated with the property.

Correspondence may also include information from other sources, drafts of the nomination, letters of support or objection, memorandums, and ephemera which document the efforts to recognize the property.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NOMINATION
PROPERTY Converse Heights Historic District NAME:
MULTIPLE NAME:
STATE & COUNTY: SOUTH CAROLINA, Spartanburg
DATE RECEIVED: 8/13/07 DATE OF PENDING LIST: 8/31/07 DATE OF 16TH DAY: 9/15/07 DATE OF 45TH DAY: 9/26/07 DATE OF WEEKLY LIST:
REFERENCE NUMBER: 07001021
REASONS FOR REVIEW:
APPEAL: N DATA PROBLEM: N LANDSCAPE: N LESS THAN 50 YEARS: N OTHER: Y PDIL: N PERIOD: N PROGRAM UNAPPROVED: N REQUEST: Y SAMPLE: N SLR DRAFT: N NATIONAL: N
COMMENT WAIVER: N
ACCEPTRETURNREJECTDATE
ABSTRACT/SUMMARY COMMENTS:  Notable collection (1900 - c 1950) 8 20 th century
house designs in one of city's "streetear dwellings
ABSTRACT/SUMMARY COMMENTS:  Notable collection (1900 - c 1950) & 20 th century  house designs in one of city's "streetcar subushs",  includes single and multiple family dwellings  includes single and multiple family dwellings  for middle and upper middle member sitizens.  Theigh has hoad is importantly associated to  minimize the planning and clevelopments  community planning and clevelopments
community danning amonasion ordaides min
RECOM. / CRITERIA Accept At mal information about platting and evaluation of
REVIEWER LONG TO CHEEK BISCIFILINE ( 500) THOSE STORY
TELEPHONE DATE $9/25/07$ is a collepta-
DOCUMENTATION see attached comments Y/N see attached SLR Y/N  The pasis
If a nomination is returned to the nominating authority, the nomination is no longer under consideration by the NPS.  The pasis  The
LODSOSEU ta tron & 2010 century
street car suburt Type.





Thursday, 9 August 2007

Ms. Janet Matthews Keeper, National Register of Historic Places U.S. Department of the Interior National Park Service 1201 Eye (I) Street, NW, 8th Floor Washington, DC 20005

Dear Ms. Matthews:

Enclosed is the National Register nomination for the Converse Heights Historic District, in Spartanburg County, South Carolina.

This nomination was recently approved by the South Carolina State Board of Review and we are now submitting it for formal listing in the Register.

If I may be of further assistance, please do not hesitate to contact me at the address below, call me at (803) 896-6182, fax me at (803) 896-6167, or e-mail me at power@scdah.state.sc.us. I hope to hear from you soon.

Sincerely,

J. Tracy Power

Historian

State Historic Preservation Office





Tuesday, 25 September 2007

Ms. Janet Matthews Keeper, National Register of Historic Places U.S. Department of the Interior National Park Service 1201 Eye (I) Street, NW, 8th Floor Washington, DC 20005

Dear Ms. Matthews:

We recently submitted a National Register nomination for the Converse Heights Historic District, in Spartanburg County, South Carolina.

We are now enclosing a CD-R containing seventy-eight (78) digital photographs to accompany the archivally stable digital black and white prints and accompanying photo identification continuation sheet submitted with that nomination.

If I may be of further assistance, please do not hesitate to contact me at the address below, call me at (803) 896-6182, fax me at (803) 896-6167, or e-mail me at POWER@.scdah.state.sc.us. I hope to hear from you soon.

Sincerely,

J. Tracy Power

Historian

State Historic Preservation Office

Linda McClelland

To: tpower@scdah.state.sc.us

09/25/2007 01:23 PM

**EDT** 

Subject: Converse Heights H.D.


Hi Tracy--

This is another nomination that arrived without a disk. Also, the acreage is missing, and I'll need to add it with an slr.

Linda

Linda McClelland Historian National Register of Historic Places 202-354-2258 202-371-6447 (FAX) linda\_mcclelland@nps.gov





Monday, March 3, 2014

Ms. Carol Shull Interim Keeper, National Register of Historic Places U.S. Department of the Interior National Park Service 1201 Eye (I) Street, NW, 8th Floor Washington, DC 20005

Dear Ms. Shull:

75001706

Enclosed is an amendment to the National Register nomination for the Converse Heights Historic District in Spartanburg, Spartanburg County, South Carolina, with specific reference to the property at 268 Connecticut Avenue [Ben Hill Brown House]. This additional information is submitted to correct an error in the original nomination submission in 2007 that categorized the property as a non-contributing resource. The property's status should be changed from non-contributing to contributing.

If we may be of any further assistance, please do not hesitate to contact me at the address below, at (803) 896-6179, by fax at (803) 896-6167, or by e-mail at chandler@scdah.state.sc.us.

Sincerely,

Andrew W. Chandler

Senior Architectural Historian and National Register Co-Coordinator

W. Chardle

State Historic Preservation Office

enclosure