



- 1) Name of Property: Lamonta Compound--Office/
Warehouse #2006
- 2) City and State: Prineville, Oregon
- 3) Photographer: Sally Anderson
- 4) Date: 01/27/84
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southeast at east gable end
and main north-facing facade
- 7) Photograph Number: 07-S0-2006-1



- 1) Name of Property: Lamonta Compound, Office/
Warehouse #2006
- 2) City and State: Prineville, OR
- 3) Photographer: Sally Anderson
- 4) Date: 1/27/84
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southeast at rear elevation
of Office/Warehouse
- 7) Photograph Number: 07-S0-2006-2



- 1) Name of Property: Lamonta Compound--Maintenance Shop # 7.2101
- 2) City and State: Prineville, Oregon
- 3) Photographer: Sally Anderson
- 4) Date: 1/27/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Northeast corner.
- 7) Photograph Number: 07-S0-7.2101-1



- 1) Name of Property: Lamonta Compound, Maintenance Shop #7.2101
- 2) City and State: Prineville, OR
- 3) Photographer: Sally Anderson
- 4) Date: 1/27/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southeast at north gable end and rear elevation of Maintenance Shop
- 7) Photograph Number: 07-S0-7.2101-2



- 1) Name of Property: Lamonta Compound--Vehicle Storage #7.2301
- 2) City and State: Prineville, Oregon
- 3) Photographer: Sally Anderson
- 4) Date: 1/27/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northwest at south gable end and main east-facing facade
- 7) Photograph Number: 07-S0-7.2301



- 1) Name of Property: Lamonta Compound--Gas and Oil House 7.2502
- 2) City and State: Prineville, Oregon
- 3) Photographer: Sally Anderson
- 4) Date: 1/27/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southeast at north gable end and main west-facing facade
- 7) Photograph Number: 07-S0-7.2502