-14

United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

NATIONAL REGISTER

Date of Action

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for *Completing National Register Forms* (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

(Form 10-900a). Type all entries.			
1. Name of Property			
historic name John Humphrey	House		
other names/site number			
2. Location			
street & number 115 East Weatoque Street		NA not for publication	
city, town Simsbury		x	vicinity E. Weatoque
state CT code CT	county Hartford	code 003	zip code 06070
3. Classification			
	Category of Property	Number of Resource	es within Property
🔀 private	🔀 building(s)	Contributing N	Noncontributing
public-local	district	<u> </u>	<u> </u>
public-State	site		sites
public-Federal	structure	in toral descent in state of survival	structures
	object		objects
	,		<u> </u>
Name of related multiple property listing:		Number of contribut	ting resources previously
NA		listed in the Nationa	al Register <u>0</u>
A State/Endered Ageney Cartificati			
4. State/Federal Agency Certification			
X nomination request for determined National Register of Historic Places and In my opinion, the property X In my opinion, the property X meets Signature of certifying official John W. State or Federal agency and bureau	d meets the procedural and profess does not meet the National Regi	ilonal requirements set i ster criteria. 🗌 See con	forth in 36 CFR Part 60.
In my opinion, the property meets [does not meet the National Regi	ster criteria. 🛄 See con	tinuation sheet.
Signature of commenting or other official	,		Date
State or Federal agency and bureau			
5. National Park Service Certification	on	entered in	the
I, hereby, certify that this property is:	and a second	7 National F	legister
 entered in the National Register. See continuation sheet. determined eligible for the National Register. See continuation sheet. determined not eligible for the National Register. 	Alous	jen	11/15/90
removed from the National Register.		. :	

ASignature of the Keeper

6. Function or Use		
Historic Functions (enter categories from instructions) DOMESTIC/single dwelling	Current Functions (enter categories from instructions) DOMESTIC/single dwelling	
7. Description		
Architectural Classification (enter categories from instructions)	Materials (enter categories from instructions)	
	foundationS	TONE/Sandstone
COLONIAL/Post medieval English		100D/Weatherboard
	roofA	SPHALT
	other	

Describe present and historic physical appearance.

The John Humphrey House, built c. 1760, is a 2-story frame gable-roofed Colonial building that faces east close to the road in the East Weatogue section of Simsbury. (Photograph 1) The neighborhood is still rural in nature, with the houses well spaced and surrounded in part by open fields. In the five-bay front elevation of the John Humphrey House, 12-over-12 windows are arranged in a 2-1-2 pattern, with central doorway and central chimney. A long one-story ell, perhaps dating from the 18th century, runs to the rear, while a mid-19th century 12-story wing, set back half the depth of the house, extends to the north. (Photographs 1-4, Figure 1)

The house is covered with clapboards. The plain window trim at the second floor abuts the cornice, which is embellished by mutules. (Photograph 5) Corner boards are plain. The two-leaf front door is set in a molded splayed surround. (Photograph 1) In the south side elevation, two 12-over-12 windows similar to those on the front are evenly spaced at first and second floors under two closely spaced attic windows which have 9-over-6 glazing. A door with a flat cornice adjoins the westerly firstfloor window. (Photograph 2)

The rear elevation is covered with wider weather boards. Its fenestration consists of a multi-paned picture window at the first floor and two 12-over-12 windows at the second. The one-story ell, extending back from the north part of the rear elevation, consists of several sections that total a length of 52 feet. The first section jogs out to the south in a glazed bay, then continues under a central chimney to a vertical divider where the floor level drops to grade. A final section under a slightly lower roof line is a garage; its west wall supports an external chimney. (Photographs 3, 4)

On the north side elevation fenestration is similar to that on the south side, except that the door is toward the front rather than the rear. The door has tapered paneled pilasters embellished with incised spiral moldings under a molded cap, indicating it may be an early 19th-century alteration. The rear part of the elevation is obscured by the set-back 1¹/₂-story north wing. The wing has three 6-over-6 windows at the first floor and three 3-over-3 windows at the second which are evenly spaced but not centered. As a group, they are off center to the south. A door under plain frieze and cornice fills the space between the first and second windows at the first floor. (Photograph 7) The wing has a central chimney. A one-story ell under cross gable and a low shed complete the wing. (Photographs 1, 4) Foundations of the wing are brownstone ashlar similar to the main block foundations. United States Department of the interior National Park Service

National Register of Historic Places Continuation Sheet

John Humphrey House Simsbury, CT

Section number ____7 Page _1___

The front door opens to a small stair hall, immediately establishing the existence of the conventional Colonial floor plan of hall in front of the massive central chimney, front rooms on either side, and kitchen in the rear. To the left of the stairway's paneled front there are three risers to a landing, a 90 degree turn in front of the chimney followed by six risers to a landing, and a 90 degree turn toward the front followed by two risers. There are no winders. Under the handrail which has no balusters, is a closed string stopped by square newels at the landings and a turned newel at the bottom. (Photograph 8)

In the paneled fireplace wall of the south front room, the fireplace is flanked by fluted pilasters with rosette capitals. (Photographs 9, 10) The fireplace and its hearth are brick, the mantel and molded surround Colonial Revival. There is a large panel with molded border over the fireplace. A cased summer runs from the fireplace wall to the south wall, while a molded cornice runs around three sides of the room. The dado is made of wide horizontal boards. At the southeast front corner is a corner cupboard with tombstone-shaped opening, panels in its spandrels, and fluting under rosettes, which match similar features in the fireplace wall. (Photograph 11)

In the north front room, the paneled fireplace wall is not as elaborate, while the brick fireplace and hearth are surrounded by bolection molding. (Photograph 13) The summer is similar to that of the south front room, but the dado of the front and rear walls is paneled and that of the north wall is narrow vertical boards. The dado along the north wall, the installation of the door toward the front with embellished exterior surround, and addition of the wing may all have been parts of a single building campaign. In both front rooms the doors to the hall and to the kitchen are three panel.

The kitchen fireplace is brick with rear bake oven and stone hearth. There is no mantel over the wooden lintel, but the wall above the lintel is paneled. (Photograph 14) The floor boards are wide (as they are throughout the house); walls are wide feather-edged vertical boards; and the girts on either side of the fireplace are sheathed. The kitchen is open to the south door, the original partition having been removed, while at the north there is a stair with one riser to a landing, then a second 90-degree turn toward the front and a straight run to the second floor. In the ell, wide floor boards continue; the ceiling is exposed rafters without plaster; and there is a small fireplace with bake oven on the front right, indicating it is not as old as the fireplace in the kitchen.

On the second floor, the hall railing has square balusters. The two front rooms are similar to one another with cased corner posts, four-panel doors, and no cornices or dados. Window lintels are at ceiling height. Each room has a small fireplace with plain frieze, flat mantel, and cupboard and adjoining narrow closet door in front of the chimney. (Photograph 15) To the rear of the chimney is a lateral hall which has a similar fireplace, somewhat wider but as shallow, with cupboard above and adjoining narrow door. United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

John Humphrey House Simsbury, CT

Section number ____7 Page __2

There is a cluster of three fireplaces in the first floor of the wing. The south half of the space is a single room whose fireplace has been bricked up and fitted with an iron stove. The north half of the space is divided laterally; each of the two rooms has a plain fireplace that resembles the second-floor fireplaces of the main block. (Photograph 16, Figure 1) The second floor of the wing is plain.

In the main block, there is a basement under the south front room and kitchen, but not under the north front room. The massive chimney base is solid, without openings. There is a basement under the wing, but not under the ell. In the attic, the roof is framed with common rafters, massive purlins, and diagonal braces. An exterior finish detail is a horizontal water table board placed just above the skirt board over the sill. While primarily decorative, its utilitarian purpose is to serve as a drip cap protecting the skirt board and sill.

The l_2 -story barn of weathered vertical siding, dating from 1976, is non-contributing because of its age. (Photograph 17)

A 1936 photograph of the house shows it with an enclosed porch on the south and an enclosed entrance way at the north, in the angle of the ell formed by the house and the wing. Windows were 12-over-1. The front door at this time was a single leaf but it was flanked by small windows glazed in four tiers of two panes, similar to the arrangement at the nearby James Cornish House, 85 East Weatogue Street. A flat molded cornice was several inches above the door. The rehabilitation of the house to its present condition was carried out in the 1970s. The present double-leaf front door, found in the attic, was reinstalled and the added porches removed.

8. Statement of Significance		
Certifying official has considered the significance of this	s property in relation to other properties:	
Applicable National Register Criteria	xc D	
Criteria Considerations (Exceptions)	C D E F G	
Areas of Significance (enter categories from instructions ARCHITECTURE	s) Period of Significance <u>C.</u> 1760	Significant Dates <u>c.</u> 1760
	Cultural Affiliation	
Significant Person NA	Architect/Builder John Humphrey	······

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The John Humphrey House is significant architecturally because it is a good example of a Colonial structure, well preserved, with an added mid-19th-century wing. The original interior architectural detailing of the first floor, including paneled walls, fluting, rosettes, and three-paneled doors, are finely crafted.

The age of the house, c. 1760, is suggested by the land records and by the presence of a bake oven in the rear wall of the kitchen fireplace. Subsequent to the mid-18th century, the bake oven usually was placed in the more convenient location of the front wall adjoining the fireplace opening, as found in the ell of this house. The three-panel doors also strengthen the mid-18th-century attribution. The presence of a basement under only the south room encourages the conjecture that this may have been an early one-room house. Unfortunately most of the framing supporting the first floor appears to have been replaced, making it impossible to confirm the one-room possibility by examination of the visible framing. The components that make up the existing five-room first floor are consistent with one another, e.g., the fireplace-wall paneling and summers are similar, suggesting that what exists now was all built, or finished, at one time. The front-room fireplaces have been re-bricked; it would be useful to know whether there is a bake oven behind the now-visible south room fireplace. A bake oven there would indicate the cooking function of a one-room house.

The interior wooden finishes are probably the house's finest feature. The two paneled fireplace walls establish the high quality, particularly with the fluting and rosettes of the south room. The repetition of the fluting and rosettes in the corner cupboard presents an ensemble not often found. The wide floor boards throughout, on both the first and second floors, are unusually complete, while the wide horizontal boards of the south room dado and wide feather-edged kitchen wall boards round out the good work.

The presence of the ell with a second kitchen, leading to unfinished space and then a shed, is not unusual for a New England Colonial house. But the mid-19th-century north wing, almost a second residence in itself, is unusual, and is unexplained. There is no record or tradition of the circumstances surrounding this addition. The similarity of the three fireplaces clustered on its first floor to the fireplaces on the second floor of the main block is striking. Second-floor fireplaces usually tend to be less elaborate than their X See continuation sheet

9. Major Bibliographical References

Ellsworth, Abigail Eno, and Carver, Gra	
for the Fohn Humphrey House, 1936.	At Simsbury Historical Society.
Historic photograph in <u>Historic Simsb</u> from the Colonial Era, 1717-1834. S Society, 1965.	
50Crecy, 1905.	
"Report of the Historic District Study togue Historic District Study Commit	
	•
Previous documentation on file (NPS):	See continuation sheet
preliminary determination of individual listing (36 CFR 67)	Primary location of additional data:
has been requested	State historic preservation office
previously listed in the National Register	Other State agency
previously determined eligible by the National Register	Federal agency
designated a National Historic Landmark	Local government
recorded by Historic American Buildings Survey #	University Other
recorded by Historic American Engineering	Specify repository:
Record #	
10. Geographical Data	
Acreage of property <u>5,1 acres</u>	
UTM References	
A 1.8 68.30.0.0 4.6 3.6 7.3.0 B Zone Easting Northing	Zone Easting Northing
	have have a first the standard have been been been been been been been be
	See continuation sheet
Verbal Boundary Description	
The nominated property is described at	volume 262, page 711, of the Simsbury
Land Records.	
	See continuation sheet
Boundary Justification	
The property boundary is drawn to inclu	de land that has gone with the house
during the 20th century.	
	See continuation sheet
11 Form Prenarod Du	
11. Form Prepared By name/title David F. Ransom/Consultant, Revie	wed by John Horgan National Design
name/title <u>David F. Ransom/Consultant, Revie</u> organization <u>NA</u>	date June 3, 1990 Coordinator
street & number 33 Sunrise Hill Drive	telephone 203 521-2518
city or townWest Hartford	

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

John Humphrey House Simsbury, CT

Section number ____ Page _____

first-floor counterparts, but here the similarity of the second-floor and wing fireplace surrounds suggests that they may have been done at about the same time.

The massive stone chimney base in the basement and massive long purlins in the attic are characteristic features of a mid-18th-century house, here represented with impressive examples.

A study of the chain of title was made by a knowledgeable Simsbury antiquarian in 1936. This study gives reason to believe that the land in question may have been part of 20 acres granted to Michael Humphrey as early as 1668, but reasonable evidence of a house being in existence came only at the death of Michael's grandson, Jonn Humphrey, Jr., in 1760; hence, the construction date of c. 1760. Owners of the house during most of the 19th century, when the wing was added, were Oliver Bradley and his son Justin Bradley. United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

John Humphrey House Simsbury, CT

Section number Photos Page _____

Photographs were taken by David F. Ransom in May 1990. Negatives are on file at Connecticut Historical Commission

Photograph 1 View southwest

Photograph 2 View northwest

Photograph 3 View northeast

Photograph 4 View southeast

Photograph 5 Front eaves, View northwest

Photograph 6 North doorway, view south

Photograph 7 Wing doorway, view west

Photograph 8 Front stair, view southwest

Photograph 9 South front room, view northeast

Photograph 10 Detail of Photograph 9, view north

Photograph 11 North front room, view southeast Photograph 12 South front room, view southwest

Photograph 13 North front room, view southwest

Photograph 14 Kitchen, view southeast

Photograph 15 Second floor, south front room, view northeast

Photograph 16 Wing, northeast room, view southwest

Photograph 17 Barn, view northwest



First-floor plan Photo key

Scale: 1" = 12'

Figure 1