



Front Elevation

Merrifield - Cass House

Mishawaka, Indiana

Photo By: Phil Cartwright

Photo Date: May 1982

Negative Location: LeRoy Troyer and Assoc.
415 Lincolnway East
Mishawaka, Indiana 46544

Front Elevation - Looking North

Photo Number One (1)



Sawn Wood Detailing on Front Porch

Merrifield - Cass House

Mishawaka, Indiana

Photo By: Phil Cartwright

Photo Date: May 1982

Negative Location: LeRoy Troyer and Assoc.
415 Lincolnway East
Mishawaka, Indiana 46544

Sawn Wood Detailing on Southeast Corner
of Front Porch - Camera View to the Northwest
Photo Number Two (2)



Merrifield - Cass House

Mishawaka, Indiana

Photo By: Phil Cartwright

Photo Date: May 1982

Negative Location: LeRoy Troyer and Assoc.
415 Lincolnway East
Mishawaka, Indiana 46544

Exterior View from the Northeast - Looking
Southwest

Photo Number Three (3)



Exterior view from the southwest

Merrifield - Cass House

Mishawaka, Indiana

Photo By: Phil Cartwright

Photo Date: May 1982

Negative Location: LeRoy Troyer and Assoc.
415 Lincolnway East
Mishawaka, Indiana 46544

Exterior View from the Southwest - Looking
Northeast

Photo Number Four (4)



Attic Window
showing typical window trim and shutter

Merrifield - Cass House

Mishawaka, Indiana

Photo By: Phil Cartwright

Photo Date: May 1982

Negative Location: LeRoy Troyer and Assoc.
415 Lincolnway East
Mishawaka, Indiana 46544

Attic Window Showing Typical Window Trim and
Shutters - Camera View to the West

Photo Number Five (5)



Merrifield-Cass House

Mishawaka, Indiana

Phil Cartwright May 1982

Neg: LeRoy Troyer and Assoc.

Exterior view from the northwest,
looking southeast

Photo #6



Merrifield - Cass House

Mishawaka, Indiana

Photo By: Phil Cartwright

Photo Date: May 1982

Negative Location: LeRoy Troyer and Assoc.
415 Lincolnway East
Mishawaka, Indiana 46544

Main Entry Door and Front Porch Detail -

Camera View to the North

Photo Number Seven (7)