



St. Joseph Catholic Church

Jasper, Indiana

Dubois Co.

photographer - Robert McCarty

July, 1979

negative location - R. McCarty Studio

view facing West

photograph # 1/6

SEP 30 1980



St. Joseph Catholic Church

Jasper, Indiana *Dubois Co.,*

photographer - Robert McCarty

July, 1979

negative location - R. McCarty Studio

view facing Northwest

photograph # 2

SEP 30 1980



St. Joseph Catholic Church

Jasper, Indiana

photographer - Robert McCarty

July, 1979


Dubois Co.

negative location - R. McCarty Studio

view facing East

photograph # *3/6*

SEP 30 1980



St. Joseph Catholic Church

Jasper, Indiana *Dubois Co.*

photographer - Robert McCarty

July, 1979

negative location - R. McCarty Studio

view facing Southeast

photograph # 4/6

SEP 30 1980




St. Joseph's Catholic Church
Jasper, Indiana *Debois co.*
Photographer & Negative Location
Unknown
Date: 1953

SEP 30 1980

This picture shows a wood column in one piece supporting the church roof structure. This yellow poplar tree was cut from a nearby forest and then hand hewn. This picture was taken in 1953 during interior renovation and replastering work.

Photo #5 of 6



Catholic

St. Joseph's Church Jasper, Indiana

Photographer & Negative Location Unknown

Date: 1953

Dubois Co.

This picture of the interior shows the top of the columns and part of the supporting nave and roof structure. The interior of the sandstone blocks and their thickness is also shown.

Photo #6 of 6

SEP 30 1980