
United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form





Type an entries	complete applicable :	300110113					
1. Nam	ıe						
historic	Wilson's Inheritance (preferred)						
and/or common	Frank Englar Farm, Emil White Farm						
2. Loca	ation						
street & number	4400 Green Vall	ey Road (MD Route 7	75)	$\frac{n/a}{a}$ not for publication			
city, town	Union Bridge	X_ vicinity of	congressional district	Sixth			
state	Maryland cod	e ²⁴ county	Carroll	code 013			
3. Clas	sification						
Category districtX building(s) structure site object	Ownership public private both Public Acquisition in process being considered X not applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted X no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:			
4. Own	er of Prope	rty					
name	Emil H. White						
street & number	4400 Green Val	Ley Road					
city, town	Union Bridge	$\frac{n/a}{}$ vicinity of	state	Maryland 21791			
5. Loca	tion of Leg	al Descripti	on				
courthouse, regis	stry of deeds, etc. Carro	oll County Courthou	se Annex				
street & number	55 No	orth Court Street					
city, town	Westi	ninster	state	Maryland			
6. Repr	esentation	in Existing	Surveys				
·	nd Historic Trust cic Sites Inventory	has this pro	operty been determined e	legible? yes $rac{X}{}$ no			
date 1978			federalX sta	ite county loca			
depository for su	rvey records	tate Circle					
city, town	Annaj	polis	state	Maryland 21401			

7. Descript	ion	CARR-206
X goodru	check one eteriorated unaltered insX altered nexposed	$\begin{array}{c} \textbf{Check one} \\ \underline{X} \text{ original site} \\ \underline{ } \text{moved} \qquad \textbf{date} \ \underline{ } \underline{n/a} \\ \end{array}$
Describe the present a	nd original (if known) phy	sical appearance
Number of Res	ources	Number of previously listed
Contributing	Noncontributing	National Register properties included in this nomination: 0
	ostructures oobjects	Original and historic functions and uses: agriculture, residence
17	<u> </u>	

DESCRIPTION SUMMARY:

Wilson's Inheritance is a mid-nineteenth century farmstead that illustrates an affluent agricultural complex of central Maryland. The property retains numerous period outbuildings and the architectural character of the 1832-38 farmhouse presents a variation on the regional Pennsylvania farmhouse that indicates the prosperity of its original owner. This variation consists of an inset, double-tiered porch in the central two bays of the six-bay main facade. Other exterior features of the house, such as its L-shaped plan, stone foundation, common bond brickwork (Flemish bond on the main facade), gable roof, ornamentation, and its siting into a slope, are characteristic of farmhouse construction in Carroll and surrounding counties. However, the interior of the house displays more elaborate ornamentation in the mantelpieces, chair rails, door frames and other woodwork than is typically found in the regional farmhouses. The total farm complex, that includes a bank barn, blacksmith shop, washhouse, smokehouse, chicken houses, sheds and a privy, is relatively intact and represents a large and prosperous farming operation of the mid-nineteenth century.

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799X 1800–1899 1900–	Areas of Significance—C archeology-prehistoric archeology-historic agriculture architecture art commerce communications			religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1837–38	Builder/Arghitest	Lewis Shueey	

Statement of Significance (in one paragraph)

Applicable Criteria: C
Applicable Exceptions: none
Significance Evaluated: local

SIGNIFICANCE SUMMARY:

Wilson's Inheritance presents a farmhouse and farmstead that embodies the distinctive characteristics of the early-to-mid nineteenth century in Piedmont Maryland. The farmhouse, built in 1837-38, represents several features of the typical Pennsylvania farmhouse in style and construction, but includes significant variations in its main facade design, floor plan and interior ornamentation that indicate the affluence of the original owner. From 1875 to 1974, the farm was owned by the Francis J. Englar and Francis J. Englar, Jr., families who were influential farmers and citizens of this region. The Englar family enlarged the barn and remodeled several rooms in the farmhouse to rural Victorian-style standards. Overall, the farm complex retains almost all of its nineteenth century buildings and the significant nineteenth century features of these structures, including an abundance of period hardware. The complex possesses infinite material for the study of agriculture and rural architecture in central Maryland.

HISTORY AND SUPPORT:

Samuel Wilson inherited a 415 acre parcel of land in 1792 which he called Wilson's Inheritance. It contains parts of Susan's Fancy and Round Spring which were land patents of Thomas Wilson dating from 1761 and 1752. Samuel Wilson had a mortgage to Henry Rial on about one-half of the property from 1819 to 1824. In 1824, Wilson sold 202 acres to William Currey for \$2300. Two years later, Currey sold the same property to Lewis Shueey for \$3000, and the increase in the purchase price suggests that there were some improvements made to the property during that time. However, the house as it presently stands was most likely constructed by Shueey in 1837-38, because the tax assessment valuation for those years jumps from \$7000 to \$15,000. Shueey sold the property in 1850 for \$10,000. It passed through several hands until 1875, when a 125 acre parcel was purchased by the Englar family who retained the property until 1974.

The architect of the farmhouse and farmstead illustrates a prosperous nineteenth century farm operation of Piedmont Maryland. The farmhouse uses a main facade design found only occasionally in this area - the central two-bay inset porch of the six-bay main facade presents a prestigious architectural variation on the typical five-bay Pennsylvania farmhouse style. This prosperity

9. Major Bibliographical References

CARR-206

See Continuation Sheet No. 8

10. Ged	graphical D	ata		
Acreage of nomin Quadrangle name UMT References	ated property <u>approxima</u> Union Bridge, Mary	<u>tely 21</u> acres land	(Quadrangle scale 1:24000
Zone Easting			1 8 3 1 4 Zone Easting	7 15 10 4 13 8 12 0 14 10 Northing
3 118 3 114 5 118 3 114 6 118 114		F [H [
erbal boundar	y description and justific	ation	700	
See Cont	inuation Sheet No. 8			
ist all states a	nd counties for properti	es overlapping state	or county bou	ındaries
tate n/a	cod	e county		code
tate	cod	e county		code
ame/title rganization	Natalie Shivers/Jo		date Ja	nuary 1984
treet & number	21 State Circle		telephone	269-2438
ity or town	Annapolis		state	Maryland 21401
2. Stat	te Historic P	reservation	on Offic	er Certification
he evaluated sign	nificance of this property wi	37		
65), I hereby nom	State Historic Preservation inate this property for inclu- riteria and procedures set for	sion in the National Reports by the Heritage Co	egister and certify	vation Act of 1966 (Public Law 89– y that it has been evaluated Recreation Service.
tate Historic Pres	servation Officer signature	Mith		5-1-85
tle	STATE HISTORIC PRE	SERVATION OFFICE	R	date
lu	lify that this property is incl lines Byen	uded in the National R Entered National		date 6-/9-fs-
Keeper of the Na Attest:	itional Register			date
Chief of Registra	tion			

OMB No. 1024-0018 Exp. 10-31-84

CARR-206

1

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Wilson's Inheritance
Continuation sheet Carroll County, Maryland

Item number

7

Page

GENERAL DESCRIPTION:

The property is located on the north side of Route 75, approximately one mile east of Union Bridge Road (Main Street in Union Bridge). The house sits back from Route 75 but originally was located close to the old turnpike road that passed through this section of the county. The site is gently sloping and the house constructed so that there is a full basement story on the main facade. The main facade of the house faces south.

The L-shaped brick structure is two-stories on a stone foundation. The main facade is six-bays wide while the west facade which contains the ell is four bays. The brickwork on the main facade is laid in Flemish bond. The other facades are laid in common bond consisting of five rows of stretchers between single rows of headers. Other brickwork includes a narrow corbelled brick cornice and a string course that runs under the windows, stopping short of the corners. There are three rectangular brick chimneys with rectangular openings in the tops of the stacks: one in the north end, one in the east end, and one west of center in the south section. The basement and first floor windows have segmental arches; the second floor windows are capped with a row of headers.

The windows in the south facade have louvered shutters while elsewhere the shutters are paneled. The original fenestration was nine-over-six pane sash on the first story and six-over-six sash on the basement and second story. The bottom sash in these windows has been replaced with single pane sash. The gable ends of the main section have two four-pane windows.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

CARR-206

For RFS was early

Relatived

Continuation sheet Wilson's Inheritance

Item number

7

Pege

2.

(DESCRIPTION continued)

The six-bay main facade has an interesting arrangement with an inset, double-tiered porch in the central two bays. Occasionally in this region, a house of this style will be found, although frequently the inset porch is at one end of the main facade or in an asymmetrical arrangement instead of the central location as found at Wilson's Inheritance. The inset bays are fenestrated as described above except for an entrance in the east bay of the first and second stories and for the east and central bays of the basement: the second bay from the east has a four-pane window and the central section has two square windows covered with iron bars.

The inset porch has four, evenly-spaced Roman Doric columns with half columns on the ends that are attached to the walls of the house. The first story porch railing has square balusters; the second story has a panelled railing with protruding square blocks where the columns are attached. There is a central flight of brick steps to the first story of the porch, and three doors leading off the porch: one in the east bay, and one in both of the side walls. Each door has a flat-arch fanlight with triangular section of molding in the top corners. The fanlights over the east and west side entrances have a stencil pattern covering the glass, and the fanlight over the door in the east bay has blue glass without muntins. The door jambs have single panels and a panelled soffit, with reeded molding around the jambs and between the door and fanlight.

On the west elevation, the basement is a full-story and constructed of brick. A porch across the middle two bays of the first story forms a columned portico at basement level. The columns supporting the porch are Roman Doric, and the first story railing has plain square balusters. The central two bays have six-panel doors with glass center panels. On the first story, the north central bay has a glass-paned door with a four-light transom. The door in the south central bay has been made into a window with a panelled transom.

The gable end of the north facade is unfenestrated except for two gable windows flanking the interior-end chimney. The stone foundation steps up towards the west on this side. The outlines of a projecting bake oven were visible in the basement level above the foundation and the current owner had a beehive bake oven reconstructed in 1980.

The inner side of the ell has a one-story porch running along one-bay of the ell and two bays of the north facade of the main block. The porch appears to be an original feature of the house although it has recently been reconstructed. The ell has a entrance under the porch and six-over-six sash windows in the other bays. The north facade of the main section has three bays on the first story and two bays on the second story. Each of these bays have windows except for an entrance in the central bay. Both of the entrances under the porch have plain jambs, stone sills and segmental arches. The east gable end of the main section has two four-pane windows in the gable.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

CARR-206

Continuation sheet Wilson's Inheritance

Hem number 7

Page 3

(DESCRIPTION continued)

The interior plan conforms to the exterior appearance of the house. The inset section of the main facade is laid out for two small rooms of which one is an entrance foyer with a stairway. Off each end of the inset section are large rectangular-shaped rooms—a parlor on the east side and a dining room on the west side. The ell contains a kitchen but appears to originally been partitioned into two rooms. Along with the main stairway, there are corner stairs in the dining room and ell kitchen. There are fireplaces in the parlor, dining room and a large hearth in the kitchen.

The first story kitchen has its original hand-cut oak floor. Now a kitchen, at one time it may have been divided into two rooms by a wall on the west side of the fireplace. On the north wall, the fireplace is flanked on the west by a cupboard and on the east by a storage closet and a corner staircase. The fireplace has a wooden beam above the rectangular opening, a plain surround, and a molded cornice under the shelf. The cupboard, closet, and staircase doors all have handmade butt hinges. The double-leaf cupboard doors with handmade knobs have two panels in the top and one in the bottom section. The storage closet has a beaded board-and-batten door and the six-panel staircase door has a handmade latch. The surbase and subbase of the baseboard are molded. There are four doors in the room: two lead into the rooms in the main block and two lead outside (one on the east wall and one on the west wall).

The door on the west enters the dining room next to that room's corner staircase, which is enclosed with beaded vertical-board walls. On the east wall is a fireplace flanked on the north by a glass-paned door to the central room and on the south by a door to the front inset porch. The fireplace is off-center in the chimney breast. It has deep molded cornice, a plain frieze, reeded-end blocks with triangular-shaped insets of horizontal reeding at the top and bottom, an architrave of three reeded bands; reeded Roman Doric quarter columns, and a square brick opening with a plain surround. The opening probably had some kind of facing, as there is a space between the mantelpiece and the brick. There is a plain base-board and a chairrail with a rounded shelf, fillet and a beaded bottom.

The east central room is a narrow space with one window at each end. The north corner of its east wall has a six-panel door leading into the stairhall and the south corner has a flat-arch doorway. The molded trim around the arch is different from that in the rest of the house. The stairhall side of the arch also has trim that is different with beaded edges and a strip of reeding down the center. The anomalous trim and the projection of the staircase beyond the opening suggest the arch was added later.

United States Department of the InteriorNational Park Service

National Register of Historic Places Inventory—Nomination Form

CARR-206

For 1975 time step

Pacifical

State state of

Continuation sheet Wilson's Inheritance

Item number 7

Page 4

(DESCRIPTION continued)

The staircase hall doors lead to the back porch and to the front porch. Against the west wall is an open-well staircase with two flights and a landing. The open-string stairs have square balusters, a turned newel post, and scrolled ogee brackets. There is a door to the basement underneath the stairs in the rear.

The parlor contains an excellent example of a rural Victorian-style interior through a late nineteenth century remodeling that includes marbelized trim and grained woodwork. The fireplace is in the center of the east wall and is marbelized with a black U-shaped shelf, an ovolo cornice, stepped-bed molding, panelled-end blocks and frieze, (the latter is set in a black frame), black Roman Doric double columns on plain square bases, a marbelized surround with beaded trim, and a plaster opening. The molded trim on the door and windows is uniform with circular designs in the corner blocks. Both doors have grained panels, panelled jambs and soffits. The door to the hall has a grained transom panel. The subbase of the baseboard is bevelled out from the top section.

The plan of the second floor is similar to the first floor except that the main block has been divided into three rooms: one on the east side and two on the west. The stairs that descended from the east room into the kitchen have been blocked up, and the south room has been made into a bathroom. The window trim is the same as in the rest of the house, and there are plain baseboards. Ornamental features of the second floor include a six-panel door with painted graining, and a corner staircase railing with square balusters and a squared rail, four-pane transom with patterned glass in the door to the front porch, and Victorian-style trim in the east bedroom.

The east bedroom has the same dark trim with corner blocks as the room below it except that the window trim is simpler and has trapezoidal sills. The six-panel door is grained. The fireplace design is like the one on the first floor but has single columns; the frieze is deeper and projects over the opening; and the opening surround is a plain wide band.

The basement consists of one room in the north section and three rooms and a central hall in the south section. All interior walls are brick, and the exterior walls are brick and stone. The north room was probably the original kitchen. In the west corner of the north wall is a corner staircase, and the rest of the wall contained the fireplace. (The fireplace beam is fourteen feet long.) The west end of the fireplace which contains brickwork for the exterior bake oven retains the original iron door. There is a brick partition between this part of the fireplace and a storage space to the east. Wooden doors cover all the openings in the north wall. In the south wall is a panelled wainscot with a beaded shelf and doors in the center and east corner to the south section. The center door has six panels and leads to the southwest room.

CARR-206

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPE may sally received Mate entered

Continuation sheet

Wilson's Inheritance

Item number

Page

5

(DESCRIPTION continued)

The southeast basement room appears to have served as a summer dining room in the original plan. There is a winder staircase in the northwest corner end a fireplace in the center of the east wall. The fireplace has a plain shelf, a molded cornice, a panelled frieze, fluted pilasters on plain block bases with diagonally reeded capitals, and a plain surround. The rest of the south section was not lived in. It consists of a central "hall" in the north with a small central room to the south and a furnace room to the east. The south room has a board-and-batten door with handmade nails and strap hinges. The furnace room has two brick cisterns in the northwest corner, with a hole in the brick pier next to it that is in line with a hole in the east wall--perhaps for a well-supplied water system.

The property contains several significant outbuildings, all of which contain original hardware. North of the house and placed diagonally to it is a two-story square smokehouse built into a slope. The brick is laid in common bond with six (sometimes seven) rows of stretchers to each row of headers. In the south end there is a stepped stone foundation and near the top are four ventilating holes in a diamond pattern. In the first story of the west side and in the second story of the east side are beaded board-and-batten doors with pegged frames and handmade strap hinges, nails, and latches. Inside, most of the floor joists have been replaced, but one full log joist remains.

North of the smokehouse is a two-story washhouse (two rooms long and one room deep) built over a spring. The building has a stone foundation, a gable roof and an interior-end chimney in the south end. The springhouse is built into the side of the hill, so the basement is at ground level and the main floor is entered from the top of the hill. Both exterior doors are board-and-batten with handmade latches and strap hinges. All windows are six-over-six pane each and the molding, including the interior and exterior window and door trim as well as the baseboards, is beaded. The basement level has two rooms opening on to a hall that runs the length of the east side. The south room has a large fireplace and the north room contains a water trough fed by the spring which indicates that this room probably functioned as a dairy. The main floor has a hall and parlor plan with a fireplace in the south room and beaded baseboards in both rooms.

North of the springhouse is a brick neccessary that has had extensive masonry reconstruction.

A stream separates the farmhouse and these outbuildings from the other farm buildings on the property. The stream has been dammed to provide a function to the farm operation. There is also a well in front of the washhouse which once was used to pump water to the barn.

CARR-206

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For 1875 was stilly received Sate enlared

Continuation sheet Wilson's Inheritance

Item number

7

Page 6


(DESCRIPTION continued)

A group of buildings extend in a straight line west from the stream towards the barn. These include a frame shed with a pigeon house (also north of this shed are two chicken houses), a frame tool house with louvered windows, an extended frame wagon shed, and a brick blacksmith shop with an attached vertical board shed. The blacksmith shop is constructed of stretcher bond on a stone foundation. It has a board-and-batten door on the east wall and an interior-end chimney on the west wall.

South of this line of buildings is a frame bank barn that appears to have been rebuilt in the late 19th century. The rafters of the barn roof each contain two wood sections which indicate the possibility that the rafters of an earlier, smaller barn were reused in the construction of this barn. Also the ventilator trim uses a design that was popular during the late nineteenth century. The south gable end has a large gable ventilator window with a panel that contain the initials "FJE" (two Frank J. Englars owned the property from 1875 to 1974). The forebay faces southeast and has a large fenced barnyard. At the northeast corner of the barnyard is a carriage shed. At the southwest corner of the barn is the base of a brick silo and a frame sheep shed. Just west of the barn is a large wagon shed.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Wilson's Inheritance

Item number

8

Page '

(SIGNIFICANCE continued)

reflected through architecture was continued through the nineteenth century as shown in the rural Victorian style parlor of the house with its marbelized mantel and grained woodwork. A similar impression is given in the bank barn which was enlarged and ornamented by the Englars during the late nineteenth century.

The presentation of the outbuildings and their retention of period hardware are also significant features of the farm complex. These building possess many features that provide evidence of the daily life of residents in this agricultural region. Immediately behind the house is a two-story brick smokehouse, a two-story brick washhouse built atop a spring, and a square brick privy. West of this grouping is a straight line of farm buildings and sheds including a tool shed and a blacksmith shop. Also, grouped around the bank barn is a wagon shed, sheep shed, carriage shed and base of a brick silo. Many of the doors to these sheds contain wrought strap hinges, wrought thumb latches, and other wrought hardware which was probably made in the blacksmith shop on the farm.

The Englar family was typical of a large segment of Carroll County's first settlers, being part of the group that left the Swiss-German Palatinate region in the early eighteenth century, sailed to Philadelphia, and then moved west and south settling Lancaster and York counties in Pennsylvania as well as sections of central Maryland and the Valley of Virginia. The first Englar, Philip, to settle in Maryland moved from Chester County, Pennsylvania, to the Uniontown area (presently Carroll County) in 1764. His decendants were prominent in the farming and agricultural-related industries throughout this section of the county. The Englar family was primarily responsible for the development of Linwood (a National Register Historic District) as a railroad depot and village. Linwood is located one mile east of Wilson's Inheritance and the five Englar houses there date from 1866 to 1900, the same period when Francis J. Englar moved to Wilson's Inheritance.

Francis J. Englar was a fifth generation Englar in Carroll County (Philip-David--Joseph--William--Francis J.). He is listed as a patron in the 1877 Atlas of Carroll County as a farmer and dairyman. His farm reflects his prosperity from his occupation and his interests in maintaining an effecient and up-to-date farming operation. Francis J. Englar was born February 5, 1853 and died in October 1921. His farm passed to his son, Francis J. Englar, Jr., who continued the farm and dairy operations until his death in 1974.

Continuation sheet

CARR-206

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

Wilson's Inheritance Carroll County, Maryland

Item number 9 and 10

For NPS use only received date entered

Page

8

MAJOR BIBLIOGRAPHICAL REFERENCES:

Barnes, Vivian Englar. History of the Englar Family. Taneytown, MD: Carroll Record, 1929.

1877 Atlas of Carroll County.

Linwood Historic District National Register Nomination form.

Land Records of Carroll County.

Interviews with current owner, Emil H. White.

GEOGRAPHICAL DATA:

Verbal Boundary Description/Boundary Justification:

The nominated property, approximately 21 acres, encompasses all elements of the resource within their immediate historic rural setting. Boundaries are depicted on the attached USGS quad map, and are defined by Maryland Route 75 on the south, a branch of Little Pipe Creek on the west, and the 440' contour line on the northwest and northeast. Boundaries were selected based on the visual effect of rising topography, which encloses the house, outbuildings, and farmyard on the northwest and northeast, and that of Maryland Route 75, a modern highway on the south.

LAKK- AUG

431

CAKR - 206 Wilson's Inheritance, 1837-38 Union Bridge vic.

Drawn by Natalie Shive