



86 A136

Joslin Farm
Waitsfield, Vermont
Credit: Trish Bensinger
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Barn and farmhouse

View looking southeast.

Photograph 1



Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Joslin Farmhouse

View looking northeast.

Photograph 2

88-A-156



28 A-156

Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Joslin Farmhouse

View looking southeast.

Photograph 3



Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Main entrance to
Joslin Farmhouse
View looking northeast.

Photograph 6

88-A-156



86A136

Joslin Farm
Waitsfield, Vermont
Credit: Trish Bensinger
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Interior, Joslin
Farmhouse, entry hall door trim

Photograph 7



86A136

Joslin Farm
Waitsfield, Vermont
Credit: Trish Bensinger
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Interior, Joslin
Farmhouse, window trim

Photograph 8



86 A 136

Joslin Farm
Waitsfield, Vermont
Credit: Trish Bensinger
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Interior Joslin
Farmhouse, plaster ceiling
medallion

Photograph 9



88A-156

Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Joslin Carriage Barn
E11
View looking east.
Photograph 4



88-A-156

Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Rear of Joslin
Farmhouse
View looking southwest.

Photograph 5



86A 136

Joslin Farm
Waitsfield, Vermont
Credit: Trish Bensinger
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Joslin Round Barn

View looking east-southeast.

Photograph 10



Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Joslin Round Barn
during restoration
View looking northwest.

Photograph 11

88-A-156



86A136

Joslin Farm
Waitsfield, Vermont
Credit: Trish Bensinger
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Interior, Joslin Round
Barn, 1st floor cow stanchions

Photograph 12



86A/136

Joslin Farm
Waitsfield, Vermont
Credit: Trish Bensinger
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Interior, Joslin Round
Barn, 2nd floor framing, central
silo and cupola

Photograph 13




88A-156

Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Joslin Farm Field Barn

View looking northwest.

Photograph 14




88-7-156

Joslin Farm
Waitsfield, Vermont
Credit: David Tansey
Date: July 1988
Negative filed at Vermont Division
for Historic Preservation
Description: Joslin Farm Field Barn

View looking northeast.

Photograph 15



88-A-156

Joslin Farm

Waitsfield, Vermont

Credit: David Tansey

Date: July 1988

Negative filed at Vermont Division
for Historic Preservation

Description: Joslin Farm Ice House

View looking southeast.

Photograph 16