1. Historic Name(s) Pat Lyddan House		Lincoln' Trail/Wash.	1115
Original Owner		23. U.S.G.S. Quadrant (15'/75')	G.I.S. Mod.
		Maud	
- 2. Present Name Ed Yocum Place		24. UTM Reference	
3. Location	71,61 (5,3,4,2,0) 4,1,8	3,3,8,1,01	
E sd. Hwy 55, 10 m, N. of Springfield			Vorthing
4. Owner's Name John Edward Keeling		25. Coordinate Accuracy	1 1
S. Owner's Address Rt. 3B, Springfield, Ky.	26. Prehistoric Site Object Historic Site Struct		
6. Open to Public 7. Visible from road X	8. Ownership	Building Other	
Yes No Yes No	X	27. National Register District Name:	
9. Local Contact/Organization	Private	N/A	
	State	IN/A	1
Owner	Federal	28. Significance Evaluation	
10. Site Plan with North Arrow	11. Architect	NR	N
	unknown	29. Status Date	
X + [~~]	12. Builder	National Landmark	
	· unknown · · ·	National Register	
	13. Date	Landmark Certificate	
	1853* A. 4 B.	Kentucky Survey	
	14. Style	Local Landmark	
	A.Grk. Rev.	HABS/HAER	
 	B	30. Historic Theme Architectur	٠ ال
	15. Original Use	Primary ATCITTECTUI	
	Sing. fam. res. A	Secondary	
	16. Present use	⊣ ~	1 1 1
	10. Present use	Other	
ဆုံးမှ ေမေး မေဆ မေးကို	As above	31. Endangered	Yes
ģ;;··· s ········ ò	As above	31. Endangered	Yes X
<u>ά</u> γ,··· ຍ ······ ά	As above	31. Endangered 32. Preservation Project Status	X
18. Description	As above 17. Condition Good B	31. Endangered	X
3 bay, 2 story, log	As above 17. Condition Good No. Stories 2	31. Endangered 32. Preservation Project Status N/A	X
<pre>3 bay, 2 story, log w/single story ell;</pre>	As above 17. Condition	31. Endangered 32. Preservation Project Status N/A	X
<pre>3 bay, 2 story, log w/single story ell; double windows on</pre>	As above 17. Condition	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
<pre>3 bay, 2 story, log w/single story ell; double windows on facade; name plate over</pre>	As above 17. Condition	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
<pre>3 bay, 2 story, log w/single story ell; double windows on</pre>	As above 17. Condition GOOD No. Stories 2 Single Pile X Double Pile Floor Plan Sing.p./cent.p. []	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en-	As above 17. Condition Good B No. Stories 2 Single Pile X Double Pile NA Floor Plan Sing.p./cent.p. Structural Fabric	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central entrance w/sidelights,	As above 17. Condition Good B No. Stories 2 C Single Pile X Double Pile Floor Pian Sing. p./cent.p. Structural Fabric	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central entrance w/sidelights, corner lights, transom,	As above 17. Condition Good B No. Stories 2 Single Pile X Double Pile Floor Plan Sing.p./cent.p. Structural Fabric Log Decorative Fabric Weatherbd. A. J	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central entrance w/sidelights, corner lights, transom, pilasters and shouldered	As above 17. Condition Good B No. Stories 2 Single Pile X Double Pile Floor Plan Sing. p./cent.p. I Structural Fabric Log Decorative Fabric Weatherbd. A	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central entrance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch	As above 17. Condition Good B No. Stories 2 C Single Pile X Double Pile Floor Pian Sing. p./cent.p. I Structural Fabric LOg A. A. B. Decorative Fabric Weatherbd. B.	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central entrance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over)	As above 17. Condition GOOD No. Stories 2 Single Pile X Double Pile Floor Pian Sing.p./cent.p. I Structural Fabric LOG Decorative Fabric Weatherbd. B Roof Form	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back)	As above 17. Condition Good B No. Stories 2 C Single Pile X Double Pile Floor Pian Sing. p./cent.p. I Structural Fabric LOg A. A. B. Decorative Fabric Weatherbd. B.	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back)	As above 17. Condition GOOd No. Stories 2 Single Pile X Double Pile Floor Plan Sing.p./cent.p. I Structural Fabric LOG Decorative Fabric Weatherbd. B. Roof Form Gable end	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou	As above 17. Condition GOOd B No. Stories 2 C Single Pile X Double Pile Floor Plan Sing.p./cent.p. Structural Fabric Log A B Roof Form Gable end se 1853. John	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned	As above 17. Condition Good B No. Stories 2 Single Pile X Double Pile Floor Plan Sing.p./cent.p. I Structural Fabric Log A B Roof Form Gable end se 1853. John the land c. 1800.	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned Thomas built a log struc	As above 17. Condition GOOD No. Stories 2 Single Pile X Double Pile Floor Pian Sing.p./cent.p. I Structural Fabric LOG A A B Decorative Fabric Weatherbd. A B. Roof Form Gable end se 1853. John the land c. 1800. ture in the field	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO Roll No	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned Thomas built a log struc behind the present house	As above 17. Condition GOOD No. Stories 2 Single Pile X Double Pile Floor Plan Sing.p./cent.p. [] Structural Fabric LOG A. A. B Decorative Fabric Weatherbd. B Roof Form Gable end se 1853. John the land c. 1800. ture in the field . Lyddan married	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO Roll No	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned Thomas built a log struc behind the present house one of Thomas daughters	As above 17. Condition Good B No. Stories 2 C Single Pile X Double Pile Floor Pian Sing.p./cent.p. LOG A B Decorative Fabric Weatherbd. B Roof Form Gable end se 1853. John the land c. 1800. ture in the field Lyddan married and lived (over)	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO Roll No	X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned Thomas built a log struc behind the present house one of Thomas daughters	As above 17. Condition Good B No. Stories 2 C Single Pile X Double Pile Floor Pian Sing.p./cent.p. LOG A B Decorative Fabric Weatherbd. B Roof Form Gable end se 1853. John the land c. 1800. ture in the field Lyddan married and lived (over)	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO 14 Roll No	No_X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned Thomas built a log struc behind the present house	As above 17. Condition GOOd P No. Stories 2 Single Pile X Double Pile Floor Plan Sing.p./cent.p. Structural Fabric Log A B Roof Form Gable end se 1853. John the land c. 1800. ture in the field . Lyddan married and lived (over) cant under criterion C,	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO Roll No14 Picture No1A/2-16 Direction 34. Prepared by: Joe DeSpain	No_X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned Thomas built a log struc behind the present house one of Thomas daughters 20. Significance This property is signifi	As above 17. Condition Good B No. Stories 2 C Single Pile X Double Pile Floor Plan Sing.p./cent.p. LOG A. A. B. Decorative Fabric Weatherbd. B. Roof Form Gable end se 1853. John the land c. 1800. ture in the field Lyddan married and lived (over) cant under criterion C, houses from the period	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO Roll No	No_X
3 bay, 2 story, log w/single story ell; double windows on facade; name plate over central door shows CONTINENTAL, NEW YORK; recessed central en- trance w/sidelights, corner lights, transom, pilasters and shouldered architrave; Vic. porch added; dentil work(over) (Continue on Back) 19. History Pat Lyddan built the hou Thomas (See WS-95) owned Thomas built a log struc behind the present house one of Thomas daughters 20. Significance This property is significant the most interesting of 8 log I- an the county. Unusual are the do	As above 17. Condition Good B No. Stories 2 C Single Pile X Double Pile Floor Plan Sing.p./cent.p. LOG A A B Decorative Fabric LOG Weatherbd. B. Roof Form Gable end se 1853. John the land c. 1800. ture in the field . Lyddan married and lived (over) cant under criterion C, houses from the period uble windows and fine	31. Endangered 32. Preservation Project Status N/A Actual Cost in \$1,000s 33. ATTACH PHOTO 14 Roll No	e., Inc.

DESCRIPTION: (cont.) under eaves; internal end chimneys; INTERIOR: central stairs is dog-leg variation w/three landings; shouldered architrave; Grk. Rev. mantel w/fluted pilasters in E. rm.; Grk. Rev. mantel w/heavy shelf and pilasters in W. rm. and in ell.

HISTORY: (cont.) in the log structure 1850-1853 until he built the new house. Thomas' died 1849. Lyddan obtained Thomas' land and sold the land where WS-95 sits to John Able Thomas.




KENTUCKY HISTORIC RESOURCE INVENTORY SUPPLEMENT BOUNDARY AND LOCATION INFORMATION

Historic Property Name Pat Lyddan Ho	ouse	Site #WS-96	
Multiple Resource/Thematic Nomination 7	Title <u>Washi</u>	ngton County Multiple Resou	ırce Area
U.T.M. Coordinates - List multiple UTMs	s if property	is ten or more acres.	-
A. <u>16</u> <u>653420</u> <u>4183810</u>	D		
В	E		
C	F		
Verbal Boundary Description	Acreage	0.23 acre	

Beginning at point A on the north side of Ky 55, north with a fence 80 feet to point B, west along fence 125 feet to point C on drive on west side of house, south along east side of drive 80 ft.to point D, thence 125 feet east on side Ky 55 to point of origin. The boundaries were drawn to include the house and domestic-related space as enclosed by fences and the highway. There are no outbuildings.

The nominated area includes one contributing building.

Sketch of Site Plan (Showing outbuildings, structures, landscape features and the site boundary as described above.)



Official Courthouse Property Reference:

Washington County Courthouse, Springfield, Kentucky