



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

View: nw.

Malheur Co., OR

Corrals and bottomlands

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River
Malheur Co., OR

Corrals and Barn

View: nw.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Owyhee River

view: n down the Owyhee River.

Waterwheel

Malheur Co., OR

Stephen Dow Beckham

22 July 1988

Negatives with Photographer



Birch Creek Ranch Historic Rural Landscape

Corrals and barn, tack building

Malheur Co., OR

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River
View: ne.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Sec. 18

T27S, R43E, W.M., Birch Creek,
Owyhee River

Malheur Co, OR

Eastlake Door in Bunkhouse/Shop
(one of two such doors in this
building)

Stephen Dow Beckham
22 July 1988

Birch Creek Ranch

Historic Rural Landscape

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Foundations (?) of outbuildings

View: w.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Barn, W (side) and S (front/end) elevations

View: nw.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Stone Walls on east face of mesa descending toward
Birch Creek

View: se

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Chicken House, E (front) and S (side) elevations
(semi-subterranean with massive stone foundation)

View: sw.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 18, Birch Creek, Owyhee River

Malheur Co., OR

Tack Building, W (front) and S (side) elevations
View: ne.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

House #1, E (front) elevation and N (side) elevation

View: sw.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Stone walls in headquarters area of ranch.

View: nw.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

House #1, South (side) and W (rear) elevations

View: nw.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

House #2, Rust (Martin), Jr., E (front) and N (side)
elevations

View: sw.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

House #2, Rust (Martin), Jr., E (front) and S (side)
elevations

View: nw.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Generator Building, E (front) and S (side) elevations

View: sw.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Bunkhouse and shop, E (front) and south (side)
elevations

View: sw.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

Rust (Martin), Jr., Guest Cottage, S (front) and
E (side) elevations

View: sw.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

Corrals

View: sw.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

Ruins of stone house at base of mesa

View: e.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 01 Rust (Martin) outhouse, west (front) and north (side) elevations, T27S, R43E, Sec. 7, U.I.

Malheur Co., OR

22 July 1988

Stephen Dow Beckham

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

Ruins of stone house at base of mesa

View: s.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, W.M., Owyhee River
Sec. 7

Malheur Co., OR

Equipment Midden

View: e.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



T27S, R43E, Sec. 18, W.M.,
Owyhee River

Malheur Co., OR

Detail of waterwheel

View: nw.

Stephen Dow Beckham
22 July 1988

Birch Creek Ranch
Historic Rural Landscape
Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Owyhee River

Malheur Co., OR

Waterwheel and view up the Owyhee toward Birch
Creek in Sec. 18. View: s. up the Owyhee.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Owyhee River

Malheur Co., OR

View: n.

Waterwheel and flood debris on Owyhee River

Stephen Dow Beckham

22 July 1988

Negatives with Photographer



Sec. 18

T27S, R43E, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Cistern : east elevation.

View: w.

Stephen Dow Beckham

22 July 1988

Birch Creek Ranch Historic Rural Landscape

Negative with Photographer



T27S, R43E, Sec.18, W.M., Birch
Creek, Owyhee River

Malheur Co., OR

Outhouse : east (front) and south
(side) elevations. View: sw.

Stephen Dow Beckham
22 July 1988

Birch Creek Ranch
Historic Rural Landscape
Negatives with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 06 Grindstone from Jim Morison's tenure on
side of garage, T27S, R43E, Sec. 7, W.M.

Malheur Co., OR

22 July 1988

Stephen Dow Beckham

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Dressed stone cooler/root cellar, E (front) elevation

View: w,

Malheur Co., OR

Stephen Dow Beckham

22 July 1988

Negatives with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

Corrals

View: n.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek at the
Owyhee River

View east looking down the Owyhee a the mouth of
Birch Creek.

Malheur Co., OR

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 18, W.M., Birch Creek, Owyhee River

Foundation stones of former outbuildings

View: w.

Malheur Co., OR

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 08 Illuminated beef head (with woodpecker nest in right eye) mounted on garage, T27S, R43E, Sec. 7, W.M.

Malheur Co., OR

22 July 1988

Stephen Dow Beckham

Negative with Photographer



Sec. 18

T27S, R43E, W.M., Birch Creek, Owyhee River

Malheur Co., OR

Dressed stone cooler/root cellar E (front) elevation
and south (side) elevation.

View: sw.

Birch Creek Ranch Historic Rural

Stephen Dow Beckham

22 July 1988

Landscape

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 05 Singletrees from Jim Brisson's tenure
on west (rear) elevation of garage, T27S, R43E,
Sec. 7, W.M.

Malheur Co., OR

22 July 1988

Stephen Dow Becknam

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 07 Hames on west (rear) elevation of
garage, from Jim Morrison's tenure, T27S, R43E,
Sec. 7, W.M.

Malheur Co., OR
22 July 1988)

Stephen Dow Beckham

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 04 Remains of stone corral #2, located between bottomland and bluffs near base of dry waterfall, T27S, R43E, Sec. 7, W.M.

Malheur Co., OR

22 July 1988

Stephen Dow Beckham

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

One of several mortars, dime to left of pestle.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



T27S, R43E, Sec. 7, W.M., Owyhee
River

Birch Creek Ranch
Historic Rural Landscape
Geological formation at ruins
of stone house.

View: se.

Malheur Co., OR

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape
T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

Garage and blacksmith shop, S (front) and E (side)
elevations.

View: nw.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 00 Rust (Martin) Outhouse, east (rear) and north (side) elevations, T27S, R43E, Sec. 7. N.W.

Malheur Co., OR

22 July 1988

Stephen Dow Beckham

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. 03 Remains of stone corral #1, located between bottomland (alfalfa field of ca. 60 acres) and rocky bluff area, T27S, R43E, Sec. 7, W.M.

Malheur Co., OR

22 July 1982

Stepnen Dow Beckham

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

"Stud Barn," converted into the "Honeymoon Cottage"
West (front) and south (side) elevations.

View: ne.

Stephen Dow Beckham
22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

T27S, R43E, Sec. 7, W.M., Owyhee River

Malheur Co., OR

Dressed stone cooler/root cellar /Guest Cottage/,
E (front) and N (side) elevations.

View: s.

Stephen Dow Beckham

22 July 1988

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. xx Rust (Martin) Hangar, East (front) and
south (side) elevations, T27S, R43E, Sec. 7,
W.M.

22 July 1988

Stephen Dow Beckham

Malheur Co., OR

Negative with Photographer



Birch Creek Ranch Historic Rural Landscape

Neg. J2 Bureau of Reclamation tramway, erected
1942, Chris Latt in car, T27S, R43E, Sec. 7,
H.H.

Malheur Co., OR

22 July 1988

Stephen Dow Beckham

Negative with Photographer