


**United States Department of the Interior
National Park Service**

**National Register of Historic Places
Inventory—Nomination Form**



Continuation sheet

Item number 1, 4, 7, 8, 10 Page 99

#249 Miguel Valdez Barn, ill. 118, 50 yards E of San Joaquin Church Loop Road (east) and 140 yards S of Ensenada Headgate Road. Ensenada, NM.

4. Owner: Miguel Valdez, Box 62, Tierra Amarilla, 87575

7. Description: three rectangular modules of horizontal logs with double saddle notches; spanned by log beams; covered by planks covered with hay. Double post and rail corral extends c. 20 feet in front (NE) of barn.

Located in a field east of Ensenada near the southeast corner of the village's irrigated fields.

8. Significance: Perhaps built in the 1920's, this barn is one of the best local examples of Hispanic modular barn construction. It is one of the few shed-roofed barns in the area; most have received gabled metal roofs against the heavy winter snows.

10. Acreage: under 1. UTM Ref: 13 363450 4065300

Boundary: A rectangle, roughly 80' by 40', formed by a line parallel to and ten feet from the barn walls. Since this property is unplatted, the boundary has been drawn tightly to include only the historic structure.