



Nº 1 in a set of 5

EDIFICIO OLIVER

JOSE DE DIEGO AVE. ARECIBO, P.R.

PHOTOGRAPHER MARNY LINARES

DATE OF PHOTO MARCH 1986

NEGATIVES AT P.R.S.H.P.O.

MAIN FACADE, DE DIEGO AVE. & CORREGIMIENTO



EDIFICIO OLIVER

JOSE DE DIEGO AVE. ARECIBO, P.R.

PHOTOGRAPHER MARNY LINARES

DATE OF PHOTO MARCH 1986

NEGATIVES AT P.R.S.H.P.O.

CALLEJON DEL CORREGIMIENTO FACADE

Nº 2 in a set of 5



EDIFICIO OLIVER

JOSE DE DIEGO AVE. ARECIBO, P.R.

PHOTOGRAPHER MARNY LINARES

DATE OF PHOTO MARCH 1986

NEGATIVES AT P.R.S.H.P.O.

NORTH WEST CORNER DETAIL

N^o 3 in a set of 5



EDIFICIO OLIVER

JOSE DE DIEGO AVE. ARECIBO, P.R.

PHOTOGRAPHER MARNY LINARES

NEGATIVES AT P.R.S.H.P.O.

SECOND FLOOR DETAIL

N^o 5 in a set of five



EDIFICIO OLIVER

JOSE DE DIEGO AVE. ARECIBO, P.R.

PHOTOGRAPHER MARNY LINARES

NEGATIVES AT P.R.S.H.P.O.

FIRST FLOOR DETAIL

N^o 4 in a set of 5