United States Department of the Interior **National Park Service**

National Register of Historic Places Inventory—Nomination Form

Murray Kentucky Continuation sheet Multiple Resource Item number 7

Name: First Baptist Church

Owner: First Baptist Church

Location: 203 S. 4th St. Murray, KY 42071

Classification: Building

Description: Constructed at the same time as the neighboring Murray Post Office, the First Baptist Church shares that building's decorative brickwork. The church's most distinctive feature is the beautiful orange and blue glazed brick used in the construction and decoration of the exterior. The two-story sanctuary of the church rest on a raised basement level. A beltcourse of decorative brickwork marks this basement level. A monumental flight of steps leads up to a recessed porch where double entrances lead to the sanctuary. Double brick piers support the three ogee arches defining the top of the entrance porch. Above this recessed porch are a pair of double stained glass windows that provide light to the sanctuary. Other stained glass windows on the facade rise with the double interior staircases to the balcony in the sanctuary. Another beltcourse of decorative brickwork and a stone cornice run across the top of the building. Rising above this is a parapet wall containing diamond panels of blue glazed bricks.

Two sides of the church have large stained glass windows with double panes of glass and a transom pane. Each window bay is divided from the next by a brick pilaster. Continuing on the sides of the building are several details from the facade, such as the basement level beltcourse, the stone cornice, and the parapet wall with the diamond panels of blue glazed bricks.

The 1958 addition to the church is very harmonious to the main building due to the careful matching of materials and details. This addition runs across the rear of the original church to create an L-shaped building. The addition has similar glazed brick, brick pilasters, and a stone cornice as the main building. This addition is mainly devoted to classrooms and meeting places.

Also on the property is a structure constructed in 1931 as a residence for the church's minister. This structure is a simple bungalow constructed of bricks matching the church. This building is now used for a church office.

Also running along a portion of the northern property line of the church is a cast iron fence that once was part of the fencing that surrounded the town square until 1906.

For NPS use only 9 1986 received JAN date entered

Page 8

OMB No. 1024-0018 Expires 10-31-87

NPS Form 10-900-a (3-82)				1024-0018 10-31-87
United States Department of the Inte National Park Service	rior		For NPS use only	
National Register of Hist Inventory—Nomination F		S	raceived date entered	
First Baptist Church, Murray, Kentucky Continuation sheet Multiple Resource Area	Item number	7	Page	9

<u>Significance</u>: The First Baptist Church of Murray is significant under Criterion C because it exhibits high artistic values in its exterior detailing. Although this eclectic building does not have significance as a type or style or architecture, it contains highly decorative brick work which is very uncommon in the region. Of particular interest is the corbelling in the entrance arch and the lozenge patterns in the parapet. The use of vertical brick in the belt courses indicate a creative use of a common building material during a period of economic hardship when institutions could not afford more expensive materials.

The church was founded in Murray in 1846. The first frame church was constructed in 1848 at a cost of \$440. A second church was built in 1901 at a cost of \$5,500. The monumental brick structure built by the First Baptist Church in 1931 was a testament to the strength of the congregation. Construction began on the structure in 1931 and wasn't completely finished for two years. The cost of \$130,000 was covered by a free-will offering under a "faith plan" type of budgeting. This type of financing kept the church free from debt at all times during the construction. This is especially remarkable considering the economically depressed period.

A 1931 history of Murray reports that First Baptist Church "worships in a beautiful and commodious building next to the government building now being erected. This church building is one of the most magnificent in Western Kentucky." The church was formally dedicated on October 25, 1958. A \$196,000 addition to the rear of the church was formally opened on June 22, 1958. The addition was harmonious to the original design of the church and enlarged the main auditorium to 1600 seats.

The pride of the congregation is reflected in the superb maintenance of the building. The congregation recently erected a historic marker in the front of their church explaining the history of the church.

Acreage: Approximately .75 acres.

UTM References: (Murray Quadrangle) 16/383620/4052100

<u>Verbal Boundary Description</u>: The First Baptist Church is located on the accompanying Murray tax map as Lot 3, Block 4.

KENTUCKY	HISTORIC RESOURC	ES INV	VENTORY (1)a	-B - 180
1. Historic Name (s) First Baptist Church			22. ADD/County	
Original Owner Trustees			23. Zoning Classification	
Present Name	1 1012*		Magisterial District	
First Baptist Ch 3. Owner's Name	urch - 1913		24. U.S.G. S. Quadrant (1) Bowling (51751 South
Toustees			25, UTM, Reference Wi	
4. Owner's Address 1216 Sta Chestny	t St.		Zone Eas	ting Northing
5. Location	che th 541216 54	L	26. Prehistoric Site	Object
6. Open to Public 7. Visible from road	8. Ownership		Historie Site Building	Structure
(Yes) No (Yes) No	Private	X,	27. District Ye	
9. Local Contact/Organization	Local State		Name: College	e Hill
	Federal		28. Significance Evaluation	
10. Site Plan with North Arrow	Creedmore He	tehor	Kentucky Surv 29. Status	Date
	12. Builder		National Landmark	
	13. Date		National Register Landmark Certificate	
	1913-1915		Kentucky Survey	
	Roman Revival	7	Local Landmark HABS/HAER	
	15. Original Use		30, Theme	
	religious Mectina 16. Present Use	5	Primary Veligi Secondary Qrch	ecture
	religious meetin	95	Other	
	17. Condition		31. Endangered	No X 410
	Exterior good/excelle	nt	32. MODAK SAFETY	
18. Description 2-story stone; crucito	- 1 1	an		
Baths window units as princi 3 fronts. pyramidal roof a	bove clerestor.	sn		
			Kolt	
portico, pilasters other two site in district	tronts. Key			
sire in district				
-	- 2 • • • •	-		Contraction of the second s
19. History # 1 The original Baptist 1818 - Called the United Bapt	Church was orga	anizod	L HER	
vouce was on the corner of Cer	her and Main	. 1	194 F	
Streets. The second one wasbuilt in 1854 . Thepresent building was begun in 1913 - It is constructed of				
Warren County Line stone	+ 15 cons avuese	aor	Roll	
·			Picture No.	
+ Designed by Creedmore Fleenor				Rolls 11+46
20. Significance The First Baptist Chur	ch was organized	d initi	33. Tape No.	Negative No.
one year before any other congregation. Close proximity to other similar historic structures.				
			JCH-KT(35. Organization	J.
			<u>KHC</u>	
			36. Date Spring	
21. Source of Information * plaque	K II. C	k	37. Revision Dates	38. Staff Review
* Beard, Ald Homes In and nea + mrs. Roy Morning Star	v Dowling Greek	2 54		
in miss way morning star		,		
~	·			



8

