



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

STRATFORD GREAT HOUSE AND FLANKING OUT HOUSES



Stratford Hall
PLANTATION



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

GENERAL VIEW OF GREAT HOUSE STRATFORD HALL PLANTATION



Stratford Hall
PLANTATION



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

WARPED AND SPLIT WOODEN PANELS IN THE GREAT HALL



Stratford Hall
PLANTATION



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

**WARPED AND SPLIT WOODEN PANELING
IN THE NORTHWEST CORNER OF THE
GREAT HALL - CONDITION TYPICAL**



Stratford Hall
PLANTATION



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

TYPICAL SPALLING PAINT AND PLASTER ON MASONRY WALL IN GREAT HOUSE



Stratford Hall
PLANTATION



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

TYPICAL EXFOLIATION OF PLASTER ON EXTERIOR MASONRY WALL OF GREAT HOUSE



Stratford Hall
PLANTATION



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

**TYPICAL SPALLING PLASTER IN EXTERIOR
MASONRY WALL FOUND AT ALL
GREAT HOUSE WINDOWS**



Stratford Hall
PLANTATION



STRATFORD HALL PLANTATION

Robert E. Lee Memorial Association, Inc.

Stratford, Virginia 22558

PLASTER DAMAGE CAUSED BY MOISTURE INFILTRATION AND CONDENSATION, TYPICAL IN GREAT HOUSE



Stratford Hall
PLANTATION