



1. Henry F. Whitelock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. North elevation, camera looking  
South
7. #1



1. Henry F. Whitelock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. East Elevation, camera looking  
West
7. #2



1. Henry F. Whitelock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 West 11th St., Anderson, IN
6. West elevation, camera looking  
East
7. #3




1. Henry F. Whitelock House
2. Shirley, Indiana
3. James Daus
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. South elevation, camera looking  
North
7. #4





1. Henry F. Whitelock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Eave & Cornice detail, camera  
facing N.E.
7. #5



1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W.11th St., Anderson, IN
6. Close up of North gable showing door & windows onto porch, camera facing South

7. #6



1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Living Room showing windows,  
doors, & wainscote details  
camera facing S.E.

7. #7



1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Living Room showing flue on wood 'china' cabinet camera facing South

7. #8





1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Daus
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Typical interior door detail
7. #9



1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Daus
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Dining room-flue w/cabinet below  
camera facing West
7. #10




1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W.11th St., Anderson, IN
6. Dining Room showing doors to  
pantry & winter kitchen, camera  
facing South

7. #11



1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Stairway from second floor  
camera facing North
7. #12





1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Interior view of door to porch  
roof camera facing North
7. #13

TOP



1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Attic at second floor level to show framing camera facing NE
7. #14



1. Henry F. Whitlock House
2. Shirley, Indiana
3. James Dauss
4. 6-1-83
5. 227 W. 11th St., Anderson, IN
6. Attic at second floor level to show framing camera facing East
7. #15



1. Henry Whitlock Home
2. Shirley, Indiana
3. James Dauss
4. 7 / 27 / 83
5. 227 W. 11th St., Anderson, IN
6. Stair railing & wall of upstairs bedroom, camera facing North
7. #16





1. Henry Whitlock Home
2. Shirley, Indiana
3. James Dauss
4. 7/27/83
5. 227 W. 11th St., Anderson, IN
6. South wall, west side of upstairs  
bedroom, camera facing South
7. #17



1. Henry Whitlock Home
2. Shirley, Indiana
3. James Dauss
4. 7 / 27 / 83
5. 227 W. 11th St., Anderson, IN
6. Southeast corner of upstairs  
bedroom, camera facing Southeast
7. #18



1. Henry Whitlock Home
2. Shirley, Indiana
3. James Daus
4. 7/27/83
5. 227 W. 11th St., Anderson, IN
6. North & East side of garage,  
camera facing Southeast
7. #19



1. Henry Whitlock Home
2. Shirley, Indiana
3. James Dauss
4. 7 / 27 / 83
5. 227 W. 11th St., Anderson, IN
6. North & West side of Summer  
kitchen, camera facing Southeast
7. #20





1. Henry Whitlock Home
2. Shirley, Indiana
3. James Dauss
4. 7 / 27 / 83
5. 227 W. 11th St., Anderson, IN
6. South & East side of Summer  
kitchen, camera facing Northwest
7. #21



1. Henry Whitlock Home

2. Shirley, Indiana

3. James Dauss

4. 7/27/83

5. 227 W. 11th St., Anderson, IN

6. North & East side of ~~Well~~<sup>Smoke</sup> house,  
camera facing Southwest

7. #22



1. Henry Whitlock Home
2. Shirley, Indiana
3. James A Daus
4. 7 / 27 / 83
5. 227 W. 11th St., Anderson, IN
6. North & East side of Barn,  
camera facing Southwest
7. #23



1. Henry Whitlock Home
2. Shirley, Indiana
3. James Daus
4. 7 / 27 / 83
5. 227 W. 11th St., Anderson, IN
6. South & East side of Chicken house, camera facing Northwest
7. #24





1. Henry Whitlock Home
2. Shirley, Indiana
3. James Dauss
4. 7 / 27 / 83
5. 227 W. 11th St., Anderson, IN
6. North & West side of Barn,  
camera facing Southeast
7. #25



1. Henry Whitlock Home
2. Shirley, Indiana
3. James Dauss
4. 7/27/83
5. 227 W. 11th St., Anderson, IN
6. Slate roof, <sup>(house)</sup> North side, camera facing South
7. #26