



SIMMONS HOUSE

102 S. 10<sup>TH</sup> STREET

FERNANDINA BEACH, FLORIDA

PHOTOGRAPHER: ELSEBETH GORDON

DATE: SEPT 1981

NEGATIVE: ADAPTIVE RESTORATION  
6124 S.W. 30<sup>TH</sup> AVE.

GAINESVILLE FLORIDA 32608

DESCRIPTION: WEST FACADE  
MAIN ENTRY

1. Merrick-Simmons House
2. Fernandina Beach, FL
3. Elsbeth Gordon
4. September, 1982
5. Adaptive Restoration  
6124 S. W. 30th Ave.  
Gainesville, FL  
32608
6. west facade, main entry
7. #1 of 7





SIMMONS HOUSE

102 S. 10<sup>th</sup> Street

FERNANDINA BEACH, Florida

PHOTOGRAPHER: ELSEBETH K. GORDON

DATE: SEPT 1982

NEGATIVE: ADAPTIVE RESTORATION

6124 S.W. 30<sup>th</sup> Ave.

Gainesville, Florida 32608

DESCRIPTION: SOUTH FACADE

1. Merrick-Simmons House
2. Fernandina Beach, FL
3. Elsbeth Gordon
4. September, 1982
5. Adaptive Restoration  
6124 S. W. 30th Ave.  
Gainesville, FL  
32608
6. south facade
7. #2 of 7



SIMMONS HOUSE  
102 S. 10<sup>TH</sup> STREET  
FERNANDINA BEACH, FLORIDA

PHOTOGRAPHER: ELSBETH GORDON

DATE: SEPT 1982

NEGATIVE: ADAPTIVE RESTORATION  
6124 S.W. 30<sup>TH</sup> AVE  
GAINESVILLE, FLORIDA 32608

DESCRIPTION: NORTH FACADE  
WEST FACADE, (ENTRY)

1. Merrick-Simmons House
2. Fernandina Beach, FL
3. Elsbeth Gordon
4. September, 1982
5. Adaptive Restoration  
6124 S. W. 30th Ave.  
Gainesville, FL  
32608
6. north facade and west facade, main  
entry
7. #3 of 7





Simmons House  
102 S. 10<sup>th</sup> Street  
Fernandina Beach, Florida

PHOTOGRAPHER: Elsbeth Gordon

DATE: FEBRUARY 1981

NEGATIVE:

(from color slide)

ADAPTIVE RESTORATION  
6124 S.W. 30<sup>th</sup> Ave.  
Gainesville, Florida

Description: EAST FACADE  
Back Entry

1. Merrick-Simmons House
2. Fernandina Beach, FL
3. Elsbeth Gordon
4. September, 1982
5. Adaptive Restoration  
6124 S. W. 30th Ave.  
Gainesville, FL  
32608
6. east facade, back entry
7. #4 of 7





Simmons House

102 S. 10<sup>th</sup> Street

Fernandina Beach, Florida

PHOTOGRAPHER: Elsbeth Gordon

DATE: July 1981

NEGATIVE

(COLOR): ADAPTIVE RESTORATION  
6124 S.W. 30<sup>th</sup> Ave  
Gainesville, Florida

DESCRIPTION:

EAST PARLOR, 1<sup>st</sup> FLOOR  
WEST WALL

1. Merrick-Simmons House
2. Fernandina Beach, FL
3. Elsbeth Gordon
4. September, 1982
5. Adaptive Restoration  
6124 S. W. 30th Ave.  
Gainesville, FL  
32608
6. east parlor, 1st floor, west wall
7. #5 of 7





Simmons House  
102 S. 10<sup>th</sup> Street  
Fernandina Beach, Florida

PHOTOGRAPHER: Elsbeth Gordon

DATE: June 1981

NEGATIVE: Adaptive Restoration  
6124 S.W. 30<sup>th</sup> Ave.  
Gainesville, Florida

DESCRIPTION: WEST PARLOR, 2<sup>nd</sup> FLOOR  
EAST WALL

1. Merrick-Simmons House
2. Fernandina Beach, FL
3. Elsbeth Gordon
4. September, 1982
5. Adaptive Restoration  
6124 S. W. 30th Ave.  
Gainesville, FL  
32608
6. West parlor, 2nd floor east wall
7. #6 of 7



SIMMONS HOUSE  
102 S. 10<sup>th</sup> STREET  
FERNANDINA BEACH, FLORIDA

PHOTOGRAPHER: ELSBETH GORDON

DATE: OCTOBER 1981

NEGATIVE FILED: ADAPTIVE RESTORATION  
6124 S.W. 30<sup>th</sup> AVE.  
GAINESVILLE, Florida

DESCRIPTION: FIREPLACE  
LEADED GLASS CABINET  
WEST PARLOR, 1<sup>st</sup> FLOOR  
EAST WALL

1. Merrick-Simmons House
2. Fernandina Beach, FL
3. Elsbeth Gordon
4. September, 1982
5. Adaptive Restoration  
6124 S. W. 30th Ave.  
Gainesville, FL  
32608
6. Fireplace, leaded glass cabinet, west  
parlor, 1st floor east wall

7. #7 of 7





Merrick-Simmons House,  
front-view showing

Ice house STACK & SEPARATE  
KITCHEN

102 So. 10 Street

Fernandina Beach, Fl. 32034

photographer; J.A. Alexander

repositary: 6124 SW 30 Ave.

Gainesville, Fl. 32608

date of photo, circa 1901





MERRICK - SIMMONS HOUSE

FRONT VIEW

102 SO. 10<sup>TH</sup> STREET

FERNANDINA BEACH, FLA. 32034

PHOTOGRAPHER: J.A. ALEXANDER

REPOSITORY: 6124 SW. 30 Ave

GAINESVILLE, FLA 32608

DATE OF PHOTO: 1901