



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS.
WOODBURN, MARION COUNTY, OREGON

NORA FIVES, PHOTOGRAPHER
FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH AT DOUBLE HUNG WINDOW AT
FIRST FLOOR LEVEL - RESTORED ORIGINAL TRIM.

INTERIOR VIEW
1 OF 21



BANK OF WOODBURN Building
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION County, OREGON
NORA FIVE'S PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH AT EXPOSED ORIGINAL BRICK WALL.
CIRCULAR DUCT WORK - NEW FURNACE
FIRST FLOOR LEVEL, INTERIOR VIEW

2 of 21



BANK OF WOODBURN Building
CORNER of ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVES photographer
FEBRUARY 20, 1966
NEGATIVE HOLDER?

NORA FIVES
12676 WHISKEY HILL RD
HUBBARD, OR 97032

LOOKING WEST. NEWLY INSTALLED BATHROOM,
REPRODUCED ORIGINAL TRIM & MOLDING.
FIRST FLOOR LEVEL, INTERIOR VIEW.

3 of 21



BANK of Woodburn building.
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON

NORA FIVES' PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD
HUBBARD, OR 97032

NORTH SIDE, ARTHUR STREET ENTRANCE DOOR.
RE-USE OF ORIGINAL HARDWARE. FIRST FLOOR LEVEL

4 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON

NORA FIVES PHOTOGRAPHER

FEBRUARY 20, 1986

NEGATIVE HOLDER: NORA FIVES

12676 WHISKEY HILL RD.

HUBBARD, OR 97032

LOOKING NORTH EAST. DOOR ON ANGLE FRONT & ARTHUR.
FIRST FLOOR LEVEL, INTERIOR VIEW.

RESTORATION OF ORIGINAL TRIM. REPRODUCTION
OF BRASS HARDWARE. SINGLE PANE GLASS REPLACED.

5 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN MARION COUNTY, OREGON
NORA FIVES 'PHOTOGRAPHER

FEBRUARY 20, 1956

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

ORIGINAL CEDAR PLANK FLOORS. UPPER LEVEL

6 of 21

Handwritten text, likely bleed-through from the reverse side of the page. The text is illegible due to blurring and low contrast.

Handwritten text, likely bleed-through from the reverse side of the page. The text is illegible due to blurring and low contrast.

BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON

NORA FIVES PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH, FIRST FLOOR LEVEL INTERIOR VIEW.
ARTHUR ST. ENTRANCE DOOR. ORIGINAL DOOR AND
TRIM, AND HARDWARE RESTORED.

7 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVES' PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING EAST, FIRST FLOOR LEVEL, INTERIOR VIEW.
REPRODUCED ORIGINAL TRIM SINGLE PANE GLASS
REPLACED. WOOD WAINSCOTTING INSTALLED.

8 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVES' PHOTOGRAPHER
FEBRUARY 20, 1996

NEGATIVE HOLDER:

NORA FIVES

12676 WHISKEY HILL RD.

HUBBARD, OR 97032

LOOKING NORTH, FIRST FLOOR LEVEL INTERIOR VIEW.
RESTORED ORIGINAL WINDOW TRIM. DOUBLE HUNG
WINDOWS RETAIN ORIGINAL WAVY GLASS. ORIGINAL
HARDWARE RETAINED.

9921



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVE'S PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVE'S
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH, FIRST FLOOR LEVEL, INTERIOR VIEW.
REPRODUCED ORIGINAL WINDOW TRIM & CORNER
BLOCKS. WALL WAINSCOTTING INSTALLED BELOW.

10 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN MARION COUNTY OREGON
NORA FIVES PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH EAST, UPPER LEVEL, INTERIOR VIEW.
EXPOSED BRICK WALL, WAINSCOTTING.
WORK IN PROGRESS.

11 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVES' PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING WEST UPPER LEVEL, INTERIOR VIEW, NORTH
WALL DOUBLE HUNG WINDOWS, ORIGINAL WAVY GLASS
& TRIM. EXPOSED BRICK WALL SHOWS ARCHES OVER
WINDOWS.

12 721



BANK OF WOODBURN BUILDING
CORNER OF Arthur & Front streets
WOODBURN, MARION County, OREGON
NORA FINE'S photographer

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FINE'S
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING EAST, UPPER LEVEL, INTERIOR VIEW.
FRONT ROOM, WALL REBUILT DUE TO EARTH-
QUAKE DAMAGE (RECESSED WINDOWS.)
ORIGINAL FRAMES, GLASS, AND TRIM RETAINED.

13 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVES PHOTOGRAPHER
FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH, UPPER LEVEL, INTERIOR VIEW.
NORTH WALL ROW OF WINDOWS ALL RETAIN ORIGINAL
GLASS & TRIM. EXPOSED BRICK WALL IN FRONT ROOM
SHOWS ARCHES OVER WINDOWS.

14 of 21

COMING
SOON

FUTURE
WILSON BURN BR

OPEN

WILSON BURN BR

OPEN

BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVES PHOTOGRAPHER
FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH EAST, FIRST FLOOR LEVEL, INTERIOR
VIEW. REPRODUCED TRIM ON WINDOW, ORIGINAL
DOORS AND GLASS, RESTORED DOOR TRIM &
REPRODUCED HARDWARE ON DOORS. WAINSCOTTING
15 721 ADDED BELOW.



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVE'S PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER:

NORA FIVE'S
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING EAST, FIRST FLOOR LEVEL, INTERIOR VIEW.
16 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
NORA FIVE'S PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVE'S

12676 WHISKEY HILL RD.
HUBBARD, OR 97032

EXTERIOR VIEW EAST FACING WEST. Bldg.
REPAINTED MATCHING ORIGINAL PAINT COLORS.
REPRODUCED COLUMN TOPS, BANDING AND
CORNICE PIECE. ORIGINAL ~~DOORS~~ DOORS & STEPS.

17 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN MARION COUNTY, OREGON
NORA FIVES' PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

EXTERIOR VIEW EAST FACING WEST.

REPRODUCED COLUMN TOPS, BANDING, & CORNICE.

REPAINT, MATCHING ORIGINAL COLORS.

18 x 21' ORIGINAL DOORS & STEPS



COMING
SOON

FUTURE 
WOODBURN BRANCH

ARTHUR ST

BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN MARION COUNTY, OREGON
NORA FIVES' PHOTOGRAPHER

FEBRUARY 20, 1996

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

EXTERIOR VIEW NORTH WALL. REPAINT TO MATCH
ORIGINAL COLORS. REPRODUCED COLUMN TOPS,
BANDING, AND CORNICE (to old photo.)
ORIGINAL DOORS & STEPS & SOME WINDOWS.

19 of 21



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH ALONG FRONT STREET
AT BANK BUILDING.

1 of 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS.
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, Photographer
July 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 Whiskey Hill Rd.
Hubbard, OR 97032

Looking Southwest, Entry Elevation
to Bank Building!

3 of 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES

12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING WEST, AT EAST ELEVATION
OF BANK BUILDING.

2 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FINES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH, NORTH ELEVATION OF
BANK BUILDING.

4 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1954

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTHEAST, NORTH ELEVATION
OF BANK BUILDING'

5 OF 27



BANK OF WOODBURN BUILDING

CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON

RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1954

NEGATIVE HOLDER: NORA FWES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING EAST WEST ELEVATION OF
BANK BUILDING.

6 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12626 WHISKEY HILL RD
HUBBARD, OR 97032

LOOKING NORTHEAST, SOUTH ELEVATION
OF BANK BUILDING.

7 of 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHERS
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH NORTH ENTRY DOOR TO
BANK BUILDING.

8 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH NORTH ENTRY DOOR
TO BANK BUILDING

9 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH EAST IRON VENTILATION
GRILLES AND CAST IRON SILL BELOW
FIXED PANE NORTH ELEVATION WINDOW.

10 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE 'HOLDER': NORA FINES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH, NORTH ELEVATION FIXED
'PANE WINDOW'

11 of 27



BANK OF WOODBURN Building
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, Photographers

JULY 25, 1984

Negative Holder:

NORA FIVES
12676 Whiskey Hill Rd.
HUBBARD, OREGON 97032

Looking South, Double Hung MAIN
FLOOR Windows.

12 OR 27.



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER

JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES

12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH, SECOND FLOOR DOUBLE
HUNG WINDOWS.

13 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING WEST, CAST IRON SILL AT MAIN
FLOOR WINDOW OPENINGS.

14 0727



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
NEGATIVE HOLDER: NORA FWES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032
LOOKING SOUTHWEST, PAIR OF MAIN ENTRY
DOORS TO GROUND FLOOR.

15 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTHWEST, EAST IRON
MAIN ENTRY STAIRS' TO GROUND FLOOR.

16 OF 27



FOR SALE
LANDMARK
REALTY
572-2888

CAUTION

BANK OF WOODBURN BUILDING
CORNER OF FRONT & ARTHUR STREETS
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER : NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTHWEST, EAST ELEVATION FIXED
PANE WINDOW AT EAST ELEVATION.

17 OF 27



BANK OF WOODBURN BUILDING
CORNER OF Front & Arthur streets
WOODBURN MARION COUNTY OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12626 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING WEST ALONG NORTH ELEVATION
OF BANK BUILDING

18 of 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL E. SAUNDERS, PHOTOGRAPHER

JULY 28, 1994

NEGATIVE HOLDER: NORA FIVES

12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING WEST, MAIN FLOOR, INTERIOR

19 of 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1954

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING EAST, MAIN FLOOR INTERIOR.

20 of 27



BANK OF WOODBURN BUILDING
CORNER OF Arthur & Front STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, photographer
NEGATIVE HOLDER: NORA FIVES

12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH, HISTORIC WOOD CHAIR RAIL
VERTICAL WOOD WAINSCOT, AND WOOD BASE.

22 OF 27

JULY 25, 1994



BANK OF WOODBURN Building
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTH, MIDDLE STAMPED HINGE
AT NORTH ELEVATION ENTRY DOOR.

23 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING SOUTHWEST, ACROSS APARTMENT
AREA, SECOND FLOOR, SOUTH BRICK WALL
AT LEFT.

24 of 27



BANK OF WOODBURN, Building
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDALL S. SAUNDERS, Photographer
July 25, 1994

Negative Holder: NORA FIVES
12676 WHISKEY HILL Rd.
HUBBARD, OR 97032

LOOKING WEST, ALONG SOUTH WALL OF
Building AT SECOND FLOOR

25 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER.
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH EAST AT DOUBLE HUNG
WINDOW AT SECOND FLOOR ABOVE
MAIN ENTRY DOORS. - INTERIOR VIEW.
26 OF 27



BANK OF WOODBURN BUILDING
CORNER OF ARTHUR & FRONT STREETS
WOODBURN, MARION COUNTY, OREGON
RANDAL S. SAUNDERS, PHOTOGRAPHER
JULY 25, 1994

NEGATIVE HOLDER: NORA FIVES
12676 WHISKEY HILL RD.
HUBBARD, OR 97032

LOOKING NORTH, SECOND FLOOR AT
DOUBLE HUNG WINDOWS OVER SINGLE
PANE WINDOW AT NORTH ELEVATION.

~~11/11/94~~

27 OF 27