

Photo No. 2 By: Ralph J. Christian, AASLH Negative at: Historic Sites Survey Date: January, 1977

View: Front (north) facade



Photo No. 3 By: Ralph J. Christian, AASLH Negative at: Historic Sites Survey Date: January, 1977

View: Entrance on front (north) facade



Photo No. 4 By: Ralph J. Christian, AASLH Negative at: Historic Sites Survey Date: January, 1977

View: West facade on Sherman Street



Photo No. 5 By: Ralph J. Christian, AASLH Negative at: Historic Sites Survey Date: January, 1977

View: Rear (south) facade and portion of east facade



Photo No. 6 By: Ralph J. Christian, AASLH Negative at: Historic Sites Survey Date: January, 1977

View: Second floor area of Art Deco lobby