



ADENA
Chillicothe, Ohio
North (entrance) Front
Photo by David R. Barker, April 2001

Fig 1




ADENA
Chillicothe, Ohio
East Elevation

Photo by David R. Barker, April 2001



ADENA
Chillicothe, Ohio
South (garden) Front
Photo by David R. Barker, April 2001

Fig 4




ADENA
Chillicothe, Ohio
West Elevation

Fig 5

Photo by David R. Barker, April 2001







ADENA
Chillicothe, Ohio
Entrance Hall (center north room, first floor)
Photo by David R. Barker, April 2001



ADENA


Chillicothe, Ohio

Parlor (southeast room, first floor)


Photo by David R. Barker, April 2001



ADENA
Chillicothe, Ohio
Smokehouse
Photo by David R. Barker, April 2001



ADENA
Chillicothe, Ohio
Washhouse
Photo by David R. Barker, April 2001



ADENA

Chillicothe, Ohio

General view of grounds, from north lawn, looking east

Photo by David R. Barker, April 2001




ADENA
Chillicothe, Ohio
Flower Garden
Photo by David R. Barker, April 2001












ADENA
Chillicothe, Ohio
Springhouse
Photo by David R. Barker, April 2001



ADENA
Chillicothe, Ohio
Barn

Photo by David R. Barker, April 2001



ADENA
Chillicothe, Ohio
Tenant House
Photo by David R. Barker, April 2001