



HISTORIC RESOURCES INVENTORY

1a. Property name, historic b. Property name, common Lillian Boteler House		14. MDAH Inventory Code <hr/> 15. County Hinds		16. Survey sequence no. 7
2. Property address/descriptive location 214 Port Gibson Rd. Raymond		17. Was interior surveyed? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> no <input type="checkbox"/> not applicable	18. Visibility from public road or street <input checked="" type="checkbox"/> good <input type="checkbox"/> poor <input type="checkbox"/> not visible	
3. Legal description Parcel #4969-276-1 as recorded in Second Judicial District Ownership Maps, Vol. 2 for Hinds County, Miss. Acreage = less than one acre		19. Condition <input type="checkbox"/> excellent <input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> deteriorated <input type="checkbox"/> ruins <input type="checkbox"/> no visible remains <input type="checkbox"/> incorporated into later structure		
4. Original use residence	5. Present use residence	20. USGS quadrangle map (if required) (see instructions) Raymond, MS		
6. Other uses N/A	7. Original or historically notable owner(s) or occupant(s) Unknown	21. UTM reference (if required) (see instructions) 15 742650 3571750		
8. Date of construction <input checked="" type="checkbox"/> estimated c. 1855 <input type="checkbox"/> documented	9. Changes <input type="checkbox"/> no major changes <input type="checkbox"/> moved (date) _____ <input checked="" type="checkbox"/> major alterations (date) <u>c. 1900</u>	22. Current owner's name and address (see instructions) Lillian Boteler Post Office Box 12 Raymond, MS 39154		
10. Architect Unknown <input type="checkbox"/> documented <input type="checkbox"/> attributed	11. Builder/contractor Unknown <input type="checkbox"/> documented <input type="checkbox"/> attributed	23. Tenant's name (if required), and address if different from property address (see instructions) (enter in pencil) N/A		
12. Is the property architecturally or historically important? If so, why? (continue on reverse if necessary) This house is architecturally significant locally as one of six remaining, relatively intact examples of Greek Revival residential architecture in Raymond. The addition of a wraparound porch next to the portico does not significantly diminish its architectural integrity.		24. Principal material(s) frame		
13. Identify any outbuildings and/or other structures or landscape features associated with this building or structure. (Attach an additional inventory form for each one that has particular architectural or historical interest.) none		25. Architectural character or style Greek Revival		
(Attach one 3 x 5 black and white photograph here.)		THIS SECTION FOR MDAH USE ONLY		
		26. Category building		
		27. Functional type 		
		28. Registration status and dates <input type="checkbox"/> NHL _____ <input type="checkbox"/> listed NR _____ <input type="checkbox"/> approved for NR _____ <input type="checkbox"/> federal DOE _____ <input type="checkbox"/> state landmark _____ <input type="checkbox"/> local landmark _____ <input type="checkbox"/> HABS/HAER _____		
		29. Is this property included in a historic district? <input type="checkbox"/> yes <input type="checkbox"/> NR district <input type="checkbox"/> no <input type="checkbox"/> proposed <input type="checkbox"/> local district Name of district _____ _____ <input type="checkbox"/> pivotal <input type="checkbox"/> marginal <input type="checkbox"/> contributing <input type="checkbox"/> noncontributing <input type="checkbox"/> intrusion		

MISSISSIPPI HISTORIC RESOURCES INVENTORY

30. Brief statement of the property's history The estimated date of construction for this house is c. 1855 because it bears a striking resemblance to the Johnson-Harper house which was built in the mid-1850's. The house is representative of middle class housing in antebellum Raymond.

31. Brief description. If a thorough description has been prepared separately, disregard this section and check here This 1 story, 5 bay wide house is sheathed in clapboard and has side gable peaks. The front portico has pillars supporting a pedimented gable peak with a full entablature that includes a bracketed frieze. The exterior wall in the portico area is covered in flushboard. The double door, front entrance has sidelights and a transom with diamond shaped panes of glass. To the southwest, the portico was altered and extended into a wrap-around porch with slender Doric pillars similar to those in the portico. This is a turn of the century alteration. The front windows are 9/9 double hung sash with

32. Additional remarks or continuation of other sections

31. pedimented lintels and louvred shutters. A similar pedimented lintel appears above the front door. There are additions on the SW and rear facades. The interior chimney is stuccoed in cement.

35. Photographer or photo source

Susan Enzweiler

36. Photo roll and frame number(s)

Roll 1657 - #37

37. Photo date

11-4-85

33. Sources of information

-Personal Observation

38. Inventory form completed by (name and organization)

Susan Enzweiler
MDAH


39. Survey project name

Raymond

40. Date form completed

12-85

34. Sketch of site plan. (Include north arrow. Show outline of building shape and locations of outbuildings.)



THIS SECTION FOR MDAH USE ONLY

41. Attached supplementary materials

42. Other materials in MDAH files

- plans, drawings
- correspondence
- research notes
- clippings
- project report
- early photos
- slides
- negatives
- other

43. Date logged, MDAH

44. Logged by