1. Name of Resource:

2. Original Owner:

4. Prehistoric Site

Historic Site

3805 Beaver Road

7. Owner's Address: 3805 Beaver Road

Daniel & Jane Sauer

9. Recognition & Date: Nat.Landmark

Nat.Register

10. N.R.Status & Date:

District Name: Mult.Resource Area:

Thematic Name: 12. Historical Theme: Primary:

Secondary:

Other:

11. N.R.Group:

Highway Marker

Union, KY 41091 8. Evaluation: National Register

KY Landmark Certificate

Unknown 3. Other Names:

5. Location:

Union, KY 6. Owner's Name:

None

Miller, Mrs. M., House

DEC 2 8 1988

KENTUCKY HISTO Individual In

ORIC RESOURCES	Resource # Be-300				
ventory Form	Boone	County			
16. Date:					
Original Building	mid-19th c	[]			
Addition	mid 15th C.	i i			
17 04 1	•				
17. Style: Greek Reviva	à I	[]			
		i i			
18. Architect/Builder:					
•	Unknown				
19. No. of Stories: one	e	[]			
20. Original Floor Plan:	T - h				
	T-shape	[]			
	uble Pile N.A				
22. Roof Form & Materi gable/asphalt shing	al: Original				
	les Not Original				
23. Structural Material:					
	wood frame	<u> </u>			
24. Exterior Material:	weatherboard				
25. Foundation Material		1			
		г з			
26. Major Alterations:	ursed fieldstone None				
Moved/Rebuilt	Other X				
Additions X	other "				
27. Special Features:					
r	ecessed portico				
28. Outbuildings:					
four: corn crib, b	arn, 2 sheds	[]			
29. Original Function:					
fa	rm dwelling	[]			
30. Present Use:	rm dwelling				
	im awerring	[]			
31. Condition:					
900		<u> </u>			
32. Endangered:	Yes				
	N/A	٧			

33. Attach Photos:

Photo Nos:

6 - 15

No. of Slides:

Roll:

13. Statement of Significance: This property is significant under criterion (as a good example of the Greek Revival style, particularly of the adaptation of a plan type found in high-style Greek Revival houses for a house of modes dimensions. The property is 12 also significant under criterion A as a good example of a small farm in Boone County in the period 1850-1938.

Architecture

Agriculture

Building X

Local Landmark

KY Inventory 1977

HABS/HAER

Boone County

Structure

Object

Other

14. History:

The owner indicated in the 1883 atlas is Mrs. M. Miller.

15. Source of historical information and/or contact person: 1883 Atlas

34.	Prepared by:	Kenne	th I	. Gibl	os		
35.	Organization:	Boone	Co.	Hist.	Pres.	Rev.	Brd
	Date: Sept						
37.	New Survey		F	lesurve	ух		

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource # Be-300

38.	UTM Point of Primary Building:	Zone	Easting	Northing		G.I.S. Mod.	ĺ	ļ
	Quadrant: Rising Sun	16	_693800	_4306780	40.	Coordi.Accuracy	<u> </u>	
41.	UTM Points of Boundary (for N. R.	eligibl	e sites only):					
	A. B. C.	- -	D. E. F.					
42.	Total Acreage in Present Property				ropose	ed N.R. boundary: 2	.75	
44.	Site Plan (and boundary description	and ju	stification for	N.R. sites):				
	Corn barn can	The Road	N	side of B with the proceed 3 line. Th turning n of Beaver 400' alon Road to t boundary buildings provide a	eaver north 00' s en pr orthe Road g the he po inclu and sett m the	he point where to Road (Ky 338) in west property list outhwest along to oceed 400' south ast 300' to the ast 300' to the ast 300' to the ast of origin. Then proceed south side of Bouth of origin. The house, a sufficient acreating, including kouse down Beav	nter ne, p east sout eave The oge ey s	ropert, h side hwest r ut- o ight-
	shed.	-		Contribut	ing:	5 buildings		

45. Description and House Plan:

The one-story frame house is a vernacular or local carpenter-builder's version of three-part houses built along the Ohio River (the Moore-Terrill house [listed in National Register] in Boone County may have been the model), in the Greek Revival period. The 5-bay facade (north) features a recessed central bay combined with single-bay portico. The recess contains three doors, a pedimented cnetral door with transom and sidelights leading to a central vestibule or hall, and two unlighted doors, topped with cornice strips, leading to the two principal rooms. A kitchen wing extends from the center of the rear of the main block; the first room of this wing was flanked by a pair of recessed open porches, the western of which has been enclosed. The kitchen wing was lengthened at an early date and a second chimney constructed on the gable end. All of the original cornices have modillions, the windows across the front are topped with cornice strips with dentils, and all of the original windows are 6/6 double-hung sash.

The four outbuildings, a shed behind the house and, at the entrance lane, a second shed, a barn and a corn crib, are all contemporary with the house. The <u>shed</u> south of the house is built into the hillside (frame, weatherboarding, gable roof, standing seam metal, fieldstone foundation). The <u>shed</u> at the entry lane is frame with vertical-board siding, a shed roof of metal and an east entry. Both the <u>barn</u> and the <u>corn crib</u> are of frame construction with vertical-board siding and gabled roofs with standing-seam metal. The fieldstone foundation of the barn is continuous while that of the crib consists of piers and the entry bay of the barn is in the south wall, whereas the door to the crib is in the east gable-end. All outbuildings contribute to the integrity of the property and illustrate the agricultural economy of the original occupants of the house.

1. Name of Resource:

2. Original Owner:

4. Prehistoric Site

Historic Site

3805 Beaver Road

7. Owner's Address: 3805 Beaver Road

Daniel & Jane Sauer

9. Recognition & Date: Nat.Landmark

Nat.Register

10. N.R.Status & Date:

District Name: Mult.Resource Area:

Thematic Name: 12. Historical Theme: Primary:

Secondary:

Other:

11. N.R.Group:

Highway Marker

Union, KY 41091 8. Evaluation: National Register

KY Landmark Certificate

Unknown 3. Other Names:

5. Location:

Union, KY 6. Owner's Name:

None

Miller, Mrs. M., House

DEC 2 8 1988

KENTUCKY HISTO Individual In

ORIC RESOURCES	Resource # Be-300				
ventory Form	Boone	County			
16. Date:					
Original Building	mid-19th c	[]			
Addition	mid 15th C.	i i			
17 04 1	•				
17. Style: Greek Reviva	à I	[]			
		i i			
18. Architect/Builder:					
•	Unknown				
19. No. of Stories: one	e	[]			
20. Original Floor Plan:	T - h				
	T-shape	[]			
	uble Pile N.A				
22. Roof Form & Materi gable/asphalt shing	al: Original				
	les Not Original				
23. Structural Material:					
	wood frame	<u> </u>			
24. Exterior Material:	weatherboard				
25. Foundation Material		1			
		г з			
26. Major Alterations:	ursed fieldstone None				
Moved/Rebuilt	Other X				
Additions X	other "				
27. Special Features:					
r	ecessed portico				
28. Outbuildings:					
four: corn crib, b	arn, 2 sheds	[]			
29. Original Function:					
fa	rm dwelling	[]			
30. Present Use:	rm dwelling				
	im awerring	[]			
31. Condition:					
900		<u> </u>			
32. Endangered:	Yes				
	N/A	٧			

33. Attach Photos:

Photo Nos:

6 - 15

No. of Slides:

Roll:

13. Statement of Significance: This property is significant under criterion (as a good example of the Greek Revival style, particularly of the adaptation of a plan type found in high-style Greek Revival houses for a house of modes dimensions. The property is 12 also significant under criterion A as a good example of a small farm in Boone County in the period 1850-1938.

Architecture

Agriculture

Building X

Local Landmark

KY Inventory 1977

HABS/HAER

Boone County

Structure

Object

Other

14. History:

The owner indicated in the 1883 atlas is Mrs. M. Miller.

15. Source of historical information and/or contact person: 1883 Atlas

34.	Prepared by:	Kenne	th I	. Gibl	os		
35.	Organization:	Boone	Co.	Hist.	Pres.	Rev.	Brd
	Date: Sept						
37.	New Survey		F	lesurve	у Х		

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource # Be-300

38.	UTM Point of Primary Building:	Zone	Easting	Northing		G.I.S. Mod.	ĺ	ļ
	Quadrant: Rising Sun	16	_693800	_4306780	40.	Coordi.Accuracy	<u> </u>	
41.	UTM Points of Boundary (for N. R.	eligibl	e sites only):					
	A. B. C.	- -	D. E. F.					
42.	Total Acreage in Present Property				ropose	ed N.R. boundary: 2	.75	
44.	Site Plan (and boundary description	and ju	stification for	N.R. sites):				
	Corn barn can	The Road	N	side of B with the proceed 3 line. Th turning n of Beaver 400' alon Road to t boundary buildings provide a	eaver north 00' s en pr orthe Road g the he po inclu and sett m the	he point where to Road (Ky 338) in west property list outhwest along to oceed 400' south ast 300' to the ast 300' to the ast 300' to the ast of origin. Then proceed south side of Bouth of origin. The house, a sufficient acreating, including kouse down Beav	nter ne, p east sout eave The oge ey s	ropert, h side hwest r ut- o ight-
	shed.	-		Contribut	ing:	5 buildings		

45. Description and House Plan:

The one-story frame house is a vernacular or local carpenter-builder's version of three-part houses built along the Ohio River (the Moore-Terrill house [listed in National Register] in Boone County may have been the model), in the Greek Revival period. The 5-bay facade (north) features a recessed central bay combined with single-bay portico. The recess contains three doors, a pedimented cnetral door with transom and sidelights leading to a central vestibule or hall, and two unlighted doors, topped with cornice strips, leading to the two principal rooms. A kitchen wing extends from the center of the rear of the main block; the first room of this wing was flanked by a pair of recessed open porches, the western of which has been enclosed. The kitchen wing was lengthened at an early date and a second chimney constructed on the gable end. All of the original cornices have modillions, the windows across the front are topped with cornice strips with dentils, and all of the original windows are 6/6 double-hung sash.

The four outbuildings, a shed behind the house and, at the entrance lane, a second shed, a barn and a corn crib, are all contemporary with the house. The <u>shed</u> south of the house is built into the hillside (frame, weatherboarding, gable roof, standing seam metal, fieldstone foundation). The <u>shed</u> at the entry lane is frame with vertical-board siding, a shed roof of metal and an east entry. Both the <u>barn</u> and the <u>corn crib</u> are of frame construction with vertical-board siding and gabled roofs with standing-seam metal. The fieldstone foundation of the barn is continuous while that of the crib consists of piers and the entry bay of the barn is in the south wall, whereas the door to the crib is in the east gable-end. All outbuildings contribute to the integrity of the property and illustrate the agricultural economy of the original occupants of the house.