




East or principal facade of La Fortaleza.




Diagrammatic perspective of west facade of La Fortaleza showing 16th century towers in foreground



Top of NW tower showing in the parapet loopholes for both bow and arrow and harquebus



Bedroom in La Fortaleza showing type of ceiling construction being replaced with reinforced concrete



Solution for restoring efficiency of beams without destroying original construction