



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Principal facade and main
entrance fronting on Grove
St. (south elevation).

Photo # 1 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: 3/4 view of northwest corner
Iron picket fence is visible
and "panels" in former coal
bunker along street are
visible.

Photo # 2 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: North elevation - entrance
along Pine Street. Note
twin entrances and parking
area.

Photo # 3 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Grove St. entrance showing
monumental entry and leaded
glass transom.

Photo # 4 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Landing within the system of
access stairs/ramps at the
Grove Street entrance. Note
stone settees and flagpole.

Photo # 5 Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: East elevation - showing
decorative tapestry pattern
at corners in wall plane
and slope (at right) up to
Haydon Homestead Park.

Photo # 6 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



LED
ZEP

WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Furnace stack and roof of
boiler room (concrete walk)
West elevation.

Photo # 7 Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL


Grove Street, Waterbury, Conn.

View: Roof plane looking west -
limestone coping and parapet at left; penthouse over auditorium and skylights at right.

Photo # 8

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL


Grove Street, Waterbury, Conn.

View: Interior view of auditorium penthouse.

Photo # 9

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Vertical view of skylight
illuminating stairwell at
NE corner.

Photo # 10 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Interior view of gymnasium
looking west. Balcony at
left - note original central
rolling partition still in
place.

Photo # 11 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.




WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Interior view of auditorium
looking to the entrance
(Grove St.) at rear.

Photo # 12 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Three, D.M. Dillon steam
boilers comprised the heat-
ing plant. Note titles on
faceplates and decorative
relief.

Photo # 13 Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL


Grove Street, Waterbury, Conn.

View: Cafeteria at basement level
- looking east.

Photo # 14

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL


Grove Street, Waterbury, Conn.

View: Swimming pool at basement
level on north elevation.

Photo # 15

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Decorative fountainhead
at east end of swimming
pool.

Photo # 16

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: West side of basement corridor (typical).

Photo # 17

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Typical view of main corridor on upper levels serving classrooms.

Photo # 18

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Second floor classroom
(typical)

Photo # 19

Date: 11/8/80

Neg. on file: Conn. Hist Comm



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Landing and stair at NW corner - note fire screen at right and steel fireproof stair. Typical corridor finish.

Photo # 20

Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Typical two-panel dark oak door and molded trim used for classrooms.

Photo # 21 Date: 11/8/80

Neg. on file: Conn. Hist. Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Main foyer and entrance vestibule looking toward Grove Street. Principal's office was door at left.

Photo # 22 Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Main foyer showing entrance
to gymnasium balcony at right
- note marble steps, grained
columns and transom lights.

Photo # 23 Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Interior view of principal's
office and reception area
near Grove St. entrance.

Photo # 24 Date: 11/8/80

Neg. on file: Conn. Hist Comm.



WILBY HIGH SCHOOL

Grove Street, Waterbury, Conn.

View: Lobby entrance to auditorium on second floor at south end of building. Note details; cased girts, columns and transoms.

Photo # 25 Date: 11/8/80

Neg. on file: Conn. Hist Comm.