RR 0227-6-7 JUN 22 1984 -1' 1

N.J. Office of Cultural and Environmental Services, 109 W. State Street, Trenton, N.J. 08625 609-292-2023

Prepared by Heritage Studies, Inc. Princeton, N.J. 08540 609-452-1754

RR 0227 ~
Survey # 6-7

NEW JERSEY TRANSIT RAILROAD STATION SURVEY

1.	IDEN	ITIFICA	NOITA				
U	A.	Name:	Common Historic	Hillsdale	Stution	Line:	Hoboken Division - Pascack Valley (Erie) (NJ & NY)
	L	Broadwa Hillsda	ay 🄏 Hills ale, N.J.			Munici Block	r: Bergen pality: Hillsdale Borough & lot: part of 1205 / 2 is is entire Erie right of way)
	C.		s name: No s: Newark				
		Cou	ırthouse. N	Main Stree	t. Hackensa	ck, N.J (give	Deeds, Bergen County number, category, etc., propriate)
		HABS _	H <i>A</i>	ER	_ELRR Impro	vement_	NY&LB Improvement
		Plainf	ield Corri	dor	NR(<u>name</u>	, if HD)
		NJ	SR <u>(name,</u>	if HD)			
		NJ	HSI (#)			-	•
		Northe	ast Corrid	lor			
		Local .					(date)
		Modern	ization St	udy: site	e plan <u>X</u>	floo	r plan <u>χ</u> aerial photo
			other	views	X photo	s of NR	quality?X
2.	EVALL	DATION					
	Α.	Determ	ination of	eligibil	ity: SHPO NR de	comment t.?	? (date (date
	В.	Potent	ially elig	ible for	NR: yes <u>X</u>	possibl	e no
					indivi	dual	thematic X
	С.	Survey	Evaluatio	n: 115	/140 points		

FACILITY NAME: Hillsdale

RR 0227= Survey # 6-7

3. DESCRIPTION--COMPLEX IN GENERAL

Describe the entire railroad complex at this site; mention all buildings and structures, with notation of which are not historic. Check items which apply and discuss in narrative:

<pre>Moved buildings (original location, date of and reason for move) Any non-railroad uses in complex (military recruiting, etc.) Any unusual railroad building types, such as crew quarters, etc. (specify) Known threats to complex or individual structures</pre>
Surroundings: X urbansuburbanscattered buildingsopen spaceresidentialwoodlandagriculturalindustrialindustrialother (specify)W of tracks
Relationship of station grade to track grade: X Station and track grade at same levelStation at street grade, track depressedStation spans trackTrack elevated above street grade, multi-level station
of tracks: l plus siding Pedestrian access across tracks: Pedestrian bridge:at street gradeelevated Pedestrian/vehicular bridge:at street gradeelevated Tunnel X_None provided

Discuss character of vehicular and pedestrian approaches to complex; landscaping; relationship to parking. Refer to, and key with, site plan.

The Hillsdale complex consists of a two story wood frame station, combining Stick and Second Empire styles, and outbound platform. It is located E of the tracks on a cramped site at the SW corner of a busy intersection. Tracks are alighed N-S. There are a few parking spaces just S of the station. Pedestrians may approach directly from the sidewalk to the E. Across the tracks to the W is a restaurant parking lot which is partially masked by a row of closely planted trees. Apart from the grade crossing NW of the station there is no access from that side of the tracks. The future of the station is uncertain.

-3 **RR** 022**7 ~** Survey # 6-7

FACILITY NAME: Hillsdale

3. DESCRIPTIONPLATFORMS AND CANOPIE	S.
-------------------------------------	----

Inbound	none				
x_Outbound	indeterminant	platform,	asphalt,gravel,	and	dirt
Between t	racks none				

Nature and extent of existing original material and alterations: roof type, material, supports; freestanding or attached to building; seating; lighting; signage; other.

There are no canopies at the Hillsdale complex.

4. DESCRIPTION - BUILDINGS (EXTERIOR)

key with, sit	te plan.	each building at faci	•	
Account for o	original materi	als and finishes where	different	from existing.
Station X	_Shelter	Freight House	Other	(specify)
		iption, including styl		

The Hillsdale station, located on the E side of the tracks, consists of a two-story wood frame block, 6 bays wide and 2 deep, with gabled roof, its ridge paralleling the tracks. The ends have jerkin heads, while a central gabled dormer with a concave mansard roof and round arch dormer breaks the roof plane on both the E and W and rises above the ridge. Below the gable on the first floor is a bay window projection. On the W. facade there are 3 windows in the bay flanked on either side by a door and a window with 3 windows in the dormer above. On the E, there are 3 windows and 3 doors below, and three windows in the dormer. On the N there are 2 doors on the first floor and 2 windows above, while on the S, there are 2 windows below and 2 above. There is a slender corbeled chimney rising at the N end. (One at S end has been removed.) Walls are board and batten with diagonal board panels at the base (lower walls and base were recently stuccoed) and asphalt shingle roof (originally slate). A canopy attached with shaped wood brackets once encircled the building at the first floor level.

4.	DESCRIPT	- NOI	BUILDINGS	(EXTERIOR)	CONTD.
----	----------	-------	-----------	------------	--------

Fill out separate sheet for each building at facility.

Station X Shel	terFreight HouseOther	(specify)
EXTERIOR MATERIALS	AND SYSTEMS:	
	<u>Original</u>	Existing, if different
Structural system:	wood frame	
Foundation:	brick	
Base course:	diagonal board	stucco
Walls:	board and batten	(slate blue paint) stucco, lst floor
Trim:	board framing, shaped wood brackets cut-out bargeboards	(slate blue paint)
Doors:	(2/2) and 2-pane transom, diamond pane	
Roofing:	slate	asphalt shingle
Soffit:	none	
Windows:	3/3 diamond pane; 7/7 diamond pane, seg. arch surrounds	
Lighting:	probably gas fixtures	several incan. lamps attached to wall
Signage:	standard Erie	
Drainage:		,
Other:	brick corbeled chimneys (N & S)	S. chimney missing
0ri	ginally wood frame canopy surrounded building.	Canopy dismanteled ca. 1973 (ticket agent, 198

FACILITY NAME Hillsdale

RR 0227 = Survey # 6-7

4. DESCRIPTION - BUILDINGS (INTERIOR)

Fill out separate sheets key with, floor plan.	for each building a	t facility.	Refer to, and
Station X Shelter	Freight House	Other	(specify)
General architectural dematerials and finishes.			ng original

The spaces of the Hillsdale station are on two levels. The first floor is divided into (N to S) Waiting Room (1), Ticket Office (2), Baggage Room (5), and Coal Bin (6). Adjoining the S wall of the Coal Bin is a stairway to the Second floor, accessible only from the exterior. The Second floor is divided into three offices, a hall, and a closet. Finishes, although original, are undistinguished (see schedules). Conversely, the timber arch trusses of the roof are exceptionally fine examples of the Eastlake style of ornamentation. It is unfortunate that few people other than railroad employees have ever seen these works.

-5A **RR 0227=** Survey # 6-7

FACILITY NAME: Hillsdale

4. DESCRIPTION - BUILDINGS (INTERIOR) CONTD.

STATION - F	ROOM AND FINISH SCHEDULE NUMBER	OF ROOMS7
NAMEWai	ting Room NUMBER	ON FLOOR PLAN
	<u>Original</u>	Existing, if different
Floors:	board	;
Base:	none	frag. of chairrail E. wall, above bench
Wainscot:	none	
Walls:	vertical matched board, prob. varn.	(maroon, beige paint)
Ceiling:	board and batten, stain or varn.	(beige paint)
Trim:	cornice molding, wood surrounds stain or varn.	(beige paint)
Doors:	2/3 panel, 2/2 panel, stain or varn.	(maroon paint)
Seating:	wood, simple board bench E, N,W, walls stain or varn.	(maroon paint)
Lighting:	probably gas fixtures	hanging incan. bulb, circular shade, hanging fluor. fix.
Other:	coal burning stove & pipe (center of sp counter in front of ticket window, brackets, stain or varn.	ace) (maroon paint)

-5A **RR 0227=** Survev # 6-7

FACILITY NAME:

Hillsdale

4.	DESCRIPTION	- BUILDINGS (INTERIOR) CONTD.	
	STATION -	ROOM AND FINISH SCHEDULE NUMBER	OF ROOMS
	NAMETic	cket Office NUMBER	ON FLOOR PLAN 2
		<u>Original</u>	Existing, if different
	Floors:	board	
	Base:	none	
	Wainscot:	none	
	Walls:	vertical matched board, stain or varn.	(maroon, beige paint)
	Ceiling:	board and batten	
	Trim:	wood surrounds, stain or varn.	(beige paint)
	Doors:	(2/2) wood, stain or varn.	(maroon, beige paint)
	Seating:	none	
	Lighting:	probably gas fixtures	3 hanging incan. bulbs, 2 wit metal shades
	Other:	wood built-in shelf, metal brackets under ticket window coal burning stove and pipe in center o	f space

-5A RR 02**27 =** Survey #-7

FACILITY NAME: Hillsdale

4.	DESCRIPTION	- BUILDINGS (INTERIOR) CONTD.				
	STATION -	ROOM AND FINISH SCHEDULE NU	IMBER	OF	ROOMS	7
	NAME	Baggage Room NU	IMBER	ON	FLOOR PLAN	5
		<u>Original</u>		<u>Exi</u>	sting, if di	fferent
	Floors:	board		<u></u>		
	Base:	none	<u>.</u>	·		
	Wainscot:	none	-			·
	Walls:	vertical matched board, stain or va	rn.	(he	ige paint)	·
	Ceiling:	board and batten, stain or varn.	<u>-</u>	(be	ige, slate bl	ue paint)
	Trim:	molded board surrounds, stain or va	rn.	(be	ige paint)	
	Doors:	2/2. stain or varn.	-	(be	ige, maroon p	maint)
	Seating:	none				
	Lighting:	probably gas fixtures	-	hans	ging incandes	cent bulb
	Other:					

-5A **RR 0227-**Survey # 6-7

FACILITY NAME:

Hillsdale

1.	DESCRIPTION	N - BUILDINGS (INTERIOR)	CONTD.					
	STATION -	ROOM AND FINISH SCHEDULE		NUMBER	OF F	ROOMS_	7	
	NAMECac	ol bin		NUMBER	ON F	FLOOR	PLAN_	6
		<u>Original</u>			Exis	sting,	if d	ifferent
	Floors:	board						•
	Base:	none	•					
	Wainscot:	none						
	Walls:	board		<u>.</u>				·
	Ceiling:	board	,			·		,
	Trim:	u <u>nknown</u>		·				
	Doors:	unknown						
	Seating:	none		indigendend				
	Lighting:	unknown		i	<u>ncan</u>	. bul	b hang	jing
	Other:					-		

-5A **RR 0227**-Survey # 6-7

FACILITY NAME: Hillsdale

DESCRIPTION	- BUILDINGS (INTERIOR) CONTD.		
STATION -	ROOM AND FINISH SCHEDULE	NUMBER	OF ROOMS7
NAME	Second floor offices	NUMBER	ON FLOOR PLAN
	<u>Original</u>		Existing, if different
Floors:	board		a <u>sphalt tile</u>
Base:	none		
Wainscot:	none		
Walls:	matched boards, stain or varn.		(brown, green paint)
Ceiling:	matched boards, stain or varn.	-	(green paint)
Trim:	molded door and window surrounds,		(stain)
Doors:	1/2 panel		
Seating:	none		
Lighting:			
Other: 5	arched ceiling trusses with cutout pendants, 9-pane window between ma rooms, plain frame		

RR 0227-

FACILITY NAME: Hillsdale

Survey # 6-7

5. SIGNIFICANCE OF COMPLEX (ARCHITECTURAL/HISTORICAL):

Architect Post & Camp, Hudson City source (Relics) *

Date12/23/1869 SourceStalton & Alteration dates Ca. 1964 Source Tino

Style Stick, Eastlake, Second Empire Ca. 1970- canopy removed removed passenger trains/day (present) 14 in 1980 Peak (#, Yr.) 38 in 1929

yes Original station on site 32 in 1909

10 in 1941

The Hillsdale station was one of the most distinctive on the Erie line. In design it combines elements of both the Stick and Second Empire styles. Of particular note are the arch trusses on the second floor with their Eastlake detailing.

The building once housed the offices of the Hackensack and New York Railroad, and later the New Jersey and New York Railroad (1873, Stalton & Jones, p. 17). Until completion of the NJ & NY to the New York State border in 1875, Hillsdale was a terminal station, and until 1895, when the NJ & NY came under Erie control, it served as corporate offices for the railroad. This area once had a large freight yard, engine house and turntable. By 1900 a number of trains (5 in 1929) which did not run into New York State were stored here. Today the station serves as a commuter stop for a growing number of users.

A wood frame octagonal outhouse with conical roof and finial and a wood frame freight house once stood just S of the station (Next Station). The building is scheduled for alterations in mid 1981.

* first floor stuccoed

RR 0227 -Survey # 6-7

FACILITY NAME: Hillsdale

6. GEOGRAPHIC DATA

Verbal boundary description (if Block/Lot not available)

Boundary is outlined on site plan.

Acreage: Less than one acre
UTM coordinates: Zone: 18/Easting: 5 8 0 6 4 0/Northing: 4 5 3 9 2 6 0
USGS Quad Park Ridge Scale 1:24 000

7. REFERENCES

BIBLIOGRAPHIC:
Pascack Historical Society, <u>Relics</u>, vol. 14, no. 80, "Centennial of the Railroad,"
p. 4.
Stalton and Wilson Jones, <u>Railway Historical Society Monograph</u>, Railroad Station
Historical Society, Crete, Nebraska p. 7.
Tino, Nicholas A., Jr. personal recollections.

ICONOGRAPHIC:

Photos:
2-(1910) The Next Station Will Be, vol. II, The Railroadians of America Inc. 1974, n.p.
3-(1966) Carelton, Paul, The Erie Lackawanna Story, pp. 325, 475.
Stalton and Jones, p. 11.
(c.1935): Paul Ruhenbeck collection, Kearny, N.J.

8. PHOTO

Negative index #	1293 or NJT photo	
Date1978	Photographer	Richard Browne Assocs.
Loc. of negative	N.J. Transit	Direction of view: Station from South

FACILITY NAME: Hillsdale

9.	۲R	I.	TF	R.	IΔ	FOR	F۱		110	TIC	JN
<i>-</i>				١.		1 ()()		<i></i> 11	UJF		

A. HISTORICAL	SIGNIFICANCE
---------------	--------------

A. HIS	TORICAL SIGNIFICANCE							
i.	Associated with important events of in history		ments					
	in history	nationally state-wide locally						
ii.	Representative of significant char and/or tec		oad history (30) (25)					
		common	(10)					
iii.	Original station on site		<u>X</u> (15)					
iv.	Representative of a line's standar	d design	(10)					
٧.	Constructed prior to 1900		<u>X</u> (15)					
vi.	Junction station		(10)					
vii.	Former long-distance service		(10)					
viii.	Other		X (10) former terminal,					
ix.	Less than 50 years old		corporate office (-30)					
B. ARC	HITECTURAL SIGNIFICANCE		40					
i.	STYLE Eclectic: Stick, Second Empire; Eastlake detailing a. Example of a particular architectural style (check one)							
	Exc	standing cellent	(50) (40)					

	Daniel and a final	Outstanding Excellent Very good Good Fair	(50) (40) (30) X (20) (10)
b.	Rare survivor of style	nationally state-wide locally	(20) (15) _X(10)

c. As example of railroad architecture

rare		early <u>X</u>	(30))
unusual	or	early X	(15))

RR 0227 -	-9
Survey # 6-7	-3

FACILITY NAME: Hillsdale CRITERIA CONT.

ii.	ARCI	HITECT (check one) building by architect important			
		na t s ta	cionally ste-wide cally	(25) (20) (15)	
	b.	building designed by railroad and is or appears to be the work of the supe architect or engineer or chief design	ervising	(20)	
	C.	building designed by railroad and is or appears to be the work of the staf		(5)	
	d.	architect identified but not consider to be of special importance	ed		Post and Camp, Hudson (Jersey)
iii.		RALL ARCHITECTURAL QUALITY (check one) Outstanding composition, siting, or craftsmanship			City, NJ
	b.	Notable composition, siting, or craft manship, or possessing especially picturesque or unusual exterior detai		(25)	
	с.	Possessing some detail(s) of particul interest and/or quality	ar	<u>X</u> (15)	mansard project bargeboards,
	d.	Average quality or interest		(5)	brackets
iv.		CIAL QUALITIES Noteworthy overall interior design or detailing	•	(15)	
	b.	Some noteworthy interior detailing		<u>X</u> (5)	Eastlake roof trusses
	c.	(interior not accessible) Part of cohesive complex 1) station and shelter 2) more than two buildings		(5)	o. 4004 0
٧.	CONST	TRUCTION			
	a.	Noteworthy example of particular construction method		(30)	
	b.	Rare or early survivor of particular method		(20)	
	c.	Interesting example of method		(5)	70

RR 0227= -10

Survey # 6-7

FACILITY NAME: Hillsdale

CRITERIA CONT.

C. CONDITIONS

	_		_	 _	_	_	
÷	Т	NI	т	r	ח	т	TY
1	1	IV	1	u	ĸ	1	11

	a.	Original condition		(40)
		Alterations and/or additions, beneficial		(30)
	c.	Alterations and/or additions, not detrimental		_(20)
	d.	Minor detrimental alterations and/ or additions, not affecting overall integrity		— (10)
	e.	Detrimental alterations and/or additions, reversible at considerable expense	X	
	f.	Detrimental alterations and/or additions, essentially irreversible		canopy removed (-75)
•	PHYS	SICAL CONDITION		
	a.	Excellent		(10)

ii.

a.	Excellent	(10)
b.	Good	(5)
c.	Fair	<u>x</u> (0)
d.	Poor	(-10)
e.	Severely deteriorated	(-25)

iii. RELATIONSHIP TO COMMUNITY

a.	Pivotal building	(40)
b.	Integral part of townscape	χ (30)
c.	Compatible with townscape	$\frac{-1}{(20)}$
	Unrelated to townscape	(0)
e.	Incompatible	-30)

iv. SUITABILITY FOR ADAPTIVE USE

a.	Excellent	(30)
b.	Very Good	$\overline{\chi}$ (25)
c.	Good	(20)
d.	Average	(15)
e.	Possible, with difficulty	(10)

30


TOTAL


125

Attach copy of site plan
___continuation sheets attached

FORM PREPARED BY: Richard Meyer Date: August 1981

HERITAGE STUDIES, INC. RD 4 Box 864, Mapleton Road Princeton, N.J. 08540 609-452-1754










M.P.-21.5


Looking northwest to the Hillsdale station. The neat little FREIGHT HOUSE and a tastefully decorated outhouse will be noticed in both pictures.



M.P.-21.5
When the railroad was finished to HILLSDALE in 1869, offices of the company were located on the second floor of this new station and remained there for many years. There were complete shop facilities and an engine house situated just behind the photographer.

SUMMARY

Station:	Hillsdale	Line:	Pascack Valley
Index:		Fie	eld Survey Conducted February, 1979
X	 Site Base at 1" = 100 Floor Plan at 1" = 20 Platform and Canopie Station Building Track Crossings and B Parking Access and C Information System Notes on Community Record Photograph of 	s Structural arriers irculation & Security A	·
Informati	on File:		
X X X	Aerial Photograph at 1" = Station Location Plan from Proposed Taking Lines of Summer 1970 Ground Surv September 1974 Survey = Tri-State Aerial Photo Su Conrail Data Survey for S TOPICS or Traffic Improv Community Renewal Plans Historical File for Station Schedule of Trains and Bu Other	m USGS maps 900 Day Opt yey of Rail Po NJ DOT (De rvey of Rail I station ements Plann s for Station	ion Station Parcels orking – NJ DOT opt. of Commuter Services) Parking 1970
	Count May 1977 - All Day (W	•	
Station Ri	dership Category: 4	Ownersnip:	N.J.D.O.T.
Agent:	Yes Hrs/Days:	5:45 a.m	2:15 p.m. Monday through Friday
Rehabilita	ated (10 years or less) & Desc	ription:	



3 PLATFOR	MS & C/	ANOPIES	Station	n: HILLSE	DALE	
		را <i>د</i>	1 <	SIDING		
NO. of TRACKS: 2	In-Bound (NY,H,I	N)*Out-B	•		activeI.B	O.B.
	it(Walls)	Cross Slope	Elevated		bankment Structure	
Straight <u>×</u> Curve To Board must Commuter wal		Visibility Proble			•	k f/rail:
			<i>5</i> ,			
PLATFORMS	IN-BO	UND SIDE	OUT-BO	UND SIDE	ISLAND BET'I	n track
Length X Width	<u>UA</u>	X	·	RHINANT	<u>~~</u> x	
Height Above Top of Rail			FLL			
Platform Material			ASP4, GRAVEL			
Edge Material				رحد.		
Safety Line, Material	yes/no		yes/no_YELLO	ow STRIPE	yes/no	
Guardrail (Locate)	yes/no		yes/no		yes/no	
In-cut/Retaining Walls						
Lighting - Type,			<u> </u>	<u>'</u>		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
O.C., Setback f/rail			NON			
Seating-Mat'l & Qty .	vert.rise	width	vert.rise .	width	vert.rise	width
Stairs: (ramps used: A yes / no) B						
Locate: C		<u> </u>		·		
CONDITION/LOCATION -	· (platform, lighting	, stairs, guardrails,	retaining walls. No	ote apparent poor	conditions only)	
PLATE NOT	REDUCT &	DEFINITE	PLATFORA	1, 1457	OPEN DIET	DRED.
PARTIA	LLY PAVE	D NEAR	STAT, BUT	15PH . 15	S CRUMBLIA	7G
INTO	GRAUEL.					
LIGHTING - NON	14					
200	<i></i>					
	•					
					Continue on back	of page
CANOPY/OVERHAN	IN-BO	UND SIDE	OUT-BOL	JND SIDE	ISLAND BET	N TRACK
Length x Width		X	x_		X	
Height (Lowest)						
Setback from Rail						
Structure w/Spacing		\mathcal{L}	4			
Setback-Rail to Support						
Deck Material		·				
Roofing						

CONDITION (Note apparent poor conditions only):

Shape Drainage Lighting

4	STATION E	BUILDIN	IG	×	_ SHE	LTER		
					S	TATION:	HILLS DALE	
Re I Roc	Bound (NY, H, N)I ation of Main to Track (under of Overhang - width: erior and Entry Stairs, Ramps a) width c) width	er, over, <u>leve</u> , escalators, el vertical r	l) Relation Location evators: (No iseンム	of Entry to Str : (refer to Floo te vertical rise	reetor Plan <u> </u>	- 1.B. <u>とどり</u> o Floor Plan &	label for cross-reference control control	O.B.
E>	CTERIOR MATERIALS							
Bas Wa Trii Wii	undation WODP ON EA e Course Ills STUCCO m WOOD ndows - operable - yes / (consultant_	10) цоsт В	_(photo)	Roof Soffi	Deck 45	000		
Dre	sinage EDGE DE	IN AGE-	No 8	urters				
	Space* Waiting RoomS.F. Ticket Office Mens Toilet	FINISH SC Floor was D wood	,	(Locate on W/Cot	Floor Plan) Walls wood	Ceiling woo O	Ceiling Hgt.	Lighting FLOE.+ /NCANP. /NCAND.
4.	Womens Toilet STC R. COAL BIU	ωσορ ωσορ	-		wo00	w00D	11 ⁷ 510883	INCAND
Α.	Concessions and Businesses:	Taxi Other:	Newspaper	stand/aoin bo		Pay Toilet	. ⊻ e ndin	g Machines
С.	Waiting Room Seating: des Number of Public Phones ar Indicate Visibility of appro-	nd Locations:	NE IUSID	€ >€		1.8. <u></u> Ga	Capaci	BUDD
Ε.	Describe visibility for surve	illance for wait	ing rooms wit	h and without	agents:	G000		· · · · · · · · · · · · · · · · · · ·
F.	Is passage from the station t	o platforms shel	tered: yes /	(photo d	escription)			
	Are public toilets, telephonal Are lockers provided: yes platform I.B. (NY) #	/no ; trash re	eceptacles: y	es / 🔞 , lo	cation: waiting	room #	_	
1.	Mailbox: yes / no							
J.	Water fountain: yes / fo	; location:				·		
	Describe other commuter co							
S	EN SHELTER - location: 1. ize Width Material	8. (NY, H, N)	gth	O.B _Height	(indicate on site	plan or aerial,	: photos or sketch)	
В	ase			XX				
-	ondition							
				_				

^{*}Label rooms on floor plan by function and numerical no. to aid cross referencing.

STATION: HILLS DALE

Record Photograph____

CONDITION: *

Exterior (indicate board-up areas; locate elements being described using floor plan/photos) (Consultant)

Foundations: WOOD STRUCTURE SEEMS TO REST DIRECTLY ON EARTH. STRUCTURE HAS SETTLED (SEE BELOW#)

Walls/Doors/Windows:

WALLS - STUCCO IN GOOD COND. BUT ALL WOOD TZIM CONTAINS DRY ROT.

DOORS - POOR COND., OLD, DRY ROT VERY BAD. WINDOWS - MOST BOAR DED, DRY ROT VERY BAD

Stairs: NA

Roof/Drainage: ASPH. SHINGLES APPEAR IN GOOD COND. DRAINAGE - EDGE DRAINAGE - NO GUTTERS

Other ALL WD. ON ENTIRE STAT. ROTTING FLOW LOTE: LOT THAT BARO; IT HAS BELLU SAND BURSTED.

Interior (locate elements by room; photograph poor conditions)

Walls/ Doors/Windows:

WALLS - VEET. SIDING - FAIR COND., GAPS BETWEEN BOTHERS DOORS - FAIR-POOR COND., OLD + BESTEN, NOT SOULRE IN FRAME RED. SOME FORCE TO CLOSE TIGHTLY. WINDOWS - FAIR COND., OLD + WORN, UPPER HALVES BOLR DED.

Floor: FXIE-POOR - WOOD OLD + WORN BUT SMOOTH -HIGH SPOT IN FLOOR UNDER STOVE, SLOPES TO SIDES + OUTBO END. IN FELME GUTIRE OUTBD. END HAS SETTLED, VERY NOTICABLE Ceiling: OVER DOOR.

FRIE-POOR - BOLEOS HAUG BOWED, SOME COMING LOCSE, HALF-ROUNDS AT LOINTS SEPARATING, COMING LOOSE, SCALE MISSING CRUDELY PATCHED IN ONE PLACE. Stairs: W

4b MECHANICAL & ELECTRICAL

STATION: HULSDALE

HEATING		
Location of Heating Unit: COSC STOUE Type of Unit:	ル いなけいいら TZM Output:	+ TICKET OFFICE Fuel: COAL
Controls:	Zones:	Storage Capacity:
Burner Size:	Make of Unit:	Make of Burner:
Distribution System:		
REMARKS:		
AIR CONDITIONING Location: NONE Type:		
Type:	, ,	
Spaces Handled:		
REMARKS:		
VENTILATION Windows: Yes / No Door: Yes / No Is air quality good: Yes / No	八点 Toilet Rooms: Mechanical	Natural
ELECTRIC	·	
Location of Service Entrance:		
Location of Main Panel:		
Characteristics: Amps Volts	WirePhase	
Apparent Major Deficiencies in wiring: Conduit	Circuits Fused Yes / No	
GENERAL LIGHTING EVALUATION (In Description / Condition / Quantity: ONE INCAND. BUCB OVER TO ONE FLOR. FIXTURE W/Z-4 BOTH FIXTURES OLD BUT	terior) CKET WINDOW 84465	
Lighting does / does not appear to be adequate; there	e are / are not dark spots; there i	s / (is not glare. Continue on back of page

8 Community & Security Aspects

Station: Hillsdale

1. Describe the setting of the station in terms of the activity in the surrounding area (land use and condition described in section 6). Describe the visibility of the station and site from surrounding areas of streets in terms of security through surveillance. Describe screening and shielding (note #6, page 4) and shadows, nooks and crannies, and other hiding places).

The station is located in the center of the main shopping area in the town. It is surrounded on all sides by stores and small businesses.

The station is easily visible from the local streets, and adequate surveillance by motorized police patrol is possible. There are no hiding places or dark spots.

2. Is the station out of the "main stream" of pedestrian/vehicular activity, or is it part of the fabric of life in the community? Do non-commuters walk through the station building or use any part of the station facilities/site to shorten their path to a final destination; to shop; to conduct business such as banking (refer to #4 Station Building/Interior Space _____):

The station is surrounded by streets which have heavy vehicular traffic and moderate pedestrian traffic. The station is definitely in the center of community activity. Non-commuters do cut across the site and tracks to and from the shopping center across the tracks.

3. Vandalism: Graffiti - none / low / medium / high; location:

Property damage - none / low / medium / high (describe):

4. Question the ticket agent about vandalism problems.