

Photo credit: Bonnie J. Halda
Date: 3/28/83
Negative Location: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View: Facade from south-southeast.

Photo 1 of \$10




Photo credit: Bonnie J. Halda
Date of Photo: 3/28/83
Location of Negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View: Facade from southeast.

Photo 2 of \\ 10



Photo credit: Bonnie J. Halda Date of photo: 3/28/83

Location of negative: State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

View: Rear wall and east wall from northeast showing modern elevator/stairwell addition.

Photo 3 of \$ 10



Photo credit: Bonnie J. Halda
Date of photo: 3/28/83
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View: Rear of building from north.

Photo 4 of \$10



Photo credit: Bonnie J. Halda
Date of photo: 3/28/83
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View: West wall from the northwest.

Photo 5 of **₹** 10



Photo credit: Bonnie J. Halda

Date of photo: 3/28/83

Location of negative: State Historical Society of North Dakota North Dakota Heritage Center

Bismarck, ND 58505

View: Fourth floor (attic) storage room (former dormitory room) from hallway.

Photo 6 of \$ 10



Photo credit: Bonnie J. Halda Date of photo: 3/28/83

Location of negative: State Historical Society of North Dakota

North Dakota Heritage Center Bismarck, ND 58505

View: Newel post and baluster detail at west stairwell landing between third and fourth floors.

Photo 7 of ¥ 10



Photo credit: Bonnie J. Halda
Date of photo: 3/28/83
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

/iew: Third floor classroom showing typical remodelling treatment.

Photo 8 of \$10




Photo credit: Bonnie J. Halda

Date of photo: 3/28/83

Location of negative: State Historical Society of North Dakota

North Dakota Heritage Center

Bismarck, ND 58505

View: Third floor hallway looking east to new elevator/ stairwell addition entry; typical of interior remodelling treatment of hallways.

Photo 9 of \$10




Photo credit: Unknown Date of photo: ca. 1895

Location of negative: State Historical Society of North Dakota

North Dakota Heritage Center Bismarck, ND 58505

BISHIATCK, NU 3030

View: Facade from south-southwest

Photo 10 of 10