

Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View from west

Photograph 1 of 9



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View from south

Photograph 2 of 9



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View from northeast

Photograph 3 of 9



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View of living room and dining room from the west. Interior columns and cupboards are part of 1984-85 restoration

Photograph 4 of 9



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View of corner fireplace in the southwest corner of the living room. Rebuilt in 1984-85 restoration

Photograph 5 of 9



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View of front hall/stairs from the southwest

Photograph 6 of 9



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View of stairs from the west. Panelling restored in 1984-85.

Photograph 7 of 9



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View of typical first-floor leaded glass window. Living room.

Photograph 8 of 3



Photograph by Frank Fiori January 1985

Negative on file at Preservation Services, Pocatello, Idaho

View from northeast

Photograph 9 of 9