| BU             | TORIC RESOURCES INVENTORY<br>LDING AND STRUCTURES<br>T-6 NEW 5/77   | FOR OFFICE USE;ONLY       Town No.:     Site No.:        |  |  |  |  |
|----------------|---|--|--|--|--|--|
| ·              | STATE OF CONNECTICUT<br>CONNECTICUT HISTORICAL COMMISSION<br>59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106<br>(203) 566-3005  | UTM1 8 6 8 7 1 5 0 4 6 2 8 7 5 0<br>QUAD: Hartford North |  |  |  |  |
| (              | 129   | DISTRICT IF NR. SPECIFY                                  |  |  |  |  |
|                | 1. BUILDING NAME (Common) (Historic)  |  |  |  |  |  |
| IDENTIFICATION | 2. TOWN/CITY VILLAGE  | COUNTY   |  |  |  |  |
|                | West Hartford   | Hartford   |  |  |  |  |
|                | 847 Main Street North approx8 acres Vol. 86   | 3, p. 175.   |  |  |  |  |
|                | 4 OWNER(S)<br>Forgotson, Jay M & Susannah   | Public Private   |  |  |  |  |
|                | 5. USE (Present) (Historic)<br>Residence Residence  | ce   |  |  |  |  |
|                | 6.<br>ACCESSIBILITY EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, E<br>TO PUBLIC: Yes No Yes No   |  |  |  |  |  |
| DESCRIPTION    | 7. STYLE OF BUILDING<br>Mid 19th C. vernacular  | DATE OF CONSTRUCTION<br>C.1850?                          |  |  |  |  |
|                | 8. MATERIAL(S) (Indicate use or location when appropriate)           X Clopboord         Asbestos Siding         Brick         Other (Special Special | fy)  |  |  |  |  |
|                | Wood Shingle Asphalt Siding Fieldstone  |  |  |  |  |  |
|                | Board & Batten Stucco Cobblestone   |  |  |  |  |  |
|                | Aluminum Concrete Cut stone<br>Siding Type: Type:   |  |  |  |  |  |
|                | 9. STRUCTURAL SYSTEM Wood frame Post and beam Aalloon   |  |  |  |  |  |
|                | Load bearing masonry Structural iron or steel   |  |  |  |  |  |
|                | Other (Specify)   |  |  |  |  |  |
|                | 10. ROOF (Type)           X         Gable         Flat         Mansard         Monitor         sawtor   | oth  |  |  |  |  |
|                | Gambrel Shed Hip Round Other  | oth<br>(fγ)  |  |  |  |  |
|                | (Material)  |  |  |  |  |  |
|                | Wood Shingle Roll Slate   |  |  |  |  |  |
|                | X Asphalt shingle Built up Tile Other (Specify)   |  |  |  |  |  |
|                | 11. NUMBER OF STORIES     APPROXIMATE DIMENSIONS       2     33 x 62  |  |  |  |  |  |
|                | 13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN   | ood <b>Fair</b> Deteriorated                             |  |  |  |  |
|                | 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES  | se is older and updated in 1850                          |  |  |  |  |
|                | Barn Garage Other landscape features or buildings (Specify)<br>Mature trees surround property   |  |  |  |  |  |
|                | L house Shop Garden   |  |  |  |  |  |
| i              | Open land Wood- Residential Scattered buildings vi  |  |  |  |  |  |
|                | Commercial Indus-<br>Itial Rural X High building density<br>16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS  |  |  |  |  |  |
|                | House is sited on rise of land, with stone wall embankment.<br>On busy highway, near stop light.  |  |  |  |  |  |

| DESCRIPTION (Continued)  | 2 story 5 bay symmetrical facade with paired interior end chimneys. (large)<br>Gable roof has wide overhangs with returns, small blank frieze under eaves,<br>medium width cornerboards.<br>Center entrance has no window above doorway.<br>Doorway : Composed of 1 pilaster on each side, minimal necking and capital<br>pulvinated frieze across top of door, flat hood. Entry door has 4 square<br>lights in top of door.<br>Sash windows, 2/2, minimal flat top hoods over ground floor windows.<br>Twin smaller sash windows in gable 6/6.<br>1 story gable "ell" to rear contains garage<br>Foundation appears to be cement. |                 |             |  |  |
|--|--|-----------------|-------------|--|--|
|  | 18. ARCHITECT  | BUIL            | Unkruwn     |  |  |
|  | 19 HISTORICAL OR ARCHITECTURAL IMPORTA   | ANCE            | Unrrown     |  |  |
| SIGNIFICANCE   | The entry door, and the lack of window in center of facade 2nd floor a indicative of the time span of building this vernacular house.  |                 |             |  |  |
| SOURCES  |  |                 |             |  |  |
| РНОТО  | NAME<br>Sherrill Foster $3/84$<br>ORGANIZATION<br>DATE<br>3/84   |                 |             |  |  |
| СОМР   |  |                 |             |  |  |
| <pre>20 SUBSEQUENT FIELD EVALUATIONS<br/>Hatheway research gives date as c.1777, and overhang<br/>substantiates this; doorway is Georgian (pulvinated<br/>frieze), not Greek Revival.<br/>Sign on house: Gurdon Flagg/Built in 1748<br/>Eaves treatment is mid-19<sup>th</sup>century. HRC 12/84</pre> |  |                 |             |  |  |
|  | HREATS TO BUILDING OR SITE<br>Ione known Highways Vanda  | lism Developers | Other       |  |  |
|  | Renewal Private Deteri   | ioration Zoning | Explanation |  |  |
| HIST   | 6 NEW 5/77 (BACK)  |                 |             |  |  |