

**HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES**

HIST-6 NEW 5/77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
(203) 566-3005

144

FOR OFFICE USE ONLY	
Town No.:	Site No.:
UTM 1: 8 6 8 8 4 5 0 4 6 2 4 8 8 0	
QUAD:	Hartford North
DISTRICT	IF NR, SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION	1. BUILDING NAME (Common) (Historic)		ELISHA SEYMOUR, JR.	
	2. TOWN/CITY	West Hartford	VILLAGE	COUNTY Hartford
	3. STREET AND NUMBER (and/or location) 410/412 PARK ROAD			
	4. OWNER(S) LINDSTROM, R.W. et al. approx. .4 acres Vol. 268, p. 350. <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private			
	5. USE (Present) (Historic) TWO FAMILY ONE FAMILY			
	6. ACCESSIBILITY TO PUBLIC:		EXTERIOR VISIBLE FROM PUBLIC ROAD <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
DESCRIPTION	7. STYLE OF BUILDING COLONIAL			DATE OF CONSTRUCTION C 1770
	8. MATERIAL(S) (indicate use or location when appropriate)			
	<input type="checkbox"/> Clapboard	<input type="checkbox"/> Asbestos Siding	<input checked="" type="checkbox"/> Brick	<input type="checkbox"/> Other (Specify) _____
	<input type="checkbox"/> Wood Shingle	<input type="checkbox"/> Asphalt Siding	<input type="checkbox"/> Fieldstone	
	<input type="checkbox"/> Board & Batten	<input type="checkbox"/> Stucco	<input type="checkbox"/> Cobblestone	
	<input type="checkbox"/> Aluminum Siding	<input type="checkbox"/> Concrete Type: _____	<input type="checkbox"/> Cut stone Type: _____	
	9. STRUCTURAL SYSTEM			
	<input checked="" type="checkbox"/> Wood frame	<input type="checkbox"/> Post and beam	<input checked="" type="checkbox"/> balloon	
	<input type="checkbox"/> Load bearing masonry		<input type="checkbox"/> Structural iron or steel	
	<input type="checkbox"/> Other (Specify) _____			
10. ROOF (Type)				
<input checked="" type="checkbox"/> Gable	<input type="checkbox"/> Flat	<input type="checkbox"/> Mansard	<input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth	
<input type="checkbox"/> Gambrel	<input type="checkbox"/> Shed	<input type="checkbox"/> Hip	<input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____	
(Material)				
<input type="checkbox"/> Wood Shingle	<input type="checkbox"/> Roll Asphalt	<input type="checkbox"/> Tin	<input type="checkbox"/> Slate	
<input checked="" type="checkbox"/> Asphalt shingle	<input type="checkbox"/> Built up	<input type="checkbox"/> Tile	<input type="checkbox"/> Other (Specify) _____	
11. NUMBER OF STORIES		APPROXIMATE DIMENSIONS		
TWO		28x24 wing 23x20		
12. CONDITION (Structural) (Exterior)				
<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Deteriorated <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated	
13. INTEGRITY (Location)		WHEN ?	(Alterations) IF YES, EXPLAIN	
<input checked="" type="checkbox"/> On original site	<input type="checkbox"/> Moved		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No ENTRY PORCH ADDED	
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES				
<input type="checkbox"/> Barn	<input type="checkbox"/> Shed	<input type="checkbox"/> Garage	<input checked="" type="checkbox"/> Other landscape features or buildings (Specify) YOUNG TREES, LAWN	
<input type="checkbox"/> Carriage house	<input type="checkbox"/> Shop	<input type="checkbox"/> Garden		
15. SURROUNDING ENVIRONMENT				
<input type="checkbox"/> Open land	<input type="checkbox"/> Wood-land	<input type="checkbox"/> Residential	<input type="checkbox"/> Scattered buildings visible from site	
<input type="checkbox"/> Commercial	<input type="checkbox"/> Industrial	<input type="checkbox"/> Rural	<input type="checkbox"/> High building density	
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS				
SITED ON HILL, SLOPING TO ROAD, SET WELL BACK beyond THE VERANDA LINE				

(OVER)

DESCRIPTION (Continued)

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (Interior and/or exterior)

Two story three bay center entrance painted brick house with gable roof. Side gable ends have returns, slight overhang. Paired large chimneys. Windows sash 6/1, louvered shutters. Tops of windows close to roof overhang. One story wing with 4 chamfered posts supporting shed roof. Enclosed shed roof entry porch with large side windows.

18. ARCHITECT: *N/A* BUILDER: *Unknown*

SIGNIFICANCE

19. HISTORICAL OR ARCHITECTURAL IMPORTANCE

This house is significant because it is one of few remaining brick houses of colonial vintage in the West Division, although it is quite a plain structure.

Elisha Seymour, jun. was a shoemaker.
(Information on file at West Hartford Historical Society)

INFORMATION FROM Elizabeth Hatheway 2/13/85

SOURCES

Information about this house from Miss Elizabeth Hatheway,
Letter. 2.13.1985.

PHOTO	PHOTOGRAPHER	Anthony Kapsis	DATE	4/85
	VIEW	<i>NORTH</i>	NEGATIVE ON FILE	<i>03B</i> / <i>B1B</i>
COMPILED BY	NAME	Sherrill Foster	DATE	May 1985
	ORGANIZATION	Noah Webster Foundation & Historical Soc. of West Hart.		
	ADDRESS	227 South Main Street, West Hartford, CT 06107		



20. SUBSEQUENT FIELD EVALUATIONS

21. THREATS TO BUILDING OR SITE

None known
 Highways
 Vandalism
 Developers
 Other _____

Renewal
 Private
 Deterioration
 Zoning
 Explanaton _____