CLASSIFIED STRUCTURE FIELD INVENTORY REPORT (Attach 4" x 5" Black and White Photograph)

)

REGION RMR PARK/AREA NAME ROMO PARK NUMBER 1520		
STRUCTURE NAME Mess Hall and Residence STRUCTURE NUMBER HS-220		
LOCATION OF STRUCTURE Milner Pass Road Camp PARK LOCATION CODE PG		
NATIONAL REGISTER 0 DATE: // MANAGEMENT CATEGORY: (A) (B) 🕐 (D)		
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO		
Check all of the following categories for which NPS has treatment responsibility:		
Stabilization 💓 Cyclic Maintenance 🗱 Routine Maintenance 🗱 Approved Ultimate Treatment (
(ROCKY MOUNTAIN REGION USE ONLY)		
APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION		
Preservation(PP)Restoration(RR)Reconstruction(CC)Adaptive Preservation(AP)Adaptive Restoration(AR)Adaptive Reconstruction(AC)Neglect(NG)Remove(RM)No Approved Treatment(NO)		
Approval Document()Document Date: _/ / Estimated Treatment Costs		
Stabilization: \$Date: / / Level of Approved Treatment: \$Date: / / Estimate: (A) (B) (C) Estimator: (Region) (DSC) (A&E)		
STATEMENT OF SIGNIFICANCE:		
Date of Construction: / / 1926 Date of Alterations: / / Architect/Designer: Landscape Eng.Div. Historical Theme(s): NPS Rustic Architecture History of Structure: Structure #220 was built in 1926 at an estimated cost of \$3,000. Plans were designed by personnel of the Los Angles Landscape Engineering Division, under the supervision of Daniel P. Hull. Landscape Engineer. The build- ing is currently used for NPS employee quarters.		
Evaluation of Structure: Historic Theme Contributing X Non-Contributing National Register Criteria: A B $C \not D$ (Include integrity statement) This log structure is one of the earliest structures in the park to demonstrate the "NPS Rustic" style of architecture and contributes to the historical and environmental character of ROMO. Unaltered exterior. Integrity intact. Bibliography: <u>ROMO Building Maintenance Files: "Superintendent's Annual</u> Reports 1915-1930." Representation in Other Surveys: LCS David Adams 1/14/82		
If structure has been removed, how? N/A Date: / /		
Report prepared by: <u>Carl and Karen McWilliams</u> Date: <u>8/20/1985</u>		

.

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME HS-220 Mess Hall and Residence	
LOCATION: Section <u>6</u> State <u>CO</u> Township <u>5N</u> County Larimer	Original Use <u>Mess Hall and NPS Quarters</u>
Range 75W OWNERSHIP: Present Owner: U.S. Govt. Original Owner: U.S. Govt. Intermediate Owner(s):	
PHYSICAL DESCRIPTION	
TYPE OF STRUCTURE (NPS 28 CODE): BU ARCHITECTURAL CHARACTER (STYLE): NPS Rustic Architecture Y SITE (INCLUDE ORIENTATION OF STRUCTURE): Open, native pines, firs, grasses and soils. Facade to NE.	<pre>CHIMNEYS: One - of red brick, on the interior of the SW ele Brick is crumbling. Two - Metal vent pipes.</pre> PORCHES: Seven wood steps on NW elev.
OVERALL BUILDING PLAN (FOOTPRINT): Rectangular. Bays: 3 by 1; Piles: 2 OVERALL DIMENSIONS: 35'0" by 18'0"	WINDOWS: Six - 6 beside 6 sliders. Rectangular, green wood frames and screens, flat arches.
COMPOSITION (NPS 28 CODE): WD STORIES: 1 ¹ / ₂ FOUNDATION: Low to medium, 0'0" to 3'4", of uncoursed fieldstone.	DOORS: Three - Single, brown, board and batten, two on facade, one on NW. elev. One - Single, brown, wood paneled on NW elev. ADDITIONS: One - 5' by 9', shed roof, on SW. elev. Shower
WALLS: Brown. Logs, with saddle notching at corners.	INTERIOR PLAN: Three rooms used as NPS Employee's Quarters.
ROOF: Gable. Green wood shingles doubled every fifth course, with exposed log rafter ends. Roof is badly deteriorated. Structure still retains historic character.	INTERIOR FINISHES: Walls and ceiling: Exposed log frame. Floor: Tongue and groove wood flooring.

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES: