## HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES HIST 6 NEW 5 77

CONNECTICUT HISTORICAL COMMISSION
SOUTH PROSPECT STREET, MARTFORD, CONNECTICUT 00.106
(203) 566-3005

I out	- 1	Site No
Town No	*	Site No
UTM	<b>\  \  \  1</b> ;8 6 <sub>1</sub> 9:4 7;2;0 4;6 3;3 8;0;0	2:0 4:6 3:3 8
QUAD	Hartfo	d North
] [	DISTRICT:	IF NB SPECIES
_	z z	Actual

	DESCRIPTION															IDENTIFICATION												
Located on the northwest corner of Windsor Avenue and Giddings Avenue surrounded by residential uses. $(OVER)$	TE INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS	Commerced Indus. Rural High building density	SUPPOUNDING ENVIRONMENT  Open land land Residential Scattered buildings visible from site	Carriage	George	No real	Polit Deteriorated EXE	35'x79"	Bush up	wood Stringle   Roll   Tin   Stere	Material	Gambrel Shed X Hip Round Spec-1/1	Gable   Flet   Monsord   Monitor   Sawtooth	Other Specify	X) Load bearing masonry Structural iron or steel .	X Wood frame Post and beam   balloan	Aluminum Concrete V Cut stone doballs	Board & Batten Strucco Cabbiestene	Wood Stringle Asphalt Siding   Fieldstane	Clapboard Asbestes Siding X Brick (15pecily)			1 Family Residential	Shirley M. Dudley 1003 Windsor Ave.,	1003 Windsor Avenue map 67, block 44, lot 16; .42 acre	Windsor Avenue	AME (Common)	Them 4403
HIST & NEWS	1 z 4 w									URCE		-	SIGNIFICANCE						<b></b>	5	-		DESC					
:	i	1	1		000	75 [	Plan	rest	ast	Micha	HOTOGRA	1869 U.S.	Stile	Town.			the 1	This War v	new e	969 W	Examp		HO 751H 61	ARCHI	a sou		Each	level

(Continued) 2 story masonry dwelling with flat roof, 3 bays wide by 2 bays deep. Has 2 story masonry ell attached to the rear plus 1 story ell on that. Both ells have flat rooves. Eaves project over end-walls forming bold roof configuration. Attic level has small rectilinear windows. Fenestration is symmetrical on the front. Each bay has 2 x 2 sash and cut-stone block lintel and sill. The entry is off-centered on the front and has sidelights and transom around a paneled door. A small porch covers the entry. It has turned posts and hood. South side has canted bay window (1 story) and paired window above this. Attached to the rear ell is a south side enclosed porch. 

BACK.

Privere Highways

Zaning