



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

PATEE HOUSE

AND/OR COMMON

Patee House Museum

2 LOCATION

CITY, TOWN

St. Joseph

___ VICINITY OF

COUNTY

Buchanan

STATE

Missouri

3 PHOTO REFERENCE

PHOTO CREDIT

Stephen Lissandrello

DATE OF PHOTO

May 1975

NEGATIVE FILED AT

Historic Sites Survey, Washington, D.C.

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO

Facing south across 12th and Penn Streets to front entrance, Patee House



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC PATEE HOUSE

AND/OR COMMON Patee House

2 LOCATION

CITY, TOWN St. Joseph VICINITY OF COUNTY Buchanan STATE Missouri

3 PHOTO REFERENCE

PHOTO CREDIT Stephen Lissandrello
NEGATIVE FILED AT Historic Sites Survey

DATE OF PHOTO May 1975

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

PHOTO NO

Facing northeast to rear section of Patee House. Note brick extension and smokestack from factory period.



1860

PONY EXPRESS

OFFICE



View SE, looking at N and W exposures of building. These two sides have been restored. Note new porch. Note brick work done to restore window, 3rd window S, 2nd floor, W exposure.



View of recently installed porch and restored main entrance. Plaque will be mounted on one of these brick columns. Note lighter brick, exposed during restoration - this brick in need of preservative treatment.

View of W exposure. Note woodwork separating from brick. Supports are for once extant balcony, planned for eventual restoration.





View NW, looking at S and E exposures. Pile of bricks is being used to build veneer over concrete blocks used when display area was enlarged. Note cupola.

View of SW corner. Note contact line between very old (original?) brick and old brick. Entire W exposure was apparently rebricked sometime (unknown) in the past.





View NE, looking at S exposure. Note location of Jesse James House, recently moved to the grounds to keep it in the community. House does not intrude on visual integrity of the Patee House when Patee House is viewed from NE, prime visitor area.



View SW, looking at N and E exposures. Restoration work is currently being planned for E and S exposures.