(1) RAVENWOOD PLANTATION
COLLETON CO., S.C.

MAIN UPSTREAM DIKE LOOKING S INTO RICEFIELD # 1

(2) RAVENWOOD PLANTATION
COLLETON CO., S.C.

MAIN UPSTREAM DIKE VIEW FROM INSIDE RICEFIELD #1

(3) RAVENWOOD PLANTATION
COLLETON CO., S.C.

MAIN BACK DIKE LOOKING S TOWARD INTERSECTION
OF SECONDARY DIKE DIVIDING RICEFIELDS #1 AND #2

(4) RAVENWOOD PLANTATION
COLLETON CO., S.C.

SECONDARY DIKE DIVIDING RICEFIELDS # 2 AND # 3

(5) RAVENWOOD PLANTATION
COLLETON CO., S.C.

RICEFIELD # 2 SHOWING REMAINS OF "QUARTER DIKE"
AT LEFT, MAIN BACK DIKE AT RIGHT

(6) RAVENWOOD PLANTATION
COLLETON CO., S.C.

CANAL, LOOKING S BETWEEN RESERVE POND AND RICEFIELDS # 2 AND # 3

(7) RAVENWOOD PLANTATION
COLLETON CO., S.C.

BREAK IN THE DIKE CAUSED BY A SPRING
"FRESHET"