Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on hand at AHPP
View from west



Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View from South

Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View from west

Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View from east



Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of sanctuary from east



Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of pens

Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of chancel railing


E.C. AND F.E. MORRIS

Centennial Baptist Church
Phillips Co. Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
Stained glass Memorial Window

Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of stained glass windows in west facade



Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope

July 17, 2000
Negative on file at AHPP
View of sanctuary from east

Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of Sanctuary from west



Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of sanctuary from North



Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of lancet window

Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of Brackets in Sanctuary

Centennial Baptist Church
Phillips Co. Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
View of Chancel from North


CAUTION CAUTION

Centennial Baptist Church
Phillips Co, Arkansas
Holly Hope
July 17, 2000
Negative on file at AHPP
view of sanctuary from North