RB 7810/18a
SWEDISH EVANGELICAL LUTHERAN
SALEM CHURCH (1906)
WAKEFIELD, DIXON CO., NEBR.
DX09-1
GENERAL VIEW OF SOUTH AND
EAST FACADES, LOOKING NORTHWEST
PHOTO: R. BRUHN, OCT. 1978

Photo #1 of 7

Swedish Evangelical Lutheran Church (DX09-1)
Wakefield, Dixon County, Nebraska

Photograph by R. Bruhn, Lincoln, Nebraska
October 1978 (RB7810/18A)

General view of south and east facades,
looking northwest

047 RB7810/18a NEBR.

047 RB7810/17b 06P2

RB 7810/17b

SWEDISH EVANGELICAL LUTHERAN SALEM CHURCH (1906)

WAKEFIELD, DIXON CO., NEBR.

DX09-1

GENERAL VIEW OF SOUTH AND WEST FACADES, LOOKING NORTHEAST

PHOTO: R. BRUHN, OCTOBER, 1978

Photo #2 of 7

Swedish Evangelical Lutheran Church (DX09-1)
Wakefield, Dixon County, Nebraska

Photograph by R. Bruhn, Lincoln, Nebraska
October 1978 (RB7810/17B)

General view of south and west facades,
looking northeast

RB 7810/18b

SWEDISH EVANGELICAL LUTHERAN
SALEM CHURCH (1906)
WAKEFIELD, DIXON CO., NEBR.

DX09-1

DETAIL, WEST DOOR, LOOKING
EAST

PHOTO: R. BRUHN, OCT. 1978

Photo #3 of 7

Swedish Evangelical Lutheran Church (DX09-1)
Wakefield, Dixon County, Nebraska

Photograph by R. Bruhn, Lincoln, Nebraska

October 1978 (RB 7810/18B)

Detail, west door, looking east

RB 7810/18b NEBR

047

RB 7810/17A
SWEDISH EVANGELICAL LUTHERAN
SALEM CHURCH (1906)
WAKEFIELD, DIXON CO., NEBR.
DX 09-1
INTERIOR VIEW LOOKING EAST TOWARD
ALTAR FROM THE NARTHEX.
PHOTO: R. BRUHN, OCT. 1978

Photo #4 of 7

Swedish Evangelical Lutheran Church (DX09-1)
Wakefield, Dixon County, Nebraska

Photograph by R. Bruhn, Lincoln, Nebraska
October 1978 (RB7810/17A)

Interior view looking east toward altar from the narthex.

047 RB 7810/17a 0602

RB 7810/16C
SWEDISH EVANGELICAL LUTHERAN
SALEM CHURCH (1906)
WAKEFIELD, DIXON CO., NEBR.
DX09-1
INTERIOR VIEW LOOKING WEST TOWARD
REAR OF NAVE.
PHOTO: R. BRUHN, OCT. 1978

Photo #5 of 7

Swedish Evangelical Lutheran Church (DX09-1)
Wakefield, Dixon County, Nebraska

Photograph by R. Bruhn, Lincoln, Nebraska
October 1978 (RB7810/16C)

Interior view looking west toward
rear of nave.

047 RB 7810/16C NEBR

REFORMATION SUNDAY
150
155
385
565
REFORMATION SUNDAY
150
155
385
565

RB 7810/16A
SWEDISH EVANGELICAL LUTHERAN
SALEM CHURCH (1906)
WAKEFIELD, DIXON CO., NEBR.
DX09-1
INTERIOR VIEW LOOKING EAST
TOWARD FRONT OF NAVE.
PHOTO: R. BRUHN, OCT. 1978.

Photo #6 of 7

Swedish Evangelical Lutheran Church (DX09-1)
Wakefield, Dixon County, Nebraska

Photograph by R. Bruhn, Lincoln, Nebraska
October 1978 (RB 7810/16A)

Interior view looking east toward front of nave.

047 RB 7810/16A

047 RB 7810/15d a6P2-35

RB 7810/15d
SWEDISH EVANGELICAL LUTHERAN
SALEM CHURCH (1906).
WAKEFIELD, DIXON CO., NEBR.
DX09-1
DETAIL OF THE ALTAR, LOOKING EAST
PHOTO: R. BRUHN, OCT. 1978

Photo #7 of 7

Swedish Evangelical Lutheran Church (DX09-1)
Wakefield, Dixon County, Nebraska

Photograph by R. Bruhn, Lincoln, Nebraska
October 1978 (RB 7810/15D)

Detail of the altar, looking east