ιUΝ	1	5	1001	
JUN	_			

MONTANA HISTORICAL\*ARCHITECTURAL INVENTORY

JUL 2 | 1981

	1	Reference #	Dat	:e: 1	Win	ter	198	0	
ſ	2	Photo # 3 Direction N NI	ΕE	SE	S	SW	W	NW	
	3	Historic Name: Spanish Creek School	ne: Spanish Creek School CONTACT						
Z 3a Common Name:								рното	
2	4 Address: Gallatin Gateway, Montana								
$\overline{\varsigma}$	5 Program Area: Gallatin County 6 County Code 031 State Code 030				State Code 030				
5Program Area: Gallatin County6County Code 031State Code0307Legal Description: 200' x 200' lot; N boundary is right-of-way of Burma Road8Owner & Address: Gallatin County Superintendent of Schools9PublicPrivate301Main Street, Bozeman, MT					of Burma Road				
ЦЦ	9 🖾 Public 🗌 Private 301 Main Street, Bozeman, MT								

	10 Year Built: 1896 🖾 Factual 🗔 Estimate	11 Location 🔀 Original 🗌 Moved						
	12 Architect (if known):							
	13 Builder/Original Owner (if known)							
	14 Exterior Materials: 🗋 Stone 🗋 Brick 🗋 Stucco 🕅 Wood 🕅 Log 🗋 Terra-cotta 🗋 Concrete							
	□ Shingle □ Other Materials (specify):							
	15 Condition: 🗌 Excellent 🔲 Good 🖾 Fair 🔲 Deteriorated 🔲 In Ruins 🗌 No Longer Exists							
PHYSICAL DESCRIPTION	16 Retention of Original Design: 🖾 Altered 🗌 Major 🏝 Minor 🖳 Unaltered							
	17 Present Use: vacant 18 Original Use: homestead cabi							
	south walls with a central door on the east wall. A wood stove was placed toward							

20a Reason for significance: RHistorical Associations X Architectural and Engineering

design and appearance 🗌 Presence of historic or prehistoric information

20b Please justify the historical significance; noting important persons, events and/or historical patterns associated with structure, site and surrounding area.

The Spanish Creek School, like the Horseshoe Basin School, was a homestead cabin prior to being adapted to a school in 1902. The addition of the enclosed porch was a response to the harsh winter enviornment and allowed for a protected entry vesibule. This building served as a school until 1946 when it was abandoned due to the lack of students in the area.

SIGNIFICANCE

	20c Please justify how the location, design, details, materials, and/or workmanship contribute to the property's significance.									
		weather seal. In 1915 a small hip roofed enclosed log porch was added to the east								
		wall. The added porch has a door on the north wall. The porch is part of the natural evolution of school house architecture and does								
	001	is part of the natural evolution of school house architecture and does not detract from the building's integrity.								
	20d	20d Please note if the extant structure/site may demonstrate or yield information about its historic use or construction.								
	21	Neighborhood Context: □Unrelated □Compatible x Integral element □Major component of the neighborhood								
	21a	la If the structure/site contributes to the value of a larger grouping of structures and sites, please describe the visual or historic relationships that the individual structure/site has to that grouping.								
ed										
continued										
ю										
i	·									
SIGNIFICANCE	22	2 Environmental/Economic threats to survival: Private Development Zoning Public Works Projects Vanadalism X Deterioration Other (specify):								
ž	23	3 Recognition in existing historical surveys:								
SIC	24	4 Sources of Documentation: Annual District Trustee Reports 1896-1934								
à	25									
	26	Name/Address Dave Minor and Paul Bishop								
Æ		Phone # Date:								
PREPARE		Organization: School of Architecture, MSU, Bozeman, MT								
ſ	27	Staff Evaluator: Date: Permission to Nominate X Yes No								
ł	27	National Register Status: Listed Currently nominated								
	20	Appears to meet NR Criteria 🔄 A 🗌 B 🔄 C 🗌 D 🗌 Does not appear to meet NR Criteria Eligible 🗌 Yes 🗌 No As part of a district 🗌 Yes 🗌 No Individually 🗌 Yes 🗌 No								
	29	UTM References: Zone 1 2 Easting 4 7 4 1 7 5 Northing 5 0 3 7 3 1 5								
	30	) Please Return to: State Historic Preservation Office Montana Historical Society 225 N. Roberts St. Helena, Montana 59601								
USE	31	SHPO Comments:								
STAFF										
0,1										