



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct., 1999

neg. 9515 Germantown Ave., Philadelphia, PA

St. Paul Street facade, looking NW

photo 1/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct., 1999

neg: 9515 Germantown Ave., Philadelphia, PA

St. Paul Street facade, looking NW

detail of entrance

photo 2/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct., 1999

neg: 9515 Germantown Ave., Philadelphia, PA

St. Paul Street facade, looking N

shop entrance

photo 3/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer


Oct., 1999

neg: 9515 Germantown Ave., Philadelphia, PA

St. Paul Street facade, looking N

up main facade

photo 4/11



501

Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct. 1999

neg: 9515 Germantown Ave., Philadelphia, PA

St. Paul Street facade, looking NE
portico and front door

photo 5/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct., 1999

neg. 9515 Germantown Ave., Philadelphia, PA

Hamilton Street facade looking up

photo 6/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct. 1999

neg. 9515 Germantown Ave., Philadelphia, PA

Main vestibule showing dropped ceiling

photo 7/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct. 1999

neg. 9515 Germantown Ave., Philadelphia, PA

Main vestibule, elevator lobby

photo 8/11



DANGER
ELECTRICAL EQUIPMENT, AND PARTS THEREOF,
MAY BE LOCATED BEHIND THIS PANEL.
LOOK UP AND LIVE

Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct. 1999

neg: 9515 Germantown Ave, Philadelphia, PA

Barrel vault above vestibule, with HVAC
equipment

photo 9/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct. 1999

neg: 9515 Germantown Ave., Philadelphia, PA

Internal fire stair at 4th floor

photo 10/11



Standard Oil Building

Baltimore, MD

G. Thomas, photographer

Oct., 1999

neg. 9515 Germantown Ave., Philadelphia, PA

Typical upper stories after 1950s renovation

photo 11/11