inward over tile sills. There is no basement and the laundry room is on the first flour. There is a small attic and built-in storage space. The upstairs bathroom is one step up from the level of the hall. The partitions are 1 3/4" thick. The house is not out of place in this neighborhood of somewhat larger homes.

Stone masonry
This house is architecturally significant because it is one of a group of/houses
built by Arnold F. Meyer & Company, Inc. according to construction methods of Ernest
Flagg.

