## **United States Department of the Interior National Park Service**

For NPS use only

# National Register of Historic Places Inventory—Nomination Form

received SEP 2.7 1984 date entered

See instructions in *How to Complete National Register Forms*Type all entries—complete applicable sections

1. Nam	e			
historic	Bailey`& Massi	ngill General Stor	e	
and∉or common	Same			•
2. Loca	ation			
street & number	4 N <del>orth</del> "E" S	t <del>reet-</del>		N/A not for publication
city, town	Lakeview	ң д vicinity of	Second Congression	al District
state	Oregon <b>cod</b> e	e 41 county	Lake	<b>code</b> 037
3. Clas	sification			
Category  district  X_ building(s)  structure  site  object	Ownership public private both Public Acquisition _N/Ain process _N/Abeing considered	Status _X_ occupied unoccupied work in progress Accessible yes: restricted _X_ yes: unrestricted no	Present Use agriculture _X_ commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Proper	'ty		
name	Dennis C. and E	Barbara J. Mooney		
street & number	709 North "F" S	Street		
city, town	Lakeview	N/A vicinity of	state	Oregon 97630
5. Loca	ition of Lega	al Descripti	on	*
courthouse, regis	stry of deeds, etc. La	ake County Courtho	use	
street & number	N,	/A		
city, town	La	ıkeview	state	Oregon 97630
6. Repr	esentation	in Existing	Surveys	
	vide Inventory of ric Properties	has this pr	operty been determined el	igible?yes X no
date 1984			federal _X sta	tecountylocal
depository for sui		istoric Preservati de Street, S.E.,	on Office	
city, town	Salem		state	Oregon 97310

### 7. Description

Condition excellentX good	deteriorated	Check one unaltered _X_ altered	Check one _X_ original site moved dateN/A
fair	unexposed		

#### Describe the present and original (if known) physical appearance

The Bailey and Massingill General Store is a large rectangular commercial storefront which displays a modest Italianate cornice. Dating from 1900, it is the only example of a building sheathed in embossed sheet metal remaining from Lakeview's historic period. Although the display windows have been replaced, the building retains a high degree of interior and exterior integrity.

Located on the southwest corner of the intersection of "E" (Water) and Center Streets, the building is oriented to the west and occupies the South 44 feet of Lot 1 in Block 1 of the Original Plat of the Town of Lakeview, Lake County, Oregon. Otherwise known as Tax Lot 4700, the building appears in Section 15, Township 39 South, Range 20 East of The Willamette Meridian. All other structures in the immediate area date from the same period. Most commercial buildings in town are of brick and the nominated structure is the only building in Lakeview which employs sheet metal as a wall covering.

Rectangular in shape, the dimensions are  $44 \times 96$  feet with the eastern 22.5 feet being composed of bearing wall brick. Erected in common bond, windows are set into arched brick openings but set into rectangular or square wooden frames. On the interior, walls are lath and plaster. This section of the building houses the mezzanine level, the vault, boiler, chimneys, offices and restroom facilities.

There is a full dug basement with the foundation for the brick section being basement walls of random coursed, rubble stone wall, "buttered" with mortar. The remainder of the basement is soil with wooden plank walls and floors suspended on single bricks.

The remainder of the building is single story, constructed of pine balloon-frame construction with 1 x 3 inch tongue and groove boards in the interior. The majority of the exterior elevations on the south and west (front) are covered in embossed sheet metal in imitation of rough faced ashlar with beaded joints. This material is in very good condition.


The main elevation display windows were replaced at an unknown date and the entrance centered on the elevation. However, the double entrance doors are probably original and the diagonal entrance bay simulates the original. Single light transoms appear above the new display windows and a canopy shelters the lower facade. Originally, a metal "fire awning" appeared above the current transom windows. A centered title crest is missing as are urn finials which once appeared on the corner brackets.

The roof is supported by a series of posts which are centered in the undivided space and are oriented east/west. A divider screen wall has just been installed off the south elevation freight entrance to enclose newly arrived freight, and separate the public and general store area from stocking operations.

Intrusive and historic stairways have been moved and closed for safety code reasons. Historically, the stairs to the mezzanine were at right angles, central to the building with the decending basement stairway below. The basement stairway was replaced in 1979-82 with a ramp in the south one-third of the brick portion, and a circular staircase providing basement access to a carpeted and paneled section. This stairway has been removed for safety reasons and much of the carpet and press board have been removed to allow the plank floor to breath again. The paneling and ceiling tile remain in the western two thirds of the basement, concealing the sidewalk freight elevator from inspection or repair.

### United States Department of the Interior Heritage Conservation and Recreation Service

# National Register of Historic Places Inventory—Nomination Form



Continuation sheet BAILEY & MASSINGILL GENERAL Item number

7

Page

2

**STORE** 

The mezzanine stairway has been moved to the north wall and the mezzanine divided into three office spaces. On the ground floor, in the brick section, the rest rooms appear to have been added, date unknown, with the brick vault west wall forming their east wall.

As stated, the basement beneath the brick portion is lined with a random course, rubble stone wall, with outstanding workmanship and in good shape, excepting a four foot  $\pm$  section suffering water erosion. The foundation of the frame portion of this building is actually a series of tabular stones lying on the soil, with a main stringer beam directly on these. The mid-structure stringer beams are supported by a number of vertical black iron pipes on concrete piers, original upright beams on pads, and the vault and east wall foundation.

All 2 x 12 inch main floor joists run N-S on two foot centers. Two layers of tongue and groove flooring, both E-W, have been topped with carpeting. At some point in time, most likely 30 to 40 years ago, a concrete foundation was poured along the south wall. This has covered the ends of the 2 x 12 inch main floor joists.

The roof is sound, tarred, flat but sloping to the rear with a covered over central skylight.

In 1982 the structure was converted to a mini-mall with the addition of temporary interior walls. These have all been removed.

The interior wood wall sheeting will be painted with the super graphic logo of peach and poppy around the top six feet. The ceiling and remainder of the walls will be painted white. Florescent light fixtures from the M. W. Bullard grade school have been salvaged and installed in the main store area.

### 8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799 1800–1899 _X 1900–	agriculture	community planning conservation economics education	music	re religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1900	Builder/Architect	nknown	

#### Statement of Significance (in one paragraph)

The Bailey and Massingill General Store, located at 4 North "E" Street in Lakeview, Lake County, Oregon, was built by Messrs. Harry Bailey and W. A. Massingill in 1900 after their recently purchased establishment, dating from 1876, burned on May 22, 1900. Designed to respond to any potential future fire hazard, the store's sheet metal sheathed walls and other fire preventive elements are a unique resource in Lakeview and merit consideration for listing under Criterion"c." In addition, the building can be evaluated under Criterion "a" as a long-lived commercial enterprise in Lakeview on whose site one of the city's earliest buildings was erected.

This building was constructed to replace the first "business house" of the nascent town of Lakeview, Oregon. Begun in April of 1876, by A. and C. U. Snider, the store was completed in September of 1876. On June 5, 1876, the county seat of Lake County moved from Linkville (now Klamath Falls) to Lakeview largely because of the commercial activity at "Bullard's Creek in Goose Lake Valley." The population boom, stimulated by U. S. Army activity, had begun with the arrival of the first settler in Goose Lake Valley in 1867. By 1874 Charles U. Snider was partners with his uncle A. Snider (a storekeeper for the United States Army). At that time, there was a 5/4 population ration in favor of the east side of Lake County. According to the 1875 tax record a certain John A. Moon already held land of \$2,675 in Goose Lake precinct. Late in 1876, Mr. Moon purchased the south 44 feet of Lot 1 Block 1 in "Bullard's Creek: townsite, and in fact the entire townsite, from the patented deed holder, Mr. M. W. Bullard. Construction of the first store in the town to be, began in April of 1876. In 1877, C. U. Snider purchased Mr. Moon's interest in the store. Of equal import to C. U. Snider was his return to Lakeview from Shawneetown, Illinois, where he had married Miss Mary E. McCallen on May 2nd. Therefore, when the June referendum was held, there was at least one more individual at the new townsite of the future Lakeview, Lake County seat, Oregon. Before the incorporation of Lakeview on February 20, 1889, this original store building had been sold by C. U. Snider to his uncle/partner Mr. A. Snider in 1881. Ten years later (1819), a Mr. Hawley bought A. Snider's interest in the store.

In 1897 two partners, Harry Bailey and W. A. Massingill, purchased the business from Mr. Hawley. The Bailey and Massingill general merchandise store burned to the ground the night of May 22, 1900 along with all but two out of the four brick buildings in town and virtually all other frame structures. The blaze was observed over 100 miles to the North, West South and Southeast. The loss to Bailey & Massingill of \$18,000 was the greatest single loss reported in the town. In contrast, C. U. Snider lost \$4,000 in dry goods and the Bank of Lakeview lost \$6,000. The construction of the present structure was an immediate response by the two partners to this fire.

The structure represents a relatively inexpensive building with fire precautions taken. The brick portion provided excellent security for the vault containing the safe. Futile attempts to remove the impressive safe for "safe keeping" have left their telltale signs on the walls. The brick portion also housed the boiler, chimneys, and fuel storage office space and later, the restrooms.


### 9. Major Bibliographical References

See continuation sheet

10. Geo	grap	hical Da	ata		
Acreage of nomina Quadrangle name UTM References	ited prope Lakevie	ty <u>less than</u> w NE, Oreg.	one		Quadrangle scale 1:24000
A 1 0 7 1 9 Zone Easting	3,6,0	4   6   7   4   0   5	5 <sub>1</sub> 0	Zone Easti	ng Northing
C			ДД Р ДД Н		
<b>Verbal boundary description and justification</b> Bailey and Massingill General Store occupies the south 44 feet of Lot 1 in Block 1 of the Original Town of Lakeview, in Lake County, Oregon, and is located in Section 15, Township 39 South, Range 20 East of the Willamette Meridian.					
List all states a	nd counti	es for propertie	es overlapping sta	te or county	boundaries
state	None	code	e county		code
state	None	cod	e county		code
11. Form	n Pre	epared l	Ву		
name/title	Hugh	Bunten, Jr.,	Cultural Resou	rce Specia	list
organization	None			date	March 30, 1984
street & number	Route	2 Box 77		telephor	ne (503) 947-3921
city or town	Lakev	iew		state	Oregon 97630
12. Stat	e Hi	storic P	reservati	on Off	icer Certification
The evaluated sign	ificance of	this property wit	hin the state is:		$\bigcap$ $I$
	national	state	X local	$\wedge$	
As the designated State Historic Preservation Officer for the National Historic Preservation Act of 1966 (Public Law 89–665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service.					
State Historic Pres	ervation O	fficer signature			MAMMAN -
title De	puty Sta	ate Historic	Preservation 0	fficer	date September 5, 1984
For NPS use or	nly				V
I hereby certify that this property is included in the National Register  Entered in the					
Keeper of the N	lational Re	gar	National Regis	ter	date 10-25-84
)	with idi	, <del>g</del>			,
Attest: Chief of Registr	ration				date

United States Department of the Interior Heritage Conservation and Recreation Service

# National Register of Historic Places Inventory—Nomination Form



Continuation sheet BAILEY & MASSINGILL GENERAL

Item number

8

Page

2


**STORE** 

Enclosing the frame portion with the pressed tin siding and providing a "fire-awning" to close the front window was supposed to provide protection against any outside fire. The effectiveness of this treatment was demonstrated in 1902, when the building survived another large fire unscathed.

The Bailey & Massingill General Merchandising Store of Lakeview, Oregon, had far reaching historic, social and economic influence in south-central Oregon. It was the site of the first "business house" in Lakeview, instrumental in the growth of the town and thus acquisition of the county seat for Lake County. The Bailey & Massingill Corporation controlled the big wool warehouse on the tracks and thus all wool shipped by rail from Lake County. They also transferred most of the grain raised in the county as well as supplies used through out the county, and gave credit when no one else would.

United States Department of the Interior Heritage Conservation and Recreation Service

# National Register of Historic Places Inventory—Nomination Form



Continuation sheet BAILEY & MASSINGILL GENERAL

Item number

Page

9

**STORF** 

"Now Under New Management," <u>Lakeview Examiner</u> ( historic photograph of storefront.

1952). Illustration is 1917

Barry, Bob, From Shamrocks to Sagebrush, Examiner Publishing Co., Lakeview, Oregon, 1969.

An Illustrated History of Central Oregon, embracing Wasco, Sherman, Gilliam, Wheeler, Crook, Lake and Klamath Counties. Spokane: Western Historical Publishing Co., 1905.

