



The Ryan House

Dubuque, Iowa

Robert W. Smith, photographer

May, 1984

Helen Mercer, negatives

Southeast elevation

Photo # 1.



The Ryan House

Dubuque, Iowa

Robert W. Smith

May, 1984

Negatives - Helen Mercer

Southeast elevation

Photo # 1a.



The Ryan House

Dubuque, Iowa

James Bainbridge, photographer

July, 1984

Negatives - Helen Mercer

Entrance to 1975 south stairwell

Photo # 2



The Ryan House

Dubuque, Iowa

Robert W. Smith, photographer

May, 1984

Negatives - Helen Mercer

View from southwest showing 1981 board/
batten kitchen

Photo # 3



The Ryan House

Dubuque, Iowa

Robert W. Smith, photographer

May, 1984

Negatives - Helen Mercer

West elevation, from parking lot

Photo # 4



The Ryan House

Dubuque, Iowa

Robert W. Smith, photographer

May, 1984

Negatives - Helen Mercer

North elevation

Photo # 5.



The Ryan House

Dubuque, Iowa

James Bainbridge, photographer

July, 1984

Negatives - Helen Mercer

1971 northeast stairwell addition

Photo # 6.



The Ryan House

Dubuque Iowa

James Bainbridge, photographer

July, 1984

Negatives - Helen Mercer

Street entrance to 1971 ne addition

Photo # 7.