UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC   Hollenburg Pony Express Station

AND/OR COMMON
        Hollenburg Pony Express Station

2 LOCATION

CITY, TOWN   X VICINITY OF   COUNTY   STATE
    Hanover   Washington   Kansas

3 PHOTO REFERENCE

PHOTO CREDIT   Stephen Lissandrello   DATE OF PHOTO   May, 1975

NEGATIVE FILED AT Historic Sites Survey, National Park Service, 1100 L. Street, NW
                  Washington, D.C. 20240

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET   PHOTO NO
    Facing north to front entrance, Hollenburg Pony Express Station
    (driveway in foreground).

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES --ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC   Hollenburg Pony Express Station

AND/OR COMMON
Hollenburg Pony Express Station

2 LOCATION

CITY. TOWN   X VICINITY OF   COUNTY   STATE
Hanover   Washington   Kansas

3 PHOTO REFERENCE

PHOTO CREDIT   Stephen Lissandrello   DATE OF PHOTO May, 1975

NEGATIVE FILED AT   Historic Sites Surveu, National Park Service, 1100 L. Street, NW.
   Washington, D.C.   20240

4 IDENTIFICATION

DESCRIBE VIEW. DIRECTION. ETC. IF DISTRICT. GIVE BUILDING NAME & STREET   PHOTO NO
      Facing east to rear of Pony Express Station.

INT: 2983-75

Cottonwood Station (Hollenberg Ranch Pony Express Station),
    Hanover, Kansas, Landmark Inspection, June 21, 1977

W exposure - Note variety of
siding - cedar (?) lower,
redwood - middle, original
walnut - upper. Note
deterioration of original
siding as well as a sagging
roof. This wall was
apparently damaged in a hail
storm a few years ago

E exposure - detail of siding, window and door
condition