



H. Earl Clack Service Station
Hwy 2 (South side)
Saco, Phillips Co, MT 59261
photo by Joseph M. Ashley

date: July 1993
neg: MT SHPO, Helena, MT
view SW
#1



TOURIST PARKING

REST ROOMS

Fresh
HOT

STOP SEE
RESTORED
SCHOOL
SACO

H. Earl Clack Service Station
Hwy 2 (South side)
Saco, Phillips Co, MT 59261
photo by Joseph M. Ashley

date: July 1993

neg: MT SHPO, Helena, MT

view SE

#2



H. Earl Clack Service Station
Hwy 2 (South side)
Saco, Phillips Co, MT 59261
photo by Joseph M. Ashley

date: July 1993

neg: MT SHPO, Helena, MT

view NE

#3



H. Earl Clack Service Station
Hwy 2 (south-side)
Saco, Phillips Co, MT 59261
photo by Joseph M. Ashley

date: July 1993

neg: MT SHPO, Helena, MT

view WSW

#4