

Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon

Silver Falls State Park Concession

photos. Transferred by National Park Service to:

Oregon State Parks and Recreation Div.

525 Trade Street SF

Informal 1940-1942 CCC construction

Salem, OR 97310

Looking easterly at west face of Concession Building. Roof framing

system under construction.



Informal 1940-1942 CCC construction photos. Transferred by National Park Service to:

Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

2 of 24 Interior view of Concession Building dining area, looking south at massive stone chimney and showing scissors trusses which support the roof framing.



Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon

Silver Falls State Park Concession

Informal 1940-1942 CCC construction photos. Transferred by National Park Service to:

Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

3 of 24
Looking easterly at west face, or principal facade of Concession
Building following completion of project.



Informal 1940-1942 CCC construction photos. Transferred by National Park Service to:

Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

4 of 24 Looking southwesterly at east face of Concession Building following completion of project.



Informal 1940-1942 CCC construction photos. Transferred by National Park Service to:

Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

5 of 24
Interior view of Concession Building dining area, looking north at end wall separating dining room from kitchen space. Tongue and groove millwork


is distinguished by section of herring-bone panels.



Informal 1940-1942 CCC construction photos. Transferred by National Park Service to:

Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

6 of 24
Interior view of Concession Building dining area, looking northeasterly, showing completed finish work and specially-designed suite of myrtlewood furniture installed.



Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 7 Of 24 Concession Building (Silver Falls Lodge)

Fast elevation.

Silver Falls State Park Concession



Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 8 of 24 Concession Building (Silver Falls Lodge) South elevation.

Silver Falls State Park Concession



Silver Falls State Park Concession Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 9 of 24 Concession Building (Silver Falls Lodge) West elevation, showing veranda and

terrace.



Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 10 of 24

Concession Building (Silver Falls Lodge) West elevation. Showing veranda and terrace.



Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

Silver Falls State Park Concession

Salem, OR 97310

11 of 24

Concession Building (Silver Falls Lodge)
North elevation from service yard.



Silver Falls State Park Concession Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE


12 of 24 Concession Building Garage, West and South elevations from service yard enclosure.

Salem, OR 97310



Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

13 of 24 Lodge (Log Cabin) South (front) elevation.



```
Building Area
Silver Falls State Park
20024 Silver Falls Highway
Sublimity vicinity, Marion Co., Oregon
Ed Schoaps photo, 1983
Oregon State Parks and Recreation Div.
525 Trade Street SE
```

Silver Falls State Park Concession

14 of 24 Lodge (Log Cabin), East elevation.

Salem, OR 97310



Silver Falls State Park Concession Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 15 of 24 Lodge (Log Cabin), North elevation, showing chimney of native stone.



Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310

16 of 24 Looking southwesterly at toilet building of 1972 shown in relationship to the Lodge (Log Cabin).



Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 17 of 24 Toilet Building (1972), South and

Fast elevations.

Silver Falls State Park Concession




Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE

Silver Falls State Park Concession

18 of 24 Community Kitchen (Stone Picnic Shelter South elevation.

Salem, OR 97310



Silver Falls State Park Concession Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE


19 of 24 Community Kitchen (Stone Picnic Shelter), West elevation.

Salem, OR 97310



Silver Falls State Park Concession Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 20 of 24 Community Kitchen (Stone Picnic Shelter), North elevation of ell and

port cochere.



Silver Falls State Park Concession Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 21 of 24 Community Kitchen (Stone Picnic Shelter), South and East elevation.



Silver Falls State Park Concession Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SF Salem, OR 97310 22 of 24 South Falls Viewpoint, looking northerly.



Building Area Silver Falls State Park 20024 Silver Falls Highway Sublimity vicinity, Marion Co., Oregon Ed Schoaps photo, 1983 Oregon State Parks and Recreation Div. 525 Trade Street SE Salem, OR 97310 23 of 24 Basalt Rubble Guard Wall at South

Falls, looking westerly.

Silver Falls State Park Concession



Building Area
Silver Falls State Park
20024 Silver Falls Highway
Sublimity vicinity, Marion Co.. Oregon
24 of 24
June D. Drake photo, c. 1928, prior to

Silver Falls State Park Concession

State Park development. Looking southeasterly at South Falls. Note

pathway on ledge behind Falls, a sheer drop of 177 feet. On the shelf above the canyon figures are seen in a clearing which is the nucleus of the 9.63-acre nominated area.

South Falls also was the focal point of the initial park land acquisition in 1931.

State Historic Preservation Office Oregon State Parks and Recreation Div. 525 Trade Street SE Salem. OR 97310