Historic Sites Survey Inventory No. 2



ARCHITECTURAL DESCRIPTION: The Ballentine-Seay House is a picturesquely massed NAME: Ballentine-Seay House and fenestrated, highly ornamented and intricately detailed, gable-roofed, STREET NO: Pocahontas Street two-story residence on a corner lot facing east. The main entrance is a TOWN/VIC: single door with elongated octagonal transom light and vernacular shouldered Sardis surrounds of Renaissance Revival derivation. The fenestration is irregular COUNTY: Panola 🗁 and includes a one-story, three-bay window on pavilion at southeast corner. BLOCK/LOT: See Verbal Boundary Description Three-bay window has hipped roof with heavy cornice, three four-over-four double-hung sash, and paneled corner boards. Windows are uniformly four-PRESENT OWNER: Mr. Harry Seay over-four, and other window treatments include shouldered surrounds, paired ADDRESS 2154 East 32nd Place, Tulsa, Oklahoma 7410 windows with elaborate hoods, and single windows with simple hoods. The one-PRESENT USE: Residence story, three-bay porch is defined by highly ornamented chamfered wooden posts Residence resting on paneled pedestals. The frieze and tympanum of the pedimented entry FORMER USE: bay of the porch is intricately detailed, as is the frieze along the rest of the porch. A repeating lozenge patterned balustrade with chamfered diagonals DATE: 1870-71 encloses the porch. Specific Johnson details seen in this building are: the half-octagon bay window (a predecessor of his two-bay square-cut bay STYLE: Vernacular Eastlake (continued) ALTERATIONS: ARCH/BUILDER: Andrew Johnson None. Residence is in a fine state of preservation and maintenance. SOURCE OF DATE: Newspaper **OUTBUILDINGS:** ENVIRONMENT: Residential Late nineteenth-century stone coal bin. Frame kitchen, servants' quarters, LEVEL OF SIGNIFICANCE and barn. **NEIGHBORHOOD** LANDSCAPE FEATURES: LOCAL STATE X Front lawn planted with mature oaks, cedars, and magnolias. NATIONAL PHOTOS STATEMENT OF SIGNIFICANCE: The Ballentine-Seay House was the second of Andrew Johnson's private commissions, and it appears to have been executed as a showplace for his architectural and design abilities. The residence is the most elaborate example of his early work, and this ecstatic use of decoration was not repeated in its entirety until the Kyle-Spencer House (1905). The Ballentine-Seay House is Johnson's landmark residence and provides the essential guidelines to determining the actuality of his later works.

SILE OH AREA PLAN WITH NORTH ARROW AND SHAPE OF S	TRUCTURE:	R
		CAHONTAS STREET
PHYSICAL CONDITION:		
Excellent		
THREATS:	<u></u>	
None		
VERBAL BOUNDARY DESCRIPTION:		
R. W. Crump Survey of 1871 "Fraction S, ½(1), Sec. 34, T7, R7" ACREAGE: less than one		
UTM REF:		
A 1 6 2 3 1 9 4 0 3 8 1 3 4 0 0 ZONE EASTING NORTHING		
ORM PREPARED BY:	DATE	
P. Ana Gordon, Historian Mississippi Department of Archives and History	Jan. 1983	

CONTINUATION:

window), the chamfered posts with centered bull's-eye brackets elongated octagonal transom light, and in the interior, the mantel, baseboard and window sash graining, and the interior window shutters.

÷.

15