

GEO. W. BUCKLIN Commercial Photographer

LC13:C8-301

Photograph 1
Gold and Company Store Building
(Gold-Brandeis Building)
1033 "0" Street
Lincoln, Lancaster Co., Nebr.

Architectural rendering by Davis and Wilson of proposed building. George W. Bucklin, photographer, Lincoln, Nebraska.

North and east facades shown; Viewer facing southwest.

Photograph assumedly taken in 1924.

This photograph is supplied for research purposes only. Permission to reproduce in any form must be obtained, in writing, from the NEBRASKA STATE HISTORICAL SOCIETY. Responsibility regarding questions of copyright, photographic releases, and invasion of privacy that may arise from the use this copy is assumed by the recipient. In the event of publication, the credit line must read:

Nebraska State Historical Society



LC13:C8-301

Photograph 2
Gold and Company Store Building
(Gold-Brandeis Building)
1033 "O" Street
Lincoln, Lancaster Co., Nebraska.

View of north and east facades. Macdonald's Photography, Lincoln Photographer facing southwest. 1926 This photograph is supplied for research purposes only. Permission to reproduce in any form must be obtained, in writing, from the NEBRASKA STATE HISTORICAL SOCIETY. Responsibility regarding questions of copyright, photographic releases, and invasion of privacy that may arise from the use this copy is assumed by the recipient. In the event of publication, the credit line must read;

Nebraska State Historical Society



185

Photograph 3 Gold and Company Store Building (Gold-Brandeis Building) LC13:C8-301 1033 "O" Street

Lincoln, Lancaster Co., Nebr.

North and east facades, View facing southwest.

Photographer unknown.

Circa 1950.

This photograph is supplied for research purposes only. Permission to reproduce in any form must be obtained, in writing, from the NEBRASKA STATE HISTORICAL SOCIETY. Responsibility regarding questions of copyright, photographic releases, and invasion of privacy that may arise from the use this copy is assumed by the recipient. In the event of publication, the credit line must read:

Nebraska State Historical Society



Photograph 4
Gold and Company Store Building
(Gold-Brandeis Building)
LC13:C8-301
1033 "O" Street
Lincoln, Lancaster Co., Nebraska

North and east facades, View facing southwest.

Steve Schultz, Planning Aide Lincoln City-Lancaster County Planning Department.

555 South 10th Street Lincoln, Nebraska.

June, 1982



Photograph 5

Gold and Company Store Building (Gold-Brandeis Building) LC13:C8-301

1033 "O" Street Lincoln, Nebraska

East facade; 11th Street in foreground.

Photographer facing northwest.

Steve Schultz, Planning Aide, Lincoln City-Lancaster County Planning Department.

555 South 10th Street Lincoln, Nebraska.

June, 1982.



Photograph 6

Gold and Company Building (Gold-Brandeis Building) LC13:C8-301

1033 "O" Street Lincoln, Lancaster Co., Nebr.

East facade; 12-bay section added in 1947.

Photographer facing west.

Steve Schultz, Planning Aide, Lincoln City-Landaster County Planning Department.

555 South 10th Street Lincoln, Nebraska.

June, 1982.



Photograph 7

Gold and Company Building (Gold-Brandeis Building) LC13:C8-301

1033 "O" Street, Lincoln, Lancaster Co., Nebr.

Lateral section of the L-shaped building; 1947 section on right;

1951 section on left. South and west facades shown; Photographer facing northeast.

Steve Schultz, Planning Aide, Lincoln City-Lancaster County Planning Department.

555 South 10th Street Lincoln, Nebraska

June, 1982.