
United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form



See instructions in How to Complete National Register Forms
Type all entries—complete applicable sections

1. Nan	ne	abic sc			•			
								
historic	Lyons House							
and/or common								
<u> 2. Loc</u>	ation							
street & numbe	r 1335 Horri	.dge S	treet			n/a	not for publi	cation
city, town V	inton		n/avio	cinity of	congressional distr	ct 7t	hJohn B	reaux
state L	A	code	22	county	Calcasieu Paris	h	code	019
3. Clas	ssification							
Category district _X_ building(s) structure site object	Ownership public X private both Public Acquisitio n/a_ in process being conside		X occupi unoccu work ir Accessible X yes: re yes: ur	upied n progress e estricted	Present Use agriculture commercial educational entertainmen government industrial military	- - -	museum park yrivate religious scientific transpor other:	esidence
4. Owr	ner of Pro	per	ty					
name Dan	iel B. Cooper ar	nd Bra	dv B. Fon	tenot				
street & number								
city, town	Vinton		n∕a vio	cinity of	sta	te LA	70668	
<u>5. Loc</u>	ation of L	ega	l Des	cripti	on			
courthouse, reg	istry of deeds, etc.	Cal	casieu Pa	rish Cou	rthouse			
street & number	r corner of Kirt	y and	Ryan (no	exact s	treet address)	P.0	. Box 103	0
city, town	Lake Charles		*		sta	te _{LA}	70601	
6. Rep	resentati	on i	n Exis	sting	Surveys			
title La. Hist	oric Sites Surve	Y		has this pro	operty been determined	d elegib	ole? ye	s _X_n
date 1982					federalX	state	county	loca
depository for s	survey records La.	State	Historic	Preserva	ation Office			
city, town	Baton Rouge				sta	te	LA	

7. Description Check one Check one Condition X_ original site __ excellent deteriorated __ unaltered n/a X altered __ good _ ruins ____ moved date . _X fair _ unexposed

Describe the present and original (if known) physical appearance

The Lyons House (1900) is a two-story Queen Anne Revival style house of above average quality which is considered a landmark in the small town of Vinton. It is located on a large lot on the corner of Horridge and Loree Streets near the Vinton central business district. The property consists of the house, a two-story c.1940 garage building, and a c.1950 tin shed.* There are two large oak trees in the front yard. Apart from these, little remains of the original landscaping. However, an early photograph reveals that the original landscaping was plain, so its loss should not be considered significantly detrimental to the property. The only serious integrity problem is the house's thirty year old asbestos siding. In spite of this and other changes, the Lyons House is still vastly superior to its neighbors in terms of size, massing, and richness of ornamentation.

Although the design strives for irregularity, the basic plan of the house is compact and straightforward. The main block of the house is more or less divided into four spaces on each floor. There is also a two-story rear wing which adds one room to each story. Irregularity is achieved as follows: The stair hall, which is set in the southwest corner of the house, is recessed and rounded at the corner. The northwest parlor and southeast dining room project from the mass of the house. Both of the bedrooms above these rooms are sunmounted by large gables. The dining room projection terminates in a semioctagonal bay. The rounded stair hall is encompassed by a two-story curving Eastlake gallery. There is also a one-story gallery on the rear wing and a slightly protruding wing on the north side of the house which has its own one-story gallery.

The most noteworthy interior feature is the staircase, which is triangular in plan and has three landings. It is set against the curve of the stair hall, and is consequently richly three-dimensional. It also features elaborate Eastlake woodwork with a course of spindles above the balusters, scrollsawn surrounds for each baluster, and heavy turned newel posts.

Other noteworthy features of the Lyons House include:

- (1) the one remaining mantel with its free-standing columns which rise to encompass an oval mirrored overmantel,
- (2) stained glass transoms over several of the doors,
- (3) stained glass surrounds on several of the large plate glass windows, and
- (4) corner blocks on most of the door and window frames.

Changes in the house since construction which have not previously been mentioned include:

- (1) the replacement of the bottoms of the curving gallery columns with brick bases,
- (2) the loss of a tiny balustrade which surmounted the very top of the central pyramid roof, and
- (3) the loss of the corner brackets which made the transition between the semioctagonal bay and the gable above it.

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Lyons House

Item number

7

Page 2

7. Description (Continued)

Despite all of the changes mentioned, the house retains its standing within the town of Vinton. It is still far and away the town's most elaborate work of architecture.

*N.B.: The shed and garage were excluded from the nominated area because they are less than fifty years old, and are therefore considered intrusions.