city, town

Cheyenne

United States Department of the InteriorNational Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only

WY

received AUG | 6 1984

date enteredSEP | 3 |984 See instructions in How to Complete National Register Forms Type all entries—complete applicable sections Name historic First State Bank of Baggs and or common Bank Club Location street & number 10 South Miles Street ___ not for publication Baggs vicinity of city, town Wyoming Carbon 007 056 state code county code Classification Category Ownership **Status Present Use** X occupied __ district _ public _ agriculture _ museum X building(s) X__ private __ unoccupied _X_ commercial __ park _ both _ work in progress ____ structure __ educational private residence **Public Acquisition** ___ site Accessible _ entertainment ___ religious na in process ____ object _ yes: restricted government _ scientific na being considered X yes: unrestricted industrial ____ transportation no military _ other: Owner of Property Elaine Herold name Box 203 street & number Wyoming 82321 Baggs vicinity of state city, town **Location of Legal Description** Carbon County Courthouse courthouse, registry of deeds, etc. First and Pine Streets street & number Wyoming Rawlins state city, town **Representation in Existing Surveys** title Wyoming Historic Sites Survey has this property been determined eligible? 1983 date federal X state county depository for survey records Wyoming Recreation Commission

	-			
Condition excellent	deteriorated	Check one unaltered	Check one X original site	
excenent				
x_ good	ruins	x altered	moved date	
fair	unexposed			

Describe the present and original (if known) physical appearance

7. Description

This one-story log structure has a gable roof, concrete foundation, and is covered with stumped sheet metal. The front features an oversized pediment with brackets evenly spaced in the gable end overhang and beneath the end pent. The gable end also features a stylized pediment above the recessed entry. The porch is supported by four tin fluted columns with pedestals and capitols; the two outside end columns are square with ionic treatments while the two inside columns are round, tapered and feature doric treatments. The porch floor is poured concrete. The exterior wall of the building has five evenly spaced double hung one-overone windows with plain surrounds. All the decorative elements of the structure Though the exact date the building was covered with sheet metal is not known, it is assumed it was done very early as this seems to have been a very popular trend in the area in the early part of the twentieth century. The wide front door is flanked by two oversized set-in windows with three narrow transoms evenly spaced above the door and windows. The building features a small shed roof addition on the side used for drive-in liquor sales, and another on the back. Both additions are recent and therefore not contributing for tax incentive rehabilitation purposes. The Bank Club is located on a single lot facing what used to be Baggs' main street. Only the original bank building on its lot are included in this nomination.

8. Significance

1500–1599 1600–1699 1700–1799 1800–1899	Areas of Significance—C archeology-prehistoric agriculture architecture art commerce communications	community planning conservation economics education engineering exploration/settlement	music music	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1907	Builder/Architect	Tom Vernon/J.B. Pie	erson

Statement of Significance (in one paragraph)

Constructed in 1907-08 to house the First State Bank of Baggs, the Bank Club Bar is one of a few of the original buildings still standing. Though not a false front, the bank is an excellent example of western 'boom town' attempts to provide urban scale and create a sense of stability in isolated small towns. The structure embodies distinctive characteristics of greek revival and classical trends popular near the turn of the century. It represents the ingenuity of westerners, limited by financial resources and access to authentic materials, in creatively copying the popular urban 'look' of the day. Windshield surveys of major portions of the state indicate this is likely the only one of its kind remaining. Located within a community lacking in significant architectural structures and retaining integrity of location, design, setting, materials, workmanship, feeling and association, the Bank Club Bar is a locally significant building associated with the broad patterns of early western commercial development. It definitely deserves enrollment in the National Register of Historic Places.

SEE ADDENDUM

9. Major Bibliographical References

SEE ADDENDUM

10 God	ographica	i hata			
Acreage of noming Quadrangle name UTM References	nated property <u>less</u> Baggs, WY	than one ac	cre	Quadra	angle scale 1:62500
A 1 3 2 7 Zone Eastin	سلسلسا اورواسياس	4 ₁ 5 9 ₁ 2 ₁ 5 ng	Zone D	Easting	Northing
$G \square \square$			H		
Verbal boundar	y description and	justification			
	SEE ADDEND	UM			
List all states a	and counties for pr	roperties overla	apping state or	county boundar	ies
state	na	_{code} na	county	na	_{code} na
state	na	_{code} na	county	na	_{code} na
11. For	m Prepar	ed By			
name/title	Elaine Herold				
organization				date Decemb	er 12, 1983
street & number	P. O. Box 20)3		telephone 383-	7152
city or town	Baggs			state Wyoming	9
12. Sta	te Histor	ic Prese	ervation	Officer	Certification
The evaluated sig	nificance of this prop	perty within the s	tate is:		
	_ national	state	X local		
665), I hereby nor		for inclusion in th	e National Registe	er and certify that	Act of 1966 (Public Law 89– it has been evaluated
State Historic Pre	servation Officer sig	nature Oh	mi I. Bast	ronu	
title State H	istoric Preserva	ation Officer		date	8/11/84
For NPS use					
I hereby cer	rtify that this property	Enter	red in the	er date	9-13-84
Keeper of the	National Register	- Nart	onal Register	uate	
() Attest:				date	•
Chief of Regis	stration				

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Significance

Item number

Page

1

Baggs is a ranching community. The Homestead Act brought many people to the valley as early as 1880. The bank was needed as Craig, Colorado, is 40 miles and Rawlins, Wyoming, is 78 miles away. Since the need was there, it was logical to have a bank in Baggs. When the bank closed in 1924, everyone had to do their banking business in Craig and Rawlins again. In 1981, the Valley State Bank was opened in Baggs.

There was a doctor's office for a time and also a bootleg business for illegal liquor. When liquor was legalized, it was the Baggs Liquor, owned by Owen Groshart. Bill Terrill owned the Bar for a number of years. Leo Craner bought it in 1946 and then changed the name to The Bank Club Bar. Phil Leckenby bought it from Leo Craner in 1953. After Mr. Leckenby's death, it was sold to Lee Talley and Carl Baker in 1958. Elaine Herold purchased it in 1972.

The Vernon Hotel which was across the street was the only other building that had stamped metal. The Hotel was destroyed by fire in December of 1979. There are very few old buildings left standing in Baggs today.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet Bibliography

Item number

9

Page 1

Bibliography

Brown, Ann. et al. Wagon Trails and Folk Tales. (Privately printed, 1980).

Wyoming: A Guide to its History, Highways and People. (New York Oxford University Press, 1941).

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet Verbal Boundary Description Item number

10

Page 1

This nomination includes only the original bank building located on the north 30 feet of Lot 15 Block 1, Franklin Addition Baggs, Wyoming. This area is the original location of the bank and both defines and protects the site. For purposes of tax incentive certification it should be noted that the two additions located at the back and side of the building are not eligible.

