56 2625

# United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations for individual properties and districts. See instructions in National Register Bulletin, How to Complete the National Register of Historic Places Registration Form. If any item does not apply to the property being documented, ander "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions. Place additional certification comments, entries, and narrative items on continuation sheets if needed (NPS Form 10-900a).

1. Name of Property	
Historic name Deerfield State Bank	
Other names/site number Deerfield United States Post Office; Bacon Drug Store KHRI #093	3-17
Name of related Multiple Property Listing N/A	
2. Location	
Street & number 602 Main Street	not for publication
City or town Deerfield	vicinity
State Kansas Code KS County Kearny Code 093	Zip code 67838
3. State/Federal Agency Certification	
As the designated authority under the National Historic Preservation Act, as amended,	
I hereby certify that this X_nomination _ request for determination of eligibility meets the do registering properties in the National Register of Historic Places and meets the procedural at set forth in 36 CFR Part 60.	
In my opinion, the property X_meetsdoes not meet the National Register Criteria. I reconconsidered significant at the following level(s) of significance:	nmend that this property be
national statewide _X_local Applicable National Register Criteria: _X_ABC	D
Signature of certifying official/Title Patrick Zollner, Deputy SHPO  Date	
Kansas State Historical Society	
State or Federal agency/bureau or Tribal Government	
In my opinion, the property _meets _does not meet the National Register criteria.	
Signature of commenting official Date	
Title State or Federal agency/bureau or Tribal Government	
4. National Park Service Certification	
I hereby certify that this property is: entered in the National Registerdetermined eligible for the National Register	
determined not eligible for the National Register removed from the National Register	
_other (explain:)	
Signature of the Keeper Date of Action	

Deerfield State Bank Name of Property	Kearny County, Kansas County and State			
5. Classification				
Ownership of Property (Check as many boxes as apply.)  Category of Property (Check only one box.)  X private  X building(s)		Number of Resources within Property (Do not include previously listed resources in the count.)  Contributing Noncontributing  buildings		
public - Local	district			sites
public - State	site			structures
public - Federal	structure object	2	0	objects <b>Total</b>
		Number of con listed in the Na	tributing resourd tional Register 0	ces previously
			0	<u> </u>
6. Function or Use Historic Functions (Enter categories from instructions.)		Current Function (Enter categories from		
Commerce/Trade: Financial Ir	estitution	Work in Progress		
Commerce/Trade: Drug Store				
Government: Post Office				
7 Decembring				
7. Description Architectural Classification (Enter categories from instructions.)		Materials (Enter categories fro	om instructions.)	
Late 19 <sup>th</sup> & Early 20 <sup>th</sup> Century American		foundation: Concrete & Brick		
Movements: Commercial Style		walls: Brick		
		Metal		
		roof: Asphalt/	/Tar	
		other:		

United States Department of the Interior
NPS Form 10-900

National Park Service / National Register of Historic Places Registration Form OMB No. 1024-0018

Deerfield State BankKearny County, KansasName of PropertyCounty and State

Narrative Description

## Summary

The 1907 Deerfield State Bank is located at 602 Main Street in Deerfield (2010 pop: 700), Kearny County, Kansas just two blocks north of the Santa Fe Railroad tracks. The two-story brick building occupies a corner lot at the northeast corner of Main and East 6<sup>th</sup> streets (*Figures 1 & 3*). Distinguishing features of the building include the patterned brick parapet, canted bank entrance, and large arch-top display windows. To the east of the brick building is a one-story wood-frame structure with pressed metal siding and a simple metal parapet on the south façade. Both buildings are considered contributing resources.

## **Elaboration**

#### Site

The Deerfield State Bank is located at the intersection of 6<sup>th</sup> and Main. It is one block away from the Santa Fe Railroad tracks, directly across from a fitness center, and to the north is the Deerfield Fire Station. The building is located just a block north of the Santa Fe Railroad, a block east of another historic building owned by the Kearny County Historical Society, the 1923 Texaco Station (NRHP, 2007). There are no trees surrounding the structure. Although the legal parcel associated with this building contains two lots, the building itself only occupies the west half of the south lot; the north lot historically was vacant. The parcel is open grassy area with a chain-link fence on the north, east, and south sides. A concrete sidewalk runs along the west and south facades.

#### Exterior

The building as is stands today holds much of its original charm. The exterior of the bank still has the original red bricks as it did when it was first built. Three of the exterior walls (east, south, and west) are smooth brick while the north wall has a roughness to it due to the prospect of another building being placed along this wall; however, this never occurred. A patterned brick parapet also runs the length of the public facades. A stone base runs along the west and south facades.

The west façade faces Main Street (*Photo 1*). The street level contains a historic wooden door with rectangular transom at the north end of the wall and a large arch-top display window to the south of the door. The arch is made of three brick courses. The window itself is historic with a single pane of glass in the bottom half and a rounded upper window divided into three vertical lights; the window works on a pulley system. The upper level contains two rectangular masonry openings. The original window units have been replaced at an unknown date with smaller wooden units and brick infill, but the original masonry openings are discernible. This is a typical treatment on the building unless noted otherwise. The upper portions of the masonry openings are surrounded by rectangular brick surrounds (typical of all upper windows). All windows on the building have simple stone sills that are in line with a brick datum that runs the length of the public facades.

The building's main entrance is located in the canted southwest corner of the building (*Photo 1*). The entrance is through a single, historic wooden door. This door has a lunette transom window above it that is made mainly out of glass. The original door consists mainly of glass but is also bordered by wood. A single window is located above the door.

The south façade faces 6<sup>th</sup> Street (*Photos 1 & 2*). The ground level has five historic masonry openings. The westernmost opening is a round-arch display window like that on the west façade. To the east of this window is a historic double-hung window. To the east of this window is a historic Craftsman style door (three lights in upper third with two vertical panels below). Another door is located to the east of this door. The easternmost masonry opening contains a large rectangular display window with steel lintel. The window has four vertical lights in the top third and two vertical lights in the bottom part of the window. The bulkhead is brick of a different type than the remaining wall, indicating this window, although historic, was potentially installed after the building's construction. A corrugated metal awning covers this window and sidewalk and is supported by three metal poles. Five masonry openings are located in the upper façade. The opening second from the west is wider than the others; the windows located in the center and east bays appear to be historic one-over-ones (there is not brick infill in these openings).

The east façade is partially obscured by the one-story building attached to the east of the brick building (*Photos 2 & 3*). Two historic openings are visible in the upper portion of the façade. The south window is a historic one-over-one window. The north window is covered on the interior and exterior, so its condition/integrity is currently unknown.

Deerfield State Bank

Name of Property

Kearny County, Kansas

County and State



Figure 1: Contextual image, showing location of bank within the city of Deerfield with an X (KHRI). North is up.

The north façade is unadorned and has a stepped parapet (*Photo 3*). One masonry opening is located at the upper level at the west end. This historic exterior door exits onto a metal staircase that leads down to the east along the wall, leading to a concrete pad. Underneath the fire escape is a yellow sign, advertising a circus that had come to Deerfield.

Attached to the east of the brick building is a one-story structure built around the same time as the bank building. The building is completely covered by historic pressed metal siding that emulates common bond brick. The south façade has a simple metal cornice along the top of the parapet (*Photo 2*). Two openings are located in this façade. The western opening is a wood-framed opening; a wooden window (with historic screen) is to the east of this door. The word "BEER" can still be found painted above the door and window from when this building was the original bar of Deerfield.

The east façade has a stepped parapet and two openings located at the north end of the wall (*Photos 2 & 3*). The south opening is a window that is in poor condition. A wooden door is located to the north of this window. A single window (covered) is located in the center of the north façade (*Photo 3*).

#### Interior

There are no photographs of the original interior of the bank; however, the interior appears to retain its historic 1907 materials and design. Overall materials include plaster ceilings and walls, metal ceilings in some rooms, wood trim, wood floors (some covered by carpet upstairs), and several historic five-panel doors.

#### Deerfield State Bank

Name of Property

Kearny County, Kansas
County and State



Figure 2: Vault door (Kala Lee Fortin).

The *main bank room* is accessed through the main entrance in the building's southwest wall (*Photos 4 through 6*). The room has high ceilings, which still include the original metal tiles. The room is also accessed through a door at the west end of the north wall that leads to a small foyer at the foot of the interior stair, accessed by the door in the west elevation (*Photos 6 & 8*). A door at the east end of the north wall leads into the space beneath the interior stair that was converted into a bathroom sometime after the building ceased to be used for a bank (*Photo 6*). On the north wall between the two doors is a slate chalk board; this slate was used by the post master, during the time that the building was a post office. At the north end of the east wall is the historic bank vault (*Figure 2*) (*Photo 4*). The vault has an arched ceiling and several historic vault inspection stamps from when it was Deerfield State Bank. A water heater was installed in this room at an unknown date. To the east still sits the original gas lantern that lit the inside of the vault.

At the south end of the main room's east wall is a door into the former bank president's office (Photos 4 & 7). This room has an exterior door and window in the south wall but is otherwise bare. The ceiling plaster has almost completely failed, but the floor and wood trim are extant. There is a room to the east of the office that is accessed through a door in the south façade; this room was not accessed during a recent site visit.

The upper level is accessed by an interior wooden stair at the north end of the building (*Photo 8*). The door on the west façade opens into a foyer that leads directly onto the west-east running stair; a door in the foyer's south wall leads into the main bank room. The stairway retains most of its plaster and wood trim.

At the top of the stair is a small landing. A door in the landing's south wall leads into a room in the center of the building (*Photo 9*). Immediately to the east upon entering this room is a bathroom, installed in the 1970s. The center room itself has a wood floor covered with carpet, but the ceiling is historic metal tiles. Two historic doors (one at the south and one at the north) in the center room's west wall lead into the west room (*Photo 10*); this wall is covered in non-historic wood paneling. This room also has a historic metal tile ceiling, exposed wood floor, and historic trim. An exterior door in the north wall leads onto the metal fire escape.

A door in the east wall of the upper landing leads into a large room at the east end of the building (*Photo 11*). Although the historic metal ceiling is extant in this space, its condition is poor due to a former roof leak. Likewise, the wood floor has been compromised by water damage. The room retains most of its historic finishes, including plaster walls and wood trim.

The interior of the one-story building was inaccessible during a recent site visit; however, it was partially viewable through the south exterior door (*Photo 12*). Historic doors, trim, and floor appear to be intact, at least in the south room. The two buildings are not internally connected.

In 1935, Deerfield State Bank merged with the Kearny State Bank and then in 1946 this bank merged with Lakin State Bank, and eventually became what is known today as the Kearny County Bank. When the bank moved to Kearny, Kansas in 1935, the building was used as the Bacon Drug store and Deerfield US Post Office. The post office was stationed there from 1962-1972. A slate chalk board still hangs on the wall where the post master, Henry Van Doren, would keep tabs on the mail. Also, the original front door still has a mail slot where those would drop off their outgoing mail.

Eventually the post office moved from the bank, and the Meyers family moved into the building for about 40 years, 1974-2013. When they lived in the building they did make some changes to the interior of the building. The family had some extra plumbing installed in order to have a bathroom installed under the staircase they also sectioned off the second floor into three rooms and added another bathroom. In order to accommodate a gas stove the family had a gas line installed so that it ran to the stove.

Deerfield State Bank Name of Property

Kearny County, Kansas County and State



Figure 3: Boundary Map (Google Earth).

Deerfield State Bank	Kearny County, Kansas
Name of Property	County and State
8. Statement of Significance	
-	
Applicable National Register Criteria (Mark "x" in one or more boxes for the criteria qualifying the property for National	
Register listing.)	Areas of Significance
A Property is associated with events that have made a significant contribution to the broad patterns of our history.	Commerce
B Property is associated with the lives of persons significant in our past.	
C Property embodies the distinctive characteristics of a type, period, or method of construction or	-
represents the work of a master, or possesses high artistic values, or represents a significant	Period of Significance
and distinguishable entity whose components lack individual distinction.	1907-1935
D Property has yielded, or is likely to yield, information important in prehistory or history.	
important in promotory of motory.	Significant Dates
	1907
Criteria Considerations (Mark "x" in all the boxes that apply.) Property is:	1935
A Owned by a religious institution or used for religious purposes.	Significant Person (Complete only if Criterion B is marked above.)
рагроссов.	N/A
B removed from its original location.	Cultural Affiliation
C a birthplace or grave.	N/A
D a cemetery.	Avolaitoot/Duildov
E a reconstructed building, object, or structure.	Architect/Builder Unknown
F a commemorative property.	
G less than 50 years old or achieving significance within the past 50 years.	

# Period of Significance (justification)

Deerfield State Bank received its charter in 1906 and its building was constructed in 1907; the bank was continuously in use until 1935, when it merged with the Kearney County Bank.

## **Criteria Considerations (justification)**

N/A

United States Department of the Interior NPS Form 10-900

National Park Service / National Register of Historic Places Registration Form OMB No. 1024-0018

Deerfield State Bank

Name of Property

Kearny County, Kansas

County and State

Narrative Statem ent of Significance

## Summary

Chartered on November 30<sup>th</sup>, 1906, with a capital stock of \$10,000.00, the Deerfield State Bank began construction of its new two-story brick building in January 1907. Before the building was completed, the bank operated out of the Corner Grocery (Owner: William A. Swords).¹ On August 10, 1907 the brick building was complete and the bank moved to its permanent spot at 602 Main Street. Deerfield State Bank was the first bank in Deerfield, Kearny County. From 1906-1935, the Deerfield State Bank was operated by the A.G. Campbell Family. A.G. held controlling interest and was the bank president. Carl Campbell (A.G.'s son) was a cashier, and Catherine (Campbell) Van Doren (A.G. Campbell's daughter) was a teller. In 1935 Deerfield State Bank merged with the Kearny County Bank and relocated, ending its period of significance. Deerfield State Bank is nominated to the National Register of Historic Places under Criterion A for its association with Deerfield's early commerce.

### **Elaboration**

In 1873 Kearny County was first created by the Kansas legislature. Five of the earliest settlers include: John O'Loughlin, A.B. Boylan, T. D. Brockett, E. S. Show, and C. Co. Chapman.<sup>2</sup> Kearny County was named after a United States Army officer, General Philip Kearny who is known for being a leader in both the Mexican-American War and the American War.<sup>3</sup> Within Kearny County there are two prominent cities, Lakin and Deerfield.<sup>4</sup>

One of the very first settlers of Kearny County was Richard Joice. Mr. Joice was an employee of the Santa Fe railroad; he settled in Kearny County in the month of July of 1873. In July 1874 Alonzo B. Boylan was the next settler to come to Kearny County. Boylan worked as an operator for the Santa Fe and was originally stationed in Dodge City; however, he was later stationed to the newly organized Lakin within Kearny County. A year after settling at Kearny County, Mr. Boylan's family, wife and children, Lenora Victoria and Ambrose Bradner joined him. The Boylans lived in the largest house in Lakin. This house was provided by the Santa Fe Railway Company and was also used as the church, Sunday school meetings, and as social affairs for the town. John O'Loughlin settled in Kearny County in October, 1873. J. O'Loughlin, his mother and two children were originally from County Clare, Ireland. J. O'Loughlin was the very first merchant within Lakin.<sup>5</sup>

Not long after Lakin was settled, in 1874, Deerfield was settled in 1878. The name "Deerfield" came from a large herd of deer that was in the same vicinity of Deerfield at the time. The very first settlers of Deerfield were Alva Cleveland and her sons, Henry and George. These three moved into the southwest end of Deerfield. In 1881 many new settlers came to Deerfield. Sarah Lee and her daughter and son-in-law, J.W. Wells, were the next to settle. Then Allen and Myles Lee came next, they settled on the east side of Deerfield. In 1882, the sister of Henry and George Cleveland, Mrs. Caswell and her daughter, Dolly moved to Deerfield. A year after moving to Deerfield, Dolly married a man by the name of Samuel H. Corbett who moved to Deerfield in 1881. Deerfield saw its very first post office established in 1882; shortly after the town school followed it.<sup>6</sup>

Twenty-four years after Deerfield was established A.G. Campbell and his two sons moved to town.<sup>7</sup> The Campbell family was very prominent within Deerfield. They were responsible for many businesses within both Deerfield and Kearny County. For instance, the Campbells conducted businesses in farming, stock raising, merchandising, and banking.<sup>8</sup>

8

<sup>&</sup>lt;sup>1</sup> This building was torn down in the early 1990's to build the Deerfield Community Center.

<sup>&</sup>lt;sup>2</sup> Kansas Historical Society, "Kearny County, Kansas," October 2015. *Kansapedia* <a href="https://www.kshs.org/kansapedia/kearny-county-kansas/15302">https://www.kshs.org/kansapedia/kearny-county-kansas/15302</a>. Accessed February 01, 2018.

<sup>&</sup>lt;sup>3</sup> Michael Robert Patterson, "Philip Kearny, Major General, United States Army," September 2005.

http://www.arlingtoncemetery.net/kearny.htm. Accessed February 01, 2018.

<sup>&</sup>lt;sup>4</sup> Kansas Historical Society, "Kearny County, Kansas."

<sup>&</sup>lt;sup>5</sup> Virginia P. Hicks, "Sketches of Early Days in Kearny County," *Kansas History: A Journal of the Central Plains.* Vol. VII, No. 1 (1938): 54-80; & Kansas Historical Society, "Kearny County, Kansas."

<sup>&</sup>lt;sup>6</sup> Hicks, 54-80; & Kansas Historical Society, "Kearny County, Kansas."

<sup>&</sup>lt;sup>7</sup> Hicks, 54-80.

<sup>8</sup> Hicks, 54-80.

#### Deerfield State Bank

Name of Property



**Figure 4:** Deerfield State Bank building, unknown date. Drug store is located at the east end of the building (Kearny County Historical Society).

# Kearny County, Kansas

County and State

On November 30<sup>th</sup>, 1906 the Deerfield State Bank officially received its charter from the state of Kansas with A.G. Campbell as the president of the bank.<sup>9</sup> According to the Garden City newspaper, *The Evening Telegram*, the Deerfield State Bank opened up for business on approximately January 15<sup>th</sup>, 1907 in a temporary location.<sup>10</sup> The need for the temporary location was because the building at 602 Main Street was still under construction.

In August 1907, nearly eight months after first opening, the Deerfield State Bank moved to its permanent location at 602 Main Street. 11 The new bank was a big deal to not only Deerfield but also Kearny County because banking was very limited. For instance, within Kearny County Mr. O' Loughlin was entrusted by many Kearny County inhabitants with their money because he owned a store and was well respected. 12 Mr. O'Loughlin would keep the money in many different locations such as "coffee cans, under bolts of calico, beneath kegs of fish, and anywhere that one would not expect to find it." 13 As the years

went on the need for a formal banking system was found necessary. The Kearny County residents decided to set up a makeshift bank in a storehouse in Deerfield. Unfortunately this storehouse had become too small as Kearny County grew so the town decided to tear it down and they moved the bank to larger quarters. In 1909, two years after first opening, the Deerfield State Bank became a county depository along with the Kearny County Bank and Lakin Bank.

Deerfield State Bank was significant to Deerfield because it was the only bank in Deerfield in the early 1900's. This might have contributed to the 1920 Bank robbery. On September 21st, 1920 The *Garden City Telegram* reported that the Deerfield State Bank had been robbed on August 29th, 1920; on the following day *the Wichita Beacon* also reported about the robbery. According to both newspapers, the robbers broke through the back door of the bank and then burrowed through the vault wall; by doing this the robbers protected the vault door from any damage. To Once inside the vault the robbers took about \$300 in silver and then \$2,500 in safety deposit boxes; according to *the Garden City Telegram* within those safety deposit boxes were Liberty bonds. The robbers however were never caught; this is mainly due to the cleanup work after the robbery. After taking the money, the robbers wiped down every surface they had touched with a wet towel to prevent any fingerprints from being found. The robbers wiped down every surface they had touched with a wet towel to prevent any fingerprints from being found.

Deerfield State Bank only survived approximately 15 years following the robbery. In 1930 the bank president and owner, A.G. Campbell died and left the deed to his two sons, Earl and Carl, as well his daughter; Mary Thornbrough. In 1935, five years after the death of A.G. Campbell, it was decided that the Deerfield State Bank would merge with the Kearney County Bank and reside in Lakin by the common ownership at that time.<sup>20</sup> Because of this merge the bank in Deerfield

<sup>&</sup>lt;sup>9</sup> "Deerfield and Lakin." Deerfield and Lakin Kansas sections of the *1912 Kansas Polk Business Directory*. 1911. Accessed January 18, 2018.

<sup>&</sup>lt;sup>10</sup> "Have Experience," *The Evening Telegram* (Garden City) (January 14, 1907): 1. Accessed January 23, 2018. https://basic.newspapers.com/image/?spot=16800754.

<sup>&</sup>lt;sup>11</sup> "Deerfield News." *The Evening Telegram* (Garden City) (August 10, 1907): 1. Accessed January 23, 2018 <a href="https://basic.newspapers.com/image/?spot=16801305">https://basic.newspapers.com/image/?spot=16801305</a>.

<sup>&</sup>lt;sup>12</sup> Hicks, 54-80.

<sup>&</sup>lt;sup>13</sup> Hicks, 54-80.

<sup>&</sup>lt;sup>14</sup> Hicks, 54-80.

<sup>&</sup>lt;sup>15</sup> Hicks, 54-80.

<sup>&</sup>lt;sup>16</sup> "Commissioners Proceedings," The Advocate (Lakin) (February 18th, 1909): n.p.


<sup>&</sup>lt;sup>17</sup> "Robbers Make Big Haul At Deerfield State Bank," *The Wichita Beacon* (September 03, 1920): n.p.

<sup>&</sup>lt;sup>18</sup> "Bank Robbers Robbed Bank," *The Garden City Telegram* (September 02, 1920): n.p.

<sup>&</sup>lt;sup>19</sup> "Robbers Make Big Haul At Deerfield State Bank."

<sup>&</sup>lt;sup>20</sup> "The Kearny County Bank." *Kearny County Kansas: A Wonderful Life Opportunity*. http://www.kearnycountykansas.com/dld/KearnyCountyBrochure.pdf Accessed January 18, 2018.

Name of Property



**Figure 5:** Deerfield, Kansas in 1917. View is looking north along Main Street (Kearny County Historical Society).

# Kearny County, Kansas

County and State

was officially closed. In 1946 though, the Kearny County Bank, in which the Deerfield State Bank merged, also merged with the Lakin State Bank a majority of it being bought by the Garden National Bank from local residents.<sup>21</sup> Throughout this merging the Campbell family retained its spot as the bank's minority interest.<sup>22</sup> After 1935, the Bacon Drug Store occupied a portion of the building (*Figure 4*).

Although it is unknown exactly when the one-story structure was built to the east of the bank building, the building appears in historic images of the bank (*Figure 5*). Local tradition states this building housed Deerfield's first bar.

The United States Postal Service located in the Deerfield State Bank building from 1962-1972. The Hagler family moved into the building in 1972, and lived there until 1974. Eventually the Meyers family moved into the building in 1974 and lived there until 2013. However, after the family moved, the old Deerfield State Bank building remained vacant into the present day and is owned by Kala Lee Fortin.<sup>23</sup> Since

the closing of the Deerfield State Bank, in 1935, no bank has inhabited the city of Deerfield; however, an ATM express has been placed along the highway.<sup>24</sup>

The Deerfield State Bank was significant for its time. The business, Deerfield's only bank, operated for 30 years, and the building shows how an early 1900's bank looked and functioned. It allows the residents of Deerfield to envision what the beginning of their town would have been like. This bank building is also the most intact, if not the only, extant building from Deerfield's early 20<sup>th</sup> century commercial district (*Figure 5*). As such, it is significant as one of the best tangible links to this era of Deerfield's history.

<sup>&</sup>lt;sup>21</sup> "The Kearny County Bank."

<sup>22 &</sup>quot;The Kearny County Bank."

<sup>&</sup>lt;sup>23</sup> In 1940, five years after closing, Earl Campbell transferred his portion of the deed to his brother Carl. Six years later Carl sold the deed to a Julian Wilbur Wells. J.W. Wells had the deed for about 13 years until his death in 1961. J.W. Wells's daughters, Mildred Hagler and Eleanor Moore, became sole owners of the building until 1972. On July 8, 1972 Grant Meyers and his wife Lulu, became joint tenants with Eleanor and A.W. Moore and Mildred and L.W. Hagler. Two years after becoming joint tenants, Grant and Lulu became the sole deed owners. Lulu's death in 2001 split up the building's ownership between 12 family members of Lulu's family. It was not until May 10, 2013 that the current owner, Kala Lee Fortin, took control of the deed.

<sup>&</sup>lt;sup>24</sup> "US bank locator." Bank branch and ATM locations in Deerfield, Kansas near me. Accessed February 08, 2018. http://ks.bankee.us/localities/deerfield-ks/.

Deerfield State Bank	Kearny County, Kansas		
Name of Property	County and State		

## 9. Major Bibliographical References

**Bibliography** (Cite the books, articles, and other sources used in preparing this form.)

- "CHARTERS GRANTED." *The Topeka Daily Capital*, November 30, 1906. Accessed January 23, 2018. https://basic.newspapers.com/image/?spot=16800548.
- "Commissioners Proceedings." *The Advocate* (Lakin), February 3, 1911. Accessed January 23, 2018. https://basic.newspapers.com/image/?spot=16800166.
- "Deerfield and Lakin." Deerfield and Lakin Kansas sections of the 1912 Kansas Polk Business Directory. 1911. Accessed January 18, 2018. http://www.ksgenweb.org/kearny/bits/polk1912.html.
- "Deerfield News." *The Evening Telegram* (Garden City), August 10, 1907. Accessed January 23, 2018. https://basic.newspapers.com/image/?spot=16801305.
- "HAVE EXPERIENCE." *The Evening Telegram* (Garden City), January 14, 1907. Accessed January 23, 2018. https://basic.newspapers.com/image/?spot=16800754.
- Hicks, Virginia P. "Sketches of Early Days in Kearny County." *Kansas History: A Journal of the Central Plains. Vol. VII, No. 1 (1938):54-80. Kansas Historical Society.*

History of Kearny County Kansas Volume I

History of Kearny County Kansas Volume II

Jean Campbell: (858) 551-8687

- "Kearny County Historical Society Museum." Kearnycountymuseum.org. Accessed January 18, 2018. http://www.kearnycountymuseum.org/.
- "Local News Briefs." *The Evening Telegram* (Garden City ), December 19, 1906. Accessed January 23, 2018. https://basic.newspapers.com/image/143625575

Max Van Doren (Son of Catherine Van Doren): (626)355-6587

- Patterson, Michael Robert. Philip Kearny, Major General, United States Army. September 2005. Accessed February 01, 2018. <a href="http://www.arlingtoncemetery.net/kearny.htm">http://www.arlingtoncemetery.net/kearny.htm</a>.
- "ROBBERS MAKE BIG HAUL AT DEERFIELD STATE BANK." *The Wichita Beacon*, September 03, 1920. Accessed January 23, 2018. <a href="https://basic.newspapers.com/image/76637219/">https://basic.newspapers.com/image/76637219/</a>.
- "The Kearny County Bank." *Kearny County Kansas: A Wonderful Life Opportunity*. Accessed January 18, 2018. http://www.kearnycountykansas.com/businesses/2849/the-kearny-county-bank

Previous documentation on file (NPS):	Primary location of additional data:
preliminary determination of individual listing (36 CFR 67 has been requested) previously listed in the National Register previously determined eligible by the National Register designated a National Historic Landmark recorded by Historic American Buildings Survey # recorded by Historic American Engineering Record # recorded by Historic American Landscape Survey #	X State Historic Preservation Office Other State agency Federal agency Local government University Other Name of repository: Kansas Historical Society
Historic Resources Survey Number (if assigned): N/A	

Deerfield State Bank		Kearny County, Kansas	
Name of Property		County and State	
10. Geographical Data			
Acreage of Property Less than one	<u>.                                    </u>		
Provide latitude/longitude coordinate (Place additional coordinates on a conti			
Latitude/Longitude Coordinates  Datum if other than WGS84: (enter coordinates to 6 decimal places)	_		
1 37.979931 -101.133023 Longitude:	3 Latitude:	 Longitude:	
2	4		
Latitude: Longitude:	Latitude:	Longitude:	
<b>Boundary Justification</b> (explain why the Boundary includes the building and the			
11. Form Prepared By			
name/title	ala Lee Fortin (owner)		
organization Kansas Historical Society	/	date 27 February 2018	
street & number 6425 SW 6 <sup>th</sup> Avenue		telephone (785)272-8681	
city or town: <u>Topeka</u>		State: KS zip code:	66615
e-mail Danielle.n.hall@gmail.com	1		
Property Owner: (complete this item at the	e request of the SHPO or FPO)		
name Kala Lee Fortin			
street & number 18 Boulder Drive		telephone (931)237-2917	
city or town Sanford		state NC zip code 2	7332

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C.460 et seq.).

**Estimated Burden Statement**: Public reporting burden for this form is estimated to average 100 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Office of Planning and Performance Management. U.S. Dept. of the Interior, 1849 C. Street, NW, Washington, DC.

United States Department of the Interior NPS Form 10-900

National Park Service / National Register of Historic Places Registration Form OMB No. 1024-0018

Deerfield State Bank Kearny County, Kansas Name of Property County and State

### **Additional Documentation**

Submit the following items with the completed form:

## **Photographs**

Submit clear and descriptive photographs. The size of each digital image must be 1600x1200 pixels (minimum), at 300 ppi (pixels per inch) or larger. Key all photographs to a sketch map or aerial map. Each photograph must be numbered and that number must correspond to the photograph number on the photo log. For simplicity, the name of the photographer, photo date, etc. may be listed once on the photograph log and doesn't need to be labeled on every photograph.

## **Photograph Log**

12 of 12:

Name of Property:	Deerfield State Bank
City or Vicinity:	Deerfield
County: <u>Kearny</u>	State: Kansas
Photographer:	Amanda K. Loughlin (KSHS)
Date Photographed:	March 2018

Description of Photograph(s) and number, include description of view indicating direction of camera:

01 of 12: Looking NE at west and south facades 02 of 12: Looking NW at south and east facades 03 of 12: Looking SW at east and north facades 04 of 12: Main level, main room, looking SE from near NW corner of room 05 of 12: Main level, main room, looking SSW from east wall, toward main entrance 06 of 12: Main level, main room, looking NW 07 of 12: Main level, east room, looking SW 08 of 12: Stairwell, looking down (and west) from second level 09 of 12: Second level, middle room, looking SW from near top of stair 10 of 12: Second level, west room, looking north 11 of 12: Second level, east room, looking SE Main level of east addition, looking NE from south door

























# UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE


# NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Requested Action:	Nomination				
Property Name:	Deerfield State Bank				
Multiple Name:					
State & County:	KANSAS, Kearny				
Date Rece 5/18/20			Date of 45th Day: 7/2/2018	Date of Weekly List: 6/29/2018	
Reference number:	SG100002625				
Nominator:	State				
Reason For Review	:				
X Accept	Return	Reject <b>6/2</b> 9	<b>9/2018</b> Date		
Abstract/Summary Comments:					
Recommendation/ Criteria					
Reviewer Alexis	Abernathy	Discipline	Historian		
Telephone (202)3	54-2236	Date			
DOCUMENTATION	: see attached comme	nts : No see attached S	LR : No		

If a nomination is returned to the nomination authority, the nomination is no longer under consideration by the National Park Service.



6425 SW 6th Avenue Topeka KS 66615-1099



Governor Jeff Colyer, M.D. Jennie Chinn, Executive Director

......

May 17, 2018

Paul Loether, National Register Chief National Park Service National Register of Historic Places 1849 C Street, NW, Mail Stop 7228 Washington, DC 20240

Re: National Register documents for Kansas

Dear Mr. Loether:

Please find enclosed the following National Register documents:

## NEW NOMINATIONS in Certified Local Government (3)

- Shiloh Baptist Church; Topeka, Shawnee County, Kansas (new nomination)
  - Physical, signed copy of the nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination and letter of support;
  - 1 CD (disk #2) with photographs.
- O'Sullivan, John & Anna, Farmstead; Overbrook vicinity, Douglas County, Kansas (new nomination under "Historic Agriculture-related Resources of Kansas" MPS)
  - Physical, signed copy of the nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination and .KMZ file;
  - 1 CD (disk #2) with photographs.
- Vine Street Historic District; Abilene, Dickinson County, Kansas (new nomination)
  - Physical, signed copy of the nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination, .KMZ file, PDF of non-objecting owners, and letter of support;
  - 1 CD (disk #2) with photographs.
  - There are 19 distinct property owners in this district; no notarized objections were received. Ten of the 19 owners signed a "We do not object" petition, a copy of which is enclosed on disk #1.

#### NEW NOMINATIONS in non-CLG communities (4)

- Stonehaven Farm; Tonganoxie vicinity, Leavenworth County, Kansas (new nomination)
  - Physical, signed copy of the nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination and letters of support;
  - 1 CD (disk #2) with photographs.

- Snowden S. Mouse Service Station & Tourist Home; Emporia, Lyon County, Kansas (new nomination under "Roadside Kansas" MPS)
  - Physical, signed copy of the nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination;
  - 1 CD (disk #2) with photographs.
- McPherson Community Building; McPherson, McPherson County, Kansas (new nomination)
  - Physical, signed copy of the nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination;
  - 1 CD (disk #2) with photographs.
- Deerfield State Bank; Deerfield, Kearny County, Kansas (new nomination)
  - Physical, signed copy of the nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination;
  - 1 CD (disk #2) with photographs.

# RESUBMITTAL OF NEW NOMINATION (1)

- Pawnee Tipi Ring Site, Unrien-Kraus Farmstead & Golden Spring Beach, (Address Restricted); Hays vicinity, Ellis County, Kansas (resubmitted nomination) (NRIS #SG 100002307)
  - Physical, signed copy of the nomination's first page;
  - Physical, signed copy of the REDACTED nomination's first page;
  - 1 CD (disk #1) with a PDF of the true and correct copy of the nomination, a PDF of the true and correct copy of REDACTED nomination, and .kmz file;
  - Please refer to previously submitted disk #2 with photographs, as the photo documentation has not changed in this submittal.

If you have any questions about these enclosed items, please contact me at ext. 216 or Amanda.Loughlin@ks.gov.

Sincerely,

Amanda K. Loughlin

National Register Coordinator

Kansas State Historic Preservation Office

Enclosures