OMB No. 1024-0018



NATIONAL REGISTER

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES REGISTRATION FORM

1. Name of Property	======	=========	====
historic name: First Methodist Episcopal Church			
other name/site number: First United Methodist	Church		
2. Location street & number: 503 W. Commercial St.			
	not for	publication:	N/A
city/town: Ozark		vicinity	: <u>N/A</u>
state: AR county: Franklin code:	AR 047	zip code:	72949
3. Classification			
Category of Property: <u>Building</u>			
Number of Resources within Property:			
Contributing Noncontributing			
Number of contributing resources previously lis Register: $N/A$	ted in the	he National	
Name of related multiple property listing: $N/A$			

4. State/Federal Agency Certification			
As the designated authority under the of 1986, as amended, I hereby certify request for determination of eligibili standards for registering properties i Historic Places and meets the procedur set forth in 36 CFR Part 60. In my or does not meet the National Regist sheet.	that ity me in the cal an oinion	this <u>X</u> nomination ets the documentation of the later of	on ion of uirements meets continuation
Signature of certifying official		7-16-92 Date	
Signature of certifying official		Date	
Arkansas Historic Preservation Program State or Federal agency and bureau	n		
In my opinion, the property meets Register criteria See continuati	on sh	does not meet the eet.	National
Signature of commenting or other office	cial	Date	
5. National Park Service Certification  I, hereby certify that this property i  entered in the National Register  See continuation sheet.  determined eligible for the National Register  See continuation sheet.  determined not eligible for the National Register  memoved from the National Register  cother (explain):	as: ————————————————————————————————————	elous Byers	9/4/92
		ignature of Keeper	Date of Action
6. Function or Use			
Historic: Religion			
Current : Religion	Sub:	Religious Facility	7

7. Description
Architectural Classification:
Late Gothic Revival
Other Description: N/A
Materials: foundation Stone roof Ceramic Tile walls Stone other
Describe present and historic physical appearance. $\underline{\mathbf{X}}$ See continuation sheet.
8. Statement of Significance
Applicable National Register Criteria:C
Criteria Considerations (Exceptions): A
Areas of Significance: Architecture
Period(s) of Significance: 1909
Significant Dates: N/A
Significant Person(s): N/A
Cultural Affiliation: N/A
Architect/Builder: Klingensmith, A.
State significance of property, and justify criteria, criteria

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

X See continuation sheet.

## National Register of Historic Places Continuation Sheet

Section	number	7	Page	1
000000	110111001		. ~9~	-

#### Summary

The First Methodist Episcopal Church, South, now known as the First United Methodist Church, in Ozark is a single-story, cut stone-constructed sanctuary with two towers, associated anterooms, and a full basement. Erected in 1909, the church displays the Gothic Revival style of architecture.

#### Elaboration

Constructed in 1909, the First Methodist Episcopal Church, South, now known as the First United Methodist Church, in Ozark is a one-and-a-half story sanctuary with two towers, associated anterooms, and a full basement. The cut-stone masonry structure was designed in the Gothic Revival style of architecture and displays such typical characteristics of the style as crenelated towers, buttresses, pointed arch windows, and shaped parapets. The sanctuary is covered by a clay-tile, parapeted gable roof. The full basement is partially exposed, and there is one cut-stone chimney at the rear of the church.

Two square, crenelated towers flanking a gable end that forms the sanctuary comprises the northern, or front, elevation. Both towers contain identical double-leaf entrances that are located within pointed Gothic arches. Decorative tracery adorns the arched space above the conventional doors. The eastern tower is much taller than the southern tower and houses the belfry. The belfry area is defined by three lancet openings on all four sides of the tower. Below the belfry, tall, narrow rectangular fixed stained glass windows fenestrate the three sides of the tower that are exposed at this height. The entrance is directly below this band on the northern elevation, but the eastern elevation of the tower is decorated further with an oculus window with a row of three smaller rectangular fixed stained glass windows underneath. There are also two one-over-one double-hung windows that light the basement on this elevation of the tower. They are located just above ground and below a shallow belt course.

The gable end area is also bolstered by angled buttresses at each end's juncture with the two towers. This elevation is dominated by a symmetrical group of three Gothic windows. A large pointed-arch occupies the center of the group and contains two stained-glass lancet windows with an oculus window at the apex. Two lancet arches flank the center arch and each contains a stained-glass lancet window that is identical in dimensions to the two within the center arch. All of the stained-glass windows in the church are shielded by protective plexiglass. Above this window grouping is a tall, narrow rectangular opening that serves as a louvered attic vent. Above this vent is a somewhat unusual stone finial. The two entrances on this elevation are accessed by a three-step central stoop which divides into two perpendicular six-step stoops that service the respective towers.

## National Register of Historic Places Continuation Sheet

Section	number	7	Page	2
36011011	HUHHDE		1 ago	

The previously mentioned belt course should be more appropriately called a water table at this elevation for it is located at the top of the two tower stoops. There are, however, five small rectangular basement windows located below the belt course in the space between the tower stoops.

The eastern and western elevations are basically identical. Both consist of three bays separated by three perpendicular buttresses. The end buttress gives the appearance of a continuance of the rear gable parapet. Each bay is crowned by a shaped parapet and is fenestrated by a double lancet stained-glass window and an oculus window all within a single pointed arch, as found in the northern elevation. Because of the sloping site, the eastern elevation has more exposed wall surface with enough space available to permit paired one-over-one double-hung basement windows beneath the belt course. The western elevation has only enough wall surface below the belt course for small rectangular windows; however, these openings have now been largely utilized for modern heating and air conditioning units.

A one-and-a-half story center bay that is covered with a clay-tile, gable-on-hip roof forms the southern, or rear, elevation. Just above the ridge of this roof is an oculus window located in the rear of the main gable parapet. The center section, which is not fenestrated, is flanked by two single-story hipped-roof bays with each containing a one-over-one double-hung stained-glass window on the southern elevation. Both bays also feature an identical window on their respective eastern and western elevations. The southern elevation also contains four one-over-one basement windows. The basement can be entered from the exterior by two single-leaf entrances. One is placed in the eastern elevation of the eastern hipped-roof bay, and the other is located in the southern elevation of the tall, eastern tower.

In 1957, an educational building was constructed and connected to the church by an enclosed hallway that utilized an existing doorway at the southwest corner of the church. Though attached to the church, practically all of the western elevation in its original condition remains visible from the road.

There have been no substantial alterations to the interior. Dark-stained trusses accentuate the vaulted ceiling. The pipe organ is located within the chancel which is framed by a large pointed Gothic arch. The rear wall of the chancel is filled with the organ pipes, which are in the shape of three pointed arches. Gothic arch reliefs adorn the wall surfaces to either side of the pulpit and to either side of the choir at the rear of the church. There is also a choir loft supported by two large square columns.

## National Register of Historic Places Continuation Sheet

Section number \_\_\_\_\_8 Page \_\_\_\_1

#### Summary

The First Methodist Episcopal Church, South, now known as the First United Methodist Church, is being nominated under Criterion C with local significance as the best example of the Gothic Revival style of architecture in Ozark.

#### Elaboration

The First Methodist Episcopal Church, South at 503 West Commercial Street in Ozark was constructed in 1909 to replace an earlier frame structure built in 1876, the first Methodist church in Ozark. The congregation was organized in 1871 by Reverend Hastings Puckett. This is a somewhat late date for the arrival of the Methodist presence in Ozark since the town was first laid out in 1836 by Archibald Yell, David Walker, and William Haile. As the oldest town in Franklin County, Ozark was made the county seat when the county was created in 1837. The town's growth was interrupted by the Civil War when the town was almost entirely burned. After the war the town resumed normal growth. By 1909 when the new church was built, Ozark had become the center of several coal mining operations in addition to the conventional mercantile businesses.

In 1909, a building committee of nine chaired by Marion B. Conatser selected the architect, A. Klingensmith, to design the new church. The contract price of \$13,000, which included material and labor, was awarded to Claude Talley. A ground-breaking ceremony was held on June 7, 1909 by the building committee, church teachers, and class members. By Dedication Week, November 4-10, 1912, a total of \$10,245 had been contributed by fifty-two members of the congregation. At this time a pipe organ, which was manufactured by George Kilgen and Son of St. Louis, was presented as a gift to the church from the Young Ladies' Auxiliary. This organ is still in use today.

The First Methodist Episcopal Church, South, now known as the First United Methodist Church, serves as an important link to an architectural style that was first popularized in the United States in the 1840's. Resplendent in its medieval towers, parapets, and decorative detail, this church is important for its attempt at correct Gothic detail at a relatively late date in the American duration of the style. After 1900, churches constructed in the Gothic Revival style generally became less detail oriented, and soon the style was supplanted entirely by the derivative Collegiate Gothic style. The First Methodist Episcopal Church, South is an outstanding representative of the Gothic Revival style of architecture and the best example in the town of Ozark. For these reasons, this church is being nominated under Criterion C with local significance.

9. Major Bibliographical References
X See continuation sheet.
Previous documentation on file (NPS):
<pre>preliminary determination of individual listing (36 CFR 67) has been     requested. previously listed in the National Register previously determined eligible by the National Register designated a National Historic Landmark recorded by Historic American Buildings Survey # recorded by Historic American Engineering Record #</pre>
Primary Location of Additional Data:
_ State historic preservation office _ Other state agency _ Federal agency _ Local government _ University _ Other Specify Repository:
10. Geographical Data
UTM References: Zone Easting Northing Zone Easting Northing
A 15 424770 3927150 B
See continuation sheet.
Verbal Boundary Description: See continuation sheet.
Beginning at the southwest corner of the intersection of Commerce St. (U.S. Route 64) and 5th St., proceed west along the southern curbline of Commerce St. to the point formed by the intersection of said line and the line formed by, but 5 feet away from, the western elevation of the education bldg. addition. Then proceed south to the intersection of said line and a line formed by, but 5 feet away from, the southern elevation of the church. Then proceed east to the western curbline of 5th St. Then proceed north to the point of beginning.
Boundary Justification: See continuation sheet.

This boundary reflects the close proximity of the surrounding properties and includes all of the property historically associated with this resource that retains its integrity.

# National Register of Historic Places Continuation Sheet

Section number 9 Page 1

#### Bibliography

Herndon, Dallas T. Annals of Arkansas. Little Rock: The Historical Record Association, 1947. Vol. I, p. 502.

Information Supplied by James Gilmer, Main Street Ozark Project Manager, August 21, 1991.

The Goodspeed Biographical and Historical Memoirs of Northwestern Arkansas. Chicago: The Goodspeed Publishing Co., 1889. pp. 643-654.

11. Form Prepared By
Name/Title: Patrick Zollner, National Register Historian
Organization: Arkansas Historic Preservation Program Date: 07/27/92
Street & Number: 225 E. Markham, Suite 300 Telephone: (501) 324-9346
City or Town: Little Rock State: AR ZIP: 72201

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

### NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NOMINATIO	N		
PROPERTY First Methodist E	piscopal Church	n, South	
NAME:			
MULTIPLE NAME:			
STATE & COUNTY: ARKANSAS, F	ranklin		materials
DATE RECEIVED: 8/03/92 DATE OF 16TH DAY: 9/03/92		PENDING LIST: 45TH DAY:	8/18/92 9/17/92
DATE OF WEEKLY LIST:			
REFERENCE NUMBER: 92001154			Period Are
	Builder/Archit		
REASONS FOR REVIEW:			
APPEAL: N DATA PROBLEM: N OTHER: N PDIL: N REQUEST: N SAMPLE: N	PERIOD: N SLR DRAFT: N	PROGRAM UNAPPENATIONAL:	ROVED: N N N N N N N N N N N N N N N N N N N
COMMENT WAIVER: N		of areas chec ificance to the	was to a mark the first
ACCEPTRETURN	REJECT 9/4/	·	ntered in the atlanel Register
ADGED AGE (GUMANDY, GOMMENTE)			
ABSTRACT/SUMMARY COMMENTS:			
A COLUMN TO THE REAL PROPERTY OF THE PARTY O			
			GEOGRAPHICAL DAT
			aareage UTMs
s presentation (%)			sketch maps
DECOM (CDITEDIA			OTHER COMMENTS
RECOM./CRITERIA	ad yem nordeni		
DATE	ds.		

DOCUMENTATION see attached comments Y/N see attached SLR Y/N benpis

CLASSIFICATION 3DIVERS HAS LAWOTTAN	GGILIO
countresource typealH SO SETSIDES LAW	OITAM .
STATE/FEDERAL AGENCY CERTIFICATION	REQUESTED ACTION: NOMIN
FUNCTION	ninon shortan daraadyan
historiccurrent	PROPERTY First Methodi NAME:
DESCRIPTION	MULTIPLE
architectural classificationmaterialsdescriptive text	
03/92 DATE OF PENDING LIST: 8/18/92	DATE RECEIVED: 8/0 DATE OF 16T8 DAY: 9/0
SIGNIFICANCE	
Period Areas of SignificanceCheck and jus	stify belowMUM 30M393338
Specific dates  Builder/Architect Statement of Significance (in one paragraph)	
clarity dayong AMD MARDOR MARDOR MARDOR M applicable criteria MOLTAM MARDOR M justification of areas checked relating significance to the resource context relationship of integrity to significance justification of exception	APPERL: N DATA PROBLEM OTHER: N PDIL: REQUEST: N SAMPLE: COMMENT WAIVER: N ACCEPT RETURN ABSTRACT/SUMMARY COMMENT
BIBLIOGRAPHY	
GEOGRAPHICAL DATA	
acreageverbal boundary descriptionboundary justification	
ACCOMPANYING DOCUMENTATION/PRESENTATION	
sketch mapsUSGS mapsphotographs	presentation
OTHER COMMENTS	
Questions concerning this nomination may be direct	RECOM JEHTERIA ot bette biscipilne
Phone	DATE
Date Signed V/N see _attached SLR V/N bengin	




First Methodist Episcopal Church, South Franklin Co., Arkansus Photographed by Joe De Rose April 1989 Negative on file at AHPP View from the northwest

FIRST METHODIST EPISCOPAL CHURCH SOUTH ORGANIZED BY REVELASTINGS PUCKETT A.D. 1871 PRESENT BUILDING ERECTED A D 1909-10 REV. GEORGE MCGLUMPHY PASTOR BUILDING COMMITTIEE M.B. CONATSER CHAURMAN A.H. TREADWAY VICE-CHAIRMAN WALTER CLINITON SECRETARY W.G. BILL TREASURER GEORGE RUSSELL LE FORD FINANCE COMMUTTEE A. D. REYNOLDS J.E. BRYAN


A KLINGENS MITH ARCHITECT

CLAUDE TALLEY, BUILDER

First Methodist Episcopal Church, South Frenklin Co., Arkansas Photographed by De DeRose, April 1989 Negative on file at AHPP View of plaque




First Methodist Episcopa | Church, South Franklin Co., Arkansas Photographed by Joe De Rose April 1989 Negative on fike at AHPP View from the east




First Methodist Elpiscopal Church, South
Franklin Co., Arkansas
Photographed by Joe DeRose
April 1989
Negative on File at AHPP
Negative on tite at AHPP
View of interior stained glass windows.



First Methodist Episcopal Church, South Franklin Co., Arkansas Photographed by Joe De Rose April 1989 Negative on file at AHPP View of interior from the south.



First Methodist Episcopal Church, South Franklin Co., Arkansas Photographed by Joe De Rose April 1989 Negative on file at AHPP View of pointed-arch relief over doorway, from the north




First Methodist Episcopal Church, South Franklin Go., Arkansas Photographed by Joe DeRose April 1989 Negative on file at AHPP View from the north



First Methodist Episcopal Church, South Franklin Co., Arkansas Photographed by Joe De Rose April 1989 Negative on file at AHPP View from the South




First Methodist Episcopal Church, South Franklin Co., Arkansas Photographed by Joe De Rose April 1989 Negative on file at AHPP View of interior from the north



First Methodist Episcopal Church, South Franklin Co., Arkansas Photographed by Joe DeRose April 1989 Negative on file at AHPP View from the northeast



ARKANSAS HISTORIC PRESERVATION PROGRAM



July 16, 1992

Carol D. Shull
Chief of Registration
United States Department of the Interior
National Register of Historic Places
National Park Service
1100 "L" Street, NW
Washington, DC 20240

RE: First Methodist Episcopal Church, South Ozark County, AR

Dear Carol:

We are enclosing for your review the nomination of the above referenced property. The Arkansas Historic Preservation Program has complied with all applicable nominating procedures and notification requirements in the nomination process.

Thank you for your consideration in this matter.

Sincerely,

Cathy Buford

State Historic Preservation Officer

CB:kg

Enclosures





DESCRIPTION SHEET	State Name HR	County Name Franklin
	Resource Name First Methodist Episc	copal Church, South
	Data Collector's Surname Mackie	
	Federal Register List//	Cert. Date//
	Reference No. 9200 1154	
Describe Problem:		
	Added 1909 as sign, date in architectural significance.	conjunction w/
	architectural Dignifecance.	
	· c	
Team Leader	Date / / N R Staff	Date / /
Problem Team	Date / /	