United States Department of the Interior National Park Service

National Register of Historic Places Inventory---Nomination Form

For NPS use o	nly			
received	APR	14	7 19	985
date entered	May	1	6	1985

See instructions in *How to Complete National Register Forms* Type all entries—complete applicable sections

1. Name

historic	Kissock Block	k Building		
and/or common	Kissock Block	k Building		
2. Loca	ation			
street & number	115–117–119– 2	121 East Mountain Av	venue	n/a not for publication
city, town	Fort Collins	n/a vicinity of		
state Co1	orado co	de 08 county	Larimer	code 069
3. Clas	sification			
Category district XX building(s) structure site object	Ownership public XX private both Public Acquisition n/a in process n/a being considered	Status _XX occupied unoccupied work in progress Accessible _XX yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	ner of Prope	rty		
name Moun street & number	tain Avenue Propert 117 East Mountai	ties-Joint Venture in Avenue, Suite 205	c/o Walter F. Br	own, Partner
city, town Fo	rt Collins	$\underline{n/a}$ vicinity of	state	colorado
5. Loca	ation of Leg	al Descripti	on	
courthouse, regi	istry of deeds, etc.	nty Recorders Office	e-Larimer County C	ourthouse
street & number	200 West Oal	k Street		
	Fort Collins		state	Colorado
	resentation	in Existing	Surveys	
	Inventory of Histo	oric Sites	porty been determined	eligible? yes _XX_ no
0ngoi date	ng			tate county local
depository for su	urvey records Colorad	<u>do Historical Societ</u>	v, OAHP, 1300 Bro	adway
city, town De	nver		state	·

7. Description

Condition	
<u>X</u> excellent	dete
good	ruin
fair	une

Check one deteriorated _____ unaltered ruins ____X_altered unexposed Check one __X_ original site ____ moved date _____

Describe the present and original (if known) physical appearance

The Kissock Block Building, originally constructed in 1889, currently stands as the only remaining Colorado Commercial Victorian structure on East Mountain Avenue outside of the Old Town Historic District. The recently renovated two story sixty-one foot wide facade consists of red brick highlighted with native sandstone lintels, formed metal cornices with applied ornament, and typical period grade level storefronts. This facade also serves as the streetscape focal point of the south side of the 100 Block of East Mountain Avenue since it is flanked by an alley to the east and open nondescript parking lots on both sides.

The plan dimensions of the Kissock Block Building, being approximately 61 feet by 98 feet incorporates three 20 foot wide grade level retail bays with a full basement below and approximately 5000 feet of second floor office space.

Exterior (Refer to Photos 1, 2, and 3)

The original 1889 structure abutted a similar 40 feet wide structure to the west thus encompassing the easterly 100 feet of Lots 7, 8, 9, and 10 in Block 121. However, due to split ownership through the years, the western two retail bays were demolished leaving the current 61 foot wide Kissock Block Building. In approximately 1895, as a result of significant fire damage, the entire first floor and second floor of the Kissock Block Building was rebuilt under the direction of the IOOF. At this time, the second level was converted to meet the IOOF's needs, one of which was a "clearspan" ballroom 40 feet wide. Thus the new roof was rebuilt incorporating a large coffered ceiling still evidenced externally by the existing rear roof line (See photo #2.).

Prior to renovation,¹ the primary front elevation consisted of flat upper level stone aggregate panels accompanied by a mil finish aluminum storefront system. However the east elevation and the rear elevation remained essentially as originally constructed. But the "fake" applied front veneer covered all historic detail at grade level and totally eliminated all second story fenestration and facade detail.

Removal of this "slipcovered" facade revealed that many of the original details such as the castiron columns, brickwork and native stone were in tact and in good condition though all original pressed metal cornices, pediment and typical period storefront detail had been removed.

The current renovated facade reflects a conscientious decision to specifically replace, through numerous reconstruction methods and historic photographs an historically correct circa 1889-1895 facade. As a result the facade now features appropriate replacement of the vast majority of the historic facade detail originally designed by the architect, Montezuma Fuller.

At grade level, a wood storefront system, consisting of wood kickplates, properly proportioned windows with transoms above, recessed entries with transoms and dentiled belt cornice signband re-establishes the historic street level proportions. Likewise the brick pilasters with rustic cut buff colored sandstone inlays were restored and/or replaced. Also, the original exposed castiron support columns were refurbished and their missing cap and base detail replaced.

¹The renovation was completed in 1984.

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Item number 7 Page 2 Continuation sheet Kissock Block Building

Renovation has also addressed re-establishing the second story fenestration and detail. Therefore the one-over-one double hung wood windows (with pink sandstone sills, intermediate transom lintel, and bold structural lintel) reflect the symmetry and rhythm of the 3-3-3 upper story fenestration pattern. Of major impact is the reconstruction of the upper cornice and pediment. Using a combination of formed sheet metal, pressed metal reproduction appliques, and milled wood ornament, this detail has been replaced. Thus the historic architectural elements of 4 major corbels, 6 minor brackets, 27 modillions, dentils and festooning have all been replaced.

Interior

The original first floor retail spaces of the Kissock Block Building most likely contained minimal detail or ornamentation. Review of limited interior photographs only revealed smooth plastered walls, wood floors, and basic millwork detail. However, actual detail remaining has been rehabilitated, including an intact pressed tin ceiling in the most westerly retail bay.

The second level contains a higher level of millwork detailing as exemplified by window jamb and sill trim, deep wood base molding, and "bead-board" wainscotting in the stairway, hallway, northern office, and the "old" ballroom space. Therefore missing sections were duplicated and replaced using a model of existing millwork.

Due to extensive subsequent fire damage on at least three occasions to the "old" ballroom space, the original plastered coffered ceiling in this space was destroyed beyond repair. Plus subsequent inplace structural roof repairs and reinforcement precluded reconstruction of this circa 1895 interior element without jeopardizing building integrity, let alone meeting current roof load capacity requirements.

Only one skylight was discovered on the second level (refer to photo #5). This single skylight was saved and refurbished. Likewise in this same space, the existing pressed tin ceiling was also refurbished by replacing missing panels and cove molding (refer to photo #4). Plus "spare" tin ceiling components discovered in the "attic space" were recycled within the second floor spaces adjacent to this space. Various areas where existing finished wood flooring was discovered were refurbished.



Exp. 10-31-84

OMB No. 1024-0018

8. Significance

Period	Areas of SignificanceC	heck and justify below		
prehistoric 1400–1499 1500–1599	archeology-prehistoric archeology-historic agriculture	 community planning conservation economics 	landscape architecture law literature	e religion science sculpture
1600–1699 1700–1799	XX architecture art	education engineering	military music	XX social/ humanitarian
XX 1800–1899 1900–	commerce communications	exploration/settlement industry invention	t philosophy politics/government	theater transportation other (specify)
		· · · · · · · · · · · · · · · · · · ·		(-t /)

Specific dates 1889

Builder/Architect Architect: Montezuma Fuller

Statement of Significance (in one paragraph)

The Kissock Block Building in Fort Collins is significant as a good representative of the late 19th Century Commercial style within the community. As restored, the building is one of few commercial structures of its period with an intact storefront. It is also of interest for its association with John A. C. Kissock, a prominent local figure whose major public contribution was in the founding of the city's sewer system.

Constructed in 1889, the Kissock Block was designed and built for owner John A. C. Kissock by noted local architect Montezuma Fuller. (Other structures on the National Register credited to Fuller in Fort Collins include the Avery House and the Montezuma Fuller House.)¹ Upon completion, the initial tenants of the building were a furniture store; Edwards, Kissock and Abbott, the city's first abstracting company; and Scotts' Drugstore. ²

Kissock is especially known in Fort Collins for his part in the establishment of the city's first sanitary sewer system. Although Kissock clearly recognized the need for a sewer system in the rapidly growing community, the general populace initially opposed the project because of the expense. Persistent in his convictions, Kissock brought experts from Denver at his own expense to make feasability studies and cost estimates. Finally, in 1888, he persuaded city officials to install 2,870 feet of sewer line down Mountain Avenue to observe the results. City officials and citizens apparently gave their approval in that by 1911 over 19 miles of sewer system had been laid. For his early and financial support, John A. C. Kissock is now known as "the Father of Fort Collins' Sewer System."³

The Kissock Building was also an important center for social activities in the Fort Collins community. In 1895, the Independent Order of Oddfellows opened their new Grand Hall, occupying the entire second floor of the building. The agreement between Kissock and the Lodge required the Oddfellows to keep the roof in good repair and rebuild the second floor. For \$6,000 this was done and for the next fifty years the Kissock Block Building was the site of grand balls, banquets and dances sponsored by the Oddfellows.⁴

The structure as now restored reflects a style typical of the late 19th century. Almost all the original exterior elements such as the cornice, window treatment, and storefront have been restored. Of special note is the storefront which has been carefully restored with only minor modifications, such as the front entrance.

¹Evadene Burris Swanson, <u>Fort Collins, Yesterdays</u> (Evadene Burris Swanson, 1975), p. 170 ²Ibid., p. 170.

³Ansel Watrous, <u>History of Larimer County, Colorado</u> (Courier Printing and Publishing Company, 1911), p. 25.

⁴Stewart G. Case, <u>The First 100 Years A Historical Sketch of Fort Collins I.O.O.F.</u> #19, 1874-1974.

9. Major Bibliographical References

(see continuation sheet, Item $#8 \ 1 \ of \ 1$)

· ·	15	acres			
Acreage of	nominated property15 e nameSE/4 Fort Coll	ling 15' Ouadr	angle	Quadranal	scale1:24000
Juaorangie JTM Refere		True to dam	angre	Quadrangi	
	inces				
A 1 3 Zone	4 9 3 5 9 0 Easting Northing	12 6 17 1 g	B Zone E	Easting	Northing
			D		
	┶ ╶┖╴┖╶┫╸╹ ╴╹╴╹╴╹				
		┸──┠──┠──┩	нЦті		
/erbal bo	undary description and j	ustification			
Block	60 feet of Lots 7, 8, 121 in the city of F	Fort Collins.			feet of Lot 10, ea, the Kissock
	is the only building ates and counties for pro		ning state or cou	nty boundaries	
	NA		-	inty boundaries	
state		code	county		code
state		code	county		code
		ad Dr			
<u> </u>	Form Prepare	еа ву			
(a b a b	Dick Beardmore				
name/title	Walter F. Brown	•	Edit	ted: Gloria 1	<u>/ills</u>
organizatio	 A-E Design Associ Mountain Avenue P 		nt Venture date	2 1/9/85	
	110 North Colle				
treet & nu	mber 117 E. Mountain	n Avenue,Suite	205 tele	phone (303)	482-3600
ity or towr	Fort Collins		state	e Colorado 8)524
12. 3	State Histori	c Preser	vation U	otticer C	ertification
The evaluat	ted significance of this prop	erty within the state	e is:		
	national		local		
	ignated State Historic Preser by nominate this property fo				
according t	to the criteria and procedure	s set forth by the N	lational Park Servi		
State Histo	ric Preservation Officer sign		Jaaro	- (کر ز ک	Y
				0000	
itle Stat	te Historic Preserva	ation Officer		date	1-15-85
Cor NOC	•	is included in the M	lational Register		
For NPS	INV CEPTITY THAT THE APARAMY				
	eby certify that this property	/ 13	NOTION IN COMPANY		Plinn
	Lelous Byce	2	tional Register	date	5/16/85
	of the National Register	2		date	5/16/85
I here Keeper	Velous Byen	2		. ,	5/16/85
I here Keeper Attest:	Velous Byen	2		date date	5/16/85

Kissock Block Building Larimer County, Colorado Photo: Photographer & date unknown. Shows building as it appeared in 1895. Photo courtesy of Fort Collins Library.

