		PH	03563	36	DAT	A SHE
Form 10-300 (Rev. 6-72)		S DEPARTMENT OF FIONAL PARK SERV		•	New Hampshi	re
N	ATIONAL REC	SISTER OF HIST	TORIC PLA		Merrimack	
	INVENTOF	Y - NOMINATI	ON FORM	F	FOR NPS US	
					INTRY DATE	
	(Type all entries	s - complete appl	icable sectio	ns)		•
A PAPAL						
COMMON:	** 100 Covered	d Bridge )	、 、	J		
AND/OR HI		I DITURE 1				
	loo Bridge					
2. LOCATION						· · · ·
	ND NUMBER:		<u></u>			
Newma	rket Road					
CITY OR TO				CONGRESSIO	NAL DISTRICT:	
Marne	r	• •		Second	1	
STATE			CODE	COUNTY:	,	COD
The second se	ampshire		33	Merrin	nack	013
3. CLASSIFIC	ATION	· · · · · · · · · · · · · · · · · · ·			e de <u>la sur de la</u>	- <u>_</u>
	ATEGORY Check One)		OWNERSHIP		STATUS	ACCESSIBLE TO THE PUBLI
District	Building	X Public	Public Acquisit	ion:	🕅 Occupied	Yes:
🔲 Site	Structure	🔲 Private	🔲 In Pro-	cess	Unoccupied	Restricted
	_ Object	🔲 Both	🔲 Being	Considered	Preservation wor	k 🔀 Unrestricted
					in progress	□ N•
PRESENT	JSE (Check One or M	lore as Appropriate)			<b>_</b>	
Agricul	tural 🔲 G	overnment	] Park		Transportation	Comments
🔲 Commer	cial 🗌 In	dustrial 🗌	] Private Reside	ence [	Other (Specity)	
🔲 Educati	ional 📋 Mi	litary 🗌	Religious	_		
🔲 Enterta	inment 🗌 Mı	useum	Scientific			
4. OWNER OF				n el fin el 🔊		
OWNER'S N		NI II				
		New Hampsh	118			
STREET AT	tmen's Offi	ce				
Main S	Street	R.D.	<u>#2</u>			
Varner				STATE:	lampshire 03	278 33
						210 33
	OF LEGAL DESC					
		Registry	of Deeds		,	
•	ND NUMBER:		Merri	nack Cou	nty Courthor reet	use
	Box 248		North		reet	
CITY OR T	DWN:	8		STATE		CODE
Conco	rd			Nou	Hampshire 0.	3301 013





DESCRIPTION						
				(Check One)		
CONDITION	🔲 Excellent	🔀 Good	🗌 Fair	Deteriorated	🗋 Ruins	🔲 Unexposed
		(Check Or	ne)		(Che	ck One)
	🔀 Alter	ed	Unaltered		Moved	🔀 Original Site

<u>Present Physical Appearance</u>: The Waterloo Bridge spans the Warner River near Waterloo Village connecting the town-owned Newmarket Road on either side.

The bridge consists of one span of Town lattice truss constructed of  $1\overline{1}$ " x  $2\frac{1}{2}$ " members bolted to other lattic members at their crossings. Each lattice member is joined in this manner to five opposite leaning members. The upper and lower chords are each made up of two members (each member 8" x 6") separated by a five inch space through which the lattice passes. Lattice members are both wooden pinned and iron bolted to the chords. On the inside face of each north leaning lattice member and on the outside face of each south leaning member are attached boards of the same size as the members themselves. These boards are cut at an angle to fit flush against the faces of the chords, but are not attached to the chords and provide extra support largely by bearing pressure. The truss walls are laterally braced by thirteen beams extended across the top chords, perpend- m icular to the roadbed; these beams are bolted to the chords. Beneath these beams, five sets of crossed iron tension rods connected through the top chords to provide further bracing. The same arrangement provides lateral bracing for the bottom chords.

The lattice truss is set on 11" square timbers at each corner which in turn rest on concrete footings at the top of each The abutments are of rectangular shape constructed abutment. out of split and irregular stone laid up without mortar.

The bridge has an overall roof and roadbed length of 84'5" C and 76'5" respectlively, with a vertical clearance of 12'. The -1 bridge has an overall width of 16'9" and a roadbed of 13'9" (pas-\_ able width of 12'11" due to guard rails). The road bed is of Ο boards laid length wise in the direction of the road and spiked Z to 11" thick supports that sit on top of the bottom chord. S

The roof is of corrugated metal set on rafters which rise from the outside member of the top chord and are strengthened by braces from the truss walls to the rafters at a point near the peak of the roof. The roof, supported by the top chord, overhangs each end of the bridge by four feet but is not connected by a cut back. Both walls and portals are sheathed in vertical boarding being allowed to weather gray. Each sidewall has three windows and is sheathed to a height twenty inches below the top chord; this opening is protected by a roof overhang on each side of two feet. The bridge has been assigned the following numbers: 29-07-04 in the World Guide to Covered Bridges published by the National Society for the Preservation of Covered Bridges; 157-087 by the New Hampshire Department of Public Works and Highways; 13 by the New Hampshire Department of Resources and Economic Development.

S m

Z

S

-

고

Original Physical Appearance: The concrete footings on

Continued on Continuation Sheet 2

	Appropriate)		
🏾 Pre-Columbian (	16th Century	18th Century	20th Century
15th Century	17th Century	🛐 19th Century	• ·
SPECIFIC DATE(S) (II Applical	ble and Known)	1859-1860	
AREAS OF SIGNIFICANCE (Ch	eck One or More as Approp	riate)	
Abor iginal	Education	Political	. 🔲 Urban Planning
Prehistoric	🕅 Engineering	🔲 Religion/Phi-	Other (Specify)
🔲 Historic	🔲 Industry	. losophy	<u> </u>
🔲 Agriculture	Invention	Science .	•
Architecture	Landscape	Sculpture	
🗋 Art	Architecture	Social/Human-	
Commerce	Literature	itarian	
Communications	🔲 Military	Theater	
Conservation	Music	🕅 Transportation	
least one of the the early ninete the Dalton Bridg ed where, for th	mer River, it many bridges enth century s ge, it is diff: ney were mostly	is reasonable to built by the to spanned this cro icult to know wh y attached to pl	to assume that own of Warner ossing. (As to hich bridge co lace and perso
least one of the the early ninete the Dalton Bridg ed where, for th names which no 1 umentation.) In was repaired at the town of Warn this amount was of the bridge wi	ner River, it many bridges enth century s ge, it is diff: onger exist an 1857 a bridge a cost of \$78 ner for buildin paid to Duttor th lesser amou	is reasonable to built by the to spanned this cro icult to know wh y attached to pl nd for which the e referred to as .00. <sup>2</sup> In 1860 \$4 ng Waterloo Brid n Woods for the unts being paid	to assume that own of Warner ossing. (As we have and person ere is no good "Waterloo Br 73.65 was pai lge. The bulk actual build to William Be
least one of the the early ninete the Dalton Bridg ed where, for th names which no 1 umentation.) In was repaired at the town of Warn this amount was of the bridge wi William B. Davis tasks. <sup>3</sup> The smal	ner River, it many bridges enth century s ge, it is diff: ney were mostly onger exist an 1857 a bridge a cost of \$78 ner for buildin paid to Dutton th lesser amon , Eleazor Davi 1 cost of the	is reasonable to built by the to spanned this cro icult to know wh y attached to pl nd for which the e referred to as .00. <sup>2</sup> In 1860 \$4 ng Waterloo Brid n Woods for the unts being paid is, and John Col bridge relative	to assume that own of Warner ossing. (As we have and person re is no good "Waterloo Br 73.65 was pai lge. The bulk actual build to William Be by for relate to other bri
least one of the the early ninete the Dalton Bridg ed where, for th names which no 1 umentation.) In was repaired at the town of Warn this amount was of the bridge wi William B. Davis tasks. <sup>3</sup> The smal being built at t	ner River, it many bridges enth century s de, it is diff: ney were mostly onger exist and 1857 a bridge a cost of \$78 ner for buildin paid to Duttor th lesser amount f, Eleazor Davis 1 cost of the the time by the	is reasonable to built by the to spanned this cro icult to know wh y attached to pl nd for which the e referred to as .00. <sup>2</sup> In 1860 \$4 ng Waterloo Brid n Woods for the unts being paid is, and John Col bridge relative e town of Warner	to assume that own of Warner ossing. (As we have bridge of ace and person re is no good "Waterloo Br 73.65 was pai lge. The bulk actual build to William Be by for relate to other bri seems to ind
least one of the the early ninete the Dalton Bridg ed where, for th names which no 1 umentation.) In was repaired at the town of Warn this amount was of the bridge wi William B. Davis tasks. <sup>3</sup> The smal being built at t that the abutmen	ner River, it many bridges enth century s de, it is diff: ney were mostly onger exist and 1857 a bridge a cost of \$78 ner for building paid to Duttor th lesser amon , Eleazor Davi 1 cost of the the time by the sts were merely	is reasonable to built by the to spanned this cro icult to know wh y attached to pl nd for which the e referred to as .00. <sup>2</sup> In 1860 \$4 ng Waterloo Brid n Woods for the unts being paid is, and John Col bridge relative e town of Warner y repaired and n	own of Warner ossing. (As we hich bridge cr ace and person re is no good "Waterloo Br 73.65 was pai lge. The bulk actual build to William Be by for relate to other bri seems to ind not new, and t
least one of the the early ninete the Dalton Bridg ed where, for th names which no 1 umentation.) In was repaired at the town of Warn this amount was of the bridge wi William B. Davis tasks. <sup>3</sup> The smal being built at t that the abutmen the bridge might	ner River, it many bridges enth century s ge, it is diff: ney were mostly onger exist an 1857 a bridge a cost of \$78 ner for buildin paid to Duttor th lesser amon , Eleazor Davi 1 cost of the the time by the the time by the	is reasonable to built by the to spanned this cro icult to know wh y attached to pl nd for which the e referred to as .00. <sup>2</sup> In 1860 \$4 ng Waterloo Brid n Woods for the unts being paid is, and John Col bridge relative e town of Warner y repaired and n avily rebuilt in	to assume that own of Warner ossing. (As we have bridge of ace and person re is no good "Waterloo Br 73.65 was pai lge. The bulk actual build to William Be by for relate to other bri seems to ind ot new, and to stead of beir
least one of the the early ninete the Dalton Bridg ed where, for th names which no 1 umentation.) In was repaired at the town of Warn this amount was of the bridge wi William B. Davis tasks. <sup>3</sup> The smal being built at t that the abutmen	ner River, it many bridges enth century s ge, it is diff: ney were mostly onger exist an 1857 a bridge a cost of \$78 ner for buildin paid to Duttor th lesser amon , Eleazor Davi 1 cost of the the time by the the time by the	is reasonable to built by the to spanned this cro icult to know wh y attached to pl nd for which the e referred to as .00. <sup>2</sup> In 1860 \$4 ng Waterloo Brid n Woods for the unts being paid is, and John Col bridge relative e town of Warner y repaired and n avily rebuilt in	to assume that own of Warner ossing. (As we have and person ace and person re is no good "Waterloo Br 73.65 was pai lge. The bulk actual build to William Be by for relate to other bri seems to ind ot new, and to stead of bein

or possible reconstruction, Waterloo Village had several mills, the ruins and basement walls of which are visible from the bridge; the village had grown up around these mills and a railroad line that had had a small station near the north end of the Waterloo Bridge.<sup>5</sup> With the abandonment of the mills and the railroad line, only a small rural population is left which the bridge continues to serve. Waterloo Bridge porvides one lane passage with no posted weight limits.

```
<sup>1</sup>Town Clerk's Records, Selectmen's Office, Warner, New Hampshire, Vol. 3, p. 457.
<sup>2</sup><u>Report of the Selectmen of the Town of Warner</u> (Concord: Tripp & Osgood, 1857), p. 6.
<sup>3</sup>Ibid., (1860), p. 7.
Continued on Continuation Sheet 3
```

9. MAJOR BIBLIOGRAPHICAL REFERE	NCES				
Secondary Sources:					
Hurd, D. Hamilton, ed.: <u>The History of Merrimack and Belknap</u> <u>Counties</u> . Philadelphia: J.W.L. wis & Co., 1885. p. 667.					
Report of the Selectmen of the Town of Warner. Concord: Tripp & Osgood, 1857. p. 6.					
Report of the Selectmen of the Town of Warner. Concord: Tripp & Osgood, 1860. p. 7.					
Continued on Continuat	ion Sheet	_4	° e		
10. GEOGRAPHICAL DATA					
LATITUDE AND LONGITUDE COO DEFINING A RECTANGLE LOCATING T		O R	DEFINING THE CENTER		
CORNER LATITUDE L	ONGITUDE		LATITUDE	LONGITUDI	Ξ
Degrees Minutes Seconds Degrees			Degrees Minutes Seconds	Degrees Minutes	Seconds
	) , w		43 17 17 2 Jone 19 17	71° 51	29
SE	· · ·		E-268-175	N-4796-	525
APPROXIMATE ACREAGE OF NOMINATED	PROPERTY:	a	pprox .04 acres		
LIST ALL STATES AND COUNTIES FOR P	ROPERTIES OVER		PPING STATE OR COUNTY BO	UNDARIES	<b></b>
STATE:	CODE		COUNTY		CODE
STATE:	CODE		COUNTY:		CODE
STATE:	CODE		COUNTY:	•	CODE
STATE:	CODE		COUNTY:		CODE
I. FORM PREPARED BY	<b>.</b>				L
NAME AND TITLE:	<u>18899911801180118</u>		<u> </u>		
Brian R. Pfeiffer			:	• _	
ORGANIZATION			· · ·	June 20,	1974
STREET AND NUMBER:					
135 Ivy Street					
CITY OR TOWN:		s	TATE	00110	CODE
Brookline			Massachusetts	<u>02146</u>	23
As the designated State Liaison Offic tional Historic Preservation Act of 19 89-665), I hereby nominate this proper in the National Register and certify th	er for the Na- 66 (Public Law ty for inclusion		I hereby certify that this pr National Register		

S

.

NSTRUCT

-0

S N



☆ U.S. GOVERNMENT PRINTING OFFICE : 1973-729-147/1442 3-1

Form 10-300a (July 1969)	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE	STATE Nou Homophiro
	NATIONAL REGISTER OF HISTORIC PLACES	New Hampshire
	INVENTORY - NOMINATION FORM	Merrimack
		FOR NPS USE ONLY
	(Continuation Sheet) 1.	
(Number all entri	es)	NOV 2 1 1073
Histo 1974 Histo	ESENTATION IN EXISTING SURVEYS, con oric American Engineering Record , x Federal oric American Engineering Record	ntinued
	L Street, NE Ington, D.C. 20240, 11	
New H 1970 State Depai P.O.	Hampshire's Historic Preservation , x State e of New Hampshire ctment of Resources and Economic D Box 856, State House Annex, 25 Ca ord, New Hampshire 03301, 33	evelopment
	RECEIVE	ONAL AND

GP0 921.724

Form 10-300a (July 1969)	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE	New Hampshire	
	NATIONAL REGISTER OF HISTORIC PLACES	COUNTY	
	INVENTORY - NOMINATION FORM	Merrimack	
	INVENTORI - NOMINATION FORM	FOR NPS USE ONLY	
	(Continuation Sheet) 2.	ENTRY NUMBER DATE	
(Number all entri	les)		
7. DESCR	IPTION, continued		
the a to th new w in 19	<u>nal Physical Appearance, continued</u> : dded members of the lattice which a le truss system, but merely brace it ood exterior and metal roof are alt 70 when the bridge was extensively 00 under the state Town Bridge Aid	re not incorporated in on its sides, and the erations that were mad repaired at a cost of	
inte	erview, Concord, New Hampshire, June	11, 1974.	
		PEREL'S ATE	



GPO 921-724

Form 10-300a (July 1969)	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE	STATE New Hampshire
	NATIONAL REGISTER OF HISTORIC PLACES	Merrimack
	INVENTORY - NOMINATION FORM	FOR NPS USE ONLY
	(Continuation Sheet) 3.	ENTRY NUMBER DATE
(Number all entri	ea)	
8. SIGNIF	ICANCE, continued	
	book of Warner, New Hampshire, com Pillsbury Public Library, Warner,	
5 <sub>D</sub> . He	milton Hurd, ed., The History of Me	errimack and Belknap
Count	ics (Philadelphia: J.W.Lewis & Co.	, 1885), p. 667.
		Jr. Marine Strange
		10.
	-	

## GPO 921-724

.

	10-300a 1969)	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE NATIONAL REGISTER OF HISTORIC PLACES	New Hampshire
		INVENTORY - NOMINATION FORM	Merrimack
			FOR NPS USE ONLY
		(Continuation Sheet) 4.	ENTRY NUMBER DATE
(Nun	nber all enti	ries)	
9.	MAJOR	BIBLIOGRAPHICAL REFERENCES, continu	ued
	Unpub	lished Sources:	
	Sarge	ent, Dollie M. Scrapbook of Warner, bury Public Library, Warner, New Har	
		Clerk's Records, Selectmen's Office Vol. 3, p. 457.	, Warner, New Hampshire,
			NSI IIO
			IN RECEIVIL
		/ 	
			0 STEN STEN
			H. M. Ch



GPO 921.724

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## FOR NPS USE ONLY

RECEIVED 1970

## NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

DATE ENTERED NO

NOV 2 1 1973

CONTINUATION SHEET	ITEM NUMBER $10$ .	PAGE	5.

- 10. GEOGRAPHICAL DATA, continued
- 10.2 UTM References

Zone	Easting	Northing
19	2.68.175	47.96.525