

MS HARDWARE CO



Photo # 1

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

November 27, 1981

Negative at Photo House, Andalusia, AL

View: looking southeast at side and front
of building



100

Photo # 2

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

November 27, 1981

Negative at Photo House, Andalusia, AL

View: looking northwest at backside and
rear of building



Photo # 3

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

November 27, 1981

Negative at Photo House, Andalusia, AL

View: looking north at backside of building



Photo # 4

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

November 27, 1981

Negative at Photo House, Andalusia, AL

View: looking south at side of building



Photo # 5

FIRST NATIONAL BANK BUILDING
101 S. Cotton St., Andalusia, AL
Harold Williams, photographer
November 27, 1981

Negative at Photo House, Andalusia, AL
View: looking southeast at side and front
of fifth and sixth stories, showing
decorative molding between those
stories and decorative molding
around the roof



Photo # 6

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

November 27, 1981

Negative at Photo House, Andalusia, AL

View: looking southwest at rear and side
of building



Photo # 7

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

November 27, 1981

Negative at Photo House, Andalusia, AL

View: showing decorative moldings



Photo # 8

FIRST NATIONAL BANK BUILDING
101 S. Cotton St., Andalusia, AL
Harold Williams, photographer

November 27, 1981

Negative at Photo House, Andalusia,
View: showing detail of molding around
roof of building

8



Photo # 10

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

December 14, 1981

Negative at Photo House, Andalusia, AL

View: looking east at front of building
showing main entrance; also,
showing front window on ground floor
after restoration



Photo # 11

FIRST NATIONAL BANK BUILDING

101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

December 14, 1981

Negative at Photo House, Andalusia, AL

View: looking south at the Coffee Street
entrance located about half way
between front and rear of building
(original doors)



Photo # 12

FIRST NATIONAL BANK BUILDING


101 S. Cotton St., Andalusia, AL

Harold Williams, photographer

December 14, 1981

Negative at Photo House, Andalusia, AL

View: looking south at Coffee Street
entrance to elevator lobby, located
near rear of building
(original doors)



W LOAN

Photo # 13

FIRST NATIONAL BANK BUILDING
101 S. Cotton St., Andalusia, AL
Photographer unknown

July 1943

Original photo at Commercial Bank, Andalusia
View: Interior of ground floor looking
east toward rear of bank



Photo # 14

FIRST NATIONAL BANK BUILDING

101 S. Cotton Street, Andalusia, AL

Bob Hale, photographer

October 1981

Negative at Andalusia Star News, Andalusia

View: Interior of ground floor looking
east toward rear of ice cream parlor
(originally bank area)



Photo # 16

FIRST NATIONAL BANK BUILDING

101 S. Cotton Street, Andalusia, AL

Harold Williams, photographer

December 14, 1981

Negative at Photo House, Andalusia, AL

View: Interior of ground floor looking up
at ceiling at southwest corner of
main room, showing decorative
moldings